



JACK CARS

ESTIMATE

DATE OF ACCIDENT : 29/07/2018
VEHICLE : SLU3332U
MAKE & MODEL : HONDA ODYSSEY
INSURANCE : AXA INSURANCE <i>Cecilia. RC11127407.</i>
SURVEYOR : LKK AUTO

	PARTS	CONDITION	COST
1.	REAR BOOT <i>Distorted</i>		\$ 1805 1210
2.	REAR BOOT GARNISH - UPPER <i>ut</i>		\$ 430 ✓ 275
3.	REAR BOOT GARNISH - LOWER <i>could</i>		\$ 300 ✓ 215
4.	REAR BOOT HINGE - LEFT <i>3 up</i>		\$ 150 +
5.	REAR BOOT HINGE - RIGHT <i>m</i>		\$ 150 +
6.	REAR BOOT LOCK <i>Jammed</i>		\$ 305 ✓
7.	REAR BOOT WEATHER STRIP <i>ut</i>		\$ 405 126
8.	TAIL LAMP - OUTER LEFT <i>3 ut</i>		\$ 1045 821
9.	TAIL LAMP - OUTER RIGHT <i>could</i>		\$ 1045 821
10.	TAIL LAMP - INNER LEFT <i>could</i>		\$ 610 388
11.	TAIL LAMP - OUTER RIGHT <i>could</i>		\$ 610 388
12.	REAR BUMPER <i>Distorted</i>		\$ 990 - 725
13.	REAR BUMPER CHROME LINING - RIGHT <i>could</i>		\$ 152 ✓
14.	REAR BUMPER BRACKET - RIGHT <i>m</i>		\$ 40 ✓
15.	REAR RIGHT DOOR COVER <i>Here</i>		\$ 460 ✓
16.	REAR RIGHT SIDE PAD <i>Rel d.</i>		\$ 115 ✓
17.	REFLECTOR - RIGHT <i>ut</i>		\$ 70 ✓
18.	REAR END PANEL <i>Distorted</i>		\$ 685 ✓
19.	REAR END PANEL TOP COVER <i>Rel d</i>		\$ 180 ✓
20.	REAR RIGHT FENDER	REPAIR	

6536
522880



JACK CARS

SPECIAL NETT			
2.	REVERSE SENSOR <i>2nd</i>		\$ 200 ✓
3.	WINDSCREEN MOULDING <i>in</i>		\$ 120 ✓
4.	CLIPS <i>in</i> <i>350</i>		\$ 80 <i>30</i>
LABOUR			
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA		\$ 2200 <i>1200</i>
2.	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS		\$ 2500 <i>1200</i>
3.	TO CHECK WIRING & REWIRE		\$ 80 <i>30</i>
4.	TO REMOVE AND REINSTALL TAIL LAMP COMPONENTS		\$ 120 <i>x.</i>
5.	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY		\$ 120 <i>80</i>
6.	TO REMOVE AND REINSTALL REAR WINDSCREEN		\$ 200 <i>120</i>
7.	TO REMOVE & REINSTALL REVERSE SENSOR		\$ 150 <i>50</i>
8.	TO CHECK LIGHTING SYSTEM & WATER TEST FOR ANY LEAKAGE	<i>2740</i>	\$ 120 <i>x.</i>
9.	ANTI RUST TREATMENT		\$ 120 <i>60</i>
PARTS - 20%:		\$ 7,637.60	
SPECIAL NETT :		\$ 400	
LABOUR :		\$ 5,610	
TOTAL :		\$ 13,647.60	
7% GST :		\$ 955.33	
GRAND TOTAL :		\$ 14,602.93	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lij *Supplementary: 272720*
06/08/18- *total: 11046*
P/P 08-09 Days. *(P/P)*



SUPPLEMENTARY

DATE OF ACCIDENT : 29/07/2018
VEHICLE : SLU3332U
MAKE & MODEL : HONDA ODYSSEY
INSURANCE : AXA INSURANCE
SURVEYOR : LKK AUTO

PARTS		CONDITION	COST
1.	REAR BOOT INNER HANDLE <i>cracked</i>		\$ 75 ✓
2.	REAR BOOT INNER COVER <i>Deformed</i>		\$ 580 ✓
3.	REAR RIGHT FENDER INNER COVER <i>Deformed</i>		\$ 1080 779 ✓
4.	REAR END PANEL SPEAKER <i>2 Damaged</i>		\$ 135 ✓
5.	REAR END PANEL SENSOR		\$ 110 ✓
6.	REAR RIGHT SEAT BELT <i>Jammed</i>		\$ 1020 750 ✓
7.	REAR AIRCON BLOWER <i>cracked</i>		\$ 980 ✓
PARTS - 20%:		\$ 3,184	
7% GST :		\$ 222.88	
GRAND TOTAL :		\$ 3,406.88	

3409

Supplementary : 2727.20