

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III18014228/KTD3E2

Date: 26/10/2018

REFERENCE

Insured/Claimant:	TEO HUI CHU JOYCE	Policy No:	18MPC00012082	
Date of Loss:	26/07/2018	Nature of Claim:	OD	Claim No: MC20182657

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV351C	Engine No:	G4FC9U767991
Make & Model:	HYUNDAI I30 CW, 1.6 GLS (FD) (A)	Chassis No:	KMHDC81DMAU063422
Reg. Date:	08/01/2010 (Man. Year: 2009)	Odometer:	83380 km
Colour:	Metallic Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$17,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,201.73	3,154.80	2,046.93	39.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,840.00	1,040.00	800.00	43.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,041.73	4,194.80	2,846.93	40.43
Approved Total (Overridden) (S\$)		3,300.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
Nett Amount (S\$)	6,441.73	2,700.00	3,741.73	58.09

INSPECTION

Date of Assignment:	06/08/2018		
Date Inspected:	06/08/2018	Inspected At:	Loh Heng (HQ) 176 Sin Ming Drive, #03-08 Sin Ming Auto Care Singapore 575721
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 Oct 2018)	
Parts:	N/A	HYUNDAI I30 CW 1.6 GLS (FD) (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV351C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER	Buckled	643.30 FL	*643.30 FL	
2	1		*FRONT BONNET	Bent	1,774.10 FL	*1,774.10 FL	
3	1		*HEADLAMP RIGHT	Mtg Cracked	686.30 FL	*686.30 FL	
4	1		*HEADLAMP LEFT	Serviceable	686.30 FL	*- FL	
5	1		*BUMPER REINFORCEMENT	Bent	324.60 FL	*324.60 FL	
6	1		*FRONT SUPPORT PANEL	Repair	876.90 FL	*- FL	
7	1		*BUMPER RETAINER RIGHT	Distorted	29.70 FL	*29.70 FL	
8	1		*BUMPER SPONGE	Cracked	121.40 FL	*121.40 FL	
9	1		*FOG LAMP LEFT	Serviceable	186.70 FL	*- FL	
10	1		*FOG LAMP RIGHT	Mtg Cracked	186.70 FL	*186.70 FL	
11	1		*BUMPER GRILLE	Dented	87.20 FL	*87.20 FL	
12	1		*BONNET LOCK	Repair	86.30 FL	*- FL	
13	1		*WIPER TANK	Dented	90.20 FL	*90.20 FL	
					Sub Total (\$\$)	5,779.70	3,943.50
					- List Item Discount on L Items 10.00/20.00% (\$\$)	577.97	788.70
					Total Parts (\$\$)	5,201.73	3,154.80

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE DAMAGED PARTS, KNOCKING AND RESTRAIGHTENING OF INNER PANEL, REALIGNMENT AND READJUSTMENT.	New	880.00	500.00
2	TO REMOVE AND REPLACE AIR-CON CONDENSER, REFILL AIR-CON GAS.	New	160.00	0.00
3	TO RESPRAY + PUTTY ON DAMAGED PARTS.	New	800.00	540.00
			Gross Labour Cost (\$)	1,840.00
				1,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >