

Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Enquire Vehicle & Owner Information (Vehicle No. SHC8472H As At 06 Apr 2018 / 18:05:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: FBG9643A

Current Owner Details

Owner ID Type: Company

Owner ID: 199303821R

Owner Name: COMFORT TRANSPORTATION PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 383

Registered Street Name: SIN MING DRIVE

Registered Unit No.: -

Registered Building Name: GAS BUILDING

Registered Postal Code: 575717

Current Vehicle Details

Vehicle No.: SHC8472H

Make Description/Model: HYUNDAI / I40 1.7 CRDI F/L AT ABS AIRBAG 4DR

Insurance Company Name: INDIA INT'L INS PTE LTD

TAX INVOICE

Our Ref No: GR-18-073871

Date of Request: 15/05/2018

Your Ref No: WALK IN POON YW

MOTO 51 PTE LTD
2 KAKI BUKIT AVENUE 2, #01-17, KAKI BUKIT AUTOHUB
SINGAPORE 417921

Dear Sir/Madam,

Date of Accident: 06/04/2018

Vehicle No: FBG9643A

Place of Accident: 110 SELETAR AEROSPACE VIEW

Involving Vehicle No: SHC8472H

With reference to your application for the accident report, we have attached the following accident reports as requested:

| DOCUMENTS | ACCIDENT LOCATION | PER DOC (S\$) | QTY | AMOUNT (S\$) |
|----------------------------------|----------------------------|---------------|-----|--------------|
| SHC8472H | 110 SELETAR AEROSPACE VIEW | 14.00 | 1 | 13.08 |
| GST Amount | | | | 0.92 |
| Total Amount Due (GST Inclusive) | | | | 14.00 |

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-066803

Date of Request: 03/05/2018

Your Ref No: WALK IN POON YW

MOTO 51 PTE LTD
2 KAKI BUKIT AVENUE 2, #01-17, KAKI BUKIT AUTOHUB
SINGAPORE 417921

Dear Sir/Madam,

Your Vehicle No: FBG9643A

Date of Accident: 06/04/2018

Place of Accident: 110 SELETAR AEROSPACE VIEW

Involving Vehicle No: SHC8472H (NO REPORT) CALL WITHIN 7 DAYS 4-14/5

| DESCRIPTION | AMOUNT (S\$) |
|----------------------------------|--------------|
| E-File Search Fee (Public) | 14.02 |
| GST Amount | 0.98 |
| Total Amount Due (GST Inclusive) | 15.00 |

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque

MOTO 51 PTE LTD

Kaki Bukit Autohub, 2 Kaki Bukit Ave 2, #01-18

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : moto51@n51.com.sg

Company Reg. No. : 201536417C

MA CHEE TUAN

BLK 246 BANGKIT ROAD #06-298

SINGAPORE 670246

Contact : 90296230, 96670858

TAX INVOICE

Date : 09/07/2018

Date in : 27/04/2018

Vehicle Num. : FBG9643A

Make/Model : P.G.O. TIGRA 150 EFI-2012

Chassis/Eng# : RFVAFAFASC1003007/A5F03057

Accident Date : 06/04/2018

Claim No : CLM13286

Reference : APR-08/2018

Policy No. : MC/00446131 (25/01/2019)

LUMPSUM REPAIR BILL

AS PER SURVEYOR REPORT

REF : CAS/18-06/042 DATED 27/04/2018

BY CONSTANT APPRAISER SERVICES

Amount S\$

6,500.00

E. & O.E. Sub S\$: 6,500.00

Total Amount S\$: 6,500.00



for MOTO 51 PTE LTD

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters
Blk 2 Rivervale Link, #09-02 Singapore 545040
Tel/Fax: 6886 1106 Mobile: 9007 5234
Email: constant_as@yahoo.com.sg
RCB No. 53138015K

INVOICE

To: Ma Chee Tuan
c/o 2 Kaki Bukit Ave 2
#01-17 Kaki Bukit Autohub
Singapore 417921

Date : 18/06/2018

Invoice No : IV18-06042/CAS

| Particulars | Amount |
|---|----------|
| Fee For Services Rendered In Respect Of: Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle FBG 9643A (Inclusive Of Photographs And Transport Charges) Our reference : CAS/18-06/042 | \$713.00 |
| Total | \$713.00 |

E. & O.E.

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

Constant Appraiser Services

Vehicle No : FBG 9643A

Our ref : CAS/18-06/042

Adjustment On Repair Costs And Replacement Of Parts:

| S/No | Qty | Descriptions | Assessed Condition | Estimate by Workshop (\$) | Revised Amount (\$) |
|---|------|--|--------------------|---------------------------|---------------------|
| <u>PARTS REPLACEMENT – LIST ITEMS</u> | | | | | |
| 1 | 1pc | Air box assy | Grazed | 220.00 | 220.00 |
| 2 | 1pc | Belt casing | Dented/Grazed | 280.00 | 280.00 |
| 3 | 1pc | Exhaust muffler | Dented/Grazed | 960.00 | 960.00 |
| 4 | 1pc | Exhaust muffler cover | Grazed | 177.00 | 177.00 |
| 5 | 1pc | Front brake disc | Serviceable | 225.00 | - |
| 6 | 1pc | Front brake lever RH | Grazed/Bent | 76.00 | 76.00 |
| 7 | 1pc | Front cowling | Grazed/Broken | 408.00 | 408.00 |
| 8 | 1pc | Front cowling outer cover | Broken | 164.00 | 164.00 |
| 9 | 1pc | Front mudguard | Grazed/Broken | 308.00 | 308.00 |
| 10 | 2pcs | Front side cover R/L @ \$225.00 | Grazed/Broken | 450.00 | 450.00 |
| 11 | 2pcs | Front signal R/L @ \$107.00 | O/S Grazed | 214.00 | 107.00 |
| 12 | 1pc | Front step board | Grazed | 491.00 | 491.00 |
| 13 | 2pcs | Front step board side bottom cover R/L @ \$98.00 | Grazed/Broken | 196.00 | 196.00 |
| 14 | 1pc | Handle bar | Repair | 89.00 | - |
| 15 | 1pc | Headlamp assy | Serviceable | 334.00 | - |
| 16 | 1pc | Headlamp cover | Broken | 227.00 | 227.00 |
| 17 | 2pcs | Mirror R/L @ \$180.00 | O/S Grazed | 360.00 | 180.00 |
| 18 | 1pc | Rear footrest LH | Grazed | 72.00 | 72.00 |
| 19 | 1pc | Rear mudguard | Dented/Deformed | 256.00 | 256.00 |
| 20 | 1pc | Rear mudguard reflector | Necessary | 34.00 | 34.00 |
| 21 | 2pcs | Rear side cover emblem R/L @ \$105.00 | Necessary | 210.00 | 210.00 |
| 22 | 2pcs | Rear side cover R/L @ \$528.00 | Grazed/Broken | 1,056.00 | 1,056.00 |
| 23 | 2pcs | Rear suspension R/L @ \$568.00 | N/S Dented/Bent | 1,136.00 | 568.00 |
| 24 | 1pc | Taillamp assy | Serviceable | 282.00 | - |
| | | | | 8,225.00 | 6,440.00 |
| | | Less 10% | | (822.50) | (644.00) |
| | | Sub total | | 7,402.50 | 5,796.00 |
| <u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u> | | | | | |
| 1 | 1pc | Front no plate (sticker) | Necessary | 25.00 | 25.00 |
| 2 | 1set | Handle bar balancer set | Grazed | 65.00 | 65.00 |
| 3 | 1pc | Rear box | Grazed | 280.00 | 280.00 |

Constant Appraiser Services

Vehicle No : FBG 9643A

Our ref : CAS/18-06/042

| S/No | Qty | Descriptions | Assessed Condition | Estimate by Workshop (\$) | Revised Amount (\$) |
|--|-----|--|--------------------|---------------------------|---------------------|
| | | <u>PARTS REPLACEMENT – SPECIAL NETT ITEMS (CONT'D)</u> | | | |
| 4 | 1pc | Rear box bracket | Bent/Twisted | 220.00 | 220.00 |
| 5 | 1pc | Rear no plate | Bent | 30.00 | 30.00 |
| | | | Sub total | 8,022.50 | 6,416.00 |
| | | <u>LABOUR & MISC. CHARGES</u> | | | |
| 1 | | To remove, reinstall electrical wiring harness, check lighting. (to FR) | | 60.00 | 30.00 |
| 2 | | To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident | | 600.00 | 500.00 |
| 3 | | To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident | | 550.00 | 400.00 |
| 4 | | To Straighten body frame to the original position | | 350.00 | 250.00 |
| | | | Grand total | 9,582.50 | 7,596.00 |
| Recommended cost of lump sum repair (To its pre-accident condition) | | | | | 6,500.00 |

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$6,500.00** on a contractual basis. Under normal circumstances, the repair period would be about **14 (Fourteen)** working days.

Yours faithfully,

Constant Appraiser Services


Lim Yong Tian (Sebastian)
 Licensed Appraiser
 Adv. Dip. In Mechanical Engineering (AUS)
 MSAAA

6 days




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|-------------------------------|-------------------------------|---|
| INDIA INTERNATIONAL INSURANCE PL | | Ref : CS3/III18007978/Lsbs2-1 | |
| 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711 | | Date : 13-09-2018 |  |
| | | Code : III2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SHC 8472H | Veh. Inspected | FBG 9643A |
| Policy No. | MCOM0015 | Coverage (\$) | 0.00 |
| Claim No. | MCT18040882 | Excess (\$) | 0.00 |
| Assign From | JOEL NAH | Assign Date | 06/08/2018 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | P.G.O. TIGRA 150 | c.c | 150 |
| Engine No. | HIDDEN | Year of Reg. | 2013 |
| Chassis No. | RFVAFafa5C1003007 | Colour | RED |
| Odometer | 65859 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | GOOD | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 120/70-12 | PIRELLI | 5 mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | 130/70-12 | PIRELLI | 5 mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 06/04/2018 | Inspection Date | 02/05/2018 |
| Survey held at | BLK 10 KAKI BUKIT RD 2 #01-16 | | |
| Repairer | MOTO 51 PTE LTD | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 6 Working Days | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 9643A

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|----------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | AIR BOX ASSY | TO REPAIR SEE LABOUR | 220.00 | - |
| 1 | BELT CASING | TO REPAIR SEE LABOUR | 280.00 | - |
| 1 | EXHAUST MUFFLER | TO REPAIR SEE LABOUR | 960.00 | - |
| 1 | EXHAUST MUFFLER COVER | GRAZED | 177.00 | 177.00 |
| 1 | FRONT BRAKE DISC | SERVICEABLE | 225.00 | - |
| 1 | FRONT BRAKE LEVER RH | GRAZED / BENT | 76.00 | 76.00 |
| 1 | FRONT COWLING | TO REPAIR SEE LABOUR | 408.00 | - |
| 1 | FRONT COWLING OUTER COVER | BROKEN | 164.00 | 164.00 |
| 1 | FRONT MUDGUARD | TO REPAIR SEE LABOUR | 308.00 | - |
| 2 | FRONT SIDE COVER R/L @ \$225.00 | TO REPAIR SEE LABOUR | 450.00 | - |
| 2 | FRONT SIGNAL R/L @ \$107.00 | O/S GRAZED | 214.00 | 107.00 |
| 1 | FRONT STEP BOARD | TO REPAIR SEE LABOUR | 491.00 | - |
| 2 | FRONT STEP BOARD SIDE BOTTOM COVER R/L @ \$98.00 | GRAZED / BROKEN | 196.00 | 196.00 |
| 1 | HANDLE BAR | TO REPAIR SEE LABOUR | 89.00 | - |
| 1 | HEADLAMP ASSY | SERVICEABLE | 334.00 | - |
| 1 | HEADLAMP COVER | BROKEN | 227.00 | 227.00 |
| 2 | MIRROR R/L @ \$180.00 | O/S GRAZED | 360.00 | 180.00 |
| 1 | REAR FOOTREST LH | GRAZED | 72.00 | 72.00 |
| 1 | REAR MUDGUARD | DENTED / DEFORMED | 256.00 | 256.00 |
| 1 | REAR MUDGUARD REFLECTOR | NECESSARY | 34.00 | 34.00 |
| 2 | REAR SIDE COVER EMBLEM R/L @ \$105.00 | NECESSARY | 210.00 | 210.00 |
| 2 | REAR SIDE COVER R/L @ \$528.00 | TO REPAIR SEE LABOUR | 1,056.00 | - |
| 2 | REAR SUSPENSION R/L @ \$568.00 | SERVICEABLE | 1,136.00 | - |
| 1 | TAILLAMP ASSY | SERVICEABLE | 282.00 | - |
| | LESS 10% DISCOUNT | | -822.50 | -169.90 |
| | | | 7,402.50 | 1,529.10 |

Report Ref No. CS3/III18007978/Lsbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|----------------------|---------------------------|-------------------|
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | FRONT NO PLATE (STICKER) (SN) | NECESSARY | 25.00 | 25.00 |
| 1 | SET HANDLE BAR BALANCER (SN) | GRAZED | 65.00 | 65.00 |
| 1 | REAR BOX (SN) | TO REPAIR SEE LABOUR | 280.00 | - |
| 1 | REAR BOX BRACKET (SN) | TO REPAIR SEE LABOUR | 220.00 | - |
| 1 | REAR NO PLATE (SN) | BENT | 30.00 | 30.00 |
| | | | 620.00 | 120.00 |
| | <u>LABOUR</u> | | | |
| | TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING. (TO FR) | | 60.00 | 30.00 |
| | TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT. | | 600.00 | 300.00 |
| | TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF AIR BOX ASSY, BELT CASING, EXHAUST MUFFLER, FRONT COWLING, FRONT MUDGUARD, FRONT SIDE COVER R/L, FRONT STEP BOARD, HANDLE BAR, REAR SIDE COVER R/L, REAR BOX AND REAR BOX BRACKET. | | 550.00 | 240.00 |
| | TO STRAIGHTEN BODY FRAME TO THE ORIGINAL POSITION. | | 350.00 | 120.00 |
| | | | 1,560.00 | 690.00 |
| | GRAND TOTAL | | 9,582.50 | 2,339.10 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 1,800.00 |

Report Ref No. CS3/III18007978/Lsbs2-1

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.