























AutoProbe Consultants (Co.Reg.No:53140386J)

Blk 151A, Serangoon North Avenue 2, #02-81

Singapore 551151

Tel: 6269 9235 Fax: 6269 1446 Email: admin@autoprobe.com.sg

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CH/SU/A995/16S(PRS)

Date: 01/08/2016

REFERENCE

Indemnifying Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No: DDMCVSN1538381500

Insured Vehicle No: SGS1075U

Insured Vehicle No: GBD3110B

Date of Loss: 15/06/2016

Nature of Claim: TP

Claim No: SNM16D02579C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGS1075U

Make & Model: MITSUBISHI LANCER, 1.6 (A)

Engine No: 4G18HR8117

Reg. Date: 02/03/2007 (Man. Year: 2007)

Chassis No: JMYSTCS3A7U004843

Colour: Silver

Odometer: 131417 km

Engine Capacity: 1584 cc

Market Value/New Car Price: N/A

Insured (\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60R15	Rear Tyre Size:	195/60R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 7 mm

* Above values represent the remaining tyre tread depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff
Parts	0.00	0.00	0.00	
Scellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Intw... Labour	0.00	0.00	0.00	
Win...	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	0.00	0.00	0.00	
Approved Total (Overridden) (\$\$)		1,000.00		
(\$\$)	0.00	1,000.00	-1,000.00	
+ GST 7.00/7.00% (\$\$)	0.00	70.00	-70.00	
Nett Amount (\$\$)	0.00	1,070.00	-1,070.00	

SECTION

Date of Assignment: 16/06/2016

Date Inspected: 16/06/2016, 17/06/2016

Inspected At:

Perfect Motor (HQ)
NO.51 DEFU LANE 9
Singapore 539277

Estimated Period of Repair: 2.0 days

Inspector: Samuel Phun
Motor Assessor

Manager: Tay Beng Hee

"E: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

The vehicle sustained damages on the driver's door portion.

Despite our request, the repairer did not provide us with the repair estimate.

JR RECOMMENDATION

Repair Cost - \$1,000.00

Repair Duration - 2 Days

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Aug 2016)

Parts: 143 MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: **AutoProbe Consultants/SGS1075U/01/08/2016 19:29**

Valid: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

AutoProbe Consultants/SGS1075U/01/08/2016 19:29. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

AutoProbe Consultants/SGS1075U/01/08/2016 19:29. Not valid without Reference section.

< END OF ESTIMATES >

SGS1075U [GBD3110B] - Submitted by: AutoProbe Consultants (HQ)



1/26: PRS-Pre-Repair Photo



2/26: PRS-Pre-Repair Photo



3/26: PRS-Pre-Repair Photo

SGS1075U [GBD3110B] - Submitted by: AutoProbe Consultants (HQ)



4/26: PRS-Pre-Repair Photo



5/26: PRS-Pre-Repair Photo



6/26: PRS-Pre-Repair Photo

SGS1075U [GBD3110B] - Submitted by: AutoProbe Consultants (HQ)



7/26: PRS-Pre-Repair Photo



8/26: PRS-Pre-Repair Photo



9/26: PRS-Pre-Repair Photo

SGS1075U [GBD3110B] - Submitted by: AutoProbe Consultants (HQ)



10/26: PRS-Pre-Repair Photo



11/26: PRS-Pre-Repair Photo



12/26: PRS-Pre-Repair Photo

3S1075U [GBD3110B] - Submitted by: AutoProbe Consultants (HQ)



13/26: PRS-Pre-Repair Photo



14/26: PRS-Pre-Repair Photo



15/26: PRS-Pre-Repair Photo

SGS1075U [GBD3110B] - Submitted by: AutoProbe Consultants (HQ)



16/26: PRS-Pre-Repair Photo



17/26: PRS-Pre-Repair Photo



18/26: PRS-Pre-Repair Photo

SGS1075U [GBD3110B] - Submitted by: AutoProbe Consultants (HQ)



19/26: PRS-Post Repair Photo



20/26: PRS-Post Repair Photo



21/26: PRS-Post Repair Photo

SGS1075U [GBD3110B] - Submitted by: AutoProbe Consultants (HQ)



22/26: PRS-Post Repair Photo



23/26: PRS-Post Repair Photo



24/26: PRS-Post Repair Photo

SGS1075U [GBD3110B] - Submitted by: AutoProbe Consultants (HQ)



25/26: PRS-Post Repair Photo



26/26: PRS-Post Repair Photo

