

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SHD6389Z

Ref. No

TAX/08/18/2002

Reg. Date

09/01/2012

Vehicle Type

TAXI

Make

SSANGYONG

Model

RODIUS-SV270

Name of Driver

TAN KOK WAH

Type of Accident

HEAD TO REAR

Date / Time of Accident

01/08/2018 10:25:00 PM

Accident Reported Date / Time: 02/08/2018 12:00:00 AM

Surveyor is Required?

Yes

Survey by

Vehicle is Towed Back?

No

Towed Back Date/Time

Replacement Vehicle issued? :


Accident Repair Job Card No : 000024097351

Special Instruction to ARC, if any :

SHB4335C(COMFORT) - III

Prepared Date

: 02/08/2018 10:21:29 AM



Chassis No: KPTV0B1FSCP066727

Mileage

0

Work Shop:

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

507.00

Total Spray Painting Charges

653.00

0.00 0.00

Total Material Charges

Total Labout Charges

1,269.08

1,269.08

Other Charges

260.00

0.00

TOTAL

2,689.08

0.00

Lum Sum Total

2,700.00

0.00

No. of Repair Days

4.00

0.00 2.00

Prepared / Adjusted By

Arc / Surveyor Sing Off Date

: 02/08/2018 04:07:47 PM

06/08/2018 12:40:44 PM

Prepared / Adjusted Date

Remarks

Prepared Date : 02/08/2018 04:06:10 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date

Invoice Date :

Invoice Amount : 0.00

Prepared Date:

8/6/2018 3:59:32 PM

----- Downo of Nopali Latillates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO REPAIR REAR PORTION	507.00 3.00	0.00		
Total Labour	507.00	0.00		

Part 2 - Spray Painting & Panel Beating Related Works

Total Spray Painting & Panel Beating	653.00 300	0.00		
TO RESPRAY BUMPER BEAM	180.00 100	0.00		
TO REPSRAY REAR BUMPER	473.00 200	0.00		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Total Other Costs	260.00	0.00		
Total Other Costs	10	0.00		
TO WASH AND VACUUM	60.00	0.00		
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00		
TO CHECK WIRING AND SYSTEM FUNCTION	80.00 20	0.00		
	Quotation from ARC	Adjusted by Surveyor, if applicable		
Job Scope	Quotation from ABC	IA		

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

NAZ LKIC

6/8/18 1600

L/S

2 DAYS

APTER REPORT PHOTO

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen	Surveyor Approved	Photos Attached
7881A21 000	REAR		Rear Bumper Assy	1	925.27	10.00	832.74	Replace	Replace	NOXR
	COMMO N		REAR BUMPER CLIP	6	4.25	10.00	22.95	Replace	Replace	No 7
83901211 00	BODY		LAMP ASSY, REFLEX REFLECTOR LH	1	10.52	10.00	9.47	Replace	Replace	No X JVZ
83902211 00	BODY		LAMP ASSY, REFLEX REFLECTOR RH	1	10.52	10.00	9.47	Replace	Replace	Noxsuc
	REAR		REVERSE SENSOR	1	165.10	10.00	148.59	Replace		
78821210 00	BODY		ABSORBER ENERGY RR BUMPER	1	111.73	10.00	100.56	Replace	Replace	S ON
78830210 00	COMMO N		BEAM ASSY-IMPACT RR BUMPER	1	513.97	10.00	462.57	Replace	Replace	No o
		Т	OTAL MATERIALS					1,586.35	1,586.35	-
TOTAL MATERIALS(Discounted)							1,269.08			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price	Discount (%)	Final Price	ARC Check	, ,	LT
TOTAL SUPPLEMENTARY MATERIALS								Check	Check

AX/08/18/2002