

Surveyor

REF: CS3 / FCL 8007526 / THB 32

Special Instruction:

US: \$ 60900.00

ASSIGNMENT (Office)

From (Person): May Chua of FA Date/Time: 27072018
Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: SK Auto

Workshop: AMA Autocare

OD/FP Re-inspection / Evaluation

To Inspect Vehicle No: SKV 7870M Insured: SHD 6930K
at Workshop m/s: AMA Autocare Tel: 6778 3636 (M/min)
of: 36 Toh Guan Rd East #01-36

Policy No: Claim No: D1800306AMFSH

Sum Insured: Excess: 19042018

Make of Veh: D.O.A.

(Client's Record) 16.08.2018 (Thursday) @ 2pm - 3.30pm H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 24 days)

Date/Time: 10/10/2018 Submit Final Fig US 32,600, 17 days (Red \$ 28300, 46%; Original 24 days)

Date/Time	Action/Instruction
	SKV 7870M - (CS/FCL) 8007526 / THB 32
	SHD 6930K - X
	Cycle & Luggage (301 Alexandra Rd) (Jack - 9186 5601)
	Taufik, pls check all parts prices.
	Pls See me. 4/10.

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 11 OCT 2018

Para(3) : Nett Value

Market Value :
Salvage Value :
Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Date:

Basic & Add
Transport
Photos
Others
Total

420
50
98
1068

- 1) Date/Time 10/10/2018 File Pass to Typist
2) Date/Time File Return to
3) Date/Time File Pass to
4) Date/Time File Return to
5) Date/Time File Pass to
6) Date/Time File Return to

REF:

ASSIGNMENT

From _____ Date: _____
 Estimated Cost _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured _____

Excess: _____

(Client's Record)

Make of Veh. _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res: Yes or No

Lum Sum: _____

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date _____

Person Contacted: _____

Veh No. SKV 7870 M Yr Regn: 2015 / at
 Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mercedes BenzColour: Si/WhiteSp. Reading: 91364

Eng/No: _____

C/No: WDD 205 04 02 R 099 995Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/50R17R: N/A

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.I. _____

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 16/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Date/Time: File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time: File Return to?

2)

Report Format :

Lump Sum / I.B.L. / \$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Insp (\$)
☐ Weekend (\$)
☐

Survey Fee:

Transportation

) \$ + RS. \$

1) Photos

2) Other

TOTAL

[Signature]
 11/10/2018

Tanpin

REF:

FCI

ASSIGNMENT

Year: _____ Date: _____
 Estimated Cost: _____
 OD ☒ WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 in Workshop no: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. of Market Value: **4132K**
 IDAC Accident Report Consistent? Yes or No
 GMA / PR Seen Consistent? Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lump Sum: _____ % 3 Val Yes or No

CA / REV / REP. / 24 HRS

PRS

Vehicle IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction **PR Key week**
25/4/18 Submit PRS Report

Year: **2015** Out **SKV 7870m**
 Type: ☒ M/Cycle / Bds / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: **Mercedes Benz C180 Montgardo 1595**
 Colour: **Silver** Insured / Std / NI / NA
 Sp Reading: **-** T-Ratio Insured / Std / NI / NA

Eng/No: _____
 C/No: **WDD 205 0402 R09495**

Gen Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ Nil / STD A/Rim or

Tyre Size: F: **225/50K17**
 R: **-**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front: **6** mm R/Bal: **6** mm
 L/Bal: **6** mm

D.O.A: _____ D.O.I: **24/4/18 @ 620**

Survey held at: **AMBA 36 Jln Guan**

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

Fnt o/s, u/c

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 26 APR 2018

View/Time File Past in: ☐ Prel. Report

View/Time File Return to: ☐ Final Report

View/Time File Return to:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Handwritten

Add Fee: ☐ Site Insp: \$

☐ Inter. Insp: \$

☐ Photo Insp: \$

☐ Material Insp: \$

Report Format:

Lump Sum / f.B / f.C



Nivitha (LKK Auto)

From: Siew Leng <siewleng@chiaarul.com>
Sent: Friday, 3 August 2018 4:56 PM
To: cwsmotorclaims@msfirstcapital.com.sg
Cc: maychua@msfirstcapital.com.sg; ASSIGNMENTS@LKKAUTO.COM; cwsmotorclaims@msfirstcapital.com.sg
Subject: FW: Our Ref: D18003069MFSH , SKV7870M accident involving with SHD6930K on 19-04-2018.Your Ref: AS.181229.sl

Dear Sir,

We refer to the above matter and to your email below.

Kindly be advised that our client has confirmed the details of re-inspection as follows:-

Date : 16th Aug 2018 Thursday

Time : 2pm

Venue : 36 Toh Guan Road East (Enterprise Hub) #01-36 S(608580) AMA Automotive Workshop

Person to contact: Melvin 8778 3636

Kindly let us have your confirmation on the above time and venue at the earliest.

Thanks.

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Friday, July 27, 2018 5:33 PM

To: info@chiaarul.com

Cc: maychua@msfirstcapital.com.sg; ASSIGNMENTS@LKKAUTO.COM; cwsmotorclaims@msfirstcapital.com.sg

Subject: Our Ref: D18003069MFSH , SKV7870M accident involving with SHD6930K on 19-04-2018.Your Ref: AS.181229.sl

Without Prejudice

Dear Sirs

RE-INSPECTION: THIRD PARTY VEHICLE NO: SKV7870M

We refer to the above matter.

Please note that we wish to carry out a re-inspection. Please advise the date, time, venue and person to contact at least 7 working days in advance of the appointment.

Kindly let us have copy of the video footage for our perusal.

Thank you.

Thanks & Regards,

Motor Claims Department

MS First Capital Insurance Ltd

cwsmotorclaims@msfirstcapital.com.sg

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/04/2018 14:33
Date Of Accident	19/04/2018 02:45
Exact Location Of Accident	ALONG ROAD 1 DICKSON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKV7870M
Insured/Policyholder	
Name Of Registered Owner	HENG AI LI (WANG AILI)
Co Reg No	S7516647H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98676677
Alternative Phone No	OFFICE-98676677

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C180

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VA1/GA127781
Cover Note Number	

Driver

Name of Driver	SEE HONG YUN
NRIC No	S8310205E
Date Of Birth	20/03/1983
Occupation	OUTDOOR
Date Of Driving Pass	17/12/2009
Driving Experience	8 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98676677
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 802, WOODLANDS ST 81 #03-75
Postcode	S730802
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - EMPLOYEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS WEST NPC
Police Station Address	ROAD: 9 MARSILING LANE , POSTCODE: 739146 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD6930K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	LAI SHIAW TUAN
NRIC/Passport Number	S2018920G
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name SEE HONG YUN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SKV7870M

Were seat belts worn?


Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to police report # T/20170415/017

However, I would like to add that the taxi SHP 6930 K did not stop at the stop line and just dash out without checking that lead to this accident and my injuries.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

S K AUTO CONSULTANTS

Invoice

Bill To: HENG AI LI
C/o AMA Autocare Pte Ltd
Enterprise Hub #01-36
36 Toh Guan Road East
Singapore 608580

Invoice No:	2018249
Date:	12/6/2018
Our Ref	TP/018/0249SK

Description	Amount (S\$)
PARTICULARS	
Vehicle Registration No : SKV 7870 M	1200.00
Date of Accident : 19/04/2018	
Date of Inspection : 20/04/2018	
SERVICES:	
Assessment with report (inclusive of transport charges and photographs etc)	
Total	1200.00
Balance Due	1200.00

We would appreciate your cheque crossed and made payable to:
S K AUTO CONSULTANTS



Authorized Signature

S K AUTO CONSULTANTS

AUTOMOBILE ASSESSMENT REPORT

Page No. 1

Our Reference: TP/018/0249SK
Your Reference: TBA

Date: 12/6/2018

TO: HENG AI LI
C/o AMA Autocare Pte Ltd
Enterprise Hub #01-36
36 Toh Guan Road East
Singapore 608580

Assessment of Vehicle No : SKV 7870 M
Date of Accident : 19/04/2018
Date of Inspection : 20/04/2018

We have carried out a physical assessment of SKV 7870 M at AMA Autocare Pte Ltd according to your instructions on 20/04/2018 and are pleased to submit our report as follows;

1.VEHICLE PARTICULARS

Registration No.	:	SKV 7870 M
Make & Model	:	MERCEDES BENZ C180
Year of Registration	:	2015
Engine Capacity (cc)	:	1595
Chassis No.	:	WDD2050402R099495
Engine No.	:	30432831
Colour	:	SILVER
Mileage (km)	:	na

2.VEHICLE CONDITION

Body Paint:	:	Good
Steering	:	Serviceable
Foot Brake	:	Serviceable
Parking Brake	:	Serviceable

3.TYRE PARTICULARS & CONDITION

Front

RH Make/Size	:	YOKOHAMA 225/50R17 - 70%
LH Make/Size	:	YOKOHAMA 225/50R17 - 70%

Rear

RH Make/Size	:	YOKOHAMA 225/50R17 - 70%
LH Make/Size	:	YOKOHAMA 225/50R17 - 70%

Note: % denotes the remaining percentage of the tyre


S K AUTO CONSULTANTS

Page No. 2

Our Reference TP/018/0249SK
Vehicle No. SKV 7870 M

4.DESRIPTION OF DAMAGE

At the time of inspection observed that this vehicle had sustained damages to the Right side front portion, front right suspension & air bags deployed
Please see attached schedule & photos for details.



REMARKS: 1) Active bonnet triggered due to collision event. The special bonnet hinges which are locked into place with strong springs was activated. The 3 impact sensors in the front section of the car and the hinges with springs need to be replaced.

*** 2) Diagnostic checks showed that the radar sensor controller unit (collision prevention assist) was impaired due to collision event. Replacement and service adjustment was required.**

Estimated Amount : S\$69,922.70
Adjusted Amount : S\$60,900/-
Estimated Repair Days : 24 days

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.

The assessment was conducted on a "**Without Prejudice**" basis.

If we are not notified of anything to the contrary within **14 Days** from the date hereof, this report shall be treated as correct

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by **S K AUTO CONSULTANTS** for any reliance on this report by any third party.

S K AUTO CONSULTANTS

Page No. 3

Our Reference TP/018/0249SK

Vehicle No. SKV 7870 M

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	OUR ASSESSMENT(\$\$)
	<u>PARTS (LIST ITEMS)</u>			
1	Front Bumper	Deformed	2065.00	1485 2065.00
1	Front Bumper lower reinforcement	Necessary	483.00	483.00
1	Front Bumper lower grille	Deformed	284.00	284.00
1	Front Bumper reinforcement	Bent	560.00	560.00
1	Front Bumper sponge	Cracked	345.00	165 345.00
1	Front Bumper under cover	Torn	345.00	345.00
1	RHS Front bumper tow cover	Damaged	120.00	45 120.00
1	RHS Front bumper fog lamp cover	Broken	136.00	136.00
1	Front bumper lower chrome moulding	Cracked	302.00	302.00
1	Front bumper sensors wiring harness	Damaged	345.00	345.00
1	RHS Front headlamp washer assy	Broken	480.00	480.00 XNN
1	RHS Front headlamp washer pipeline assy	Torn	280.00	280.00 XNN
1	Front RHS under cover	Torn	410.00	410.00
1	Front bonnet	Distorted	2120.00	1965 2120.00
2	Front bonnet hinges @\$255 24120	Activated	510.00	482.40 510.00 XN
2	Front bonnet spring actuators @ \$950	Activated	1900.00	1900.00 XNN
1	Front active bonnet acceleration sensors	Necessary	980.00	980.00 XNN
1	Front active bonnet power electronics	Necessary	680.00	680.00 XNN
1	Front bonnet v panel	Bent	180.00	180.00
1	Front windscreen	Cracked	2450.00	2450.00
1	Front grille	Cracked	680.00	680.00
1	Front grille top trip moulding	Distorted	214.00	214.00
1	Front grille star emblem	Necessary	122.00	122.00
1	Front support panel	Distorted	980.00	980.00
1	Front support panel garnish	Deformed	311.00	311.00
2	Front horn @\$185	Damaged	370.00	370.00
1	Front RHS oil top up container	Damaged	431.00	431.00
1	RHS Headlamp Assy gone to get Rrr	Broken	3120.00	3120.00
1	RHS Headlamp ballast	Damaged	950.00	510 950.00 X
1	RHS Headlamp panel	Bent	550.00	550.00
1	RHS Front Fender	Distorted	980.00	980.00
1	RHS Front Fender rear Inner Shield	Deformed	240.00	240.00
1	RHS Front Fender frt inner shield	Deformed	280.00	280.00
4	Front and rear seat belts @\$940 9925	Jammed	3760.00	2900 3760.00
1 set	Seat belt sensors	Necessary	580.00	580.00
1	Roof lining	Necessary	1025.00	1025.00
2	LH and RH roof airbag @\$1650 950 ✓	Deployed	3300.00	1900 3300.00
1	Front driver steering airbag	Deployed	1210.00	1210.00
1	Front driver steering coil spring	Damaged	1650.00	1650.00 XNN
1	Front driver steering	Damaged	1220.00	1220.00 XNN
1	Front passenger airbag	Deployed	1005.00	1005.00
1	Front driver side lower dashboard airbag	Deployed	730.00	730.00
2	Side seat belt garnish @288	Deformed	576.00	576.00 XNN

S K AUTO CONSULTANTS

Page No. 4

1	Front dashboard	Torn	2520.00	2520.00	
1	Front dashboard centre console	Damaged	2300.00	nnx 2300.00	
1	Front centre arm rest console	Damaged	820.00	nnx 820.00	
1	Front centre display panel	Damaged	850.00	nnx 850.00	
1	Front meter display	Damaged	1100.00	nnx 1100.00	
1	Front dashboard LH console box	Damaged	275.00	275.00	XNN
1	Airbag ECU	Necessary	1540.00	GOO 1540.00	
1 set	Airbag sensor	Necessary	580.00	580.00	
1	Front RHS hoses housing for engine oil	Torn	285.00	285.00	
1	Front airduct inner garnish	Distored	485.00	485.00	
1	Front centre light control panel	Damaged	740.00	740.00	XNN
1	Front RHS fender inner panel	Distored	812.00	812.00	RX
1	Front rack and pinion	Broken	3450.00	3450.00	
1	RHS Front shock absorber	Damaged	780.00	780.00	
1	RHS Front lower arm	Damaged	298.00	298.00	
1	RHS Front trailer arm	Damaged	315.00	315.00	
1	RHS Tie Rod outer	Damaged	198.00	198.00	
1	RHS Tie Rod inner	Damaged	214.00	214.00	
1	RHS Front wheel bearing	Damaged	511.00	511.00	
1	RHS Front knuckle arm	Damaged	421.00	421.00	
			57753.00	57753.00	38,222.40
less 10%			5775.30	10% 5775.30	
			51977.70	51977.70	34,400.16
<u>SPECIAL NETT ITEMS</u>					
1set	RHS Front fender inner shield clips	Necessary	60.00	50.00	
2	RHS Front bumper sensor @\$245 ⁰²¹⁰	Damaged	490.00	490.00	420
1 set	Front bumper clips	Necessary	50.00	40.00	
1	Electrical wiring harness	Damaged	375.00	375.00	X50C
1	Current limiter	Necessary	340.00	340.00	XNN
2	ACC sensor @\$185	Necessary	370.00	370.00	XNN
1	Radar sensor control unit (see remarks)*	Damaged	3450.00	3450.00	XNN
1	Battery cable	Necessary	340.00	340.00	
1	Battery	Necessary	580.00	380.00	XNN
1	RHS Front Sports Rim	Damaged	1280.00	1280.00	1000
1	RHS Front tyre	Cut	580.00	480.00	300
1	Front windscreen sealant	Necessary	180.00	150.00	
1	Front windscreen seal	Necessary	150.00	120.00	
TOTAL PARTS			60222.70	59842.70	2420

S K AUTO CONSULTANTS

Page No. 5


Our Reference TP/018/0249SK
Vehicle No. SKV 7870 M

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	2400.00	1200 2000.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1600.00	1200 1400.00
3	To clear fault code with diagnostic computer and reset to specification	750.00	500.00 200
4	To remove and replace RHS front undercarriage parts (suspension system)	450.00	200 300.00
5	To conduct full computerised wheel alignment test	450.00	350.00 80
6	To perform anti-rust treatment on affected areas	450.00	350.00 120
7	To remove and replace front rack and pinion	550.00	450.00 150
8	To remove and replace root lining	550.00	300 450.00
9	To remove and replace seatbelt	550.00	450.00 280
10	To remove and replace windscreen	300.00	120 240.00
11	To remove and replace front dashboard	550.00	250 450.00
12	To remove and replace radar control unit and reset the system (see remarks in page 2)	550.00	450.00 X 100
13	To remove and replace all airbag and airbag sensors	550.00	300 450.00
Labour Total :		9700.00	7840.00 4370
TOTAL (PARTS & LABOUR):		69922.70	67682.70

Note: (For Lump Sum Repair)

The workshop has agreed to undertake the repair on a Lump Sum Basis, and/or the use of ex stock/reconditioned parts whichever is possible (having taken into consideration to repair instead of replacements.

The final adjusted Lump Sum contract amount is S\$60,900/-


S. Kumanan
Motor Surveyor






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS3/FCI18007526/T1tbs2-1	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 12-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SHD 6930K	Veh. Inspected	SKV 7870M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18003069MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	27/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C180 AVANTGARDE	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WDD2050402R099495	Colour	SILVER	
Odometer	91364	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50R17	YOKOHAMA	6 mm	
L/H Front Tyre	225/50R17	YOKOHAMA	6 mm	
R/H Rear Tyre	225/50R17	YOKOHAMA	6 mm	
L/H Rear Tyre	225/50R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	19/04/2018	Inspection Date	16/08/2018	
Survey held at	AMA AUTOMOTIVE PTE. LTD. 36 TOH GUAN ROAD EAST #03-36 SINGAPORE 608580			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		17 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 7870M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	REPLACED	2,065.00	1,485.00
1	FRONT BUMPER LOWER REINFORCEMENT	REPLACED	483.00	483.00
1	FRONT BUMPER LOWER GRILLE	REPLACED	284.00	284.00
1	FRONT BUMPER REINFORCEMENT	REPLACED	560.00	560.00
1	FRONT BUMPER SPONGE	REPLACED	345.00	165.00
1	FRONT BUMPER UNDER COVER	REPLACED	345.00	345.00
1	RHS FRONT BUMPER TOW COVER	REPLACED	120.00	45.00
1	RHS FRONT BUMPER FOG LAMP COVER	REPLACED	136.00	136.00
1	FRONT BUMPER LOWER CHROME MOULDING	REPLACED	302.00	302.00
1	FRONT BUMPER SENSORS WIRING HARNESS	REPLACED	345.00	345.00
1	RHS FRONT HEADLAMP WASHER ASSY	NOT NECESSARY	480.00	-
1	RHS FRONT HEADLAMP WASHER PIPELINE ASSY	NOT NECESSARY	280.00	-
1	FRONT RHS UNDER COVER	REPLACED	410.00	410.00
1	FRONT BONNET	REPLACED	2,120.00	1,965.00
2	FRONT BONNET HINGES @ \$255.00	REPAIRED SEE LABOUR	510.00	-
2	FRONT BONNET SPRING ACTUATORS @ \$950.00	NOT NECESSARY	1,900.00	-
1	FRONT ACTIVE BONNET ACCELERATION SENSORS	NOT NECESSARY	980.00	-
1	FRONT ACTIVE BONNET POWER STEERING	NOT NECESSARY	680.00	-
1	FRONT BONNET V PANEL	REPLACED	180.00	180.00
1	FRONT WINDSCREEN	REPLACED	2,450.00	2,450.00
1	FRONT GRILLE	REPLACED	680.00	680.00
1	FRONT GRILLE TOP TRIP MOULDING	REPLACED	214.00	214.00
1	FRONT GRILLE STAR EMBLEM	REPLACED	122.00	122.00
1	FRONT SUPPORT PANEL	REPLACED	980.00	980.00
1	FRONT SUPPORT PANEL GARNISH	REPLACED	311.00	311.00
2	FRONT HORN @ \$185.00	REPLACED	370.00	370.00
1	FRONT RHS OIL TOP UP CONTAINER	REPLACED	431.00	431.00
1	RHS HEADLAMP ASSY }	REPLACED	3,120.00	3,120.00
1	RHS HEADLAMP BALLAST }		950.00	-
1	RHS HEADLAMP PANEL	REPLACED	550.00	550.00

Report Ref No. CS3/FCI18007526/T1tbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RHS FRONT FENDER	REPLACED	980.00	980.00
1	RHS FRONT FENDER REAR INNER SHIELD	REPLACED	240.00	240.00
1	RHS FRONT FENDER FRT INNER SHIELD	REPLACED	280.00	280.00
4	FRONT AND REAR SEAT BELTS @ \$940.00	REPLACED	3,760.00	2,900.00
1	SET SEAT BELT SENSORS	REPLACED	580.00	580.00
1	ROOF LINING	REPLACED	1,025.00	1,025.00
2	LH AND RH ROOF AIRBAG @ \$1650.00	REPLACED	3,300.00	1,900.00
1	FRONT DRIVER STEERING AIRBAG	REPLACED	1,210.00	1,210.00
1	FRONT DRIVER STEERING COIL SPRING	NOT NECESSARY	1,650.00	-
1	FRONT DRIVER STEERING	NOT NECESSARY	1,220.00	-
1	FRONT PASSENGER AIRBAG	REPLACED	1,005.00	1,005.00
1	FRONT DIRVER SIDE LOWER DASHBOARD AIRBAG	REPLACED	730.00	730.00
2	SIDE SEAT BELT GARNISH @ \$288.00	NOT NECESSARY	576.00	-
1	FRONT DASHBOARD	REPLACED	2,520.00	2,520.00
1	FRONT DASHBOARD CENTRE CONSOLE	NOT NECESSARY	2,300.00	-
1	FRONT CENTRE ARM REST CONSOLE	NOT NECESSARY	820.00	-
1	FRONT CENTRE DISPLAY PANEL	NOT NECESSARY	850.00	-
1	FRONT METER DISPLAY	NOT NECESSARY	1,100.00	-
1	FRONT DASHBOARD LH CONSOLE BOX	NOT NECESSARY	275.00	-
1	AIRBAG ECU	REPLACED	1,540.00	900.00
1	SET AIRBAG SENSOR	REPLACED	580.00	580.00
1	FRONT RHS HOSES HOUSING FOR ENGINE OIL	REPLACED	285.00	285.00
1	FRONT AIRDUCT INNER GARNISH	REPLACED	485.00	485.00
1	FRONT CENTRE LIGHT CONTROL PANEL	NOT NECESSARY	740.00	-
1	FRONT RHS FENDER INNER PANEL	REPAIRED SEE LABOUR	812.00	-
1	FRONT RACK AND PINION	REPLACED	3,450.00	3,450.00
1	RHS FRONT SHOCK ABSORBER	REPLACED	780.00	780.00
1	RHS FRONT LOWER ARM	REPLACED	298.00	298.00
1	RHS FRONT TRAILER ARM	REPLACED	315.00	315.00
1	RHS TIE ROD OUTER	REPLACED	198.00	198.00
1	RHS TIE ROD INNER	REPLACED	214.00	214.00
1	RHS FRONTWHEEL BEARING	REPLACED	511.00	511.00

Report Ref No. CS3/FCI18007526/T1tbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RHS FRONT KNUCKLE ARM	REPLACED	421.00	421.00
	LESS 10% DISCOUNT		-5,775.30	-3,774.00
			51,977.70	33,966.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET RHS FRONT FENDER INNER SHIELD CLIPS (SN)	REPLACED	60.00	50.00
2	RHS FRONT BUMPER SENSOR @ \$245.00 (SN)	REPLACED	490.00	420.00
1	SET FRONT BUMPER CLIPS (SN)	REPLACED	50.00	40.00
1	ELECTRICAL WIRING HARNESS (SN)	SERVICEABLE	375.00	-
1	CURRENT LIMITER (SN)	NOT NECESSARY	340.00	-
2	ACC SENSOR @ \$185.00 (SN)	NOT NECESSARY	370.00	-
1	RADAR SENSOR CONTROL UNIT (SN)	NOT NECESSARY	3,450.00	-
1	BATTERY CABLE (SN)	REPLACED	340.00	340.00
1	BATTERY (SN)	NOT NECESSARY	580.00	-
1	RHS FRONT SPORTS RIM (SN)	REPLACED	1,280.00	1,000.00
1	RHS FRONT TYRE (SN)	REPLACED	580.00	300.00
1	FRONT WINDSCREEN SEALANT (SN)	REPLACED	180.00	150.00
1	FRONT WINDSCREEN SEAL (SN)	REPLACED	150.00	120.00
			8,245.00	2,420.00
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF FRONT BONNET HINGES AND FRONT RHS FENDER INNER PANEL.		2,400.00	1,200.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		1,600.00	1,200.00
	TO CLEAR FAULT CODE WITH DIAGNOSTIC COMOUTER AND RESET TO SPECIFICATION.		750.00	200.00
	TO REMOVE AND REPLACE RHS FRONT UNDERCARRIAGE PARTS (SUSPENSION SYSTEM)		450.00	200.00
	TO CONDUCT FULL COMPUTERISED WHEEL ALIGNMENT TEST.		450.00	80.00
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.		450.00	120.00
	TO REMOVE AND REPLACE FRONT RACK AND PINION.		550.00	150.00

Report Ref No. CS3/FCI18007526/T1tbs2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REPLACE ROOF LINING.	NOT NECESSARY	550.00	300.00
	TO REMOVE AND REPLACE SEAT BELT.		550.00	250.00
	TO REMOVE AND REPLACE WINDSCREEN.		300.00	120.00
	TO REMOVE AND REPLACE FRONT DASHBOARD.		550.00	250.00
	TO REMOVE AND REPLACE RADAR CONTROL UNIT AND RESET THE SYSTEM.		550.00	-
	TO REMOVE AND REPLACE ALL AIRBAG AND AIRBAG SENSORS.		550.00	300.00
			9,700.00	4,370.00
GRAND TOTAL			69,922.70	40,756.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				32,600.00

Report Ref No. CS3/FCI18007526/T1tbs2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.