

22/03/2001

ASS. REC. BY:

REF:

CS/ASM18014347/Avd3b

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Yunne Ang

of

ASM (AXA)

Date/Time:

7/8/2018

Estimated Cost:

Bill to:

☒ OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLH 5509H

Insured:

at Workshop m/s

SME Motor

Tel:

6747 6106

of

Ikaki Bkt Ave 6 #02-15

Policy No:

Claim No:

SRM00R50

Sum Insured:

Excess:

\$ 300.00

Make of Veh:

(Client's Record)

D.O.A.

5/8/2018

8/8/18 @ Morning

☒ CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4.20pm @ 7/8/18

Person Contacted:

Pei Ying

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SLH 5509H - NA1AIG18014347/13

DOA: 5/8/2018

8/8/18

Send preli revised via merimen

27/8/18

Final fig \$ 3283.90 confirmed by email (Ref 1322, 2910) (No LS)

(08/11/13) wef

REF: ASM(AXA)

ASS. REC. BY:

## ASSIGNMENT

From: Date: 8/8/2018

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLH 5509H

at Workshop m/s

SME Motor

of 1 Kaki Bkt Ave 6 # 02-15

Insured:

Policy No.

Claims No.

Sum Insured: Excess: \$300.00

(Client's Record)

Morning

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 27K.

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

☒ CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLH 5509H. Yr Regn: 2010 / Jan.

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish. c.c 1797

Colour: Red. A/C: Insured / Std / NI / NA

Sp. Reading: 121550 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ZGE2000000000

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Jammed / Leaked / Burnt orBrake: ☒ Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 08/08/18

Survey held at SME.

Des. of Damages ☒ Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD AXA.

RECEIVED 20 AUG 2018

27/8/2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

seps - typist

Report Format: SMART claim

Lump Sum / I.B.I. (\$) 3283.90

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ )☐ : Interview (\$ )☐ : Tech. Invs (\$ )☐ : Weekend (\$ )

Survey Fee: 150

Transportation:

S + RS, SI

Photos

Others

TOTAL

150



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18014347/Avd3

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 07-08-2018



Code : ASM

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SLH 5509H
Policy No.	Coverage (\$)	0.00
Claim No. S8M00R5O	Excess (\$)	300.00
Assign From SMARTCLAIM (YVONNE ANG)	Assign Date	07/08/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date 05/08/2018	Inspection Date 08/08/2018
Survey held at SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883	

## 5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--




## Service Request Details

Claim

S8M00R5O

Reference

None 

Loss Date

August 5, 2018

Request Date

August 7, 2018

Due Date

August 15, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

### Actions

Next Step

Agree to perform service

[Decline Work](#)

[Accept Work](#)

### Vehicle Information

Incident Vehicle Registration #

SLH5509H

Make

TOYOTA

Model

WISH 1.8

## Service Address

1 Kaki Bukit Ave 6 #02-15, , 417883

## Primary Contact/Insured

COLIN ONG THIAM CHYE (WANG TIANCAI)  
BLK 221A BEDOK CENTRAL, #08-62, 461221, Singapore  
96518199

## Claim Handler

ANG Yvonne  
6568804461  
yvonne.ang@axa.com.sg

Additional Instructions  
EXCESS 300

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

[+ Upload Documents](#)

## New Message

Type \*



Message

Subject \*

IA SUBMITTED FOR SLH 5509H

Message \*

Dear Sir/Madam,  
Please be informed that IA submitted. We have Authorize repair.Thanks Veron Chen

CancelSend



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX.: (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 8/8/2018

### Survey details

Date of loss	5/8/2018
Date of appointment	7/8/2018
Date of survey	8/8/2018
Location of survey	SME MOTOR PTE LTD

### Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SLH 5509H
Make and Model	TOYOTA WISH
Date of registration	7/1/2010
Excess	\$300/-
Market Value	\$27,000.00
Parf Rebate	\$14,265.00
Nett Loss	\$12,735.00

### Repair details

Initial Estimate	\$4,489.90
------------------	------------

#### Proposed/Revised repair cost:

Revised Estimate Amount	\$1,848.00
"Check items (Estimated)	\$1,083.50
Labour	\$643.70
Total Repair (Estimated)	\$3,575.20
Lump Sum (Estimated)	

Number of days of repair	4 days (est)
--------------------------	--------------

#### Remarks:

The vehicle sustained damages at the front portion.

Damages Consistent  
Repair Cost Economical

We have authorize repair.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	4281D
<b>Vehicle Details</b>	
Vehicle No.:	SLH5509H
Vehicle to be Exported:	No
Intended De-registration Date:	08 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8X A
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	2ZR0453885
Chassis No.:	ZGE200020060
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$21,291.00
Original Registration Date:	07 Jan 2010
First Registration Date:	07 Jan 2010
Transfer Count:	1
Actual ARF Paid:	\$21,291.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Jan 2020
PARF Rebate Amount:	\$11,710.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	06 Jan 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$21,301.00
COE Rebate Amount:	\$2,555.00
<b>Total Rebate Amount:</b>	<b>\$14,265.00</b>

The information contained herein is correct as at 08 Aug 2018

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/08/2018 16:54
Date Of Accident	05/08/2018 12:45
Exact Location Of Accident	PIE BEFORE CTE EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH5509H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COLIN ONG THIAM CHYE
NRIC No	S7634281D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96518199
Alternative Phone No	OFFICE-96518199

### Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA158861
Cover Note Number	

### Driver

Name of Driver	COLIN ONG THIAM CHYE
NRIC No	S7634281D
Date Of Birth	01/11/1976
Occupation	INDOOR
Date Of Driving Pass	24/04/2000
Driving Experience	18 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96518199
Fax Number	
Contact Number	OFFICE-96518199
Email Address	NOEMAIL

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



Vehicle B Sudden Jam Brake I couldn't stop  
in time And hit onto vehicle B rear

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**SME Motor Pte Ltd**  
**1 Kaki Bukit Ave**  
**6, #02-15/16/17/18**  
**AutoBay @ Kaki Bukit**  
**Singapore**

**Claim Reference:**  
**Assessment Number: GS001714**  
**Version: SMEMOT01/1**  
**Date Calculated: 06/08/2018 07:45**

**Full Report - V1**  
**Registration: SLH5509H**  
**Printed: 06/08/2018 14:46**

### Summary Information

#### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Gary Seah	Date of Incident:	05/08/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:	OD	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

#### Vehicle Details

##### Vehicle

Manufacturer:	TOYOTA
Model:	Wish
Sub Model:	BASE MODEL
Model Sheet Number:	YCW 01
Registration:	SLH5509H
Registration Month:	January
Registration Year:	2010
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

##### Model Specs

FROM 08/2009	AIR CONDITIONING
1.8 LTR 95 KW	TWO COAT METALLIC
PREPARE OFF VEHICLE	

#### Vehicle Condition

##### Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	06/08/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

Claim Reference:

Assessment Number: GS001714


Version: SMEMOT01/1

Date Calculated: 06/08/2018 07:45

Full Report - V1

Registration: SLH5509H

Printed: 06/08/2018 14:46



## Addresses

## Cost Summary

Total Labour	\$814.50
Total Paint/Material	\$144.40
Total Parts	\$3,531.00
Excess:	TBA
Grand Total Exc GST:	\$4,489.90
7 % GST:	\$314.29
Grand Total Inc GST:	\$4,804.19

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR

Price/Dent = \$0.00/HR

### Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
810151A	ADJUST HEADLAMP	3.0	13.50
NO NUMBER	RENEW FRONT PANEL CPL	84.0	378.00
	INCLUDES: R + R FRONT BUMPER, HEADLAMPS, RADIATOR AND ALL ATTACHED PARTS IN THE REPAIR SECTION		
531011)	RENEW LEFT FRONT WING	1.0	4.50
	INCLUDES: TRANSFER ATTACHED PARTS		
520011)	RENEW FRONT BUMPER (REMOVED)	6.0	27.00
	INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT		
530051)	TRANSFER ATTACHED PARTS FROM BONNET	3.0	13.50
530051)	RENEW BONNET	1.0	4.50
	INCLUDES: R + R OR RENEW ATTACHED PARTS		
883151)	R + R CONDENSER	8.0	36.00
	(FRONT BUMPER REMOVED)		
	INCLUDES: DRAIN + REFILL AIR CONDITIONING		
	DOES NOT INCLUDE: DETACH + REFIT RADIATOR		
<b>LABOUR COST</b>			
	<b>Total Work Units</b>	<b>106.0</b>	
	<b>Corrosion Protection External Labour</b>	<b>0.0HRS</b>	<b>0.00</b>
	<b>Corrosion Protection Internal Labour</b>	<b>0.0HRS</b>	<b>0.00</b>
	<b>Sub Total</b>	<b>10.6HRS</b>	<b>\$477.00</b>
	<b>Paint Labour</b>	<b>7.5HRS</b>	<b>\$337.50</b>
	<b>Total Labour</b>	<b>18.1HRS</b>	<b>\$814.50</b>

### PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

## SME Motor Pte Ltd

Claim Reference:

Assessment Number: GS001714

Version: SMEMOT01/1

Date Calculated: 06/08/2018 07:45

Full Report - V1

Registration: SLH5509H

Printed: 06/08/2018 14:46

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
471	BONNET NEW PART PAINTING	15.0	
741	L/F WING NEW PART PAINTING	10.0	
1009	FRONT PANEL CPL SURFACE PAINT	6.0	
1018	LOCK CARRIER STRUT SURFACE PAINT	4.0	
742	R/F WING SURFACE PAINT	6.0	
1481	LEFT FRONT DOOR SURFACE PAINT	9.0	
<b>LABOUR COST - PAINT</b>			
	<b>TIME(PAINT)</b>	<b>50.0</b>	
	<b>Preparation Work Multi Layer Paint</b>	<b>0.0</b>	
	<b>Total Work Units (10WU/HR)</b>	<b>75.0</b>	
	<b>Total Paintwork Labour</b>	<b>7.5HRS</b>	<b>\$337.50</b>
<b>MATERIAL COST - PAINT</b>			
	<b>New Part Painting</b>		<b>\$64.50</b>
	<b>Material-Constant Main Work Metal</b>		<b>\$28.60</b>
	<b>Surface-/Blend Paint</b>		<b>\$51.30</b>
	<b>Total Excluding Pearlescent Uplift</b>		<b>\$144.40</b>
	<b>Pearlescent Uplift @ 0.0%</b>		<b>\$0.00</b>
	<b>Total Paint Material Cost</b>		<b>\$144.40</b>

## PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1000	1	4PCS GRILLE CLIPS <i>new</i>	Renew		0%	✓ 8.00*
1000	1	8PC SUPPORT TOP <i>new</i>	GARNISH CLIPS		0%	✓ 16.00*
471	1	BONNET <i>Dented</i>	53301 68012		0%	✓ 280.00*
1021	1	CLOSING PANEL SEAL <i>new</i>	53292 68010		0%	x 70.00*
4465	1	CONDENSER <i>DD</i>	88460 21040		0%	? 290.00*
281	1	FRONT BUMPER <i>Delaminated</i>	52119 68061A0		0%	✓ 220.00*
340	1	FRONT BUMPER SUPPORT <i>gent</i>	52021 68010		0%	? 95.00*
1009	1	FRONT PANEL CPL <i>Rep</i>	53201 68901	20 work unit	0%	x 395.00*
341	1	FRT BUMPER ABSORBER <i>new</i>	52611 68020		0%	? 50.00*
350	1	FRT BUMPER CLAMP KIT <i>new</i>	USE SINGLE PARTS		0%	? 20.00*
1000	1	FRT BUMPER LOWER <i>Delaminated</i>	GRILLE RH		0%	x 35.00*
410	1	GRILLE <i>crushed</i>	53111 68030		0%	✓ 85.00*
317	1	L/F BUMPER BRACKET <i>new</i>	52116 68020		0%	✓ 28.00*
561	1	L/F HEADLAMP <i>crushed</i>	81170 68040		0%	✓ 330.00*
741	1	L/F WING <i>Buckled</i>	53802 68010		0%	✓ 220.00*
789	1	L/F WING CLAMP KIT <i>new</i>	USE SINGLE PARTS		0%	✓ 20.00*
1018	1	LOCK CARRIER STRUT <i>Best</i>	53208 68010		0%	✓ 50.00*
493	1	LOWER BONNET LOCK <i>new</i>	53510 68020		0%	x 45.00*
431	1	MANUFACTURER BADGE <i>new</i>	75341 68040		0%	✓ 30.00*
318	1	R/F BUMPER BRACKET <i>new</i>	52115 68020		0%	✓ 28.00*
298	1	R/F BUMPER COVER <i>Delaminated</i>	52127 68040		0%	✓ 35.00*
562	1	R/F HEADLAMP <i>crushed</i>	81130 68040		0%	✓ 330.00*
7761	1	RADIATOR CPL <i>NN</i>	16400 28110		0%	? 530.00*
f: OEM Parts				Sub Total		\$3,210.00
g: Original				Mark Up From Cost	(10 %)	\$321.00
h: Secondhand				<b>Total Parts</b>		<b>\$3,531.00</b>
p: Parallel						
x: Exchange						

Claim Reference:  
 Assessment Number: GS001714  
 Version: SMEMOT01/1  
 Date Calculated: 06/08/2018 07:45

Full Report - V1  
 Registration: SLH5509H  
 Printed: 06/08/2018 14:46

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras

\$0.00

### Final Calculation

Total Parts		\$3,531.00
Labour		
Total Panel/Mechanical	\$477.00	202.50 337.50
Total Paintwork	\$337.50	310.50 337.50
Total Labour		\$814.50
Total Paint/Material Costs		130.70 \$144.40 144.40
Grand Total Excludes GST	4605.90	\$4,489.90
GST @ 7 %		\$314.29
Grand Total Includes GST		\$4,804.19

### Assessment Notes

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Adrian Lim  
 P/P 08/08/18.

04 Days.

Authorised Repairs  
 Excess \$300.

51 Ubi Avenue 1, #01-25  
Paya Ubi Industrial Park  
Singapore  
408933

Revert

Claim Reference:  
Assessment Number: GS001714  
Version: SMEMOT01/1  
Date Calculated: 08/08/2018 07:20

Full Report - V1  
Registration: SLH5509H  
Printed: 08/08/2018 14:20

## Summary Information

### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	05/08/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:	OD	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

### Vehicle Details

Vehicle	Model Specs
Manufacturer:	TOYOTA
Model:	Wish
Sub Model:	BASE MODEL
Model Sheet Number:	YCW 01
Registration:	SLH5509H
Registration Month:	January
Registration Year:	2010
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

### Vehicle Condition

#### Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	06/08/2018
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:



Claim Reference:

Full Report - V1



Assessment Number: GS001714

Registration: SLH5509H

Version: SMEMOT01/1

Printed: 08/08/2018 14:20

Date Calculated: 08/08/2018 07:20



## Addresses

## Cost Summary

Total Labour	\$513.00
Total Paint/Material	\$130.70
Total Parts	\$2,931.50
Excess:	TBA
Grand Total Exc GST:	\$3,575.20
7 % GST:	\$250.26
Grand Total Inc GST:	\$3,825.46

## Repair Information

## LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR  
Price/Dent = \$0.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
810151A	ADJUST HEADLAMP	3.0	13.50
531011)	R + R L/F WING	5.0	22.50
	INCLUDES: R + R FRONT BUMPER, HEADLAMP AND WHEELHOUSE COVER		
531011)	RENEW LEFT FRONT WING	1.0	4.50
	INCLUDES: TRANSFER ATTACHED PARTS		
520011)	RENEW FRONT BUMPER (REMOVED)	6.0	27.00
	INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT		
810051)	R + R RIGHT HEADLAMP	7.0	31.50
530051)	TRANSFER ATTACHED PARTS FROM BONNET	3.0	13.50
530051)	RENEW BONNET	1.0	4.50
	INCLUDES: R + R OR RENEW ATTACHED PARTS		
NO NUMBER	R + R LANDING PANEL SUPPORT	2.0	9.00
883151)	R + R CONDENSER	8.0	36.00
	(FRONT BUMPER REMOVED)		
	INCLUDES: DRAIN + REFILL AIR CONDITIONING		
	DOES NOT INCLUDE: DETACH + REFIT RADIATOR		
160011	R + R RADIATOR	9.0	40.50
	INCLUDES: BLEED COOLING SYSTEM		

## LABOUR COST

Total Work Units	45.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	4.5HRS	\$202.50
Paint Labour	6.9HRS	\$310.50
Total Labour	11.4HRS	\$513.00

Claim Reference:

Full Report - V1

Assessment Number: GS001714

Registration: SLH5509H

Version: SMEMOT01/1

Printed: 08/08/2018 14:20

Date Calculated: 08/08/2018 07:20

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$45.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
471	BONNET NEW PART PAINTING	15.0	
741	L/F WING NEW PART PAINTING	10.0	
1018	LOCK CARRIER STRUT SURFACE PAINT	4.0	
742	R/F WING SURFACE PAINT	6.0	
1481	LEFT FRONT DOOR SURFACE PAINT	9.0	
<b>LABOUR COST - PAINT</b>			
<b>TIME(PAINT)</b>		<b>44.0</b>	
<b>Preparation Work Multi Layer Paint</b>		<b>0.0</b>	
<b>Total Work Units (10WU/HR)</b>		<b>69.0</b>	
<b>Total Paintwork Labour</b>		<b>6.9HRS</b>	<b>\$310.50</b>
<b>MATERIAL COST - PAINT</b>			<b>Cost Price</b>
<b>New Part Painting</b>			<b>\$64.50</b>
<b>Material-Constant Main Work Metal</b>			<b>\$28.60</b>
<b>Surface-/Blend Paint</b>			<b>\$37.60</b>
<b>Total Excluding Pearlescent Uplift</b>			<b>\$130.70</b>
<b>Pearlescent Uplift @ 0.0%</b>			<b>\$0.00</b>
<b>Total Paint Material Cost</b>			<b>\$130.70</b>

## PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
1000	1	4PCS GRILLE CLIPS	Renew		0% 8.00*
1000	1	8PC SUPPORT TOP	GARNISH CLIPS		0% 16.00*
471	1	BONNET	53301 68012		0% 280.00*
4465	1	CONDENSER	88460 21040		0% 290.00*
281	1	FRONT BUMPER	52119 68061A0		0% 220.00*
340	1	FRONT BUMPER SUPPORT	52021 68010		0% 95.00*
341	1	FRT BUMPER ABSORBER	52611 68020		0% 50.00*
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		0% 20.00*
410	1	GRILLE	53111 68030		0% 85.00*
317	1	L/F BUMPER BRACKET	52116 68020		0% 28.00*
561	1	L/F HEADLAMP	81170 68040		0% 330.00*
741	1	L/F WING	53802 68010		0% 220.00*
789	1	L/F WING CLAMP KIT	USE SINGLE PARTS		0% 20.00*
1018	1	LOCK CARRIER STRUT	53208 68010		0% 50.00*
431	1	MANUFACTURER BADGE	75341 68040		0% 30.00*
318	1	R/F BUMPER BRACKET	52115 68020		0% 28.00*
298	1	R/F BUMPER COVER	52127 68040		0% 35.00*
562	1	R/F HEADLAMP	81130 68040		0% 330.00*
7761	1	RADIATOR CPL	16400 28110		0% 530.00*
f: OEM Parts		Sub Total			\$2,665.00
g: Original		Mark Up From Cost		(10 %)	\$266.50
h: Secondhand		<b>Total Parts</b>			<b>\$2,931.50</b>
p: Parallel					
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

**Total Extras****\$0.00**

Claim Reference:

Full Report - V1

Assessment Number: GS001714

Registration: SLH5509H

Version: SMEMOT01/1

Printed: 08/08/2018 14:20

Date Calculated: 08/08/2018 07:20

### Final Calculation

Total Parts		\$2,931.50
Labour		
	Total Panel/Mechanical	\$202.50
	Total Paintwork	\$310.50
Total Labour		\$513.00
Total Paint/Material Costs		\$130.70
Grand Total Excludes GST		\$3,575.20
	GST @ 7 %	\$250.26
Grand Total Includes GST		\$3,825.46

### Assessment Notes

Claim Reference:  
 Assessment Number: GS001714  
 Version: SMEMOT01/1  
 Date Calculated: 06/08/2018 07:45

Full Report - V1  
 Registration: SLH5509H  
 Printed: 06/08/2018 14:46

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC - PREPARE OFF VEHICLE		
471	BONNET NEW PART PAINTING	15.0	
741	L/F WING NEW PART PAINTING	10.0	
1009	FRONT PANEL CPL SURFACE PAINT	6.0	
1018	LOCK CARRIER STRUT SURFACE PAINT	4.0	
742	R/F WING SURFACE PAINT	6.0	
1481	LEFT FRONT DOOR SURFACE PAINT	9.0	
<b>LABOUR COST - PAINT</b>			
	TIME(PAINT)	50.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	75.0	
	Total Paintwork Labour	7.5HRS	\$337.50
<b>MATERIAL COST - PAINT</b>			Cost Price
	New Part Painting		\$64.50
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$51.30
	Total Excluding Pearlescent Uplift		\$144.40
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$144.40

## PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1000	1	4PCS GRILLE CLIPS <i>Ren</i>	Renew		0%	✓ 8.00*
1000	1	8PC SUPPORT TOP <i>Ren</i>	GARNISH CLIPS		0%	✓ 16.00*
471	1	BONNET <i>Dented</i>	53301 68012		0%	✓ 280.00*
1021	1	CLOSING PANEL SEAL <i>He NA</i>	53292 68010		0%	x 70.00*
4465	1	CONDENSER <i>Dented</i>	88460 21040		0%	✓ 290.00*
281	1	FRONT BUMPER <i>Dented</i>	52119 68061A0		0%	✓ 220.00*
340	1	FRONT BUMPER SUPPORT <i>Best</i>	52021 68010		0%	✓ 95.00*
1009	1	FRONT PANEL CPL <i>Rep</i>	53201 68901		0%	x 395.00*
341	1	FRT BUMPER ABSORBER <i>Cracked</i>	52611 68020		0%	✓ 50.00*
350	1	FRT BUMPER CLAMP KIT <i>Ren</i>	USE SINGLE PARTS		0%	✓ 20.00*
1000	1	FRT BUMPER LOWER <i>Cracked</i>	GRILLE RH		0%	✓ 35.00*
410	1	GRILLE <i>Cracked</i>	53111 68030		0%	✓ 85.00*
317	1	L/F BUMPER BRACKET <i>Ren</i>	52116 68020		0%	✓ 28.00*
561	1	L/F HEADLAMP <i>Cracked</i>	81170 68040		0%	✓ 330.00*
741	1	L/F WING <i>Buckled</i>	53802 68010		0%	✓ 220.00*
789	1	L/F WING CLAMP KIT <i>Ren</i>	USE SINGLE PARTS		0%	✓ 20.00*
1018	1	LOCK CARRIER STRUT <i>Best</i>	53208 68010		0%	✓ 50.00*
493	1	LOWER BONNET LOCK <i>Ren</i>	53510 68020		0%	✓ 45.00*
431	1	MANUFACTURER BADGE <i>Ren</i>	75341 68040		0%	✓ 30.00*
318	1	R/F BUMPER BRACKET <i>Ren</i>	52115 68020		0%	✓ 28.00*
298	1	R/F BUMPER COVER <i>Dented</i>	52127 68040		0%	✓ 35.00*
562	1	R/F HEADLAMP <i>Cracked</i>	81130 68040		0%	✓ 330.00*
7761	1	RADIATOR CPL <i>Ren</i>	16400 28110		0%	✓ 530.00*
f: OEM Parts			Sub Total			\$3,210.00
g: Original			Mark Up From Cost	(10 %)		\$321.00
h: Secondhand			Total Parts			\$3,531.00
p: Parallel						
x: Exchange						

2pc FRT bonnet hinge \$30 x 2  
 Best

Air-coolant  
 Air-coolant \$50 (net) Nec ✓

Audatex System Using Manufacturer Times

workshop finalise ..

## SME Motor Pte Ltd

Claim Reference:

Assessment Number: GS001714



Version: SMEMOT01/1

Date Calculated: 06/08/2018 07:45

Full Report - V1

Registration: SLH5509H

Printed: 06/08/2018 14:46



## Addresses

## Cost Summary

Total Labour	\$814.50
Total Paint/Material	\$144.40
Total Parts	\$3,531.00
Excess:	TBA
Grand Total Exc GST:	\$4,489.90
7 % GST:	\$314.29
Grand Total Inc GST:	\$4,804.19

## Repair Information

## LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR  
Price/Dent = \$0.00/HR

## Repair /

## Guide Number Repair Details

		WU	Cost Price (\$)
810151A	ADJUST HEADLAMP	3.0	13.50
NO NUMBER	RENEW FRONT PANEL CPL	84.0	378.00
	INCLUDES: R + R FRONT BUMPER, HEADLAMPS, RADIATOR AND ALL ATTACHED PARTS IN THE REPAIR SECTION		
531011)	RENEW LEFT FRONT WING	1.0	4.50
	INCLUDES: TRANSFER ATTACHED PARTS		
520011)	RENEW FRONT BUMPER (REMOVED)	6.0	27.00
	INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT		
530051)	TRANSFER ATTACHED PARTS FROM BONNET	3.0	13.50
530051)	RENEW BONNET	1.0	4.50
	INCLUDES: R + R OR RENEW ATTACHED PARTS		
883151)	R + R CONDENSER	8.0	36.00
	(FRONT BUMPER REMOVED)		
	INCLUDES: DRAIN + REFILL AIR CONDITIONING		
	DOES NOT INCLUDE: DETACH + REFIT RADIATOR		
<b>LABOUR COST</b>			
	Total Work Units	106.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	10.6HRS	\$477.00
	Paint Labour	7.5HRS	\$337.50
	Total Labour	18.1HRS	\$814.50

## PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

## SME Motor Pte Ltd

Claim Reference:

Assessment Number: GS001714

Version: SMEMOT01/1

Date Calculated: 06/08/2018 07:45

Full Report - V1

Registration: SLH5509H

Printed: 06/08/2018 14:46

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
471	BONNET NEW PART PAINTING	15.0	
741	L/F WING NEW PART PAINTING	10.0	
1009	FRONT PANEL CPL SURFACE PAINT	6.0	
1018	LOCK CARRIER STRUT SURFACE PAINT	4.0	
742	R/F WING SURFACE PAINT	6.0	
1481	LEFT FRONT DOOR SURFACE PAINT	9.0	
	<b>LABOUR COST - PAINT</b>		
	<b>TIME(PAINT)</b>	<b>50.0</b>	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	75.0	
	Total Paintwork Labour	7.5HRS	\$337.50
	<b>MATERIAL COST - PAINT</b>		<b>Cost Price</b>
	New Part Painting		\$64.50
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$51.30
	Total Excluding Pearlescent Uplift		\$144.40
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$144.40

## PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1000	1	4PCS GRILLE CLIPS <i>ren</i>	Renew		0%	8.00*
1000	1	8PC SUPPORT TOP <i>ren</i>	GARNISH CLIPS		0%	16.00*
471	1	BONNET <i>Defect</i>	53301 68012		0%	280.00*
1021	1	CLOSING PANEL SEAL <i>He No</i>	53292 68010		0%	70.00*
4465	1	CONDENSER <i>Defect</i>	88460 21040		0%	290.00*
281	1	FRONT BUMPER <i>Defect</i>	52119 68061A0		0%	220.00*
340	1	FRONT BUMPER SUPPORT <i>Best</i>	52021 68010		0%	95.00*
1009	1	FRONT PANEL CPL <i>Defect</i>	53201 68901	<i>2nd work Unit</i>	0%	395.00*
341	1	FRT BUMPER ABSORBER <i>crushed</i>	52611 68020		0%	50.00*
350	1	FRT BUMPER CLAMP KIT <i>ren</i>	USE SINGLE PARTS		0%	20.00*
1000	1	FRT BUMPER LOWER <i>Defect</i>	GRILLE RH		0%	35.00*
410	1	GRILLE <i>crushed</i>	53111 68030		0%	85.00*
317	1	L/F BUMPER BRACKET <i>ren</i>	52116 68020		0%	28.00*
561	1	L/F HEADLAMP <i>crushed</i>	81170 68040		0%	330.00*
741	1	L/F WING <i>Buckled</i>	53802 68010		0%	220.00*
789	1	L/F WING CLAMP KIT <i>ren</i>	USE SINGLE PARTS		0%	20.00*
1018	1	LOCK CARRIER STRUT <i>Best</i>	53208 68010		0%	50.00*
493	1	LOWER BONNET LOCK <i>ren</i>	53510 68020		0%	45.00*
431	1	MANUFACTURER BADGE <i>ren</i>	75341 68040		0%	30.00*
318	1	R/F BUMPER BRACKET <i>ren</i>	52115 68020		0%	28.00*
298	1	R/F BUMPER COVER <i>Defect</i>	52127 68040		0%	35.00*
562	1	R/F HEADLAMP <i>crushed</i>	81130 68040		0%	330.00*
7761	1	RADIATOR CPL <i>ren</i>	16400 28110		0%	530.00*

f: OEM Parts

g: Original

h: Secondhand

p: Parallel

x: Exchange

Sub Total

Mark Up From Cost (10 %)

Total Parts

\$3,210.00

\$321.00

\$3,531.00

2pc fct bonnet hinge \$30 x 2  
Best

Aircon Coolant  
Aircon Coolant \$50/unit Nec ✓

Audatex System Using Manufacturer Times

Claim Reference:

Assessment Number: GS001714

Version: SMEMOT01/1

Date Calculated: 06/08/2018 07:45

Full Report - V1

Registration: SLH5509H

Printed: 06/08/2018 14:46

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras

\$0.00

**Final Calculation**

Total Parts		\$3,531.00
Labour		
	Total Panel/Mechanical	\$477.00
	Total Paintwork	\$337.50
Total Labour		\$814.50
Total Paint/Material Costs		\$144.40
Grand Total Excludes GST		\$4,489.90
	GST @ 7 %	\$314.29
Grand Total Includes GST		\$4,804.19

**Assessment Notes**

Parts 2195  
 +10% ~~2195~~ 2414.50  
 SN 80  
 LC 337.50 = 819.40  
 337.50  
 144.40  


---

 328390

22/08/2018

Adrian King  
 P/P 08/08/18.  
 04 Days.  
 Authorised Repairs  
 Excess \$300.





合興汽車零件私人有限公司

## HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403  
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /  
DAIHATSU / KIA / SUZUKI / HONDA  
TEL: 6291 2827 FAX: 6296 4390  
A/C: 6291 1886 FAX: 6291 7717  
Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

### TAX INVOICE

M/S: SME MOTOR PTE LTD

1 KAKI BUKIT AVE.6  
#02-15/16/17/18 AUTOBAY @KAKI BUKIT  
SINGAPORE 417883  
SLH5509H  
SEBAST

NO: DLI9206712  
PAGE: 1  
DATE: 17/08/2018  
A/C CODE: LDSM446  
TERMS: CR

Part No	Description	Location	Qty	Unit Price SIN	Amount SIN	
Our D/O No: DDO9022073						
1	T53301-68020	BONNET	DB1C33	1	280.00	280.00
2	T53111-68070	GRILLE	DB1K10	1	85.00	85.00
3	T52119-68909	BUMPER FR	DB2G	1	220.00	220.00
4	T52127-68060	BUMPER COVER STD FR RH	DU1AD57-2	1	35.00	35.00
5	T81130-68070	H/LAMP RH	DB1H20	1	330.00	330.00
6	T81170-68070	H/LAMP LH	DB1G23	1	330.00	330.00
7	T53208-68020	BRACE PANEL	DU1E30-1	1	50.00	50.00
Our D/O No: DDO9022074						
1	T53410-68030	BONNET HINGE RH	DU1AD19-5	1	30.00	30.00
2	T53420-68030	BONNET HINGE LH	DU1AD20-5	1	30.00	30.00
3	T88450-02350	CONDENSER	DB2C	1	290.00	290.00
4	T52021-68020	BUMPER REINF FR	DB1J24L	1	95.00	95.00
5	T52115-68030	BUMPER RETAINER FR RH	DU1AD32-3	1	28.00	28.00
6	T52116-68030	BUMPER RETAINER FR LH	DDS	1	28.00	28.00
7	T53812-68030	FENDER FR LH	DB1B5	1	220.00	220.00
Our D/O No: DDO9022080						
1	T52611-68030	BUMPER SPONGE FR	DB1E49	1	50.00	50.00
2	T52161-16010	CLIP,GRILLE	DDS	4	2.00	8.00
3	T52161-16010-1	CLIP,FR BUMPER	DDS	10	2.00	20.00
4	T90467-06181-C0	CLIP,SUPPORT TOP GARNISH	DDS	8	2.00	16.00
5	T90467-07164	CLIP,COWLING	DDS	10	2.00	20.00
6	T75341-68010	BONNET LOGO	DDS	1	30.00	30.00

Print / MT / 17/08/2018 10:31:29 AM

...Cont'd







# 合興汽車零件私人有限公司

## HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403  
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /  
DAIHATSU / KIA / SUZUKI / HONDA  
TEL: 6291 2827 FAX: 6296 4390  
A/C: 6291 1886 FAX: 6291 7717  
Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

### TAX INVOICE

M/S: SME MOTOR PTE LTD

NO: DLI9206712  
PAGE: 2

TOTAL QUANTITY:	48	TOTAL	SIN 2,195.00
		ADD GST @ 7%	153.65
		GRAND TOTAL	<u>SIN 2,348.65</u>

#02-18

Print / MT / 17/08/2018 10:31:29 AM

SALESMAN: MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY



51 Ubi Avenue 1, #01-25  
Paya Ubi Industrial Park  
Singapore  
408933

Finalised

**Claim Reference:**  
**Assessment Number: GS001714**  
**Version: SMEMOT01/2**  
**Date Calculated: 27/08/2018 10:20**

**Full Report - V1**  
**Registration: SLH5509H**  
**Printed: 27/08/2018 17:22**

## Summary Information

### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	05/08/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:	OD	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

### Vehicle Details

#### Vehicle

Manufacturer:	TOYOTA
Model:	Wish
Sub Model:	BASE MODEL
Model Sheet Number:	YCW 01
Registration:	SLH5509H
Registration Month:	January
Registration Year:	2010
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

#### Model Specs

FROM 08/2009	AIR CONDITIONING
1.8 LTR 95 KW	TWO COAT METALLIC
PREPARE OFF VEHICLE	

### Vehicle Condition

#### Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	06/08/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

Claim Reference:

Full Report - V1



Assessment Number: GS001714

Registration: SLH5509H

Version: SMEMOT01/2

Printed: 27/08/2018 17:22

Date Calculated: 27/08/2018 10:20



## Addresses

## Cost Summary

Total Labour	\$675.00
Total Paint/Material	\$144.40
Total Parts	\$2,414.50
Total of Additional Costs	\$50.00
Excess:	TBA
Grand Total Exc GST:	\$3,283.90
7 % GST:	\$229.87
Grand Total Inc GST:	\$3,513.77

## Repair Information

## LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR  
Price/Dent = \$0.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
810151A	ADJUST HEADLAMP	3.0	13.50
531011)	R + R L/F WING	5.0	22.50
	INCLUDES: R + R FRONT BUMPER, HEADLAMP AND WHEELHOUSE COVER		
531011)	RENEW LEFT FRONT WING	1.0	4.50
	INCLUDES: TRANSFER ATTACHED PARTS		
520011)	RENEW FRONT BUMPER (REMOVED)	6.0	27.00
	INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT		
810051)	R + R RIGHT HEADLAMP	7.0	31.50
530051)	TRANSFER ATTACHED PARTS FROM BONNET	3.0	13.50
530051)	RENEW BONNET	1.0	4.50
	INCLUDES: R + R OR RENEW ATTACHED PARTS		
530101)	RENEW LEFT BONNET HINGE (BONNET REMOVED)	4.0	18.00
530101)	RENEW RIGHT BONNET HINGE (BONNET REMOVED)	4.0	18.00
530111	R + R BONNET LOCK	2.0	9.00
NO NUMBER	R + R LANDING PANEL SUPPORT	2.0	9.00
883151)	R + R CONDENSER (FRONT BUMPER REMOVED)	8.0	36.00
	INCLUDES: DRAIN + REFILL AIR CONDITIONING		
	DOES NOT INCLUDE: DETACH + REFIT RADIATOR		
160011	R + R RADIATOR	9.0	40.50
	INCLUDES: BLEED COOLING SYSTEM		
1009	REPAIR FRONT PANEL CPL	20.0*	90.00

Claim Reference:

Full Report - V1

Assessment Number: GS001714

Registration: SLH5509H

Version: SMEMOT01/2

Printed: 27/08/2018 17:22

Date Calculated: 27/08/2018 10:20

**LABOUR COST**

Total Work Units	75.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	7.5HRS	\$337.50
Paint Labour	7.5HRS	\$337.50
Total Labour	15.0HRS	\$675.00

**PAINT WORK**

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
471	BONNET NEW PART PAINTING	15.0	
741	L/F WING NEW PART PAINTING	10.0	
1018	LOCK CARRIER STRUT SURFACE PAINT	4.0	
742	R/F WING SURFACE PAINT	6.0	
1009	FRONT PANEL CPL SURFACE PAINT	6.0	
1481	LEFT FRONT DOOR SURFACE PAINT	9.0	

**LABOUR COST - PAINT**

TIME(PAINT)	50.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	75.0	
Total Paintwork Labour	7.5HRS	\$337.50

**MATERIAL COST - PAINT**

New Part Painting	\$64.50
Material-Constant Main Work Metal	\$28.60
Surface-/Blend Paint	\$51.30
Total Excluding Pearlescent Uplift	\$144.40
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$144.40

**PARTS**

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1000	1	4PCS GRILLE CLIPS	Renew		0%	8.00*
1000	1	8PC SUPPORT TOP	GARNISH CLIPS		0%	16.00*
471	1	BONNET	53301 68012		0%	280.00*
4465	1	CONDENSER	88460 21040		0%	290.00*
281	1	FRONT BUMPER	52119 68061A0		0%	220.00*
340	1	FRONT BUMPER SUPPORT	52021 68010		0%	95.00*
341	1	FRT BUMPER ABSORBER	52611 68020		0%	50.00*
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		0%	20.00*
410	1	GRILLE	53111 68030		0%	85.00*
475	1	L/BONNET HINGE	53420 68010	SUPPLEMENTARY	0%	30.00F
317	1	L/F BUMPER BRACKET	52116 68020		0%	28.00*
561	1	L/F HEADLAMP	81170 68040		0%	330.00*
741	1	L/F WING	53802 68010		0%	220.00*
789	1	L/F WING CLAMP KIT	USE SINGLE PARTS		0%	20.00*
1018	1	LOCK CARRIER STRUT	53208 68010		0%	50.00*
431	1	MANUFACTURER BADGE	75341 68040		0%	30.00*
476	1	R/BONNET HINGE	53410 68010	SUPPLEMENTARY	0%	30.00F
318	1	R/F BUMPER BRACKET	52115 68020		0%	28.00*

Claim Reference:

Full Report - V1

Assessment Number: GS001714

Registration: SLH5509H

Version: SMEMOT01/2

Printed: 27/08/2018 17:22

Date Calculated: 27/08/2018 10:20

298	1	R/F BUMPER COVER	52127 68040	0%	35.00*
562	1	R/F HEADLAMP	81130 68040	0%	330.00*
f: OEM Parts			Sub Total		\$2,195.00
g: Original			Mark Up From Cost (10 %)		\$219.50
h: Secondhand			<b>Total Parts</b>		<b>\$2,414.50</b>
p: Parallel					
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

**Extras**

Description	Betterment	Price
AIRCON COOLANT SPECIALIST	0%	\$50.00
	<b>Total Extras</b>	<b>\$50.00</b>

**Final Calculation**

<b>Total Parts</b>		<b>\$2,414.50</b>
<b>Labour</b>		
Total Panel/Mechanical	\$337.50	
Total Paintwork	\$337.50	
<b>Total Labour</b>		<b>\$675.00</b>
<b>Additional Costs</b>		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$50.00	
<b>Total of Additional Costs</b>		<b>\$50.00</b>
<b>Total Paint/Material Costs</b>		<b>\$144.40</b>
<b>Grand Total Excludes GST</b>		<b>\$3,283.90</b>
GST @ 7 %		<b>\$229.87</b>
<b>Grand Total Includes GST</b>		<b>\$3,513.77</b>

**Assessment Notes**

## Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Monday, 27 August 2018 5:35 PM  
**To:** 'ying@smemotor.com.sg'; Mei Kwan (LKKAUTO)  
**Cc:** SUR  
**Subject:** RE: SLH5509H PENDING FOR FINALISE

Dear Ying,

Confirmed amount \$3,283.90 before excess \$300 @ 4 working days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** ying@smemotor.com.sg <ying@smemotor.com.sg>  
**Sent:** Monday, 27 August 2018 3:12 PM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** Re: SLH5509H PENDING FOR FINALISE

Hi Veron,

Based on marking, front panel cps is repair 20 wu, kindly add in.

**From:** Veron Chen (LKKAUTO)  
**Sent:** Monday, August 27, 2018 2:49 PM  
**To:** Mei Kwan (LKKAUTO) ; ying@smemotor.com.sg  
**Cc:** SUR  
**Subject:** RE: SLH5509H PENDING FOR FINALISE

Dear Ying,

Finalise amount \$3,085.70 before excess \$300

Please check and confirm.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

• **From:** Mei Kwan (LKKAuto)  
**Sent:** Monday, 27 August 2018 1:23 PM  
**To:** Admin-D (LKKAuto) <admin-d@lkkauto.com>  
**Subject:** FW: SLH5509H PENDING FOR FINALISE

*To check availability of the case handler, you may contact the undersigned.*

Thank you.

Best Regards, **Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** [ying@smemotor.com.sg](mailto:ying@smemotor.com.sg) <[ying@smemotor.com.sg](mailto:ying@smemotor.com.sg)>  
**Sent:** Monday, 27 August, 2018 12:57 PM  
**To:** Adrian Ling (LKKAuto) <[adrianling@lkkauto.com](mailto:adrianling@lkkauto.com)>  
**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** SLH5509H PENDING FOR FINALISE

Hi Adrian,

Please check and confirm.

thanks & regards  
YING

**From:** [ptr2@smemotor.com.sg](mailto:ptr2@smemotor.com.sg)  
**Sent:** Monday, August 27, 2018 11:27 AM  
**To:** SME Motor-Ying  
**Subject:** Attached Image