



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	1 2009 TOYOTA WISH 1.8 (SLH5509H)
Date of Loss	5 August 2018
Time of Loss	12.45
Loss Description	SLH5509H (INSD) C/W SKV2524X (TP) AT REAR
Comment	

Workshop Details

Total Rebate Amount	14265
Nett Loss Amount	\$12,735.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Target Date of Completion *	23/09/2018
Days of work completion *	24



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SLH5509H

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

07/01/2010



Mileage

121550

Age of Vehicle

8

Driver Details

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2009	2009
Make	TOYOTA	TOYOTA
Model	WISH 1.8	WISH 1.8X A

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	COLIN ONG THIAM CHYE (WANG TIANCAI)	
Date of Birth	1 November 1976	dd/mm/yy
Age	41	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No	ZGE200020060	ZGE200020060
Engine No	2ZR0453885	2ZR0453885
Engine Capacity		1797
Sum Insured	0	0
Market Value	0	27000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	19	
Driver License #		
License Type		
License Issue Date		dd/mm/yy 
License Expiration Date		dd/mm/yy 
Address	BLK 221A BEDOK CENTRAL, #08-62, 461221, Singapore	
Address type	Residential	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	
Marital status	Married	
Identification #	S7634281D	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

08/08/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

300

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

195/65R15

Rear Tyre Size

195/65R15

Front left side

BRIDGESTONE6mm

Rear left side

BRIDGESTONE6mm

Front right side

BRIDGESTONE6mm

Rear right side

BRIDGESTONE6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details			Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	Parts							
Add			Approve			Deny			Submit All								
		EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
			1	4			GRILLE CLIPS (WCP) (10%)			Necessary	2.2				8.8	Reviewing	
			2	8			SUPPORT TOP (WCP) (10%)			Necessary	2.2				17.6	Reviewing	
			3	1			BONNET (WCP) (10%)			Dented	308				308	Reviewing	
			4	1			CLOSING PANEL SEAL			Serviceable	0	0	0	0	0	Deny	
			5	1			CONDENSER (WCP) (10%)			Dented	319				319	Reviewing	
			6	1			FRONT BUMPER (WCP) (10%)			Deformed	242				242	Reviewing	
			7	1			FRONT BUMPER SUPPORT (WCP) (10%)			Bent	104.5				104.5	Reviewing	
			8	1			FRONT PANEL CPL			Repair	0	0	0	0	0	Deny	
			9	1			FRT BUMPER ABSORBER (WCP) (10%)			Cracked	55				55	Reviewing	
			10	1			FRT BUMPER CLAMP KIT (WCP) (10%)			Necessary	22				22	Reviewing	
			11	1			FRT BUMPER LOWER			Serviceable	0	0	0	0	0	Deny	
			12	1			GRILLE (WCP) (10%)			Cracked	93.5				93.5	Reviewing	
			13	1			L/F BUMPER BRACKET (WCP) (10%)			Necessary	30.8				30.8	Reviewing	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		14	1			L/F HEADLAMP (WCP) (10%)			Cracked	363				363	Reviewing	
		15	1			L/F WING (WCP) (10%)			Buckled	242				242	Reviewing	
		16	1			L/F WING CLAMP KIT (WCP) (10%)			Necessary	22				22	Reviewing	
		17	1			LOCK CARRIER STRUT (WCP) (10%)			Bent	55				55	Reviewing	
		18	1			LOWER BONNET LOCK			Serviceable	0	0	0	0	0	Deny	
		19	1			MANUFACTURER BADGE (WCP) (10%)			Necessary	33				33	Reviewing	
		20	1			R/F BUMPER BRACKET (WCP) (10%)			Necessary	30.8				30.8	Reviewing	
		21	1			R/F BUMPER COVER (WCP) (10%)			Deformed	38.5				38.5	Reviewing	
		22	1			R/F HEADLAMP (WCP) (10%)			Cracked	363				363	Reviewing	
		23	1			RADIATOR CPL (WCP) (10%)			Serviceable	0	0	0	0	0	Deny	
		24	2			FRONT BONNET HINGE (WCP) (10%)			Bent	33				66	Reviewing	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		TOTAL PANEL/ MECHANICAL	337.5	0	0	Reviewing		
		2		TOTAL PAINTWORK	337.5	0	0	Reviewing		
		3		TOTAL PAINT / MATERIAL COSTS	144.4	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

DAYS OF
REPAIR :
4 DAYS

Reviewing



2

AIRCON
COOLANT

Reviewing

50

NECESSARY



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$2,983.90

Claim Amount \$2,983.90

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$819.40	\$819.40
Miscellaneous	\$50.00	\$50.00
Excess	-\$300.00	-\$300.00
Spare Parts	\$2,414.50	\$2,414.50

Submit for Review