

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR INS	PECTION REPORT	
SOMPO INSURANCE SINGAPORE PL			Ref: CS3/SMO18014375/Gz4d3e2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWER SINGAPORE 048623			Date: 06-09-2018	
			Code: SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SKA 2155M	Veh. Inspected	SLS 5369L
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD1803371/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	06/08/2018
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	GP71116755	Colour	WHITE
	Odometer	78000 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
	1411110111111111			
	L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
	-	185/60 R15 185/60 R15	YOKOHAMA YOKOHAMA	6 mm
	L/H Front Tyre			
4.	L/H Front Tyre R/H Rear Tyre	185/60 R15 185/60 R15	YOKOHAMA	6 mm
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	185/60 R15 185/60 R15	YOKOHAMA YOKOHAMA ion of Damages	6 mm
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	185/60 R15 185/60 R15  Descript STAINED DAMAGES AT THE RE	YOKOHAMA YOKOHAMA ion of Damages	6 mm
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	185/60 R15 185/60 R15  Descript STAINED DAMAGES AT THE RE	YOKOHAMA YOKOHAMA ion of Damages AR PORTION.	6 mm
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS	185/60 R15 185/60 R15 Descript STAINED DAMAGES AT THE RE	YOKOHAMA YOKOHAMA ion of Damages AR PORTION. al Information	6 mm 6 mm
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS	185/60 R15 185/60 R15  Descript  STAINED DAMAGES AT THE RE  Gener  04/08/2018	YOKOHAMA YOKOHAMA tion of Damages AR PORTION. al Information Inspect Date / Time	6 mm 6 mm
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS	185/60 R15  Descript  STAINED DAMAGES AT THE RE  04/08/2018  TRIPLE-T AUTOMOBILE  BLK 5 DEFU LANE 10 #01-574	YOKOHAMA YOKOHAMA tion of Damages AR PORTION. al Information Inspect Date / Time	6 mm 6 mm
5.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  THE VEHICLE SUS  Accident Date Survey held at  A) THE INSPECTION B) THE REPAIR ESTHE REPAIRER W C) ENCLOSED PL	185/60 R15  Descript  STAINED DAMAGES AT THE RE  04/08/2018  TRIPLE-T AUTOMOBILE  BLK 5 DEFU LANE 10 #01-574	YOKOHAMA YOKOHAMA Tion of Damages  AR PORTION.  al Information Inspect Date / Time  SINGAPORE 539186  Remarks ITHOUT PREJUDICE" BASIS. D AT THE TIME OF INSPECTION IN	6 mm 6 mm 20/08/2018 ( 01:00 PM )

Report Ref No. CS3/SMO18014375/Gz4d3e2

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

4 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.