

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

EQ Insurance Company Ltd

22 Gemmill Lane

Singapore 069257

Tel: 6223 9433 Fax: 6223 4190

*Not Notarized
L1Ling @ ?
Resurvey After Pain*

ACCIDENT REPAIR ON : SJT9105Z

MODEL : HYUNDAI AVANTE 1.6M

POLICY NO : MPC18A00117301

CHASSIS NO : KMHDU41BR9U810727

MANUFACTURING YEAR : 2009

DATE / TIME OF ACCIDENT: 04/08/2018 Time: 0810Hrs ALONG SERANGOON RD SLIP RD TO HG AVE 3

THIRD PARTY VEHICLE NO : EY3321M

Date: 20/06/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Bootlid	1	985.90	B	985.90 ✓
2 Bootlid Hinge LH	1	132.00	R	132.00 X
3 Bootlid Hinge RH	1	132.00	R	132.00 ✓
4 Bootlid Emblem	1	23.30	nn	23.30 ✓
5 Bootlid Lock Assy	1	118.30	R	118.30 X
6 Bootlid Lamp LH	1	163.60	sn	163.60 X
7 Bootlid Lamp RH	1	163.60	sn	163.60 X
8 Bootlid Inner Trim	1	151.20	sn	151.20 X
9 Bootlid Weatherstrip	1	79.31	Dit 1/2	79.31 50% sn
10 Rear Windscreen Moulding	1	47.50	nn	47.50 X
11 Rear Fender LH	1	1806.70	R	1,806.70 X
12 Rear Fender Shield LH	1	15.00	sn	15.00 X
13 Rear Fender RH	1	1806.70	R	1,806.70 X
14 Rear Fender Shield RH	1	15.00	sn	15.00 X
15 Rear Bumper	1	489.10	B	489.10 ✓
16 Rear Bumper Sponge	1	109.90		109.90 ?
17 Rear Bumper Reinforcement	1	270.00		270.00 ?
18 Rear End Panel	1	493.80	B	493.80 ✓
19 Rear End Panel Top Garnish	1	34.40		34.40 ?
20 Spare Tyre Panel	1	878.30	R	878.30 X
21 Tail Lamp LH	1	288.40	ngent	288.40 ✓
22 Tail Lamp RH	1	288.40	cnr	288.40 ✓
23 Tail Lamp Bracket LH	1	175.70	R	175.70 X
24 Tail Lamp Bracket RH	1	175.70	R	175.70 X
Sub-Total:				8,843.81
Less Discount 20%				1,768.76
Total Parts:				7,075.05

Special Nett Items

1 Anti-rust coating	5	80.00	bol	400.00
2 Rear Bumper Clips	10	2.00	nn	20.00 ✓
3 Rear Fender Shield Clips	20	2.00	nn	40.00 X
4 Windscreen Sealant	1	100.00	nn	100.00 X
5 Spare Tyre Panel Sealant	1	100.00	nn	100.00 X
6 Bumper Sensor Set	1	250.00	shot	250.00 200% sn
7 Rear Number Plate	1	50.00	sn	50.00 X

Total Parts: 960.00

Labour Charges For Rear Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	6001	2,500.00
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	6001	1,500.00
3	Provide skill labour to disconnect and check electrical wiring		30.00 201
4	Remove and refit rear end panel lining and garnish to facilitate repair		100.00 601
5	Remove and replace bumper sensors		100.00 501
Total Labour:			4,230.00
Total Parts & Labour:			12,265.05
GST 7%			858.55
Grand Total:			13,123.60

Estimate Repair Duration 10 days
5 days

ACCIDENT VEHICLE OF : SJT9105Z

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by:

Name : Kennerly
Company : CKIC
Date : 8/8/18
Time : 11.40am
Contact No: 96910663
Email : _____