



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18014395/Kga3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 20-01-2020	
ATTN: STACEY NG		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	S 7215CD	Veh. Inspected	SHD 660D
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00R40	Excess (\$)	0.00
Assign From	STACEY NG	Assign Date	06/08/2018
2. Vehicle Particulars & Condition			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VF1ABL15AUC283410	Colour	METALLIC WHITE / RED
Odometer	184414	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	6 mm
L/H Front Tyre	215/60 R16	GITI	6 mm
R/H Rear Tyre	215/60 R16	GITI	9 mm
L/H Rear Tyre	215/60 R16	GITI	9 mm
4. Description of Damages			
THE VEHICLE SUSTANED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/07/2018	Inspection Date	07/08/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 660D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	DOOR PANEL FRT RH (CONSISTENT)	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR HINGE UPPER RH (CONSISTENT)	TO REPAIR SEE LABOUR	261.28	-
1	DOOR HINGE LOWER RH (CONSISTENT)	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK FRT RH (CONSISTENT)	SERVICEABLE	194.77	-
1	DOOR LOCK FRT RH (CONSISTENT)	TO REPAIR SEE LABOUR	908.75	-
1	DOOR CATCH FRT RH (CONSISTENT)	SERVICEABLE	131.23	-
1	DOOR HANDLE OUTER FRT RH (CONSISTENT)	SERVICEABLE	477.76	-
1	DOOR HANDLE COVER FRT RH (CONSISTENT)	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT RH (CONSISTENT)	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT RH (CONSISTENT)	TO REPAIR SEE LABOUR	505.19	-
1	DOOR REGULATOR MOTOR FRT RH (CONSISTENT)	SERVICEABLE	796.46	-
1	DOOR REGULATOR GUIDE FRT RH (CONSISTENT)	SERVICEABLE	120.97	-
1	DOOR PANEL REAR RH (CONSISTENT)	BENT	2,844.66	2,844.66
1	DOOR GUIDE REAR RH (CONSISTENT)	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH (CONSISTENT)	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER RH (CONSISTENT)	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHCK REAR LH/RH L70Y (CONSISTENT)	SERVICEABLE	203.06	-
1	DOOR LOCK REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	908.75	-
1	DOOR HANDLE OUTER REAR RH (CONSISTENT)	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR RH (CONSISTENT)	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR RH (CONSISTENT)	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR RH (CONSISTENT)	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	133.60	-
1	DOOR RERGULATOR REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	1,135.10	-

Report Ref No. CC4/ASM18014395/Kga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR REGULATOR MOTOR REAR RH (CONSISTENT)	SERVICEABLE	893.75	-
1	DOOR REGULATOR NUT REAR L70Y (CONSISTENT)	SERVICEABLE	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y (CONSISTENT)	SERVICEABLE	6.31	-
1	DOOR FINISHER REAR RH (CONSISTENT)	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR RH (CONSISTENT)	SERVICEABLE	176.82	-
1	DOOR MOULDING CLIP L70Y (CONSISTENT)	NOT NECESSARY	5.92	-
1	DOOR MOULDING SCREW L70Y (CONSISTENT)	NOT NECESSARY	6.91	-
1	DOOR CASING REAR RH (CONSISTENT)	SERVICEABLE	1,509.06	-
1	DOOR WATER SHIELD REAR RH (CONSISTENT)	SERVICEABLE	30.39	-
1	DOOR CASING CLIP (CONSISTENT)	NOT NECESSARY	12.63	-
1	DOOR CASING LIGHT L70Y (CONSISTENT)	SERVICEABLE	48.74	-
1	DOOR FINISHER INNER REAR RH (CONSISTENT)	SERVICEABLE	323.44	-
1	DOOR FINISHER BRACKET INNER REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	46.97	-
1	DOOR FINISHER BRACKET INNER REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-
1	DOOR GRAB HANDLE REAR RH (CONSISTENT)	SERVICEABLE	210.96	-
1	DOOR BLIND REAR RH (CONSISTENT)	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP REAR RH (CONSISTENT)	SERVICEABLE	410.66	-
1	DOOR SEAL REAR RH (CONSISTENT)	SERVICEABLE	162.02	-
1	DOOR GLASS RUNNER SEAL REAR RH (CONSISTENT)	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER REAR RH (CONSISTENT)	SERVICEABLE	334.69	-
1	DOOR WAIST SEAL INNER REAR RH (CONSISTENT)	SERVICEABLE	115.64	-
	LESS 10% DISCOUNT		-1,861.10	-284.47
			16,750.04	2,560.19
	SPECIAL NETT ITEMS			
1	SET FRAME FULL SUPPORT PANEL CLIP (SN) (CONSISTENT)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN) (CONSISTENT)	NOT NECESSARY	20.00	-

Report Ref No. CC4/ASM18014395/Kga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRAME FULL SUPPORT PANEL STUD (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	SET WHEELARCH CLIP FRT LH (SN) (CONSISTENT)	NOT NECESSARY	30.50	-
1	FRONT DOOR STICKER 'TRANS-CAB' (SN) (CONSISTENT)	NECESSARY	80.00	60.00
1	FRONT DOOR STICKER 'CHASSIS' (SN) (CONSISTENT)	NECESSARY	50.00	15.00
1	REAR DOOR STICKER '6555-3333' (SN) (CONSISTENT)	NECESSARY	80.00	60.00
1	DOOR CHECK BOLT (SN) (CONSISTENT)	SERVICEABLE	22.69	-
1	DOOR GUIDE SCREW (SN) (CONSISTENT)	SERVICEABLE	10.85	-
1	DOOR HINGE BOLT (SN) (CONSISTENT)	SERVICEABLE	10.85	-
1	DOOR HINGE NUT RH (SN) (CONSISTENT)	SERVICEABLE	14.60	-
1	DOOR CHECK BOLT (SN) (CONSISTENT)	SERVICEABLE	22.69	-
1	DOOR CHECK NUT (SN) (CONSISTENT)	SERVICEABLE	3.75	-
1	DOOR LOCK SCREW L70Y (SN) (CONSISTENT)	SERVICEABLE	6.12	-
1	DOOR CATCH SCREW L70Y (SN) (CONSISTENT)	SERVICEABLE	10.06	-
			462.11	135.00
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWA OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF DOOR PANEL FRT RH, DOOR HINGE UPPER RH, DOOR HINGE LOWER RH, DOOR LOCK FRT RH, DOOR REGULATOR FRT RH, DOOR LOCK REAR RH, DOOR HANDLE MODULE REAR RH, DOOR RERULATOR REAR RH AND DOOR FINISHER BRACKET INNER REAR RH.		4,500.00	440.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,200.00	660.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMTERY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-

Report Ref No. CC4/ASM18014395/Kga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRUALIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE TO JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
			11,450.00	1,210.00
	GRAND TOTAL		28,662.15	3,905.19
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,100.00

Report Ref No. CC4/ASM18014395/Kga3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.