

REPAIR ESTIMATE*

VEHICLE NO : SHA 1663E

DATE 7/8/2018 16:03

AWA

MAKE :

Chang

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door (LH) <i>x repair</i>			
	Front Door Mirror (LH) <i>- det</i>			980.50
	Front Wheel Rim (LH) <i>- hatched</i>			1091.50
	Front Pump <i>x repair</i>			
	LH Rocker Panel garnish <i>x repair</i>			
	Rear LH Door <i>x repair</i>			
	Front Fender Emblem <i>- re</i>			
				SUB TOTAL
				LESS 20%
				DISCOUNTED TOTAL
				\$2660
	Front Door Comfort Logo (LH) <i>- re</i>			\$ 75.00
	Rear Door Tel No. Sticker (LH) <i>- re</i>			\$ 80.00
				\$ 85.00
	Labour Charge			
	Panel Beating			\$ 200
	Spray Painting Charge			\$ 280.00
	Wiring Charge			\$ 1,150.00
	Tuff Kote			\$ 50.00
	Transfer of Door			\$ 50.00
				\$ 120.00
				\$ 1,720.00
				ESTIMATE TOTAL
				3103.88

To be Advise

1050
20
X 20
X 20

Kah (UAW)
8/8/18 1015h
2 Pgs.
P/P
Return Print p/h

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary repair must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.