

CS3/LPC18006671/R17d3-1

ASSIGNMENT FORM

Risul
Gerald

Lpc

08/08/2018

OD/TP WS/TP RES/OD RES/IVA/INSV/MV/CS

To Inspect Vehicle No: SFB 6911A

Insured: 92 58344

Workshop: Eng Soon Spray Painting
at Blk 4, Yew Tee Ind. Est 393-J woodlands

Ref: 6760 6271

Policy No:

Claim No: 1718/18/VCO0/020525

Sum Insured:

Excess:

Make of Vehicle
(If Not's Record)

DOA: 09/04/2018

CA / REV / REP / REV 24HRS (wp)

HOI's Endorsement

Date/Time: 9:20am @ 11/4/18

Person Contacted

Mr. Teo

Vehicle: IN OUT

Date/Time: Attached Item (X) Estimate

11/4/18

12/4/18

11/4-
12/4- Survey
dismantle.

lump sum 9850/- (cred: 11400; 53%) 7 days


11/10/2018

Repair days 87

RECEIVED 11 OCT 2018

Blim

11/10/18



LONPAC INSURANCE BHD

(S98FC5635C)

Our Ref : 17/18/18/VC00/020525

Your Ref : CS3/LPC18006671/r/1TD3e2

7 August 2018

M/s LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Pk
Singapore 408933

Dear Sirs/Madam

PAPER SURVEY OF SFB6911A

We refer to the above matter.

We enclose the following documents :-

- a) Survey report & photos of SFB6911A
- b) GIA report of SFB6911A
- c) GIA report & photos of GZ5834H

Kindly study the documents and let us have your opinion on the adjusted repair cost within the next 10 days.

Yours faithfully

GERALD POH
SENIOR EXECUTIVE
(CLAIMS)
Email : mt_claim@lonpac.com

18/03/18

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/04/2018 12:40
Date Of Accident	09/04/2018 06:50
Exact Location Of Accident	BLK 514 HOUGANG AVE 10, CARPARK ENTRANCE AREA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFB6911A
Insured/Policyholder	
Name Of Registered Owner	TAN BENG CHONG
NRIC No	S1782312D
Email Address	EEPL@EXCLUSIVE-ENGRG.COM
Mobile Phone No	(LOCAL) +65-90406911
Alternative Phone No	OFFICE-90406911

Vehicle Particulars

Manufacturer	AUDI
Model	A6 2.0T FSI MU CVT ABS D/AB HID 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA126157/1
Cover Note Number	

Driver

Name of Driver	TAN BENG CHONG
NRIC No	S1782312D
Date Of Birth	19/10/1966
Occupation	INDOOR
Date Of Driving Pass	18/07/1991
Driving Experience	26 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90406911
Fax Number	
Contact Number	OFFICE-90406911
EMail Address	EEPL@EXCLUSIVE-ENGRG.COM

• Nature Of Damage

No. Of Passenger (Including Driver)

Address BLK 162A PUNGGOL CENTRAL #08-57 SINGAPORE 821162
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1 NAME: : BROTHER
 GENDER: : MALE
 Passenger 2 NAME: : SISTER
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)


Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GZ5834H
 Vehicle Make/Model/Colour OPEL COMBO
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode

SKETCH PLAN

Refer to sketch Plan A.



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 09/04/18 at about 6.50 a.m., I was driving my vehicle SFB 6911A to leave the carpark. A vehicle of GZ 5834-H came in from the carpark did not stop at the stop line and bang into my vehicle SFB 6911-A right side cause my: head light, Bumper & Bonnet & front portion of my vehicle damage.



<p>Important: You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.</p>		- Reporting Only
		- Claim OD
		- Claim TP
	✓	- Claim OD/TP at other workshop

DECLARATION


I/WE declare the foregoing particulars are true in every respect.


 Policyholder's signature
 Date & Time
 09/04/18


 Driver's Signature
 (if driver not the policyholder)
 Date & Time


 Reporting Centre Personnel's Signature
 Name:
 Nric/Fin No.
 Toh Khar Kian

Sketch Plan A



- ① SF 6 6911-11
- ② GZ-5824-14

BIK 514
Hungary Ave 10

[Handwritten signature]

ENG SOON PAINTING SERVICES

Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677978
Tel: 6760 6271

TAN BENG CHONG
c/o M/s Eng Soon Painting Services
Block 4 Yew Tee Ind Est 393-J
Woodlands Road
Singapore 677969

Date: 19 July 2018

Dear Sir,

Date of accident : 09/04/2018
Final repair bill to SFB 6911 A

To Supply,

Lump Sum repairs recommended By the surveyor	\$21,250.00
Total	\$21,250.00

Dollars : TWENTY ONE THOUSAND TWO HUNDRED AND FIFTY ONLY

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879 Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the **front** portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 10 working days to complete

5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a "**Without Prejudice**" basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us **within 1 week**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SFB 6911 A

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
<i>List Items</i>				
1 pc	Front bumper	damaged	\$ 1,980.00	\$ 1,980.00 BRV
1 pc	Front bumper chrome moulding	cracked	\$ 335.00	\$ 335.00 BRV
2 pcs	Front bumper side retainer	bent	\$ 224.00	\$ 224.00 BTv
10 pcs	Front bumper clips	necessary	\$ 135.00	\$ 135.00 NEC
10 pcs	Front bumper day time running light RH	cracked	\$ 625.80	\$ 150.00 625.80 BRV
1 pc	Front bumper sponge	cracked	\$ 267.40	\$ 267.40 SUX
1 pc	Front bumper tow cover	cracked	\$ 200.20	\$ 200.20 BRV
1 pc	Front bumper fog lamp	cracked	\$ 502.60	\$ 502.60 NN
1 pc	Front bumper reinforcement	cracked	\$ 996.80	\$ 641.50 996.80 BTv
1 pc	Headlamp assy with led fitted	grazed	\$ 1,336.70	\$ 1,336.70 BRV
1 pc	Front support panel	bent	\$ 712.60	\$ 712.60 BTv
1 pc	Front grille with emblem	bent	\$ 725.00	\$ 649.00 725.00 BRV
1 pc	Front bonnet	bent	\$ 1,652.80	\$ 1,652.80 DDv
2 pcs	Front bonnet hinges	bent	\$ 134.40	\$ 134.40 NN
1 pc	Front bonnet hook	distorted	\$ 155.40	\$ 155.40 BT
1 pc	Front bonnet lock with micro switch	bent	\$ 145.60	\$ 145.60 BTv
1 pc	Front bonnet cable	snap	\$ 85.50	\$ 85.50 SUX
1 pc	Engine top cover	wrapped	\$ 190.50	\$ 190.50 NN
1 pc	Power steering oil fluid cooler	deformed	\$ 492.10	\$ 492.10 NN
1 pc	Intercooler pipe	dent	\$ 267.40	\$ 267.40 DDv
1 pc	Front bumper spoiler	deformed	\$ 325.00	\$ 325.00 NN
2 pcs	Front bonnet hinges cover plastic	wrapped	\$ 401.80	\$ 401.80 NN
1 pc	Temperature sensor	cracked	\$ 450.00	\$ 201.00 450.00 CUT
1 pc	Front bumper washer headlight jet	cracked	\$ 231.80	\$ 231.80 CUT
1 pc	Front bumper washer cover	cracked	\$ 204.40	\$ 204.40 CUT
1 pc	Radiator assy	damaged	\$ 825.80	\$ 825.80 BRV
1 pc	Radiator fan assy	electronic shocked	\$ 756.80	\$ 756.80 NN
2 pcs	Front bumper bracket	bent/distorted	\$ 410.00	\$ 163.00 410.00 BT

1 pc

1 pc	Condenser assy	bent/distorted	\$ 728.00	\$ 728.00 ^{su} X
1 pc	A/c hose	deformed	\$ 469.00	\$ 469.00
1 pc	A/c pipe	deformed	\$ 494.50	\$ 494.50
1 pc	A/c compressor	distorted	\$ 2,800.00	\$ 2,800.00
1 pc	Wheel housing liner	deformed	\$ 275.60	\$ 275.60
18 pcs	Front fender splash shield clips X	necessary	\$ 68.40	\$ 68.40
2 pcs	Front fender inner bracket X	bent	\$ 30.00	\$ 30.00
2 pcs	Front fender top garnish cover X	deformed	\$ 53.40	\$ 53.40
6 pcs	Front fender top garnish cover clips X	necessary	\$ 42.00	\$ 42.00
2 pcs	Bonnet stopper X	deformed	\$ 50.00	\$ 50.00 ^{CUT}
2 pcs	Bonnet inner rubber beading X	deformed	\$ 81.00	\$ 81.00 ^{CUT}
9 pcs	Bonnet inner rubber beading clips X	necessary	\$ 86.00	\$ 86.00 ^{NEC}
1 pc	Bonnet insulator X	damaged	\$ 334.60	\$ 334.60 ^{NN}
8 pcs	Bonnet insulator clips X	necessary	\$ 106.40	\$ 106.40 ^{NN}
2 pcs	Bonnet inner rubber RH & LH X	deformed	\$ 76.00	\$ 76.00 ^{CUT}
2 pcs	Bonnet stand clips X	necessary	\$ 38.50	\$ 38.50 ^{NEC}
2 pcs	Air cond condensor top mounting	bent	\$ 102.00	\$ 102.00 ^{BT}
2 pcs	Air cond condensor bottom mounting	bent	\$ 98.00	\$ 98.00 ^{BT}
2 pcs	Air cond condensor side air grille garnish RH & LH	cracked	\$ 259.00	\$ 259.00 ^{CRA}
6 pcs	Air cond condensor side air grille garnish clips	necessary	\$ 99.40	\$ 99.40 ^{NEC}
2 pcs	Radiator top mounting	bent	\$ 76.00	\$ 76.00 ^{BT}
2 pcs	Radiator bottom mounting	distorted	\$ 89.00	\$ 89.00
1 pc	Radiator top hose	deformed	\$ 79.00	\$ 79.00 ^{NN}
1 pc	Radiator bottom hose	deformed	\$ 124.00	\$ 124.00
	Parts Sub-Total		\$ 21,430.20	\$ 21,430.20
	Discount %		\$ -	\$ -
			\$ 21,430.20	\$ 21,430.20

Vehicle Number : SFB 6911 A

SPARE PARTS


QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
	<u>Special Nett Items</u>			
1 pc	Front number plate w casing	deformed	\$ 155.00	\$ 155.00 ^{BE}
2 pcs	Horn assy		\$ 529.00	\$ 529.00 ^{NN}
	Special Nett Sub-Total		\$ 684.00	\$ 684.00
	Spare Parts Total		\$ 22,114.20	\$ 22,114.20

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (\$)	Our Revised Estimation (\$)
	Spare Parts Total c/f	\$ 22,114.20	\$ 22,114.20
1	Towing	\$ 120.00	\$ 120.00 80
2	To check and reconnect snap wiring for headlamp & fog lamps.	\$ 180.00	\$ 150.00 50.00
3	To remove/replace radiator & conduct pressure test.	\$ 150.00	\$ 120.00 111
4	To tuff coat affected areas	\$ 120.00	\$ 100.00 50
5	To respray affected areas (pearl paint)	\$ 1,800.00	\$ 1,600.00 600.00
6	To renew damaged parts, straighten and repair front fender inner , structure, front chassis member and aligned all parts	\$ 1,800.00	\$ 1,600.00 800.00
7	To Remove & Refix Interior Upholstery.	\$ 180.00	\$ 150.00 111
8	To adjust chassis alignment on Car O Liner	\$ 380.00	\$ 350.00 111
9	To remove and replace air cond condensor, compressor , piping vacuum and top up gas	\$ 250.00	\$ 240.00 120.00
	Total	\$ 27,094.20	\$ 26,544.20

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 21,250.00


 Fong Kok Heng
 Qualified Appraiser

Repair days 87

Claim limit
 11/10/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC18006671/R1td3e2-1

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 11-10-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GZ 5834H	Veh. Inspected	SFB 6911A
Policy No.		Coverage (\$)	0.00
Claim No.	17/18/18/VC00/020525	Excess (\$)	0.00
Assign From	GERALD	Assign Date	08/08/2018

2. Vehicle Particulars & Condition

Make & Model	AUDI A6 2.0	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WAUZZZ4F39N030395	Colour	GREY
Odometer	162139	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45Z R17	WEST LAKE	6 mm
L/H Front Tyre	245/45Z R17	WEST LAKE	6 mm
R/H Rear Tyre	245/45Z R17	WEST LAKE	6 mm
L/H Rear Tyre	245/45Z R17	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/04/2018	Inspection Date	11/04/2018
Survey held at	ENG SOON PAINTING SVC BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFB 6911A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	BROKEN	1,980.00	1,980.00
1	FRONT BUMPER CHROME MOULDING	BROKEN	335.00	335.00
2	FRONT BUMPER SIDE RETAINER	BENT	224.00	224.00
10	FRONT BUMPER CLIPS	NECESSARY	135.00	135.00
10	FRONT BUMPER DAY TIME RUNNING LIGHT RH	BROKEN	625.80	150.00
1	FRONT BUMPER SPONGE	SERVICEABLE	267.40	-
1	FRONT BUMPER TOW COVER	BROKEN	200.20	200.20
1	FRONT BUMPER FOG LAMP	NOT NECESSARY	502.60	-
1	FRONT BUMPER REINFORCEMENT	BENT	996.80	641.50
1	HEADLAMP ASSY WITH LED FITTED	BROKEN	1,336.70	1,336.70
1	FRONT SUPPORT PANEL	BENT	712.60	712.60
1	FRONTRILLE WITH EMBLEM	BROKEN	725.00	649.00
1	FRONT BONNET	DENTED	1,652.80	1,652.80
2	FRONT BONNET HINGES	NOT NECESSARY	134.40	-
1	FRONT BONNET HOOK	BENT	155.40	155.40
1	FRONT BONNET LOCK WITH MICRO SWITCH	BENT	145.60	145.60
1	FRONT BONNET CABLE	SERVICEABLE	85.50	-
1	ENGINE TOP COVER	NOT NECESSARY	190.50	-
1	POWER STEERING OIL FLUID COOLER	NOT NECESSARY	492.10	-
1	INTERCOOLER PIPE	DENTED	267.40	267.40
1	FRONT BUMPER SPOILER	NOT NECESSARY	325.00	-
2	FRONT BONNET HINGES COVER PLASTIC	NOT NECESSARY	401.80	-
1	TEMPERATURE SENSOR	CUT	450.00	201.00
1	FRONT BUMPERWASHER HEADLIGHT JET	CUT	231.80	231.80
1	FRONT BUMPERWASHER COVER	CUT	204.40	204.40
1	RADIATOR ASSY	BROKEN	825.80	825.80
1	RADIATOR FAN ASSY	NOT NECESSARY	756.80	-
2	FRONT BUMPER BRACKET	BENT (1 PC ONLY)	410.00	163.00
1	CONDENSER ASSY	SERVICEABLE	728.00	-
1	A/C HOSE	NOT NECESSARY	469.00	-
1	A/C PIPE	NOT NECESSARY	494.50	-

Report Ref No. CS3/LPC18006671/R1td3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	A/C COMPRESSOR	NOT NECESSARY	2,800.00	-
1	WHEEL HOUSING LINER	NOT NECESSARY	275.60	-
18	FRONT FENDER SPLASH SHIELD CLIPS	NOT NECESSARY	68.40	-
2	FRONT FENDER INNER BRACKET	NOT NECESSARY	30.00	-
2	FRONT FENDER TOP GARNISH COVER	NOT NECESSARY	53.40	-
6	FRONT FENDER TOP GARNISH COVER CLIPS	NOT NECESSARY	42.00	-
2	BONNET STOPPER	CUT	50.00	50.00
2	BONNET INNER RUBBER BEADING	CUT	81.00	81.00
9	BONNET INNER RUBBER BEADING CLIPS	NECESSARY	86.00	86.00
1	BONNET INSULATOR	NOT NECESSARY	334.60	-
8	BONNET INSULATOR CLIPS	NOT NECESSARY	106.40	-
2	BONNET INNER RUBBER RH & LH	CUT	76.00	76.00
2	BONNET STAND CLIPS	NECESSARY	38.50	38.50
2	AIR COND CONDENSOR TOP MOUNTING	SERVICEABLE	102.00	-
2	AIR COND CONDENSOR BOTTOM MOUNTING	SERVICEABLE	98.00	-
2	AIR COND CONDENSOR SIDE AIR GRILLE GARNISH RH & LH	SERVICEABLE	259.00	-
6	AIR COND CONDENSOR SIDE AIR GRILLE GARNISH CLIPS	SERVICEABLE	99.40	-
2	RADIATOR TOP MOUNTING	BENT	76.00	76.00
3	RADIATOR BOTTOM MOUNTING	NOT NECESSARY	89.00	-
1	RADIATOR TOP HOSE	NOT NECESSARY	79.00	-
1	RADIATOR BOTTM HOSE	NOT NECESSARY	124.00	-
			21,430.20	10,618.70
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE W CASING (SN)	BROKEN	155.00	40.00
2	HORN ASSY (SN)	NOT NECESSARY	529.00	-
			684.00	40.00
	<u>LABOUR</u>			
	TOWING.		120.00	80.00
	TO CHECK AND RECONNECT SNAP WIRING FOR HEADLAMP & FOG LAMPS.		180.00	50.00
	TO TUFF COAT AFFECTED AREAS.		120.00	50.00

Report Ref No. CS3/LPC18006671/R1td3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY AFFECTED AREAS (PEARL PAINT).		1,800.00	600.00
	TO RENEW DAMAGED PARTS,STRAIGHTEN AND REPAIR FRONT FENDER INNER,STRUCTURE,FRONT CHASSIS MEMBER AND ALIGNED ALL PARTS.		1,800.00	800.00
	TO REMOVE & REFIX INTERIOR UPHOLSTERY.	NOT NECESSARY	180.00	-
	TO ADJUST CHASSIS ALIGNMENT ON CAR O LINER.	NOT NECESSARY	380.00	-
	TO REMOVE AND REPLACE AIR COND CONDENSOR,COMPRESSOR PIPINGS VACUUM AND TOP UP GAS.		250.00	120.00
	TO REMOVE/REPLACE RADIATOR & CONDUCT PRESSURE TEST.	NOT NECESSARY	150.00	-
			4,980.00	1,700.00
	GRAND TOTAL		27,094.20	12,358.70

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,850.00
---	--	--	--	-----------------

Report Ref No. CS3/LPC18006671/R1td3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.