



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793, Tel: 6741-1730 / 731, Fax: 6744-5746, Email: liubro@jymail.com

Invoice/Ref No: GBC5389G180804

Estimate

Customer

Name: EQ Insurance Company Limited
Address: Motor Claims Department
5 Maxwell Road #17-00
Tower Block MND Complex Singapore 069110

Date: 07-08-18
Vehicle No: GBC5389G
Model/Make: Toyota Hiace
Auto

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper <i>cut</i>	\$ 599.30	X
2	Rear Bumper Side Bracket <i>0/1</i>	\$ 98.00	X
3	Rear Bumper Clips 1 set	\$ 48.00	SN
4	Rear Tail Lamp <i>0/1</i>	\$ 303.10	X
5	Rear Fender <i>0/1</i>	\$ 1,419.70	X
6	Rear Fender Lower Member	\$ 241.10	X
7	Rear Wheel Hub-Cab <i>0/1</i>	\$ 150.00	SN
8	Rear Tyre <i>0/1</i> <i>LP200</i>	\$ 220.00	SN
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 60.00	X
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 800.00	-
	To putty & spray painting & including touch up paint	\$ 500.00	-

Total Parts & Labour of estimate for damaged vehicle

\$ 4,439.20

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

*not allowed
when photo taken
4/5/9
10/8/18
4 day*

*2-902.4
257
676.80
S.N - 318
labor - 1000
1994.80*

2/2 \$ 1994.80

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: