

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 9323S

DATE 23/7/2018 15:36

MAKE :

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Head Lamp Assy, LH ✓			\$ 1,198.80
	Front Bumper x repair			
	SUB TOTAL			\$ 1,198.80
	LESS 20%			\$ 239.76
	DISCOUNTED TOTAL			\$ 959.04
	Labour Charge			100
	Panel Beating			\$ 200.00
	Spray Painting Charge			\$ 200.00
	Wiring Charge			\$ 50.00
	TOTAL LABOUR			\$ 450.00
	ESTIMATE TOTAL			\$ 1,409.04
<p> <i>Kelvin LAY</i> <i>8/8/18 1056 L</i> <i>2 Bgr.</i> <i>P/P</i> <i>After Repair photo</i> <i>CH</i> </p>				
<p> LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date: </p>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				