

2/10/2018

ASS. REC. BY:

REF:

CS/CTI 18014529 / Ngd3

n2

Special Instruction:

SL

Driver of:
menmen

Naz

ASSIGNMENT (Office)

From (Person):

Elaire cheong

of

CTI

Date/Time:

8/8/18 @ 3:32pm

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLV 3676Y

Insured:

SLX 2638D

at Workshop m/s:

Hua Hong

Tel:

6760 8815 /

of

25D Sungai Kadut 8f-1

Policy No:

DMPCSN 3023951800

Claim No:

SNM18D 03848C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

06/08/2018

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

9:45am @ 10/8/18

Person Contacted:

Yvonne

Vehicle IN / ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLV 3676Y-X
	SLX 2638D-X
10/8/18	- Vehicle not in yet (Yvonne)
15/8/18	- Yvonne said vehicle still not in yet, she will arrange
17/8/18	- VNT (Yvonne)

REF:

CTI

CTI

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLV 3676 Y Yr Regn: 28 DEC 2017
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA SIENTA HYBRID C.C. 1,496
 Colour: MAROON A/C: Insured Std / NI / NA
 Sp. Reading: 54,181 T/Radio: Insured Std / NI / NA
 Eng/No: _____
 C/No: NH91707099304

Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In O/S / Jammed / Leaked / Burnt or
 Brake: In O/S / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 / 60 R15
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>618/18</u>	D.O.I. <u>21/18/18</u>

Survey held at HUA HONG
 Des. of Damages: Frt / Rear O/S / N/S / UIC / Rooftop or
REAR O/S
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/3/19 FINALIZED PART BY PART REPAIR \$6155.89 / 5 DAYS.
 29/3/19 @ 3.30 pm reconfirmed with Ashley final fig \$5897.40, 5 days.
 (RED \$2167.28, 29/10)

RECEIVED 08 APR 2019

29/3/2019

Date/Time, File Pass to? ☐ : Preli. Report

1) 01/4 Final ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 3

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) \$ + RS \$

) Photos

) Others

)

Report Format :

Lump Sum / I.B.I. (\$) 5897.40

TOTAL

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18014529/Nqd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 10-08-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLX 2638D	Veh. Inspected	SLV 3676Y
Policy No.	DMPCSN3023951800	Coverage (\$)	0.00
Claim No.	SNM18D03848C02	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE CHEONG)	Assign Date	10/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/08/2018	Inspection Date	21/08/2018
Survey held at	HUA HONG PTE LTD 25D SUNGEI KADUT STREET 1 SINGAPORE 729332		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Aug 2018		08 Aug 2018 15:32 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MOHAMMAD FAROOQ BIN ABDUL HAI, ID: S8209571C		
Main Claimant:	MACHERE TRANSPORT SERVICES		
Vehicle Reg. No.:	SLV3676Y	Date of Loss:	06/08/2018 18:00 - :59
Claim Type:	TP / SNM18D03848C02	Policy/Cover Note No.:	DMPCSN3023951800 (Comprehensive)
Vehicle Reg. No. (Insured):	SLX2638D	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Hua Hong Pte Ltd (Sungei Kadut) 25D Sungei Kadut Street 1, 729332 Sungei Kadut - Tel: 6760 8815 / 6760 0539		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/08/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN KELVIN ANG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- CHINA_TAIPING (08/08/2018): Cancellation of Assignment: SLV3676Y

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Shiau Chan (LKKAUTO)

From: Ashley Tan <ashley@huahong.com.sg>
Sent: Friday, 29 March 2019 3:30 PM
To: Shiau Chan (LKKAUTO)
Subject: RE: .SLV 3676Y Finalisation

Dear Shiau Chan

Confirmed COR \$5897.40.

Thanks & Regards

Ashley Tan



HUA HONG PRIVATE LIMITED
25D SUNGEI KADUT STREET 1 SINGAPORE 729332
T. 6661 9690 | M. 9816 4151 | F. 6661 9699
Follow us @ huahong.com.sg



From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Friday, 29 March 2019 9:22 AM
To: Ashley Tan <ashley@huahong.com.sg>; Naz (LKKAUTO) <Naz@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: .SLV 3676Y Finalisation

Dear Ashley,

As spoken with you.

The final fig should be \$5,897.40 instead of \$6,155.89 before GST (as apply 25% parts discount for TOYOTA).

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ashley Tan <ashley@huahong.com.sg>
Sent: Thursday, 28 March 2019 5:42 PM
To: Naz (LKKAUTO) <Naz@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: RE: .SLV 3676Y Finalisation

Dear all

Confirmed COR \$6155.89.

Shiau Chan (LKKAuto)

From: Ashley Tan <ashley@huahong.com.sg>
Sent: Thursday, 28 March 2019 5:42 PM
To: Naz (LKKAuto)
Cc: SUR; Shiau Chan (LKKAuto)
Subject: RE: .SLV 3676Y Finalisation

Dear all

Confirmed COR \$6155.89.

Thanks & Regards

Ashley Tan



HUA HONG PRIVATE LIMITED
25D SUNGEI KADUT STREET 1 SINGAPORE 729332
T. 6661 9690 | M. 9816 4151 | F. 6661 9699
Follow us @ huahong.com.sg
   

From: Naz (LKKAuto) <Naz@lkkauto.com>
Sent: Wednesday, 20 March 2019 2:40 PM
To: Ashley Tan <ashley@huahong.com.sg>
Cc: SUR <sur@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: Re: .SLV 3676Y Finalisation

Dear Ms Tan,

Apologies for the late reply. Attached herewith is the amended marked estimate following a check on part prices. We will proceed to finalize if you are agreeable with the amended COR;

PARTS - \$5169.87

LESS 20% - \$4135.89

S/NETT - \$200

LABOUR - \$1820

TOTAL - \$6155.89 / 5 REPAIR DAYS



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

10 August 2018

HHTPClaims18-82

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #15-00
Springleaf Tower
Singapore 079909

Attn: Motor Claims Department

ACCIDENT INVOLVING SLV 3676 Y & SLX 2638 D ON ALONG ECP TOWARDS CITY AT ABOUT 1820 HOURS

Insured : MACHERE TRANSPORT SERVICES
Vehicle Registration No : SLV 3676 Y
Vehicle Make : TOYOTA
Vehicle Model : SIENTA HYBRID 1.5G CVT
Vehicle Chassis No : NHP1707099304
Policy No : 5096758810
Date of Accident : 6/8/2018

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper		\$ 1,245.10 / CRA
2	10	Rear Bumper Clip	\$ 2.50	\$ 25.00 ?X SVL
3	1	Rear Bumper Extension (Center)		\$ 205.77 / BT
4	2	Rear Bumper Extension Clip	\$ 23.56	\$ 47.12 ?X SVL
5	1	Rear Bumper Extension Moulding		\$ 58.00 ?X SVL
6	1	Rear Bumper Extension (RH)		\$ 124.00 / SCR
7	1	Rear Reflector (RH)		\$ 64.67 ?X SVL
8	1	Rear Air Vent (RH)		\$ 65.90 ?X SVL
9	1	Rear Taillamp (RH)		\$ 367.00 / SCR
10	1	Rear Reverse Lamp (RH)		\$ 185.00 / SCR
11	1	Rear Tailgate		\$ 1,086.80 / DD
12	1	Rear Tailgate Lock		\$ 421.00 ?X SVL
13	1	Rear Tailgate Lock Striker		\$ 21.66 ?X SVL
14	1	Rear Windscreen Moulding		\$ 105.40 / REC
15	1	Rear Tailgate Weather Strip		\$ 357.00 / DEN
16	1	Rear Tailgate Garnish (SIENTA)		\$ 225.50 ?X SVL
17	1	Rear End Panel		\$ 824.10 ?X SVL DEF
18	1	Rear Panel Top Garnish		\$ 321.70 / SCR
19	10	Rear Panel Top Garnish Clip	\$ 2.50	\$ 25.00 ?X SVL
20	1	Rear Exhaust Pipe		\$ 395.23 ?X SVL
21	2	Rear Exhaust Pipe Stopper	\$ 24.70	\$ 49.40 ?X SVL
22	1	Rear Logo (Hybrid Synergy Drive)		\$ 50.50 / REC
23	1	Rear Emblem		\$ 32.50 / REC
			5169.87	\$ 6,303.35
			Less 20%	\$ (1,260.67)
				\$ 5,042.68 4135.89



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

ACCIDENT INVOLVING SLV 3676 Y & SLX 2638 D ON ALONG ECP TOWARDS CITY AT ABOUT 1820 HOURS

Estimate Repair List for vehicle SLV 3676 Y - Toyota Sienta

		Balance B/F	\$ 5,042.68
24	1 Reverse Sensor	NETT	\$ 200.00 <i>Actuality</i>
To dismantle, cut & weld rear panel, dismantle & change rear tailgate, rear bumper, rear RH taillamp, knocking & pull straight rear tyre floor panel, rear RH fender & all area affected by accident			\$ 1,200.00 <i>1000 800</i>
To perform wire checking			\$ 20.00 <i>mc</i>
To dismantle & refit rear bumper sensor			\$ 60.00 <i>40</i>
To dismantle & refit rear windscreen			\$ 120.00 <i>100</i>
To dismantle & transfer rear tailgate fitting & mechanism to new tailgate			\$ 60.00 <i>mc</i>
To dismantle & refit rear exhaust pipe			\$ 150.00 <i>? X NW</i>
To spray rear tailgate, rear bumper, rear panel, rear tyre floor panel & rear RH fender			\$ 1,000.00 <i>900 800</i>
		2020	\$ 7,852.68
		7% GST	\$ 549.69
		Total	\$ 8,402.37

NAZ LKK

21/8/18 1000

P/P

Before Spray Photo.



Authorised by Claims Dept
Mrs Tan @ 9639 9195

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8064.68

PARTS \$5169.87

LESS 20% \$4135.89

SINETT \$ 200

LABOUR \$1820

\$6155.89 / 5 DAYS



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Supplementary List

22 August 2018

HHTPClaims18-82


China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #15-00
Springleaf Tower
Singapore 079909

Attn: Motor Claims Department

ACCIDENT INVOLVING SLV 3676 Y & SLX 2638 D ON ALONG ECP TOWARDS CITY AT ABOUT 1820 HOURS

Insured : MACHERE TRANSPORT SERVICES
Vehicle Registration No : SLV 3676 Y
Vehicle Make : TOYOTA
Vehicle Model : SIENTA HYBRID 1.5G CVT
Vehicle Chassis No : NHP1707099304
Policy No : 5096758810
Date of Accident : 6/8/2018

			Type of Claim: Third Party	
S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Fender Cover (RH)		\$ 265.00
			Less 20%	\$ (53.00)
				\$ 212.00
			7% GST	\$ 14.84
			Total	\$ 226.84


Authorised by Claims Dept
Mrs Tan @ 9639 9195

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18014529/NQD3N2

Date: 09/04/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3023951800
Claimant Vehicle No :	SLV3676Y	Insured Vehicle No :	SLX2638D
Date of Loss:	06/08/2018	Nature of Claim:	TP
		Claim No:	SNM18D03848C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV3676Y	Engine No:	1NZ8283677
Make & Model:	TOYOTA SIENTA, 1.5 G CVT (A)	Chassis No:	NHP1707099304
Reg. Date:	28/12/2017 (Man. Year: 2017)	Odometer:	54181 km
Colour:	Maroon		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60R15	Rear Tyre Size:	195/60R15
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,454.68	4,077.40	1,377.28	25.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,610.00	1,820.00	790.00	30.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,064.68	5,897.40	2,167.28	26.87
+ GST 7.00/7.00% (S\$)	564.53	412.82	151.71	26.87
Nett Amount (S\$)	8,629.21	6,310.22	2,318.99	26.87

INSPECTION

Date of Assignment:	08/08/2018	
Date Inspected:	21/08/2018	Inspected At: Hua Hong Pte Ltd (Sungei Kadut) 25D Sungei Kadut Street 1 Singapore 729332
Estimated Period of Repair:	5.0 days	

Adjuster: Muhammad Nazril Bin Abdullah

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Apr 2019)
Parts: M1-MPV	TOYOTA SIENTA 1.5 G CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLV3676Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	1,245.10 FL	*1,245.10 FL
2	10		*REAR BUMPER CLIP	Serviceable	25.00 FL	*- FL
3	1		*REAR BUMPER EXTENSION (CENTER)	Bent	205.77 FL	*205.77 FL
4	2		*REAR BUMPER EXTENSION CLIP	Serviceable	47.12 FL	*- FL
5	1		*REAR BUMPER EXTENSION MOULDING	Serviceable	58.00 FL	*- FL
6	1		*REAR BUMPER EXTENSION (RH)	Scratched	124.00 FL	*124.00 FL
7	1		*REAR REFLECTOR (RH)	Serviceable	64.67 FL	*- FL
8	1		*REAR AIR VENT (RH)	Serviceable	65.90 FL	*- FL
9	1		*REAR TAILLAMP (RH)	Scratched	367.00 FL	*367.00 FL
10	1		*REAR REVERSE LAMP (RH)	Scratched	185.00 FL	*185.00 FL
11	1		*REAR TAILGATE	Dented	1,086.80 FL	*1,086.80 FL
12	1		*REAR TAILGATE LOCK	Serviceable	421.00 FL	*- FL
13	1		*REAR TAILGATE LOCK STRIKER	Serviceable	21.66 FL	*- FL
14	1		*REAR WINDSCREEN MOULDING	Necessary	105.40 FL	*105.40 FL
15	1		*REAR TAILGATE WEATHER STRIP	Torn	357.00 FL	*357.00 FL
16	1		*REAR TAILGATE GARNISH (SIENTA)	Serviceable	225.50 FL	*- FL
17	1		*REAR END PANEL	Deformed	824.10 FL	*824.10 FL
18	1		*REAR PANEL TOP GARNISH	Scratched	321.70 FL	*321.70 FL
19	10		*REAR PANEL TOP GARNISH CLIP	Serviceable	25.00 FL	*- FL
20	1		*REAR EXHAUST PIPE	Serviceable	395.23 FL	*- FL
21	2		*REAR EXHAUST PIPE STOPPER	Serviceable	49.40 FL	*- FL
22	1		*REAR LOGO (HYBRID SYNERGY DRIVE)	Necessary	50.50 FL	*50.50 FL
23	1		*REAR EMBLEM	Necessary	32.50 FL	*32.50 FL
24	1		*REAR FENDER COVER (RH)	Cracked	265.00 FL	*265.00 FL
25	1		*REVERSE SENSOR	Not Working	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,768.35	5,369.87
- List Item Discount on L Items 20.00/25.00% (\$\$)	1,313.67	1,292.47
Total Parts (\$\$)	5,454.68	4,077.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE,CUT & WELD REAR PANEL,DISMANTLE & CHANGE REAR TAILGATE,REAR BUMPER,REAR RH TAILLAMP,KNOCKING & PULL STRAIGHT REAR TYRE FLOOR PANEL,REAR RH FENDER & ALL AREA AFFECTED BY ACCIDENT	New	1,200.00	800.00
2	TO PERFORM WIRE CHECKING	New	20.00	20.00
3	TO DISMANTLE & REFIT REAR BUMPER SENSOR	New	60.00	40.00
4	TO DISMANTLE & REFIT REAR WINDSCREEN	New	120.00	100.00
5	TO DISMANTLE & TRANSFER REAR TAILGATE FITTING & MECHANISM TO NEW TAILGATE	New	60.00	60.00
6	TO DISMANTLE & REFIT REAR EXHAUST PIPE	New	150.00	0.00
7	TO SPRAY REAR TAILGATE,REAR BUMPER,REAR PANEL,REAR TYRE FLOOR PANEL & REAR RH FENDER	New	1,000.00	800.00
Gross Labour Cost (\$\$)			2,610.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >