

ASS. REC. BY:

REF:

CS/MSG18014531/Ktd3

72

Special Instruction:

Surveyor
menmen

Kenneth

ASSIGNMENT (Office)

From (Person):

Chhia Nyuk

of

MSG

Date/Time:

10/8/18 @ 2:00pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGT 4530Y

Insured:

SLK 4025C

at Workshop m/s

Alan's United

Tel:

6453 8686

of

Blk 7 Sin Ming Ind. Est #01-76

Policy No:

A2887817 3AVW

Claim No:

566270

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/07/2018

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

3:23pm @ 10/8/18

Person Contacted:

Kenmy

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SGT 4530Y -X

SLK 4025C -X

17/8-

Revert via preli advise

Part by Part #1814-67 (Red - 15/14-15, 45%)

ASS. REC. BY:

REF: *MSG*

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: NII / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

15/8

File pass to Catherine

RECEIVED 06 SEP 2010

Date/Time, File Pass to?



: Prell. Report



: Final Report

11/6/9 Typist

Date/Time, File Return to?

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

TP

1314.67

150

10

160



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18014531/Ktd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 10-08-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLK 4025C	Veh. Inspected	SGT 4530Y
Policy No.	A28878173AVW	Coverage (\$)	0.00
Claim No.	566270	Excess (\$)	0.00
Assign From	MERIMEN (CHHIA NYUK PUI)	Assign Date	10/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	30/07/2018	Inspection Date	14/08/2018
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 17 Aug 2018

Preliminary Advice

Insured Vehicle No	: SLK4025C	Accident Date	: 30/07/2018
TP Vehicle No	: SGT4530Y	Assignment Date	: 10/08/2018
Make	: VOLKSWAGEN GOLF	Est. Duration of Repair	: 4.00
Date of Inspection	: 14/08/2018		
Inspection At	: ALAN'S UNITED AUTO PTE LTD (HQ) BLK 7 SIN MING INDUSTRIAL ESTATE, #01-76 SINGAPORE 575642		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,328.82
Revised Amount	:S\$	797.88
Check Items (Estimated)	:S\$	2,091.93
Total	:S\$	2,889.81

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

8/10/2018

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2018		10 Aug 2018 14:00 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
[Created by insurer]									
CLAIM SUBFOLDER DETAILS									
Insured:	CHANG CHENG YU, ID: S8009651H, Tel: +6593266818, Email: immaxchang@gmail.com								
Main Claimant:	NG MUI CHEN, ID: S7717699C								
Vehicle Reg. No.:	SGT4530Y	Date of Loss:	30/07/2018 07:00 - :59 [18 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 566270	Policy/Cover Note No.:	A28878173AVW (Comprehensive) Coverage: 16/01/2018 - 15/01/2019						
Vehicle Reg. No. (Insured):	SLK4025C	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76, 575642 Sin Ming - Tel: 6453 8686								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 11/08/2018]								
Driver/Custodian (Insured):	CHANG CHENG YU (38 / Male), NRIC: S8009651H, Tel: +6593266818								
Adj Asg. Remarks:	SURVEY AGREE ON SJE - REQUEST TO ASSIGN LKK (KENNETH KONG) LIABILITY:100% CONTACT: KENNY 6453 8686								
View All Compose Case Mail									
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
View All Search Tasks Create New Task Complete									
ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport
/Company Cert
No.: S7717699C

Owner ID Type: Singapore NRIC

Owner Name: NG MUI CHEN (HUANG MEIZHEN)

Registered
Address: APT BLK 38 LORONG 5 TOA PAYOH #09-485 SINGAPORE 310038

Mailing Address: -

Birth Date: 05 Jul 1977

Vehicle Particulars

Vehicle No.: SGT4530Y

Previous Vehicle
No.: -

Effective Date of
Ownership: 12 Apr 2007

Original Regn Date: 12 Apr 2007

Registration Date: 12 Apr 2007

Year of
Manufacture: 2006

Vehicle Type: Passenger Motor Car

Vehicle Scheme: -

Vehicle
Attachment 1: No Attachment

Vehicle
Attachment 2: -

Vehicle
Attachment 3: -

Vehicle Make: TOYOTA

Vehicle Model: CAMRY 2.0 AUTO ABS AIRBAG

Primary Colour: Silver

Secondary Colour: -

Passenger
Capacity: 4

Chassis No.: MR053BK4107005513

Engine No.: 1AZE018776

Engine Capacity
/Power Rating: 1998 cc / -

Maximum Power
Output: 108.0 kW (144 bhp)

Propellant: Petrol

Max Unladen Weight:	1530 kg
Maximum Laden Weight:	1970 kg
Open Market Value:	\$27,853.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
Minimum PARF Benefit:	-
No. of Transfers:	0
IU Label No.:	1120966502
COE No.:	2007040103002167W
COE Expiry Date:	31 Mar 2027
COE Category:	B - Car (1601cc & above)
COE Registration Category:	B - Car (1601cc & above)
Quota Premium (QP) / Prevailing Quota Premium:	\$14,652.00 / -
PQP Paid:	\$50,347.00
QP (Regn Cat):	\$14,652.00
OPC Cash Rebate Eligibility:	No
QP during COE Bidding Exercise:	\$14,652.00
Additional Registration Fee Rate:	110.00 %
Actual ARF Paid:	\$30,639.00
Vehicle Lifespan Expiry Date:	No Lifespan
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-
Message:	To renew the COE, the Prevailing Quota Premium payable is that of Category B.

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05830

Vehicle Insured : SLK4025C
Accident Date : 30-Jul-2018

Date : 08-Aug-2018

Our Ref : 218135 (MSIG) / CHAN

PAGE : 1

NG MUI CHEN
BLK 38 LORONG 5 TOA PAYOH
#09-485
Singapore 310038

Not Notified
11/8/18
Recovery After Pain 11/8/18
2-4 days

ESTIMATED COST OF REPAIR FOR TOYOTA CAMRY 2.0 SGT4530Y

- 1 pc Rear bumper fascia
- 1 pc Rear bumper reinforcement
- 2 pcs Rear bumper side retainer
- 2 pcs Rear bumper side retainer (R)
- 2 pcs Rear bumper reflector
- 1 pc Rear end panel
- 1 pc End panel top garnish

	<i>Br 1/2</i>	530.50	✓
	<i>0/1</i>	420.10	✓
@ S\$	57.10	114.20	✓
@ S\$	48.10	96.20	✓
@ S\$	54.10	108.20	✓
	<i>R</i>	602.10	✓
	<i>in</i>	353.80	✓

2,225.10

Less 25% : 556.28

1 pc Rear bumper reverse sensor

Shot 1,668.82
300.00 *sn Day*

To apply undersealing

na 60.00 *X*

To putty and spray replaced parts

600.00 *400*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

700.00 *300*

Total : S\$ 3,328.82

Singapore Dollars Three Thousand Three Hundred
and Twenty Eight and Cents Eighty Two Only

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18014531/KTD3N2

Date: 10/09/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28878173AVW
Claimant Vehicle No :	SGT4530Y	Insured Vehicle No :	SLK4025C
Date of Loss:	30/07/2018	Nature of Claim:	TP
		Claim No:	566270

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGT4530Y	Engine No:	1AZE018776
Make & Model:	TOYOTA CAMRY, 2.0 ABS AIRBAG (A)	Chassis No:	MR053BK4107005513
Reg. Date:	12/04/2007 (Man. Year: 2006)	Odometer:	116059 km
Colour:	Metallic Silver		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,968.82	1,034.67	934.15	47.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,360.00	780.00	580.00	42.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,328.82	1,814.67	1,514.15	45.49
+ GST 7.00/7.00% (S\$)	233.02	127.03	105.99	45.49
Nett Amount (S\$)	3,561.84	1,941.70	1,620.14	45.49

INSPECTION

Date of Assignment:	10/08/2018	
Date Inspected:	14/08/2018	Inspected At: Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2018)
Parts:	143	TOYOTA CAMRY 2.0 ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGT4530Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Buckled/Dented	530.50 FL	*530.50 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	420.10 FL	*420.10 FL
3	2		*REAR BUMPER SIDE RETAINER	Distorted	114.20 FL	*114.20 FL
4	1		*REAR BUMPER SIDE RETAINER (R)	N/s Distorted	96.20 FL	*48.10 FL
5	2		*REAR BUMPER REFLECTOR	Serviceable	108.20 FL	*- FL
6	1		*REAR END PANEL	Repair	602.10 FL	*- FL
7	1		*END PANEL TOP GARNISH	Serviceable	353.80 FL	*- FL
8	1		*REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
					Sub Total (S\$)	2,525.10 1,312.90
					- List Item Discount on L Items 25.00/25.00% (S\$)	556.28 278.23
					Total Parts (S\$)	1,968.82 1,034.67

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO APPLY UNDERSEALING	New	60.00	-
2	TO PUTTY AND SPRAY REPLACED PARTS	New	600.00	400.00
3	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	700.00	380.00
Gross Labour Cost (\$\$)			1,360.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >