

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Ref:

PRE-REPAIR INSPECTION REPORT

50 RAFFLES PLACE #05-01/06 Date: 14-08-2018

SINGAPORE LAND TOWER SINGAPORE 048623

SOMPO INSURANCE SINGAPORE PL

e: 14-08-2018

CS3/SMO18014540/Gz4d3e2

Page No.:1 of 1

	Code: SMO				
I. Policy Particulars :- (THIRD PARTY CLAIM)					
FBL 4040X	Veh. Inspected	SLS 5510U			
	Coverage (\$)	0.00			
CMTD1803403/AGC	Excess (\$)	0.00			
GRACE TEO	Assign Date	10/08/2018			
2. Vehicle Particulars & Condition					
TOYOTA LEXUS IS250	c.c	2500			
HIDDEN	Year of Reg.	2007			
JTHBK262202049338	Colour	BLUE			
171048 KM	Steering	IN ORDER			
IN ORDER	Modification	SPORTS RIM			
GOOD					
3. Conditions of Tyres					
Size	Make	Balance			
235/35Z R19	MICHELIN	6 mm			
235/35Z R19	MICHELIN	6 mm			
235/35Z R19	MICHELIN	6 mm			
235/35Z R19	MICHELIN	6 mm			
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5. General Information					
	FBL 4040X CMTD1803403/AGC GRACE TEO Vehicle Par TOYOTA LEXUS IS250 HIDDEN JTHBK262202049338 171048 KM IN ORDER GOOD Cond Size 235/35Z R19 235/35Z R19 235/35Z R19 235/35Z R19 Pescrip STAINED DAMAGES AT THE RI	Policy Particulars :- (THIRD PARTY CLA FBL 4040X Veh. Inspected Coverage (\$) CMTD1803403/AGC Excess (\$) GRACE TEO Vehicle Particulars & Condition TOYOTA LEXUS IS250 C.C HIDDEN Year of Reg. JTHBK262202049338 Colour 171048 KM Steering IN ORDER Modification GOOD Conditions of Tyres Size Make 235/35Z R19 MICHELIN 235/35Z R19 MICHELIN Description of Damages STAINED DAMAGES AT THE REAR PORTION.			

5.	. General Information				
	Accident Date	07/08/2018	Inspect Date / Time	10/08/2018 (04:00 PM)	
	Survey held at	N-51 AUTOMOTIVE PL			
		2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
- D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days

Report Ref No. CS3/SMO18014540/Gz4d3e2

Inspected By

XING GUO QIANG

h

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.