

168

2/03/2002

S.S. REC. BY:

REF: CS / FCI18014542/TCd3 / n2

Special Instruction:

Survivor:

Taufik

ASSIGNMENT (Office)

From (Person):

Erlan Lee

of

FCI

Date/Time: 8/8/18 @ 6:13pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKS 2614K

Insured:

SHC27684

at Workshop m/s

performance motor

Tel:

63190174

of

303 Alexandra Road

Policy No:

Claim No:

018005858MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

3/107/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

DS)

H.O.D. Endorsement:

Date/Time:

10:30am @ 10/8/18

Person Contacted:

Caroline

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SKS 2614K - NBA / INC18014363/Y	DOA: 3/7/18
	SHC 27684 - NBA / INC18014363/Y	DOA: 3/7/18
10/8/18-	called caroline vehicle not in yet	
15/8/18	called caroline vehicle still not in	
16/8/18-	vehicle not in (caroline)	
17/8/18-	arrived on 17/8/18	

Tanji

REF: FCL

ASSIGNMENT

From:

Date:

17082018

Estimated Cost:

OD (TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

SKS 2614K

at Workshop m/s

Performance

of

303 Alexandra Rd

Insured

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Intiran.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Intiran

Veh No:

SKS 2614K

Yr Regn:

2010 May

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 523I

CC

2497

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading:

98025

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBAFP32050C543859

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R17

R:

N N

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

17/8/18 01645

Survey held at

PMU

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

249529.

21/11/18 Revert IA via email.

7/12 9.11am Confirmed final fig 3,682.85 with Caroline. (Red. 1446.65, 282)

Date/Time: File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time: File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

-

Survey Fee:

Transportation

1 S + R5. SI

2 Photos

3 Others:

TOTAL

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Report Format:

TP

Lump Sum / 10B: (\$

3,682.85

140
50
20

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Info Federation Internationale Des Experts En Automobile	
FIRST C	Ref : CS/FCI18014542/T1rd3
36 ROBINSON ROAD #16-01 C	DATE 10-08-2018
068877	Code : FCI2
	
1.	Policy Particulars :- THIRD PARTY CLAIM
In	Veh. Inspected SKS 2614K
P	Coverage (\$) 0.00
CI	Excess (\$) 0.00
As	Assign Date 10/08/2018
2.	Vehicle Particulars & Condition
M	c.c 0
E	Year of Reg.
C	Colour
O	Steering
E	Modification
3.	Conditions of Tyres
	Make Balance
	mm
	mm
	mm
	mm
4.	Description of Damages
5.	General Information
	Inspection Date 17/08/2018
	ENGINE MOTORS LTD
	ROAD
5a.	Remarks
	ISSUED ON A "WITHOUT PREJUDICE" BASIS. INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005858MFSH

Date: 21 November 2018

Our Ref: CS/FCI18014542/T1rb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKS 2614K

Please be informed that we had conducted the inspection of the abovementioned vehicle on 17/08/2017 at the premises of M/s PERFORMANCE MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,034.80</u>
Revised Estimate Amount	: S\$ <u>3,447.65</u>
"Check" Items Amount	: S\$ <u>1,031.15</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

TAUFIKH
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date 02-08-2018 **Claim No.** D18005858MESH

Accident Date 31-07-2018 **Claim Type** Third Party

Insured Vehicle SHC2768U **Third Party Vehicle** SKS2614K

Survey Location 303 ALEXANDRA ROAD SINE DARRY PROJECT MARINE CENTRE

Contact Person CAROLINE

Contact No. 63190174/0 **File No.** 64794601

Survey Type DIRECT SETTLEMENT

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA **File No.** 68410315

Contact Number NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with Letter of Claim for Settlement Loss of use (based on NIMA Benchmark rates) together with your copy of the report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop PERFORMANCE MOTORS LIMITED **Address** 1111

Cc : TP Solicitor NA **Address** NA

Officer Incharge EILEEN LEE

IMPORTANT

Kindly submit the survey report via CWS within 14 days of the accident for re-inspection.

This is a computer generated document.

Celine Fong (LKKAUTO)

From: Celine Fong (LKKAUTO)
Sent: Friday, 7 December 2018 9:21 AM
To: 'PBSP'; Taufikh (LKKAUTO); SUR
Subject: RE: FINAL REPORT / SKS2614K

Dear Caroline,

Confirmed final fig \$3,682.85.

Repair days: 3

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@sime-darby.com.sg>
Sent: Wednesday, 28 November 2018 4:18 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FINAL REPORT / SKS2614K

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,014.00
Total Parts : 1,668.85
Total Labour & Parts : 3,682.85

Repair days: 3

Veron Chen (LKKAUTO)

From: PBSP <pml-pbsp@sime-darby.com.sg>
Sent: Wednesday, 28 November 2018 4:18 PM
To: Taufikh (LKKAUTO); SUR
Subject: FINAL REPORT / SKS2614K
Attachments: Final Report SKS2614K_2.pdf, Final Report SKS2614K.pdf

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,014.00
Total Parts : 1,668.85
Total Labour & Parts : 3,682.85

Repair days: 3

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Wednesday, November 21, 2018 12:36 PM
To: 'Claim Workflow System'
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: RE: SURVEY ASSESSMENT - D18005858MFSH/1
Attachments: SKS 2614K.pdf

Dear Sir/ Madam,

Enclosed preliminary revised for SKS 2614K.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, August 10, 2018 3:18 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005858MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 8 August 2018 6:12 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005858MFSH/1


Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



Surgery & repair
on 17/08 @ 10.00am

GST REG. NO : M2 - 0020081 - X

07 AUG 2018

ESTIMATE

Estimate No. : b1 47964
Date Estimated : 07/08/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
Hosseini Mohammad Allahveirdi
80 Mohamed Sultan Road

Singapore 239013

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS2614K	C543859	20/05/2010	5231A	0

DESCRIPTION

To replace rear bumper and attachments.

Painting rear bumper.

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries.

LKK Auto Consultants hence notify

the Repairer of the following:

	VALUE
• To resurvey before/after spray painting	850 1,275.00
• To display damaged part(s) during resurvey	
• Parts prices are subject to confirmation	
• Third party survey is on a "Without Prejudice" basis	934 1,038.00
• No illegal modification(s) is allowed	
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	150 177.00

Acknowledged by Repairer

Signature:

Date:

800.00
80.00

Total Labour 1: 2,570.00

DESCRIPTION

Set of mount
RR BUMPER BOTTOM CENTRE GUIDE
RR BUMPER CTR GUIDE
RR BUMPER CARRIER
RR BUMPER PANEL PRIMED (PDC)
RR BUMPER TOW HOOK COVER PRIMED
RR BUMPER ADAPTER

QTY	PRIC	VALUE
1	62.60	62.60
1	58.95	58.95
1	67.35	67.35
1	714.25	714.25
1	1,467.20	1,467.20
1	46.45	46.45
1	48.00	48.00

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date&Time 17/8/18 Excess \$5 _____
Surveyor's Name Tanjil Sign Tanjil
Surveyor's Tel 97495714 Extension Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____
Surveyor's E-mail tanjil@lkh.com.sg
No. of Working Days Recommend 03 days

Total Parts : 2,464.80

LKK Auto Consultants hence notify

the Repairer of the following:

• To resurvey before/after spray painting
• To display damaged part(s) during resurvey

Labour 1	2,570.00
Parts	2,464.80
Labour 2	0.00
Excess	0.00
Total GST @ 7%	352.44
Date: Grand Total	5,387.24

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 47964
Date Estimated : 07/08/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Hosseini Mohammad Allahveirdi
80 Mohamed Sultan Road
1/12/2018 12:00:00 AM

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 239013

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SKS2614K	C543859	20/05/2010	523iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# PLUG *	1.05	10.00		10.50 <i>del</i>
# REAR RIGHT COVERING *	84.20	1.00		84.20 <i>del</i>

Total Labour :	
Total Parts :	94.70
Total Labour & Parts :	94.70

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 47964
Date Estimated : 07/08/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Hosseini Mohammad Allahveirdi
80 Mohamed Sultan Road
1/12/2018 12:00:00 AM

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 239013

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SKS2614K	C543859	20/05/2010	523iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include knocking out dents caused by the accident	850.00		850.00	
To spray paint rear bumper	934.00		934.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR BUMPER BOTTOM CENTRE GUIDE	58.95	1.00		58.95
RR BUMPER PANEL PRIMED (PDC)	1,467.20	1.00		1,467.20
RR BUMPER ADAPTER	48.00	1.00		48.00
# PLUG *	1.05	10.00		10.50
# REAR RIGHT COVERING *	84.20	1.00		84.20

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,668.85
Total Labour & Parts :	3,682.85
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,682.85
GST @7%:	257.80
Grand Total :	3,940.65



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18014542/T1cd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2768U	Veh. Inspected	SKS 2614K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005858MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	08/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	BMW 523i	c.c	2497	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WBAFP32050C543859	Colour	BLUE	
Odometer	98025	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	PIRELLI	6 mm	
L/H Front Tyre	225/55 R17	PIRELLI	6 mm	
R/H Rear Tyre	225/55 R17	PIRELLI	6 mm	
L/H Rear Tyre	225/55 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/07/2018	Inspection Date	17/08/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 2614K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SET OF MOUNT (SN)	NOT NECESSARY	62.60	-
1	RR BUMPER BOTTOM CENTRE GUIDE (SN)	NECESSARY	58.95	58.95
1	RR BUMPER CTR GUIDE (SN)	NOT NECESSARY	67.35	-
1	RR BUMPER CARRIER (SN)	NOT NECESSARY	714.25	-
1	RR BUMPER PANEL PRIMED (PDC)(SN)	DEFORMED	1,467.20	1,467.20
1	RR BUMPER TOW HOOK COVER PRIMED (SN)	NOT NECESSARY	46.45	-
1	RR BUMPER ADAPTER (SN)	NECESSARY	48.00	48.00
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
10	PLUG (ADDITIONAL)(SN)	NECESSARY	10.50	10.50
1	REAR RIGHT COVERING (ADDITIONAL)(SN)	DEFORMED	84.20	84.20
			2,639.50	1,748.85
LABOUR				
	TO REPLACE REAR BUMPER AND ATTACHMENTS.		1,275.00	850.00
	PAINTING REAR BUMPER.		1,038.00	934.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
			2,490.00	1,934.00
GRAND TOTAL			5,129.50	3,682.85
RECOMMENDED COST OF REPAIRS				3,682.85

Report Ref No. CS/FCI18014542/T1cd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.