

ASS. REC. BY:

REF:

CS/FCI18014543/Rsd3ⁿ²

Special Instruction:

Surveyor:

CWS

RDSU

ASSIGNMENT (Office)

From (Person):

Jerene jaw

of

FCI

Date/Time:

8/8/18 @ 5:40pm

Estimated Cost:

Bill to:

OD TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDS 9905H

Insured:

SHA 9188H

at Workshop m/s

Performance

Tel:

6319 0174

of

303 Alexander Road

Policy No:

Claim No:

D18 005964 MPB4

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

6/8/2018

CA / REV / REP. / REV 24 HRS

1DS

H.O.D. Endorsement:

Date/Time:

10/2/2018

Person Contacted:

Caroline

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SDS 9905H - X
	SHA 9188H - CS/FCI 18014543 / Arbn2
10/8/18 -	called carline vehicle not in yet
15/8/18 -	called carline vehicle not in
11/8/18 -	vehicle not in
17/8/18 -	VMI

Paul

REF: FEL

7425C

ASSIGNMENT

From: Date: 27082018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SDS 9905H
at Workshop m/s: Performan
of: 303 Alexandra Rd

Insured

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh: Intiran

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SDS 9905H Yr Regn: 2016 SEP

Type: ☒ Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 216D 4 door 1496

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 30632 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA 2E 320905 B4 J372

Gen. Cond: Good ☒ Fair / Poor / Burnt

Steering: ☒ Order / Jammed / Leaked / Burnt or

Brake: ☒ Order / Jammed / Leaked / Burnt or

Modi: Nil ☒ STD A/Rim or

Tyre Size: F: 205/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. 06/08/18 D.O.I. 27/08/18

Survey held at: PERFORMAN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/08/18 @ 16:20 p.m. revised PA to Lure via email.

26/11/18 Confirmed p/p \$ 5,872.90 @ 4 days with Rasul.
(\$4,029.10 red - 41%)

RECEIVED 26 NOV 2018

Date/Time: File Pass to?

26/11/18

1)

Typ 4

Date/Time: File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$ 5,872.90 p/p

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. SI

Photos:

Others:

TOTAL

Add Fee: ☐ Site Insp. (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

170
50
50
50

320

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18014543/R1sd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 10-08-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9188H	Veh. Inspected	SDS 9905H
Policy No.		Coverage (\$)	0.00
Claim No.	D18005964MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	10/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/08/2018	Inspection Date	27/08/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005964MFSH

Date: 29 August 2018

Our Ref: CS/FCI18014543/R1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SDS 9905H .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/08/2018 at the premises of M/s Performance Motors Limited and have the following to report:-

Workshop Estimate Amount	: S\$ <u>9,832.50</u> .
Revised Estimate Amount	: S\$ <u>5,670.85</u> .
"Check" Items Amount	: S\$ <u>818.85</u> .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the front o/s portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 4 Days

Yours faithfully,
Mohammed Rasul
Automotive Assessor

MOTOR SURVEY DOCUMENT

Date 08-08-2018 **Our Ref No.** D18005064/1808H

Accident Date 06-08-2018 **Claim No.** 1808H

Insured Vehicle SHA9188H **Insured Name** 30000000H

Survey Location 303 ALEXANDRA ROAD SINGAPORE 119935 **Accident Location** 303 ALEXANDRA ROAD SINGAPORE 119935

Contact Person. CAROLINE

Contact No. 63190174/0 **Phone No.** 63190174

Survey Type DIRECT SETTLEMENT

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA **Phone No.** 63190174

Contact Number. NA

FORBIDDEN TO BE USED

Please submit to us the Tax Invoice together with the NIMA Benchmark rates of the vehicle involved in the accident.

THIRD PARTY SURVEY REQUEST

Cc : Workshop PERFORMANCE MOTORS PTE LTD

Cc : TP Solicitor NA

Officer Incharge LURENE

Kindly submit the survey report via CWS within 14 days of the accident date. This is a computer generated document.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 26 November 2018 11:29 AM
To: 'PBSP'
Cc: Rasul (LKKAuto); SUR
Subject: RE: FINAL REPORT / SDS9905H

Hi Caroline,

Confirmed final fig of \$ 5,872.90 (part by part) @ 4 days of repairs before GST.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Friday, 23 November 2018 2:30 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Re: FINAL REPORT / SDS9905H

Dear Sirs

As requested, please see attached and kindly confirm COR.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 23 November 2018 2:15:01 PM
To: PBSP
Cc: Rasul (LKKAuto); SUR
Subject: RE: FINAL REPORT / SDS9905H

Hi Caroline,

Kindly send us supplementary photo.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]

Sent: Thursday, 22 November 2018 3:59 PM

To: Rasul <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: FINAL REPORT / SDS9905H

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,465.00

Total Parts : 3,407.90

Total Labour & Parts : 5,872.90

Repair days: 4

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 29 August 2018 4:20 PM
To: LURENEJAW@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'
Cc: sur@lkkauto.com; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: SURVEY ASSESSMENT - D18005964MFSH/1
Attachments: SDS 9905H - Preli Advise.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SDS 9905H.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 10 August 2018 3:18 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; sur@lkkauto.com
Subject: RE: SURVEY ASSESSMENT - D18005964MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 8 August 2018 5:39 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005964MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

07:07 @ 10am
Survey & repair
before 12pm



GST REG. NO : M2 - 0020081 - X

07 AUG 2018

ESTIMATE

Estimate No. : b1 47959
Date Estimated : 07/08/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Pee Eng Yau (Peng RongYao)
142 Bishan Street 12
#11-528

Singapore 570142

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDS9905H	5B45372	19/09/2016	216d G TOURER	0

DESCRIPTION

To replace front bumper, right headlamp support, attachments and repair right fender.

850 2,975.00

Painting front bumper and fender right.

934 1,923.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

To replace right headlight including program and conduct tests for proper function.

451 531.00

Sundries.

NEL 80.00

Total Labour 1: 5,686.00

DESCRIPTION

FRT BUMPER RH INSERT
FRT RH SIDE PANEL TOP MOUNTING
FRT FLAP TOWING EYE PRIMED
RH FINISHER (LUXURY LINE)
RH SUPPORT FOG LAMP (GESCHLOSSEN)
FRT BUMPER PANEL PRIMED (PMA)
GRILLE SIDE OPEN RH (LUXURY LINE+PD)
RH SUPPORT HEADLIGHT ARM
RH HEADLIGHT LED TECHNOLOGY
RH FOG LIGHT
ULTRASONIC SENSOR BLACK
DECOUPING RING PDC TORQUE CONVERTER

QTY	PRIC	VALUE
1	9.70	9.70
1	8.85	8.85
1	41.80	41.80
1	52.55	52.55
1	77.60	77.60
1	842.00	842.00
1	95.85	95.85
1	124.85	124.85
1	2,348.00	2,348.00
1	276.40	276.40
1	248.70	248.70
4	5.05	20.20

Total Parts : 4,146.50

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47959
Date Estimated : 07/08/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDS9905H	5B45372	19/09/2016	216d G TOURER	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 21/08/18 01145 Claim No. _____

Date&Time 21/08/18 01145 Excess S\$ _____

Surveyor's Name Ram Sign _____

Surveyor's Tel 90012568 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 4 days

[Signature]
29/8/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Labour 1	:	5,686.00
Parts	:	4,146.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	688.28
Grand Total	:	10,520.78

7902

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 47959
Date Estimated : 07/08/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -

Pee Eng Yau (Peng RongYao)
142 Bishan Street 12
#11-528

Singapore 570142

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SDS9905H	5B45372	19/09/2016	216d G TOURER	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# PLAQUE 82MM *	69.50	1.00 A		69.50

Total Labour :	
Total Parts :	69.50
Total Labour & Parts :	69.50

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 47959
Date Estimated : 07/08/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Pee Eng Yau (Peng RongYao)
142 Bishan Street 12
#11-528

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 570142

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SDS9905H	5B45372	19/09/2016	216d G TOURER	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments include knocking out dents caused by the accident	850.00		850.00	
To spray paint front bumper	934.00		934.00	
To check electrical wiring systems at the front section for proper function	150.00		150.00	
To replace RH LED technology headlight include programming and conducting tests for proper function	451.00		451.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RH FINISHER (LUXURY LINE)	52.55	1.00		52.55
FRT BUMPER PANEL PRIMED (PMA)	842.00	1.00		842.00
GRILLE SIDE OPEN RH (LUXURY LINE+PD)	95.85	1.00		95.85
# PLAQUE 82MM *	69.50	1.00		69.50
RH HEADLIGHT LED TECHNOLOGY	2,348.00	1.00		2,348.00

SUPPLEMENTARY ITEMS

Total Labour :	2,465.00
Total Parts :	3,407.90
Total Labour & Parts :	5,872.90
Deduction for Excess :	0.00
Total Repair Costs less Excess:	5,872.90
GST @7%:	411.10
Grand Total :	6,284.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18014543/R1sd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 27-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9188H	Veh. Inspected	SDS 9905H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005964MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	08/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	BMW 216D GRAN TOURER	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WBA2E320905B45372	Colour	GREY	
Odometer	30632	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R17	PIRELLI	6 mm	
L/H Front Tyre	205/55 R17	PIRELLI	6 mm	
R/H Rear Tyre	205/55 R17	PIRELLI	6 mm	
L/H Rear Tyre	205/55 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/08/2018	Inspection Date	27/08/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDS 9905H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT BUMPER RH INSERT (SN)	SERVICEABLE	9.70	-
1	FRT RH SIDE PANEL TOP MOUNTING (SN)	SERVICEABLE	8.85	-
1	FRT FLAP TOWING EYE PRIMED (SN)	SERVICEABLE	41.80	-
1	RH FINISHER (LUXURY LINE)(SN)	SCRATCHED	52.55	52.55
1	RH SUPPORT FOG LAMP (GESCHLOSSEN)(SN)	SERVICEABLE	77.60	-
1	FRT BUMPER PANEL PRIMED (PMA)(SN)	SCRATCHED	842.00	842.00
1	GRILLE SIDE OPEN RH (LUXURY LINE+PD)(SN)	SCRATCHED	95.85	95.85
1	RH SUPPORT HEADLIGHT ARM (SN)	SERVICEABLE	124.85	-
1	RH HEADLIGHT LED TECHNOLOGY (SN)	SCRATCHED	2,348.00	2,348.00
1	RH FOG LIGHT (SN)	SERVICEABLE	276.40	-
1	ULTRASONIC SENSOR BLACK (SN)	SERVICEABLE	248.70	-
4	DECOUPING RING PDC TORQUE CONVERTER (SN)	SERVICEABLE	20.20	-
1	PLAQUE 82MM (SN)(ADDITIONAL)	NECESSARY	69.50	69.50
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
			4,296.00	3,487.90
LABOUR				
TO REPLACE FRONT BUMPER,RIGHT HEADLAMP SUPPORT,ATTACHMENTS AND REPAIR RIGHT FENDER.			2,975.00	850.00
PAINTING FRONT BUMPER AND FENDER RIGHT.			1,923.00	934.00
TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.			177.00	150.00
TO REPLACE RIGHT HEADLIGHT INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION.			531.00	451.00
			5,606.00	2,385.00
GRAND TOTAL			9,902.00	5,872.90
RECOMMENDED COST OF REPAIRS				5,872.90

Report Ref No. CS/FC118014543/R1sd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.