

23/03/2003

ASS. REC. BY:

REF: CS/FCI18014547/K4d3/n2

Special Instruction:

Survivor:

CWS

Kenneth

ASSIGNMENT (Office)

From (Person):

Suzanne Ler

of

FCI

Date/Time: 8/8/18 @ 7:14pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 2500S

Insured:

SH 9219K

at Workshop m/s

C.S. Ong Auto

Tel:

61841933

of

10 AMK Ind. Park 2A # 02-16

Policy No:

Claim No:

D18005483MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 8/8/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 1PS

H.O.D. Endorsement:

Date/Time: 10:29am @ 10/8/18

Person Contacted:

Mrs. Ong

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLX 2500S - X
	SH 9219K - NBA / MSG / 5010945 / Y
31/8-	Revert via email preli advise.
30/10	L/Sy @ 45501 email (Red: 5541.44 / 54%)

ASS. REC. BY:

REF: F02/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

13/8

File pass to Carhenge

RECEIVED 30 OCT 2018

Veh No:

SLX 2500s Yr Regn: 03, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle c.c. 1456

Colour:

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

28739

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GP7 1205408

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

6

mm

L/Bal.

8

mm

L/Bal.

6

mm

D.O.A.

3/2/18

D.O.I.

10/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

cls body

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

11/30/10 Typist

Date/Time, File Return to?



: Prell. Report



: Final Report

Days Of Repair: 8

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S - RS - SI

Fixings

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

TP

Lump Sum / I.B.I. (\$

4550

170
50
50+50
27
347



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18014547/Ktd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9219K	Veh. Inspected	SLX 2500S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005983MFSH	Excess (\$)	0.00	
Assign From	CWS (SERENE LER)	Assign Date	10/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/08/2018	Inspection Date	10/08/2018	
Survey held at	C. S. ONG AUTO PTE LTD BLOCK 10 ANG MO KIO IND PK 2A #04-01/#03-11 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005983MFSH

Date: 31/8/2018

Our Ref: CS/FCI18014547/Ktd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLX 2500S

Please be informed that we had conducted the inspection of the abovementioned vehicle 10/8/2018 at the premises of M/s C.S Ong and have the following to report: -

Workshop Estimate Amount	: S\$ <u>5,100.00</u> (LABOUR ONLY)
Revised Estimate Amount	: S\$ <u>2,100.00</u>
"Check" Items Amount	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the
o/s body portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kenneth

Automotive Assessor

Date	08-08-2018	Case Ref No. D18005983M7SH
Accident Date	08-08-2018	Accident Type: Third Party
Insured Vehicle	SH9219K	Third Party Vehicle: SLX2500S
Survey Location	10 ANG MO KIO IND PARKWAY #02-113 ANG MO KIO PARK	
Contact Person.	NA	
Contact No.	64841933/0	Fax No. 64841922
Survey Type	WITHOUT PREJUDICE: VENDOR ADMITS LIABILITY OF OTHERS TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANT	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

Please submit to us the Tax Invoice together with the NIMA Benchmark rates) to

Cc : Workshop	C.S. ONG AUTO PTE LTD	010-22111111
Cc : TP Solicitor	NA	010-22111111
Officer Incharge	SERENE	

Kindly submit the survey report via CWS within 14 days for re-inspection.

Denise Tay (LKKAUTO)

From: C. S. ONG AUTO PTE. LTD. <csongauto@yahoo.com.sg>
Sent: Monday, 29 October 2018 6:04 PM
To: Denise Tay (LKKAUTO)
Subject: Re: SLX2500S question mark photos

Hi,

Have finalize with kenneth. Accept with thanks.

Warmest Regards,

C. S. ONG AUTO PTE. LTD.

Blk 10, Ang Mo Kio Ind Park 2A,
#02-16 AMK AutoPoint, Singapore 568047
Tel: 6484 1933 | Fax: 6484 1922
E-Mail: csongauto@yahoo.com.sg

On Monday, 29 October 2018, 3:54:39 PM GMT+8, Denise Tay (LKKAUTO) <denisetay@lkkauto.com> wrote:

Dear Sir/Madam,

Offer at \$4550, 8days

Please check and confirm

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 31 August 2018 10:07 AM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005983MFSH/1
Attachments: PRELI ADVISED SLX 2500S.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLX 2500S**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 10 August 2018 10:33 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005983MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 8 August 2018 7:13 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005983MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Not Notwithstanding
 11 Sep @ 455dp
 Resurvey After Paint

C. S. ONG AUTO PTE. LTD.

Today

Company & GST Reg No.: 201408916W

10, Ang Mo Kio Ind. Park 2A, #02-16, AMK AutoPoint, Singapore (568047)

Tel: 6484 1933 | Fax: 6484 1922

E-Mail: csongauto@yahoo.com.sg

To: Motor Claims Department,
 FIRST CAPITAL INSURANCE LTD

Date: 08/08/2018

Accident Involving Vehicles SLX2500S & SH9219K [Your Insured] on 08/08/2018 @
 0820 Hrs along Tavistock Ave

Estimated Repair Costs For SLX2500S [Honda Shuttle]

1Pc	Rear RH Fender	\$	Ry 1,010.90	✓
1Pc	RH Lower Rocker Panel	\$	R 455.00	X
1Pc	Rear RH Door	\$	Ry 1,150.00	✓
1Pc	Rear RH Door Handle	\$	Lu 109.00	X
1Pc	Rear RH Door Sticker	\$	Ru 40.50	✓
1Set	Rear RH Door Inner Trim Board Clips	\$	Ru 45.00	✓
1Pc	Rear RH Door Opening Trim Weatherstrip Rubber	\$	Ru 59.70	✓
1Pc	Rear RH Door Lower Rubber	\$	Lu 28.50	X
1Pc	Rear RH Door Outer Window Side Garnish [Front]	\$	Lu 75.60	X
1Pc	Rear RH Door Outer Window Side Garnish [Rear]	\$	Lu 72.10	X
1Pc	Rear RH Door Outer Window Garnish	\$	Lu 85.60	X
1Pc	Rear RH Power Window Motor	\$	Tom 361.00	X
1Pc	Rear RH Window Regulator	\$	Ry 361.00	X
1 Pc	Front RH Door	\$	Ry 1,150.00	✓
1 Pc	Front RH Door Sticker	\$	Ru 35.60	✓
1 Pc	Front RH Door Upper Hinge Assy	\$	R 48.50	X
1 Pc	Front RH Door Lower Hinge Assy	\$	R 48.50	X
1 Pc	Front RH Door Handle Assy	\$	Lu 108.00	X
1 Pc	Front RH Door Inner Lock Assy	\$	R 210.00	X
1Pc	Front RH Door Outer Lock	\$	R 105.30	X
1Pc	Front RH Door Outer Window Side Garnish [Front]	\$	Lu 74.10	X
1Pc	Front RH Door Outer Window Side Garnish [Rear]	\$	Lu 83.40	X
1Pc	Front RH Door Outer Window Garnish	\$	Lu 85.60	X
1 Pc	Front RH Door Inner Weatherstrip Rubber	\$	Lu 59.70	X
1 Pc	Front RH Door Opening Trim Weatherstrip Rubber	\$	Lu 28.10	X
1 Pc	Front RH Door Power Window Motor	\$	Lu 151.80	✓
1 Pc	Front RH Door Window Regulator	\$	Di 151.80	✓

1Set Front RH Inner Trim Board Clips

	\$	45.00 X
Total:	\$	6,239.30
Parts Less 20%:	\$	1,247.86
Parts Total:	\$	4,991.44

Labour & MISC Charges

- | | | | |
|---|----|----------|------|
| * To putty & re-spray new paintwork on all RHS Front & Rear Door affected areas. | \$ | 2,400.00 | 100% |
| * To panel beat, repair & replace all RHS Front & Rear Door damaged panels to transfer door parts, to refit & realign all of the above items. | \$ | 2,400.00 | 100% |
| * To conduct a check on all wiring systems. | \$ | 100.00 | 20% |
| * To anti-rust all affected areas. | \$ | 200.00 | 90% |

Labour & Charges Total:	\$	5,100.00
Parts Total:	\$	4,991.44
Labour & Charges Total:	\$	5,100.00
Total Cost of Repair:	\$	10,091.44
(Non inclusive of 7% GST)		

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10/08/18.

Not Authorised
1.B.1
Preserving B4 pain
2 days

C. S. ONG AUTO PTE. LTD.

Company & GST Reg No.: 201408916W
10, Ang Mo Kio Ind. Park 2A, #02-16, AMK AutoPoint, Singapore (568047)
Tel: 6484 1933 | Fax: 6484 1922
E-Mail: csongauto@yahoo.com.sg

To: Motor Claims Department,
FIRST CAPITAL INSURANCE LTD

Date: 08/08/2018

Accident Involving Vehicles SLX2500S & SH9219K [Your Insured] on 08/08/2018 @
0820 Hrs along Tavistock Ave

Estimated Repair Costs For SLX2500S [Honda Shuttle]

1Pc	Rear RH Fender	BY ✓
1Pc	RH Lower Rocker Panel	Rx
1Pc	Rear RH Door	BY ✓
1Pc	Rear RH Door Handle	Sn x
1Pc	Rear RH Door Sticker	Me
1Set	Rear RH Door Inner Trim Board Clips	Sn x
1Pc	Rear RH Door Opening Trim Weatherstrip Rubber	Me
1Pc	Rear RH Door Lower Rubber	Sn x
1Pc	Rear RH Door Outer Window Side Garnish [Front]	?
1Pc	Rear RH Door Outer Window Side Garnish [Rear]	Sn x
1Pc	Rear RH Door Outer Window Garnish	?
1Pc	Rear RH Power Window Motor	Sn x
1Pc	Rear RH Window Regulator	Rx
1 Pc	Front RH Door	BY ✓
1 Pc	Front RH Door Sticker	Me
1 Pc	Front RH Door Upper Hinge Assy	Rx
1 Pc	Front RH Door Lower Hinge Assy	Rx
1 Pc	Front RH Door Handle Assy	Sn x
1 Pc	Front RH Door Inner Lock Assy	Rx
1Pc	Front RH Door Outer Lock	?
1Pc	Front RH Door Outer Window Side Garnish [Front]	Sn x
1Pc	Front RH Door Outer Window Side Garnish [Rear]	Sn x
1Pc	Front RH Door Outer Window Garnish	?
1 Pc	Front RH Door Inner Weatherstrip Rubber	Sn x
1 Pc	Front RH Door Opening Trim Weatherstrip Rubber	?
1 Pc	Front RH Door Power Window Motor	?
1 Pc	Front RH Door Window Regulator	?
1Set	Front RH Inner Trim Board Clips	?

Total:	\$	-
Parts Less 20%:	\$	-
Parts Total:	\$	-

Labour & MISC Charges

* To putty & re-spray new paintwork on all RHS Front & Rear Door affected areas.	\$	2,400.00	1000/
* To panel beat, repair & replace all RHS Front & Rear Door damaged panels to transfer door parts, to refit & realign all of the above items.	\$	2,400.00	1000/
* To conduct a check on all wiring systems.	\$	100.00	20/
* To anti-rust all affected areas.	\$	200.00	90/
Labour & Charges Total:	\$	5,100.00	
Parts Total:	\$	-	
Labour & Charges Total:	\$	5,100.00	
Total Cost of Repair:	\$	5,100.00	
(Non inclusive of 7% GST)			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18014547/Ktd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9219K	Veh. Inspected	SLX 2500S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005983MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	08/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GP71205408	Colour	METALLIC GREY	
Odometer	28739	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	8 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	8 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/08/2018	Inspection Date	10/08/2018	
Survey held at	C. S. ONG AUTO PTE LTD BLOCK 10 ANG MO KIO IND PK 2A #04-01/#03-11 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 2500S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR RH FENDER	BENT	1,010.90	1,010.90
1	RH LOWER ROCKER PANEL	TO REPAIR SEE LABOUR	455.00	-
1	REAR RH DOOR	BENT	1,150.00	1,150.00
1	REAR RH DOOR HANDLE	SERVICEABLE	109.00	-
1	REAR RH DOOR STICKER	NECESSARY	40.50	40.50
1	SET REAR RH DOOR INNER TRIM BOARD CLIPS	NECESSARY	45.00	45.00
1	REAR RH DOOR OPENING TRIM WEATHERSTRIP RUBBER	NECESSARY	59.70	59.70
1	REAR RH DOOR LOWER RUBBER	SERVICEABLE	28.50	-
1	REAR RH DOOR OUTER WINDOW SIDE GARNISH (FRONT)	SERVICEABLE	75.60	-
1	REAR RH DOOR OUTER WINDOW SIDE GARNISH (REAR)	SERVICEABLE	72.10	-
1	REAR RH DOOR OUTER WINDOW GARNISH	SERVICEABLE	85.60	-
1	REAR RH POWER WINDOW MOTOR	JAMMED	361.00	361.00
1	REAR RH WINDOW REGULATOR	BENT	361.00	361.00
1	FRONT RH DOOR	BENT	1,150.00	1,150.00
1	FRONT RH DOOR STICKER	NECESSARY	35.60	35.60
1	FRONT RH DOOR UPPER HINGE ASSY	TO REPAIR SEE LABOUR	48.50	-
1	FRONT RH DOOR LOWER HINGE ASSY	TO REPAIR SEE LABOUR	48.50	-
1	FRONT RH DOOR HANDLE ASSY	SERVICEABLE	108.00	-
1	FRONT RH DOOR INNER LOCK ASSY	TO REPAIR SEE LABOUR	210.00	-
1	FRONT RH DOOR OUTER LOCK	TO REPAIR SEE LABOUR	105.30	-
1	FRONT RH DOOR OUTER WINDOW SIDE GARNISH (FRONT)	SERVICEABLE	74.10	-
1	FRONT RH DOOR OUTER WINDOW SIDE GARNISH (REAR)	SERVICEABLE	83.40	-
1	FRONT RH DOOR OUTER WINDOW GARNISH	SERVICEABLE	85.60	-
1	FRONT RH DOOR INNER WEATHERSTRIP RUBBER	SERVICEABLE	59.70	-
1	FRONT RH DOOR POWER WINDOW MOTOR	JAMMED	151.80	151.80

Report Ref No. CS/FC118014547/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT RH DOOR WINDOW REGULATOR	DISTORTED	151.80	151.80
1	SET FRONT RH INNER TRIM BOARD CLIPS	NOT NECESSARY	45.00	-
1	FRONT RH DOOR OPENING TRIM WEATHERSTRIP RUBBER	SERVICEABLE	28.10	-
	LESS 20% DISCOUNT		-1,247.86	-903.46
			4,991.44	3,613.84
	LABOUR			
	TO PUTTY & RE-SPRAY NEW PAINTWORK ON ALL RHS FRONT & REAR DOOR AFFECTED AREAS.		2,400.00	1,000.00
	TO PANEL BEAT,REPAIR & REPLACE ALL RHS FRONT & REAR DOOR DAMAGED PANELS TO TRANSFER DOOR PARTS,TO REFIT & REALIGNALL OF THE ABOVE ITEMS.INCLUSIVE OF THE REPAIR OF RH LOWER ROCKER PANEL, FRONT RH DOOR UPPER HINGE ASSY,FRONT RH DOOR LOWER HINGE ASSY,FRONT RH DOOR INNER LOCK ASSY AND FRONT RH DOOR OUTER LOCK.		2,400.00	1,000.00
	TO CONDUCT A CHECK ON ALL WIRING SYSTEMS.		100.00	20.00
	TO ANTI-RUST ALL AFFECTED AREAS.		200.00	90.00
			5,100.00	2,110.00
	GRAND TOTAL		10,091.44	5,723.84
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,550.00

Report Ref No. CS/FCI18014547/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.