

SS. REC. BY:

REF: CS3/FCI 18014551/G24d31⁵² Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

May chua

of

FCI

Date/Time:

10/8/18 @ 2:13pm

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJP 3796P

Insured:

SHA 5170J

at Workshop m/s

Kent Auto

Tel:

67 412539

of

2 Kelai Bkt Ave 2 # 01-21

Policy No:

Claim No:

D18005453MP&H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

4/8/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

1 up

H.O.D. Endorsement:

Date/Time:

3:19pm @ 10/8/18

Person Contacted:

Alia

Vehicle

IN/OUT

Date/Time	Action/Instruction (X) Estimate	
	SJP 3796P - NA / INC 18014286/h4	DOA: 4/8/2018
	SHA 5170J - NA / INC 18014286/h4	DOA: 4/8/2018

Summary

PRS
Karl

REF:

Sci

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

Kent Auto

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$10k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lump Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

11/8/18

Summary PRS Report

Veh No:

SJP3796P

Yr Regn:

-

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Chery V5

c.c.

2350

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

105739

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

LVVDB 24B 67D 2499 50

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

205/55 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

10-08-18

Survey held at

w/s

5:15pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others:

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS3/FCI18014551/Gz4d3

36 ROBINSON ROAD
#16-01 CITY HOUSES SINGAPORE 068877

Date : 10-08-2018



Code : FCI2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHA 5170J	Veh. Inspected	SJP 3796P
Policy No.		Coverage (\$)	0.00
Claim No.	D18005953MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	10/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	04/08/2018	Inspection Date	10/08/2018
Survey held at	KENT AUTO SERVICES 2 KAKI BUKIT AVE 2 #01-21 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

MOTOR SURVEY ASSIGNMENT

Date	07-08-2018	Our Ref No. D18005953MFSH
Accident Date	04-08-2018	Claim Type. Third Party
Insured Vehicle	SHA5170J	Third Party Vehicle. SJP3796P
Survey Location	KAKI BULKIT AUTOHUB, 2 KAKI BULKIT AVENUE 2 #01-21	
Contact Person.	MR KENT	
Contact No.	67412539/ 97547573	Fax No. 67412539
Survey Type	WITHOUT PREJUDICE: NO EST. PROVIDED **	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KENT AUTO SERVICES	Attention. NIL
Cc : TP Solicitor	CENTRO-LEGAL LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
FIRST CAPITAL INSURANCE LTD		Ref: CS3/FCI18014551/Gz4d3s2	
36 ROBINSON ROAD		Date: 14-08-2018	
#16-01 CITY HOUSESINGAPORE 068877		Code: FCI2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SHA 5170J	Veh. Inspected	SJP 3796P
Policy No.		Coverage (\$)	0.00
Claim No.	D18005953MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	10/08/2018
2. Vehicle Particulars & Condition			
Make & Model	CHERY V5	c.c	2350
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	LVVDB24B67D249950	Colour	SILVER
Odometer	105739 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55ZR16	MICHELIN	6 mm
L/H Front Tyre	205/55ZR16	MICHELIN	6 mm
R/H Rear Tyre	205/55ZR16	MICHELIN	6 mm
L/H Rear Tyre	205/55ZR16	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information			
Accident Date	04/08/2018	Inspect Date / Time	10/08/2018 (05:15 PM)
Survey held at	KENT AUTO SERVICES 2 KAKI BUKIT AVE 2 #01-21 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) MARKET VALUE \$10,000.00			

Report Ref No. CS3/FCI18014551/Gz4d3s2

Inspected By

XING GUO QIANG

M. MATAI, AMSAE-A

Automotive Assessor

K.K. LAU CPT (RET)

BEng(Hons), B.Bus, MBA, PEng, PE, Minst AEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.