CS3/MSG17024241/B+d3-1 Thise Merimen Iren tan MSIG MSIG 10/08/2018 OD WS/IT RES/OD RES/EVA/ENV/MV/CS To Long or Yellow SFW 43819 SKG 6802 X 31k 8 Sin Ming Ind. Est Sec C # 01-68 6452 3298 A80426602amx 541560 18/12/2017 CA / REV / REE, / REV 24 HRS Deserted 412pm@piliclia Nicole (1) 00 Deserting Adjunction (X) Extingula SFW4381G-X SKG 6802 x - CS/MSG17011722/RIVER D.O.A. 06/08/2017 Jump Sum \$6250 - (Red. 2420, 27%), - Fdays. 20/8 - Pile pass to typisx

mer but long	
	ASSIGNMENT
Estimated Cost	VAT 112 SFW 43816- 11
	Type M. Carr M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD/TP/WS/TPRES/OD RES/EVA/INV/MV	Taxi / Prime Mover /
TO MEDICAL VARIOUS NO SEW 4381CT	Make Disson.
# Workshop mis Em - 1 .	com 5; ver : 1597
d .	" (TSURAN / SEA)
10.00	So Reading 2935SS TRade Insured / Std / NI / NA
Pur by No	(409.45
Claims No	Ger Cond Good (Fair) Poor / Burn
Bum insured Excess	Ger Cond Good (Fair) Poor / Burnt
Client's Recordi	Steering (norder) Jammed / Leaked / Burnt or
Mare of Vec	Brake Inorder / Jammed / Leaked / Burnt Co
	Mod Nil (S/Rim) STO A/Rim C
(Policy Condition)	Treson F 185 65 RIS ,
Remark. The veh had commenced its	R 1851650
repair at the time of inspection.	BS DUN / EXNOVA / GY / FS / LIZA / MIC / ONTELL
5 s. or Market Value.	
DAC Accident Room Consistent? Yes or No	From Michall (8)
3(1 PR 3ee- Consistent? : Yes or No	RSal + mm RSal >
Err Bassin	LBay 4 mm LBay 3
Cays Res Yes or No	004 2111
	Survey reid at Me AC - (12/2017)
C4 / REV / REP. / 24 HRS	Des of Damages Fri (Read) Ols (NIC)
Date: Person Contacted:, Venice_IN/	
Date Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision
	2000 - \$4000
No.	I Days Rever
	10 Lever
RECEIVED 0 8 APR 20	mento
NEWENTED 1 - MIN 20	
THE FIRE PRINCE	Alaka
	Days Of Repair
06042018 Final Report	Resultion No4 T.
- Marine For Between 197	12.0
Add Fe	De: Site foar S
	Intervey: (\$
Report Format 9RS	П.,
Lump Sum / 1.8 1: (S	Tech 1-13 \$ 10
	Weakens 5
	180

Nivitha (LKK Auto)

From:

Irene Tan <irene_tan@sg.msig-asia.com>

Sent:

Friday, 10 August 2018 2:30 PM

To:

Nivitha (LKK Auto); ASSIGNMENTS@LKKAUTO.COM

Cc:

sur@lkkauto.com

Subject:

Please prepare paper survey report on SFW4381G; Our claim no.: 541560/IT

Importance:

High

Good afternoon Veron,

We refer to your PRI report dated 10.4.18.

Please prepare and submit your surveyor's paper report on the subject car asap.

Best Regards

Irene Tan

Senior Executive, Claims Services (Motor)

Direct line +65 6594 2541 | Direct fax +65 6225 7402 | <u>irene_tan@sg.msig-asia.com</u>





Insurer Claims Team of the Year 2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg





A Member of MS&AD INSURANCE GROUP

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Friday, 10 August, 2018 2:01 PM

To: Irene Tan <irene_tan@sg.msig-asia.com>; ASSIGNMENTS@LKKAUTO.COM

Cc: sur@lkkauto.com

Subject: RE: Mr Wilson Teo's PRI on SFW4381G; Our claim no.: 541560/IT

Dear Irene,

Thank you for the email.

Please be informed inspection after dismantled and after repair has been done for SFW 4381G.

Photos is uploaded In merimen.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) From: Irene Tan <irene tan@sg.msig-asia.com>

Sent: Tuesday, 7 August 2018 11:52 AM

To: Veron Chen (LKKAuto) < veronchen@lkkauto.com >; Shiau Chan (LKKAuto) < siewsc@lkkauto.com >; Olivia Lau

(LKKAuto) < olivialau@lkkauto.com>; Admin-D (LKKAuto) < admin-d@lkkauto.com>; assignments

<assignments@lkkauto.com>

Subject: Mr Wilson Teo's PRI on SFW4381G; Our claim no.: 541560/IT

Importance: High

FOR YOUR IMMEDIATE ACTION, PLEASE

Good afternoon Veron,

We refer to your PRI report dated 10.4.18 and we have received the total repair costs claim at \$8,760.00 pertaining to the subject vehicle from the 3rd party's law firm.

Has the repairer from EM-1 Auto Pte Ltd called your surveyor for inspection after dismantlement and after repairs on SFW4381G?

Please reply asap or within the next 3 days by Friday, 10.8.18.

Best Regards

Irene Tan Senior Executive, Claims Services (Motor) Direct line +65 6594 2541 | Direct fax +65 6225 7402 | irene_tan@sg.msig-asia.com





Insurer Claims Team of the Year 2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg 🕡 💟 🗓 🖸

A Member of MS&AD INSURANCE GROUP

From: Irene Tan

Sent: Tuesday, 7 August, 2018 11:45 AM

To: 'yvonnelim@visionlawllc.com' <<u>yvonnelim@visionlawllc.com</u>>

Subject: Your ref: JH1-ylv-Ins-E25-105355-17-er; Our claim no.: 541560/IT

WITHOUT PREJUDICE

Dear madam,

We refer to your LOD dated 2.8.18.

Please let us know whether your repairer has called our surveyor from M/s. LKK Auto to conduct inspection of your client's vehicle no.: SFW4381G after dismantlement and after repairs. If no, please arrange and revert with a date and time for our surveyor's inspection at EM -1 Auto Trade.

Best Regards

Irene Tan

Senior Executive, Claims Services (Motor)

Direct line +65 6594 2541 | Direct fax +65 6225 7402 | irene_tan@sg.msig-asia.com





Insurer Claims Team of the Year 2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg 🕡 💟 🗓 🖸

A Member of MS&AD INSURANCE GROUP

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



This email has been checked for viruses by AVG antivirus software. www.avg.com

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths Agents for Trade Marks

(Incorpora ed v. K.) limited liability)

ERIC NG CHING BOON RAYNEY WONG KENG LEONG AUDREY WONG SU-HSIEN PAUL YAP TAI SAN ANJALLI DIO MUNIANDY SEGA PARAM TIWARY ANURADHA ONG BOCK KEE DIANE ANG KIM NO! RAVENDRA KRISHNASAMY TAY HAO RAN

Unique Entity Number: 200721148H

HEAD OFFICE

133 New Bridge Road #18-01/02 Chinatown Point Singapore 059413

Branch: 490 Toa Payon Lorong 6 #03-11 HDB Hub Singapore 310490

HEAD OFFICE

TEL : (65) 65342811 (Hunting) : (65) 65356802 (General) FAX v: (65) 65355905 (Litigation)

E-mail: yvonnelim@visionlawllc.com

BRANCH

TEL: (65) 63580703

FAX : (65) 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref

JANICE HAN JIA LIN

SELWYN TAN YINGXIAN

: JH1-ylv-Ins-E25-105355-17-er

Your Ref

: SKG 6802 X

2 August 2018

5H1 560

MSIG INSURANCE (SINGAPORE) PTE. LTD.

16 Raffles Quay #24-01 Hong Leong Building

Singapore 048581

Attention: Motor Claims Department

CHNG CHEE TIONG

Blk 168 Woodlands Street 11 #07-137

Singapore 730168

REG / CS / PAY / FA 0 & AUG 2018

URGENT

BY HAND

roun, i) Uplood CA LLING

CERTIFICATE OF POSTING (For your information Only)

Dear Sirs.

CLAIMANT : LIM BAN CHOON

ACCIDENT INVOLVING SFW 4381 G & SKG 6802 X ON 18-DEC-2017 ALONG CTE (CITY) BEFORE **BRADDELL EXIT AT ABOUT 1815 HOURS**

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on 18-Dec-2017 ALONG CTE (CITY) BEFORE BRADDELL EXIT AT ABOUT 1815 HOURS involving our client's vehicle registration number SFW 4381 G and vehicle registration number SKG 6802 X driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

1.	Costs of Repair	•	0.700.00
2.	Rental fees	2	8,760.00
3.		S	914.85
	LTA/GIA/TP report/search fees	\$	44.35
4.	Survey report fees	S	843.00
5.	Costs (with GST)	\$	1,284.00
6.	Incidentals (with GST)	\$	128.40
	TOTAL:-	\$1	1,974.60

.../2 to be continued next page

.ntinuation Sheet

Our Ref

: JH1-ylv-Ins-E25-105355-17-er #

Your Ref

: SKG 6802 X

2 August 2018

MSIG INSURANCE (SINGAPORE) PTE. LTD.

16 Raffles Quay

#24-01 Hong Leong Building

Singapore 048581

Attention: Motor Claims Department

CHNG CHEE TIONG

Blk 168 Woodlands Street 11

#07-137

Singapore 730168

We enclose a copy of each of the following documents for your consideration:-

- Police/GIA report lodged by driver of SFW 4381 G & SKG 6802 X; (a)
- (b) LTANet Search:
- Certificate of Insurance: (c)
- (d) Registration Card;
- Rental agreement, rental invoice & rental receipt; (e)
- (f) Final Repair Bill:
- Surveyor's report & invoice; and (g)
- (h) 168 original photographs depicting the damages to motor vehicle SFW 4381 G.
 - (P.S:- Original photographs will be sent to insurance co. only)
 - (P.S:- Kindly return us all original photographs within 7 days hereof)

We have notified your insurers of the accident and a pre-repair inspection of our client's vehicle was carried out by your insurers.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully

JANICE HAN (HEAD OFFICE)

Encl.

SFW 4381 G- By fax: 6457 5776 only

(As per your instruction we have submitted your claim as set out above to the third party insurance company. Please do notify us if there is any discrepancy, if any, particularly, the number of days claimed for rental charges and/or loss of use as soon as possible. Thank you.}

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643

13 July 2018

Vehicle No.

: SFW 4381 G

Make/Model

: Nissan Sunny

Year of Manufacture : 2005

Chassis No.

: JN1CFAN16Z0512224

Name

: Lim Ban Choon

Address

: Blk 265 Tampines Street 21

#08-34

Singapore 520265

QTY

ITEM / PARTICULARS

\$

Third Party Accident Claim for vehicle no. SFW 4381 G

Date of Accident : 18 December 2017

Costs of Repairs

\$8,760.00

=======

SINGAPORE DOLLARS: EIGHT THOUSAND SEVEN HUNDRED AND SIXTY ONLY



DATE

Tradie 司

UNIQUE TOURIST SERVICE (PTE) LTD

PARTICULARS

SFW 4381G

Mr Lim Ban Choon Blk 265 Tampines Street 21 # 08-34 Singapore 520265

20, Sin Ming Lane,

#08-51, Midview City Singapore 573968 Tel: 6292 7656

cts

1, Rochor Centre, # 02-574 Singapore 0718.

Tel: 2927656 Fax: (65) 2939720 STPB LIC TA/076

NO. WP2017275

GST Reg. No.: M2-0019671-6

TAX INVOICE

28.12.2017 Singapore,

Rental of one unit Toyota Corolla Altis 1.6 Auto Registration no. SGS 1441 X self driven as from 18.12.2017 to 27.12.2017.

9 days at \$95.00 per day

Add GST at 7% Amount Due

855.00 855.00 \$ 59.85 914.85

(SIN DOLLARS: NINE HUNDRED FOURTEEN AND EIGHTY FIVE CENTS ONLY)

Standard Rated Supplies:\$ Total Amount of GST:\$

855.00

59.85

AUTHORISED SIGNATURE



UNIQUE TOURIST SERVICE (PTE) LTD.

20, Sin Ming Lane, #08-51, Midview City, Singapore 573968 TEL: 6292 7656 EMAIL: uniqtour@singnet.com.sg

COMPANY REG NO: 197401067R GST REG NO: M2-0019671-6

CAR RENTAL AGREEMENT

PANO 21241

SIGNATURE OF HIRER

VEHICLE NO. SES 144/X MAKE/MODEL -	OYOTA CORULI	A DITIE
NAME OF HERER LIM BAN CHURN	DATE OUT 181217	TIME OUT 1920 #
SINGAPORE 5 20 2 b T	DATE IN 37 12/17	1/4 1/2 3/4 C
OFFICE TEL HP NAMED DRIVER	PETROL IN E 1	/4 1/2 3/4 F
PASSPORT / NRIC C 0 4 5 3 6 5 2 E DATE OF BIRTH 22 /6/46 DRIVING LIC NO. So 4 5 3 6 5 2 E	arteriors of all others who would	The state of the s
PLACE OF ISSUE DATE PASS/EXPIRY 9/3/64	C.D.W. FEE PETROL CONSUMPTION	Peterse was all the
ADDITIONAL NAMED DRIVER ADDRESS	DELIVERY CHARGE COLLECTION CHARGE	
SINGAPORE	SUB-TOTAL	1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1
OCCUPATION NATIONALITY	GST 0 %	5985
PASSPORT / NRIC DATE OF BIRTH	TOTAL	914 85
PLACE OF ISSUE. DATE PASS/EXPIRY BY INITIATING MARK "X" HIRER AGREE TO PAY THE FOLLOWINGS A. COLLISION DAMAGE WAIVER (CDW) AT \$ PER DAY / WEEK / MONTH "X" B. SURCHARGE OF \$ FOR USE IN MALAYSIA FROM TO "X"	PAYMENT BY: BILL CO/CBEDI	REFUND
THE HIRER IS RESPONSIBLE FOR ANY DAMAGES UP TO THE EXTENT OF TOTAL LOSS OF CAR, LOSS OF INCOME AND COST OF RECOVERY OF VEHICLE IF THE CAR IS DRIVEN INTO MALAYSIA WITHOUT PRIOR CONSENT FROM THE COMPANY	OF UNIQUE TOURIST SERVICE	
NOTE: HIRER IS LIABLE FOR ALL PARKING & TRAFFIC VIOLATIONS. YOUR ATTENTION IS DRAWN TO TERMS & CONDITIONS PRINTED OVERLEAF.	OF YOUR MOTOR VE	E THAT NO MOTOR IRED DURING MY HIRE EHICLE AS STATED IN ED SCHEDULE * OR TO VEHICLE AS STATED
FOR SINGAPORE DRIVE ONLY	PEPLACEMENT VEHICLE NO 1 ON 2 ON 3 ON	TIME
DATE: SIGNATURE OF HIRER	DATE:	林了意



Our Reference

: 17/0143/TP

Invoice Number

: 1443

Date: 13 July 2018

Mr Lim Ban Choon C/o Block 8 Sin Ming Industrial Estate Sector C #01-68 Singapore 575643

INVOICE

DESCRIPTION	AMOUNT S\$
Professional Inspection Fee (SFW 4381 G)	\$455.00
Coloured Photographs (168 pieces)	168.00
Transport Fee	\$60.00
Re-inspection Fee (22/12/2017 & 30/12/2017)	\$160.00
TOTAL	\$843.00

Terms of payment: Cash on delivery All payments payable to "Allied Auto Appraisal"

Allied Auto Appraisal



Our Ref

11

: 17/0143/TP

Your Ref

: Not Advised

Date: 21 December 2017

Mr Lim Ban Choon C/o Block 8 Sin Ming Industrial Estate Sector C #01-68 Singapore 575643

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT (WITHOUT PREJUDICE)

Detailed accounts of our inspection are as follows:

(1) REFERENCE

Name of Claimant

Mr. Lim Ban Choon

Date of Request Referred By

: 21 December 2017 : Insured

Policy Number Claim Number Accident Date

GA049374/1 Not Advised 18 December 2017

Date of Inspection Date of Re-inspection

: 21 December 2017 : 22 Dec 2017 & 30 Dec 2017

Repairer

EM-1 Auto Trade

Sum Insured Excess Amount

: Not Applicable : Not Applicable

Block 8 Sin Ming Industrial

3rd Party Vehicle Estate Sector C #01-68

: SKG 6802 X

Singapore 575643

3rd Party Insurer

: MSIG Insurance (Singapore)

Pte Ltd

(2) PARTICULARS OF VEHICLE

Registration Number

SFW 4381 G

Mileage

293,058 km

Make & Model

Nissan Sunny 1.6 EX (A)

Chassis Number Engine Number

JN1CFAN16Z0512224

Date of Registration Colour

5 July 2005 Gold

Engine Capacity

QG16378117 1,597 cc

(3) PRE-ACCIDENT CONDITION (STATIC TEST ONLY)

Steering Foot-brake Hand-brake


In order In order In order Paint Work Modification General Condition

: Good : Sports rim : Average

(4) TYRE CONDITION

Event of the second	Remaining Thread Depth (%)	Make	Size
ront right tyre	95%	Ling Long	185/65R15
ront left tyre	95%	Ling Long	185/65R15
Rear right tyre	60%	Michelin	185/65R15
ear left tyre	60%	Michelin	185/65R15

(5) POINT OF IMPACT



(6) GENERAL DESCRIPTION OF DAMAGES

The impact of the collision has damaged/affected the trunk lid, spare wheel floor panel, rear end panel, rear combination lamps, rear bumper fascia, exhaust muffler and etc. Please refer to the Annex for a detailed account of the damages and photographs taken.

(7) RECOMMENDATION

We have inspected thoroughly the actual damages found on the vehicle before we conclude as to whether the parts needed replacement or repairs. The estimated cost of repair submitted by the repairer is \$12,592.75. We have adjusted the cost to \$10,947.50 and recommend that the repairs to be taken on a lump sum basis of \$8,760.00. In our opinion, the damaged parts are consistent with that caused by the accident.

(8) REMARKS

We have not authorised the repairs. However, for information, under normal circumstances, the period of repair should not exceed 10 working days.

This inspection was conducted on a "Without Prejudice" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Appraisal Report and photographs.

Allied Auto Appraisal

H. C. Ng

Motor Vehicle Appraiser



ANNEX

)	Qty	Particulars	Condition	Repairer's Amount	Adjuster's Amount
	OP. SALISTY	Nett Items	THE PROPERTY OF THE PROPERTY O	THE STEPPED CO. ST. ST. ST. ST. ST. ST. ST. ST. ST.	6-Resemblished (1007)
1	1	Trunk Lid	Dented/Buckled	613.30	613.30
2	1	Trunk Lid Nissan Emblem	Necessary	46.10	46.10
3	1	Trunk Lid SUNNY Emblem	Necessary	80.90	80.90
1	1	Trunk Lid EX Saloon Emblem	Necessary	95.70	95.70
5	1	Trunk Lid CVTC Emblem	Necessary	52.80	52.80
5	1	Trunk Lid E-Throttle Plate	Necessary	52.80	52.80
7	1	Trunk Lid Upper Chrome Finisher	Holder Broken	369.10	369.10
3	2	Rear License Plate Lamp @\$78.40 each	Serviceable	156.80	0.00
9	1	Trunk Lid Lower Chrome Finisher	Holder Broken	208.90	208.90
0	1	Trunk Lid Chrome Finisher Clip Set	Necessary	40.00	40.00
1	1	Trunk Lid Inner Trim	Serviceable	212.50	0.00
2	1	Trunk Lid Inner Trim Clip Set	Necessary	50.00	50.00
3	1	Trunk Lid Hinge - O/s	Serviceable	87.60	0.00
4	1	Trunk Lid Hinge - N/s	Serviceable	87.60	0.00
5	1	Trunk Lid Lock Assembly	Bent/Twisted	96.30	96.30
6	1	Spare Wheel Floor Panel	Badly Dented/Buckled	688.20	688.20
7	1	Spare Wheel Clamp Bracket	Bent	41.60	41.60>
8	1	Spare Wheel Board	Chipped/Cracked	192.10	192.10
9	1	Trunk Compartment Side Trim - O/s	Cracked/Torn	362.20	362.20
0	1	Trunk Compartment Side Trim - N/s	Cracked/Torn	362.20	362.20
1	2	Trunk Compartment Trim Clip Set @\$40.00 each	Necessary	80.00	80.00
2	1	Rear End Panel	Badly Dented/Distorted	335.60	335.60
3	1	Rear End Panel Inner Trim	Cracked/Torn	125.30	125.30
4	1	Rear End Panel Top Garnish	Deformed/Warped	132.20	132.20
5	1	Rear End Panel Top Garnish Clip Set	Necessary	40.00	40.00
6	1	Trunk Lid Lock Striker 10	Bent	63.70	63.70
7	1	Trunk Lid Weather-strip	Deformed/Kinked	139.60	139.60
8	1	Rear Combination Lamp - O/s	Len Cracked	360.20	360.20
9	1	Rear Combination Lamp - N/s	Housing Cracked	360.20	360.20
0	2	Rear Combination Lamp Rubber Seal @\$25.00 each	Necessary	50.00	50.00
1	2	Rear Combination Lamp Grommet @\$25.70 each	Necessary	51.40	51.40
12	1	Rear Fender Drafter Duct - N/s	Holder Broken	50.30	50.30
3	1	Rear Bumper Fascia	Badly Dented/Deformed	452.50	452.50
4	1	Rear Bumper Clip Set	Necessary	60.00	60.00

"1

Al	lied
Auto	Appraisal


35	1	Rear Bumper Chrome Moulding	Deformed	175.20	175.20	
36	1	Rear Bumper Energy Absorber	Cracked/Torn	126.40	126.40	
37	1	Rear Bumper Upper Bracket - O/s		36.10	36.10	
38	1	Rear Bumper Upper Bracket - N/s		36.10	36.10	
39	1	Rear Bumper Stay - O/s	Bent	86.60	86.60	
40	1	Rear Bumper Stay - N/s	Badly Dented	86.60		
41	1	Rear Bumper Side Bracket - O/s	Holder Broken	46.20	86.60	
42	1	Rear Bumper Side Bracket - N/s	Holder Broken	46.20	46.20	
43	1	Rear Bumper Closing Shield -	Holder Snapped	25.20	46.20	
		O/s	rioider Shapped	25.20	25.20	
44	1	Rear Bumper Closing Shield - N/s	Deformed/Grazed	25.20	25.20	
45	2	Rear Bumper Closing Shield Clip Set @\$20.00 each	Necessary	40.00	40.00 30	
				6,927.50	6,383.00	
			Less 10%	692.75	638.30	
			Sub-Total	6,234.75	5,744.70	
		Special Nett Items		100000000000000000000000000000000000000		
46	1	Trunk Lid Inner Sealer	Necessary	80.00	60.00	
47	1	Rear License Plate With Casing	Serviceable	70.00	0.00	
48	2	Spare Wheel Floor Panel Joint Sealant @\$80.00 each	Necessary	160.00	120.00 100	
49	1	Spare Wheel Floor Panel Insulator Pad	Necessary	150.00	130.00 120	
50	1	Spare Wheel Clamp	Deat			
51	1	Rear End Panel Joint Sealant	Bent	44.30	44.30 XSV C	-
52	1	Breakdown Sign	Necessary	80.00	60.00 \(\square 0	
53	1	Reverse Sensor Set	Cracked/Broken	150.00	120.00 70	
54	1	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	N/s Dented/Malfunction	300.00	250.00 200	
55	3	Exhaust Muffler Assembly Exhaust Muffler Rubber	Dented/Bent	504.00	504.00 × R	
0.000	100	Mounting @\$38.40 each	Serviceable	115.20	0.00	
56	1	Exhaust Muffler Gasket	Necessary	41.60	41.60	
57	1	Exhaust Muffler Heat Shield	Dented/Deformed	152.90	152.90	
			Total Parts (S\$)	8,082.75	7,227.50	

Recommended Labour

No	Particulars	Repairer's Amount	Adjuster's Amount	
1	To cut/weld spare wheel floor panel, rear end panel to renew and replace rear accident damaged parts.	1,800.00	1,500.00 \	100
2	To transfer trunk lid locking mechanism and other components to new trunk lid include checking components for function.	120.00	80.00	60
3	To remove/install rear seat, trunk compartment trim finishers, garnishes and interior upholstery to facilitate the replacement of spare wheel floor panel and rear end panel.	250.00	180.00	80
4	To remove/install fuel tank assembly and fittings to facilitate the replacement of the spare wheel floor panel include checking system for leaks.	150.00	90.00	X

18

			Allied Auto Appraisal	
5	To check rear lightings and electrical wiring system include performing water leakage test.	80.00	50.00	30
6	To install rear bumper reverse sensors to new bumper fascia include testing for functions.	120.00	80.00	20
7	To remove/install exhaust piping system to replace exhaust muffler assembly include checking system for leaks.	150.00	120.00	
8	To putty and re-spray painting on trunk lid, spare wheel floor panel, rear end panel, right rear fender, left rear fender and rear bumper fascia.	1,680.00	1,500.00	000
9	Rust-proofing on the rear accident affected portions.	160.00	120.00	100
	Total Labour (S\$)	4,510.00	3,720.00	1
	Total Repair Cost (S\$)	12,592.75	10,947.50	
	Adjusted Repair Cost (Lump sum basis)		S\$8,760.00	





GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm GST Registration No: M400017735

TAX INVOICE

Our Ref No:

GR-18-116902

Date of Request:

31/07/2018

Your Ref No:

INS-E25-105355-17

VISION LAW LLC 133 New Bridge Road #18-01/02 Chinatown Point Singapore 059413

Dear Sir/Madam,

Date of Accident:

18/12/2017

Vehicle No:

SFW4381G

Place of Accident:

CTE (City) before Braddell exit

Involving Vehicle No: SKG6802X

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SKG6802X	CTE (City) before Braddell exit	14.00	1	13.08
GST Amount				0.92
Total Amount Due	(GST Inclusive)			14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date

[X] GIRO [] Cash [] Cheque



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

SEARCH RESULTS

Our Ref No:

GR-18-116900

Date of Request:

31/07/2018

Your Ref No:

INS-E25-105355-17

VISION LAW LLC 133 New Bridge Road #18-01/02 Chinatown Point Singapore 059413

Dear Sir/Madam,

Your Search Criteria:

Date of Accident:

18/12/2017

Place of Accident:

CTE BEFORE BRADDELL EXIT

Client Vehicle No:

SFW4381G

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
SKG6802X	CTE TOWARDS CITY AT AUSTRALIA INTERNATIONAL SCHOOL	18/12/2017 18:00

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm GST Registration No: M400017735

TAX INVOICE

Our Ref No:

GR-18-116900

Date of Request:

31/07/2018

Your Ref No:

INS-E25-105355-17

VISION LAW LLC 133 New Bridge Road #18-01/02 Chinatown Point Singapore 059413

Dear Sir/Madam,

Your Search Criteria:

Date of Accident:

18/12/2017

Place of Accident:

CTE BEFORE BRADDELL EXIT

Client Vehicle No:

SFW4381G

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque

Enquire Vehicle & Owner Information (Vehicle No. SKG6802X As At 18 Dec 2017 / 18:15:00)

Law Florit Search Details

Search Reason:

Insurance claim in relation to traffic accident

Law Firm Case No.:

INS-E25-105355-17

Current Owner Details

Owner ID Type:

Singapore NRIC

Owner ID:

S6938196J

Owner Name:

CHNG CHEETIONG

Registered Address Type: HDB / HUDC

Registered Block/House No.: 168

Registered Street Name:

WOODLANDS STREET 11

Registered Unit No.:

#07-137

Registered Building Name: -

Registered Postal Code:

730168

Current vehicle Details

Vehicle No.:

SKG6802X

Make Description/Model: FORD / MONDEO 2.3L 5DR AUTO

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

Land Fransport \(\int \text{Authority} \)

SF 61 43214

Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No. : M4-0005529-2

Print Date/Time :

19 Dec 2017 / 11:10:47

Receipt Date/Time: 19 Dec 2017 / 11:10:47

Tax Invoice/Receipt

Receipt	No. : ITNE	T-00000-1	71219-000667
---------	------------	-----------	--------------

Previ	ous Receipt No. :				
S/N	Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Resu	It of Insurance Enquiry - SKG6802X		uo. (00)	(00)	(33)
	18 Dec 2017/18:15:00				
Insur 1	ance Co: MSIG INSURANCE (SINGA Insurance Enquiry - SKG6802X	PORE) PTE LTD			
	Enquiry Fee 20171219110946865348		5.00	0.35	5.35
		Sub-Total	5.00	0.35	5.35
		Total Before Rounding	5.00	0.35	5.35
		Rounding Difference			0.00
		Total Amount Payable			5.35
		Paid By			
		20171219110952564	Direct Debit: eNE	333	5.35
		Total			5.35
		Cash Change			0.00
		Tendered Amount			5.35
		Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

> OK | Save as PDF Print Receipt

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No.:

SFW4381G

Vehicle Type:

P10 - Passenger Motor Car

Vehicle Attachment 1:

No Attachment

Vehicle Scheme:

Normal

Vehicle Make:

NISSAN

Vehicle Model:

SUNNY 1.6EXA

Chassis No.:

JN1CFAN16Z0512224

Propellant:

Petrol

Engine No.: Engine Capacity:

QG16378117

Maximum Power Output:

1597 cc

Maximum Laden Weight:

81.0 kW (108 bhp) 1630 kg

Unladen Weight:

1110 kg

Year Of Manufacture:

2005

Original Registration Date:

Lifespan Expiry Date:

05 Jul 2005

COE Category:

A - Car (1600cc & below)

PQP Paid:

\$33,128.00

COE Expiry Date:

04 Jul 2020

Road Tax Expiry Date:

Inspection Due Date :

04 Jan 2019

04 Jul 2019

Intended Transfer Date:

31 Jul 2018

CO2 Emission:

CO Emission:

HC Emission:

NOx Emission:

PM Emission:

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable. Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Umber of March State March	Amount Before GST (5\$)	GST Amount (S\$)	Amount After GST
Transfer Fee:	25.00	(33)	(5\$)
Total Amount Payable:	23.00	•	25.00
Message			25.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (If applicable), whichever is earlier.

You may print this page for reference.

OK

Print

ERIC NG CHING BOON

EMIC MS CHING BODN
RAYNEY WONG KENG LEONG
AUDREY WONG SU HSIEN
PAUL YAP TAI SAN
ANJALLI DIO MUNIANDY
SEGA PARAM
TIMARY ANURADHA

ONG BOCK KEE DIANE ANG KIM NOI RAVENDRA KRISHNASAMY

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths Agents for Trade Marks

(Incorporated with limited liability)

Unique Entity Number: 200721148H

VHEAD OFFICE 133 New Bridge Road #18-01/02 Chinatown Point Singapore 059413

Branch: 490 Toa Payoh Lorong 6 #03-11 HDB Hub Singapore 310490

HEAD OFFICE

TEL : (65) 65342811 (Hunting) FAX : (65) 65356802 (General) /: (65) 65355905 (Litigation) E-mail: yvonnelim@visionlawllc.com

EFG/CS/PAY/FA

0 1 AUG 2018

TEL: (65) 63580703

FAX: (65) 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE – PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref:

TAY HAO RAN

JANICE HAN JIA LIN

SELWYN TAN YINGXIAN

JH-ylv-Ins-E25-105355-17-er

Your Ref: SKG 6802 X

31 July 2018

URGENT

BY FAX (62257402) ONLY

MSIG INSURANCE (SINGAPORE) PTE. LTD.

16 Raffles Quay

#24-01 Hong Leong Building

Singapore 048581

Attention: Motor Claims Department

Dear Sir,

CLAIMANT: LIM BAN CHOON

ACCIDENT INVOLVING SFW 4381 G & SKG 6802 X ON 18-DEC-2017 ALONG CTE (CITY) BEFORE **BRADDELL EXIT AT ABOUT 1815 HOURS**

We act for Lim Ban Choon, the owner of motor vehicle no. SFW 4381 G.

Our investigation reveals that you were the insurers of motor vehicle SKG 6802 X at the time of the accident. Kindly confirm.

Please let us have the following particulars:-

- the name, address and NRIC No. of the owner and / or driver;
- (b) whether the said motor vehicle was at the time of the accident covered by a policy of insurance, if so, the particulars thereof;
- whether the driver was at the time of the accident driving as your insured's servant or (c) agent; and
- (d) whether the driver was an authorised driver and covered by the policy of insurance.

If the information requested above are not provided within 14 days, any amendments are to be made thereafter to the Writ of Summons and / or any Pleadings, you will be responsible for the costs and disbursements incurred.

JANICE HAN (HEAD OFFICE)

Yours faithfully

cc: SFW 4381 G - By fax: 6457 5776 only

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case 1	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj Sub	mitted	Ins Auth'ed		Status	
	19 Dec 2017		21 Dec 2017 13:44 Edit Adj Rpt	S\$6,250 Edit Est	0.00 timates	S\$6,25 View R				Pending for Surv Report Cancel Case	
	lain	R	eference		laim Deta	ils		Docume	nts		Show All
CLAIM SUE	SFOLDER DI	TAILS				[0	reated	by insurer]			
Insured:	CHNG CH	EE TIONG, ID:	56938196)					- 18-2			
Main Claimant:	LIM BAN	CHOON, ID: SO	453652E								
Vehicle Reg. No.:	SFW438	31G			Date of Lo			7 18:00 - :59 hs and 13 Day:	s From	LTA Reg Date	(Man Yr)]
Claim Type:	TP / 541	560			Policy/Co Note No.:			QMX (Comprel 24/02/2017 - 2			
Vehicle Reg. No. (Insured):	SKG6802	x			Policy No. (Claimant	97/61/0					
					Excess:		\$1,000.00	And the second s			
Repairer:	Em-1 Aut	o Pte Ltd (HQ)	3lk 8 Sin Ming Indus	strial Estate	Sector C, #	≠01-68,	575643	Sin Ming - Tel:	645232	298	
Handling Insurer:	VANDAGO ESTON		ore) Pte. Ltd. (HQ				10 m. h. oc. 10 m. n. o. j.	Charles and Charles	-		
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 6	256-3561	[Handled	by Lim	Teow G	uan] [Fina	I Rpt	due 14/08/	2018]
Driver/Custo dian (Insured):		EE TIONG (/ Male), NRIC: S693819	963							
ASSOCIAT	ED MAIL RE	CEIVED							View All	Compos	e Case Mail
MSIG_SC	6 (10/08/201	8): Report Send	Back Alerts - SFW	/4381G (TF	')			_		XV	
ALL ASSO	CIATED TAS	sks ⁼				Viev	w All	Search Tasks	Creat	e New Task	Complete
Due Date	Priority	Type Tasi	Group Subje	ct Hand	ler As	signed	Ву	Completed C)n	Created On	Done

Claim Documents

*SFW4381G (541560) [SKG6802X] TP LIM BAN CHOON Dec 18 2017 6:00PM [CHNG CHEE TIONG] Em-1 Auto Pte Ltd

-		load Photos Compose New Letter	1/58/00	View in Brows	-
Ass	essment Reports	The last the state of the state	1 per p		✓
Vo.	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	20/12/17 10:57	Accident Statement From: SC - Reg. No: SKG6802X, Claimant: CHNG CHEE TIONG	0	Load HTM	
Pho	otos/Images		3 per j	page 🔻	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
1	06/04/18 10:59	General View	0	Load JPG	~
2	06/04/18 10:59	General View	0	Load JPG	₹
3	06/04/18 10:59	General View	0	Load JPG	~
4	06/04/18 10:59	General View	0	Load JPG	¥
5	06/04/18 10:59	General View	0	Load JPG	✓
6	06/04/18 10:59	General View	0	Load JPG	V
7	06/04/18 10:59	General View	0	Load JPG	V
8	06/04/18 10:59	General View	0	Load JPG	~
9	06/04/18 10:59	General View	0	Load JPG	V
10	06/04/18 10:59	General View	0	Load JPG	V
11	06/04/18 10:59	General View	0	Load JPG	V
12	06/04/18 10:59	General View	0	Load JPG	V
13	06/04/18 10:59	General View	0	Load JPG	V
14	06/04/18 10:59	General View	0	Load JPG	V
15	06/04/18 10:59	General View	0	Load JPG	V
16	06/04/18 10:59	General View	0	Load JPG	V
17	06/04/18 10:59	General View	0	Load JPG	V
18	06/04/18 10:59	General View	0	Load JPG	V
19	06/04/18 10:59	General View	0	Load JPG	V
20	06/04/18 10:59	General View	0	Load JPG	V
21	06/04/18 10:59	General View	0	Load JPG	V
22	06/04/18 10:59	General View	0	Load JPG	V
23	06/04/18 10:59	General View	0	Load JPG	V
24	06/04/18 10:59	General View	0	Load JPG	V
25	06/04/18 10:59	General View	0	Load JPG	V
26	06/04/18 10:59	General View	0	Load JPG	V
27	06/04/18 10:59	General View	0	Load JPG	V
28	06/04/18 10:59	General View	0	Load JPG	V
		General View	0	Load JPG	V
29	06/04/18 10:59		0	Load JPG	V
30	06/04/18 10:59	General View		0.0500.0000000	1000
31	06/04/18 10:59	General View	0	Load JPG	V
32	06/04/18 10:59	General View	0	Load JPG	V
33	06/04/18 10:59	General View	0	Load JPG	~

Merimen e-Claims Page 2 of 2

Ass	essment Reports		1 per	page 🔻	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
34	06/04/18 10:59	General View	0	Load JPG	V
35	10/08/18 13:55	Dismantled Parts	0	Load PDF	
Doc	cumentation		1 per	page 🔻	~
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	20/12/17 10:56	TP GIA REPORT	0	Load PDF	10000000
2	21/12/17 13:44	EMAIL to TP reject their list of surveyor	0	Load PDF	22 2
3	21/12/17 13:44	TP workshop contact	0	Load PDF	
4	06/08/18 18:14	LOD with supporting documents	0	Load PDF	
5	06/08/18 18:14	TPD SFW4381G - COLOUR PHOTO	0	Load PDF	
6	06/08/18 18:14	TPD SFW4381G - COLOUR PHOTO	0	Load PDF	
7	06/08/18 18:14	TPD SFW4381G - COLOUR PHOTO	0	Load PDF	
8	10/08/18 14:30	instruction to LKK to prepare paper survey report	0	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/08/18 11:05	COLOUR PHOTO	0	Load PDF	
2	21/08/18 11:05	PRS Invoice	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/MSG17024241/BTD3E2-1

Date:

21/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

A80426602QMX

Claimant Vehicle SFW4381G

Insured Vehicle No:

SKG6802X

No: Date of Loss:

18/12/2017

Nature of Claim:

TP

Claim No: 541560

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SFW4381G

Make & Model:

NISSAN SUNNY, 1.6 EX (A)

Engine No:

QG16378117

Reg. Date:

05/07/2005 (Man. Year: 2005)

Chassis No: Odometer:

JN1CFAN16Z0512224 293058 km

Colour:

Silver 1597 cc

Engine Capacity: Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

185/65 R15

Rear Tyre Size:

185/65 R15

Front Left Side:

Linglong 4 mm

Rear Left Side:

Michelin 2 mm

Front Right Side:

Linglong 4 mm

Rear Right Side:

No

Michelin 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,082.75	5,371.80	2,710.95	33.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,510.00	2,490.00	2,020.00	44.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,592.75	7,861.80	4,730.95	37.57
Approved Total (Overridden) (S\$)		6,250.00		
(S\$)	12,592.75	6,250.00	6,342.75	50.37
+ GST 7.00/7.00% (S\$)	881.49	437.50	443.99	50.37
Nett Amount (S\$)	13,474.24	6,687.50	6,786.74	50.37

INSPECTION

Date of Assignment:

21/12/2017

Date Inspected:

21/12/2017 Inspected At:

Em-1 Auto Pte Ltd (HQ)

Blk 8 Sin Ming Industrial Estate Sector C,

#01-68

Singapore 575643

Estimated Period of Repair:

7.0 days

Adjuster: Lim Teow Guan Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Aug 2018)

Parts: 143 NISSAN SUNNY 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFW4381G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages running page.

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TRUNK LID	Dented / Buckled	613.30 FL	*613.30 F
2	1		*TRUNK LID NISSAN EMBLEM	Necessary	46.10 FL	*46.10 F
3	1		*TRUNK LID SUNNY EMBLEM	Necessary	80.90 FL	*80.90 F
4	1		*TRUNK LID EX SALOON EMBLEM	Necessary	95.70 FL	*95.70 F
5	1		*TRUNK LID CVTC EMBLEM	Necessary	52.80 FL	
6	1		*TRUNK LID E-THROTTLE PLATE	Necessary	52.80 FL	
7	1		*TRUNK LID UPPER CHROME FINISHER	Holder Broken		*369.10 F
8	2		*REAR LICENSE PLATE LAMP	Serviceable	156.80 FL	*-F
9	1		*TRUNK LID LOWER CHROME FINISHER	Holder Broken		*208.90 F
10	1		*SET TRUNK LID CHROME FINISHER CLIP	Necessary	40.00 FL	
11	1		*TRUNK LID INNER TRIM	Serviceable	212.50 FL	*-F
12	1		*SET TRUNK LID INNER TRIM CLIP	Necessary	50.00 FL	
13	1		*TRUNK LID HINGE - O/S	Serviceable	87.60 FL	*-F
14	1		*TRUNK LID HINGE - N/S	Serviceable	87.60 FL	*-F
15	1		*TRUNK LID LOCK ASSEMBLY	Bent / Twisted	96.30 FL	
16	1		*SPARE WHEEL FLOOR PANEL	Repair	688.20 FL	*-F
7	1		*SPARE WHEEL CLAMP BRACKET	Serviceable	41.60 FL	*-FI
8	1		*SPARE WHEEL BOARD	Chipped / Cracked		*192.10 F
19	1		*TRUNK COMPARTMENT SIDE TRIM - O/S	Serviceable	362.20 FL	*-FI
20	1		*TRUNK COMPARTMENT SIDE TRIM - N/S	Cracked / Torn		*362.20 FI
21	2		*SET TRUNK COMPARTMENT TRIM CLIP	Necessary	80.00 FL	*60.00 FI
22	1		*REAR END PANEL	Badly Dented / Distorted		*335.60 FI
3	1		*REAR END PANEL INNER TRIM	Cracked / Torn		*125.30 FI
4	1		*REAR END PANEL TOP GARNISH	Deformed / Warped		*132.20 FI
5	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	40.00 FL	*30.00 FL
6	1		*TRUNK LID WEATHERSTRIP	Deformed / Kinked	139.60 FL	
7	1		*REAR COMBINATION LAMP - O/S	Len Cracked	360.20 FL	
8	1		*REAR COMBINATION LAMP - N/S	Housing Cracked	360.20 FL	
9	2		*REAR COMBINATION LAMP RUBBER SEAL	Necessary	50.00 FL	*50.00 FL
0	2		*REAR COMBINATION LAMP GROMMET	Necessary	51.40 FL	*51.40 FL
1	1		*REAR FENDER DRAFTER DUCT - N/S	Serviceable		0.072416637763
2	1		*REAR BUMPER FASCIA	Badly Dented /	50.30 FL	*-FL
				Deformed	452.50 FL	452.50 FL
3	1		*SET REAR BUMPER CLIP	Necessary	60.00 FL	*40.00 FL
4	1		*REAR BUMPER CHROME MOULDING	Deformed	175.20 FL	
5	1		*REAR BUMPER ENERGY ABSORBER	Cracked / Torn	126.40 FL	
6	1		*REAR BUMPER UPPER BRACKET - O/S	Holder Broken	36.10 FL	*36.10 FL
7	1		*REAR BUMPER UPPER BRACKET - N/S	Cracked / Broken	36.10 FL	*36.10 FL
8	1		*REAR BUMPER STAY - O/S	Bent Broken	86.60 FL	*86.60 FL
			Report was unsubmitted during		00.00 FL	00.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*REAR BUMPER STAY - N/S	Badly Dented	86.60 FI	*86.60 FI
40	1		*REAR BUMPER SIDE BRACKET - O/S	Holder Broken	46.20 FL	00.0011
41	1		*REAR BUMPER SIDE BRACKET - N/S	Holder Broken	46.20 FL	
42	1		*REAR BUMPER CLOSING SHIELD - O/S	Holder Snapped		
43	1		*REAR BUMPER CLOSING SHIELD - N/S	Deformed / Grazed	25.20 FL	
44	2		*SET REAR BUMPER CLOSING SHIELD CLIP	Necessary	25.20 FL	20.2012
45	1		*TRUNK LID INNER SEALER	Necessary	40.00 FL	00.001 L
46	1		*REAR LICENSE PLATE WITH CASING	Serviceable	80.00 FS	
47	2		*SPARE WHEEL FLOOR PANEL JOINT SEALANT	Necessary	70.00 FS	
48	1		*SPARE WHEEL FLOOR PANEL INSULATOR PAD	Necessary		*100.00 FS
49	1		*SPARE WHEEL CLAMP	Serviceable	44.00.50	90000
50	1		*REAR END PANEL JOINT SEALANT	Necessary	44.30 FS	
51	1		*BREAKDOWN SIGN	Cracked / Broken	80.00 FS	00.0010
52	1		*SET REVERSE SENSOR	N/S Dented / Malfunction	150.00 FS	
-	1		*EXHAUST MUFFLER ASSEMBLY	Repair		*200.00 FS
	3		*EXHAUST MUFFLER RUBBER MOUNTING	Serviceable	504.00 FS	*-FS
150	1		*EVHALIST MUSEL ED CARLET	Necessary	115.20 FS	*-FS
~	1			Dented / Deformed	41.60 FS	*41.60 FS
57	1		*TRUNK LID LOCK STRIKER	Serviceable		*152.90 FS
=Fran	chise p	art. S=Sp	cNett, L=ListItemDisc.	,	63.70 FL	*-FL
			Light Home Dis-	Sub Total (S\$)	8,775.50	5,881.50
			- List Item Discount on L	tems 10.00/10.00% (S\$)	692.75	509.70
				Total Parts (S\$)	8,082.75	5,371.80
			Report was unsubmitted during th	is print out		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Dani- I	
Lab	our Items	Lub. Type	Repairer's	Amoun
1	TO CUT / WELD SPARE WHEEL FLOOR PANEL, REAR END PANEL TO RENEW AND REPLACE REAR ACCIDENT DAMAGED PARTS	New	1,800.00	1,100.00
2	TO TRANSFER TRUNK LID LOCKING MECHANISM AND OTHER COMPONENTS TO NEW TRUNK LID INCLUDE CHECKING COMPONENTS FOR FUNCTION	New	120.00	60.00
3	TO REMOVE / INSTALL REAR SEAT, TRUNK COMPARTMENT TRIM FINISHERS, GARNISHES AND INTERIOR UPHOLSTERY TO FACILITATE THE REPLACEMENT OF SPARE WHEEL FLOOR PANEL AND REAR END PANEL	New	250.00	80.00
4	TO REMOVE / INSTALL FUEL TANK ASSEMBLY AND FITTINGS TO FACILITATE THE REPLACEMENT OF THE SPARE WHEEL FLOOR PANEL INCLUDE CHECKING SYSTEM FOR LEAKS	New	150.00	0.00
5	TO CHECK REAR LIGHTINGS AND ELECTRICAL WIRING	New		
	TO THE TOTAL PERFORMING WATER I FAVACE TEST	New	80.00	30.00
	BUMPER FASCIA INCLUDE TESTING FOR FUNCTIONS	New	120.00	50.00
	TO REMOVE / INSTALL EXHAUST PIPING SYSTEM TO REPLACE EXHAUST MUFFLER ASSEMBLY INCLUDE CHECKING SYSTEM FOR LEAKS	New	150.00	70.00
	TO PUTTY AND RE-SPRAY PAINTING ON TRUNK LID, SPARE WHEEL FLOOR PANEL, REAR END PANEL, RIGHT REAR FENDER, LEFT REAR FENDER AND REAR RUMPER FASCIA	New	1,680.00	1,000.00
	RUST-PROOFING ON THE REAR ACCIDENT AFFECTED	New	160.00	100.00
	Gross Labour C	Cost (S\$)	4,510.00	2,490.00
	Report was unsubmitted during this			

< END OF ESTIMATES >