



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates		H 7008 Z
(a) Cost / List Price Items	\$	4,726.37
Plus/Less25%	\$	1,181.59
Total of Cost / List	\$	3,544.78
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items	\$	200.00
Parts Cost	\$	3,744.78
ır	\$	2,360.00
	\$	6,104.78
	(a) Cost / List Price Items Plus/Less	(a) Cost / List Price Items \$ Plus/Less 25% \$ Total of Cost / List \$ (b) Nett Price Items Less Total of Nett Item (c) Special Nett Items \$ Parts Cost \$

Not Rothories
Remy B4 pains

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

	_	
ne of Surveyor	:	Kennoth
npany	;	
vey conducted on	:	at
narks By Surveyor		
The repair of this vehicle is author	rized	is not authorized until further notice.
Recommended Days of Repair		day(s)
Resurvey	:	Required / Not Required
Excess	:\$_	Pa 04/92 8 27/8/18
Signature of surveyor	:	Date:
	npany vey conducted on narks By Surveyor The repair of this vehicle is author Recommended Days of Repair Resurvey Excess	rey conducted on rearks By Surveyor The repair of this vehicle is authorized and Recommended Days of Repair Resurvey Excess Santage Surveyor Resurvey



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No.

SLH 7008 Z

Make & Model: Chassis No

TOYOTA PRIUS JTDKB3FU503537444

Submit By

Year Manufacture

Carmen Lim

2016

Engine No.

Cost / List

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	Shan	1	\$200.00	S.N	
2	Rear bumper	Res	1	\$497.50		
3	Rear bumper clip	ne	10	\$40.00		
4	Rear bumper side retainer LH	Sinc	1	\$112.70		X
5	Rear bumper side retainer RH	Mc	1	\$112.70		X
6	Rear bumper reinforcement		1	\$398.90		7
7	Rear bumper lower garnish centre	DUIDY	1	\$582.60		
8	Rear bumper lower garnish RH	Sm	1	\$149.70		X
9	Rear bumper under cover	Su	1	\$355.20		X
10	Rear bumper under cover LH	Sin	1	\$187.60		×
11	Rear bumper under cover RH	Sn	1	\$187.60		×
12	Rear bumper under cover clip	22	4	\$14.00		X
13	Tail door emblem	na	1	\$61.70		
14	Wording "PRIUS"	Na	1	\$51.90		
15	Wording "HYBRID"	M	1	\$55.47		_
16	Tail door plate garnish	Sm	1	\$782.50		×
17	Tail end panel	n	1	\$596.60		×
18	Tail end panel garnish	Sm	1	\$151.60		×
19	Tail end panel garnish clip	n	10	\$35.00		*
20	Boot weatherstrip	Ju	1	\$353.10		X
21						
22						
23						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829 Company Reg No. 200005485N / GST No. 20-0005485-N



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No.	:	SLH 7008 Z	Submit By :	Carmen Lim	
Make & Model	:	TOYOTA PRIUS	Year of Manufacture:	2016	

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL)	\$1,000.00	4001
2	TO BUTTY DESDRAY BAINT FOR AFFECTED ACCIDENT		
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL)	\$800.00	4401
3	To check wiring	\$50.00	15/
4	To remove & refit reverse sensor	\$120.00	501
5	To remove & refit spare tyre, spare tyre board, carpet trim		
	to assist work load.	\$150.00	X
6	To tuff coat.	\$120.00	Х
7	To conduct water leakage tests to ensure proper air and		
	sealing	\$120.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.