

REF: CCL/ASM/8014611/RIFb352

Special Instruction:

From (Person): Tan Wunwun of Asm Date/Time: 01-11-2018
Estimated Cost: _____ Bill to: _____

4/3: \$ 40750.00

Third Parties:

Claimant:

Surveyor: Constant Appraiser

Workshop: FGS Tech Auto

$$\text{OD}(\overline{\text{TP Re-inspection}}) / \text{Evaluation}$$

To Inspect Vehicle No: SKW 3851 P Insured: SMP 7651 R

at Workshop m/s Fastech Auto Tel:
of Blk 1 Kaki Bukit Ave 6 # 01-45

Policy No: _____ Claim No: SSM00R8Z

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 05082018
(Client's Record)

02.11.2018 (Friday) @ 12pm

H.O.D, Enrôlement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig. _____, _____ days (Red \$ _____ / _____ %; Original 12 days)

Date/Time: _____ Submit Final Fig \$30,300.00, 12 days (Red \$ 10,350.00 / 25.40 %; Original _____ days)

[illegible]

Para(1) : Parts found not replaced	(To highlight <i>R or UB, LR, Etc</i>)
------------------------------------	---

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)
--

R1 - \$2w

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Date: _____

Basic & Add

Transport

Photos

Others

Total

1) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time: _____ File Return to: _____

REF:

7288C

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKW 3851P Yr Regn: 2015 OCTType: C M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Volkswagen Golf A71-K c.c. 1395Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 8032/84926 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: www 222 A4 2FW 357843Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orModi: Nil / C / STD A/Rim orTyre Size: F: 225/40ZR18R: "BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 05/08/18

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 02/11/18Survey held at PMTECHDes. of Damages: Frt / Rear / O/S / N/A / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

1st 30,300.00 (Rd 16,350.00/25.40%)

\$200.00 //

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + FS \$

) Photos

) Others

) -

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)

MAHADI ABU BAKAR & PARTNERS

ADVOCATES & SOLICITORS

(UEN No. 53179837B)

#14-01, TONG ENG BUILDING, 101 CECIL STREET SINGAPORE 069533

TEL: 62252355 FAX: 62279913 email: mab_law06@yahoo.com.sg

OUR REF: MAB/10697/18/zila

29 October 2018

Claims Department
AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01/02 Singapore 068811
Your ref no.: S8M00R8ZMC/WG

BY EMAIL ONLY
shekhar.batham@axa.com.sg
mary.chia@axa.com.sg

SEAH ONG & PARTNERS LLP
36 Robinson Road
#12-03 City House
Singapore 068877

BY EMAIL ONLY
cheekiong@seahong.com.sg
xinyi@seahong.com.sg
samson@seahong.com.sg

Dear Sir/Mdm

URGENT

CLAIMANT: MR CHOO MUI YONG


ACCIDENT INVOLVING SMA 7651 R & SKW 3851 P ALONG SELETAR AEROSPACE DRIVE
ON 05/08/2018 AT 1.45 AM

We refer to the above matter and to your email dated 04/10/2018.

Please note that we have our client's instructions to arrange for the re-inspection on 02/11/2018 - Friday at 11.30 am at M/s Fastech Auto Pte Ltd [1 Kaki Bukit Avenue 6 #01-46/48/50 AutoBay Singapore 417883]. Kindly contact Mr Spencer Giam of motor-workshop M/s Fastech Auto Pte Ltd at office no. 6746 5405.

Kindly confirm in writing the date, time, venue and the name and contact details of surveyor for the re-inspection of motorcar no. SKW 3851 P as soon as possible so that we can inform our client accordingly.

Yours faithfully



cc. 1) Client

2) M/S FASTECH AUTO PTE LTD
ATTN: MR SPENCER GIAM
(Your ref no. SKW 3851 P) - For your attention

BY EMAIL ONLY
spencer@fastechauto.com.sg

MAHADI ABU BAKAR & PARTNERS

ADVOCATES AND SOLICITORS

#14-01 TONG ENG BUILDING, 101 CECIL STREET, SINGAPORE 069533

TEL: 62252355

FAX: 62279913

Email: mab_law06@yahoo.com.sg

3 0 1 9 5 3 9 1 2 1 - - -

YOUR REF: SMA 7651 R

03 OCT 2018

28 September 2018

OUR REF: MAB/10697/18/ana

60112399

HITACHI CAPITAL ASIA PACIFIC PTE LTD

111 Somerset Road

#14-05-15, Tripleone Somerset

Singapore 238164

WITHOUT PREJUDICE

Certificate of Posting

URGENT

Dear Sir/Madam

PROPERTY DAMAGE CLAIM BY CHOO MUI YONG OF BLK 117C RIVERVALE DRIVE #12-50 SINGAPORE 543117

We are instructed by the above named to claim damages against you in connection with a road traffic accident on 05/08/2018 at about 1.45 am involving our client's motorcar no. SKW 3851 P and motorcar no. SMA 7651 R driven by your driver, Lim Yong Seng Stephen at the material time.

We are instructed that the accident was caused by your negligent driving and/or management of the motorcar no. SMA 7651 R.

As a result of the accident, our client's motorcar was damaged and our client has been put to great loss and expenses, particulars of which are as follows:-

1)	Cost of Repair for motorcar SKW 3851 P (inclusive of 7% GST)	\$43,602.50
2)	Loss of Rental (14 days x \$100.00 per day)	\$ 1,400.00
3)	Legal costs	\$ 1,800.00
4)	Disbursements:-	
	a) LTA search fee	\$ 7.49
	b) GIA search fee	\$ 2.00
	c) Survey Report fee	\$2,189.00
	d) Miscellaneous	\$ 100.00
		\$ 2,298.49
		\$49,100.99

Copies of the following documents supporting the claim have been forwarded to your insurers, *M/s AXA Insurance Pte Ltd*, with a copy of this letter. You may obtain the same from them if you wish so.

1. GIA Accident Report lodged by driver of SKW 3851 P
2. GIA Accident Report lodged by driver of SMA 7651 R

3. Tax Invoice for Cost of Repair from M/s Fastech Auto Pte Ltd dated 28/09/2018
4. Invoice Survey Report from Constant Appraiser Services dated 03/09/2018
5. Rental Agreement from M/s Dynamic Car Rental dated 30/08/2018
6. Certificate of Insurance
7. LTA search and all receipts incurred so far.

The demand herein is in respect of our client's claim for damages pertaining to his Cost of Repair and Loss of use of his motorcar no. SKW 3851 P and/or Rental and any settlement following or subsequent to this demand **shall not** prejudice the driver's claim in respect of his personal injuries and consequential loss.

Please note that if your driver is insured and wish to claim under the insurance policy, your company should immediately pass this letter to the insurer. Please note that your company or your insurer should send to us an acknowledgement of receipt of this letter **within 14 days of your receipt of this letter.**

Should your company fail to acknowledge receipt of this letter **within 14 days**, our client can commence court proceedings against your company without further notice to you or your insurer.

Please also note that if you have a counterclaim against our client arising out of the accident, you are required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents **within 8 weeks of your receipt of this letter.**

Kindly note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Yours faithfully



enc
cc

- 1) Client
- 2) Claims Department
AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way, #24-01
AXA Tower, Singapore 068811
(Your insured vehicle no. SMA 7651 R)



WITHOUT PREJUDICE
BY HAND

- 3) M/S FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48
Autobay Singapore 417883
BY HAND
(Your insured vehicle no. SKW 3851 P)

WITHOUT PREJUDICE



Service Request Details

Claim

S8M00R8Z

Reference

None 

Loss Date

August 5, 2018

Request Date

November 1, 2018

Due Date

November 9, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Re-inspection

12pm.

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKW3851P

Make

TPVD VOLKSWAGEN

Model

GOLF A7 1.4 TSI (DSG)RECAT EQP

Service Address

111 SOMERSET ROAD, , 238164

Primary Contact/Insured

HITACHI CAPITAL ASIA PACIFIC PTE LTD

111 SOMERSET ROAD, #14-05 TRIPLEONE SOMERSET, 238164, Singapore

67346835

gary.yeo.zihui@simedarby.com.sg

Claim Handler

TAN Wancong

tan.wancong@axa.com.sg

Additional Instructions

Please conduct RI on TP vehicle

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Enquire Vehicle & Owner Information (Vehicle No. SMA7651R As At 05 Aug 2018 / 01:45:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: MAB/10697/18

Current Owner Details

Owner ID Type: Company

Owner ID: 199400399N

Owner Name: HITACHI CAPITAL ASIA PACIFIC PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 111

Registered Street Name: SOMERSET ROAD

Registered Unit No.: # 14 - 05-15

Registered Building Name: TRIPLEONE SOMERSET

Registered Postal Code: 238164

Current Vehicle Details

Vehicle No.: SMA7651R

Make Description/Model: AUDI / Q5 SPORT 2.0 TFSI QU S TRONIC

Insurance Company Name: AXA INSURANCE PTE LTD



Thank you

Mahadi Abu Bakar has successfully logged out.

Your last login date and time was 16 Aug 2018, 15:46:37.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	SMA7651R-		18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	16 Aug 2018 / 15:47:28



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-124657

Date of Request: 14/08/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 14/08/2018
Enquiry By Tang Kok Wee, Allan
TP Vehicle No. SMA7651R
Accident Date 14/08/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SMA7651R	AXA Insurance Pte Ltd	18/06/2018-17/06/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-124657
Date of Request: 14/08/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 14/08/2018
Enquiry By Tang Kok Wee, Allan
TP Vehicle No. SMA7651R
Accident Date 14/08/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

TAX INVOICE

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax.Reg No: 200006262D

CHOO MUI YONG

BLK 117C RIVERVALE DRIVE

#12-50

Singapore 543117

Attn: Motor Claim Department

Tax Invoice : 20491

Date: 28.09.2018

Vehicle No: SKW3851P

Make/Model: VOLKSWAGEN GOLF 1.4

Accident Date: 06.08.2018

Claim No : 0818-20491

Reference :

Policy No :

		Amount
To proceed on lump sum repair	S\$	40,750.00

E. & O. E.

Total : S\$ 40,750.00

GST @ 7% : S\$ 2,852.50

Amount Due : **S\$ 43,602.50**


for FASTECH AUTO PTE LTD

All Invoices are subjected to GST

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

INVOICE

To: Choo Mui Yong
Blk 117C Rivervale Drive
#12-50
Singapore 543117

Date : 03/09/2018

Invoice No : IV18-09002/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of: Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle SKW 3851P (Inclusive Of Photographs And Transport Charges) Our reference : CAS/18-09/002	\$2,189.00
Total	\$2,189.00

E. & O.E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: Choo Mui Yong
Blk 117C Rivervale Drive
#12-50
Singapore 543117

Date : 03/09/2018

Reference No : CAS/18-09/002

General Information

Registration No. : SKW 3851P
Accident Date : 05/08/2018

Particulars of Damaged Vehicle

Colour	: White	Make & Model	: Volkswagen Golf A7
Engine Capacity	: 1395 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 8032684926	Engine No.	: CXS150106
Chassis No.	: WVWZZZAUZFW357843	Steering	: Affected
Registration Date	: 28/10/2015	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	225/40R18	PIRELLI	60%
L/H Front Tyre	225/40R18	PIRELLI	60%
R/H Rear Tyre	225/40R18	PIRELLI	60%
L/H Rear Tyre	225/40R18	PIRELLI	60%

Inspection

Repairer : Fastech Auto Pte Ltd
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, Singapore 417883

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$62,393.01
Revised Amount : \$40,750.00
Less Excess : -
Nett Total : \$40,750.00

Remarks

- (A) Survey was done on 20/08/2018
- (B) Re-survey was done on 23/02/2018
- (C) Re-survey after repair was done on 30/08/2018
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Constant Appraiser Services

Vehicle No : SKW 3851P

Our ref : CAS/18-09/002

Adjustment On Repair Costs And Replacement Of Parts:

9722.26

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>PARTS REPLACEMENT – LIST ITEMS</u>			
1	1pc	Front bonnet	Dented/Buckled	991.50	991.50
2	1pc	Front bonnet lock	Bent/Jammed	261.45	261.45 X NH
3	1pc	Front bonnet lock catch	Serviceable	112.50	-
4	1pc	Front bonnet damper	Serviceable	241.62	-
5	1pc	Front bonnet insulator	Distorted	274.85	274.85 X NH
6	12pcs	Front bonnet insulator clip @ \$4.50	Necessary	54.00	54.00
7	2pcs	Front bonnet hinge @ \$55.00	Bent	110.00	110.00
8	1pc	Front bonnet seal – ctr	Necessary	48.85	48.85
9	2pcs	Front bonnet seal @ \$48.85	Necessary	97.70	97.70
10	1pc	Front bumper	Broken	1,076.45	1,076.45
11	6pcs	Front bumper PDC sensor @ \$208.85	3pcs Damaged	1,253.10	626.55
12	1pc	Front bumper grille	Deformed/Broken	168.95	168.95
13	2pcs	Front bumper side grille @ \$68.85	Grazed/Deformed	137.70	137.70
14	2pcs	Front bumper fog lamp @ \$230.15	N/S Broken	460.30	230.15
15	1pc	Front bumper sponge	Broken	154.05	154.05
16	1pc	Front bumper reinforcement	Dented/Bent	581.95	581.95
17	2pcs	Front bumper side retainer @ \$58.85	Broken	117.70	117.70
18	1pc	Front bumper spray nozzle cover	Broken	28.15	28.15
19	1pc	Front fender LH	Dented/Buckled	547.75	547.75
20	1pc	Front fender stay	Bent	59.50	59.50
21	1pc	Front fender wheel housing	Repair	1,055.00	-
22	2pcs	Front fender inner shield @ \$247.15	N/S Torn	494.30	247.15
23	30pcs	Front fender inner shield clip @ \$4.50	Necessary	135.00	135.00
24	2pcs	Front fender inner shield extension @ \$89.95	Torn	179.90	179.90
25	1pc	Front door LH	Dented/Warped	1,878.25	1,878.25
26	1pc	Front door outer handle	Grazed/Bent	182.60	182.60 X NH
27	1pc	Front door side mirror assy	Grazed/Broken	908.60	908.60
28	1pc	Front door glass outer moulding	Twisted	180.26	180.26
29	1pc	Front door glass run channel	Necessary	241.65	241.65 X
30	1pc	Front door glass regulator	Bent	396.40	396.40 X NH
31	1pc	Front door glass regulator motor	Damaged	365.50	365.50 X
32	1pc	Front door inner lock	Bent/Jammed	431.55	431.55 X
33	1pc	Front door inner board	Broken	979.55	979.55

Constant Appraiser Services

Vehicle No : SKW 3851P

Our ref : CAS/18-09/002

15/11/18.10

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>PARTS REPLACEMENT – LIST ITEMS (CONT'D)</u>			
34	1pc	Front door weatherstr.p	Necessary	241.65	241.65
35	1pc	Front door checker	Bent	89.55	89.55 X
36	2pcs	Front door hinge @ \$35.00	Bent	170.00	170.00 X
37	1pc	Front support panel	Broken	1,087.45	1,087.45
38	1pc	Front shock absorber LH	Bent	418.95	418.95
39	1pc	Front shock absorber top mount	Distorted	159.65	159.65
40	1pc	Front lower arm	Bent	376.75	376.75
41	1pc	Front knuckle arm	Bent	616.45	616.45
42	1pc	Front wheel sport rim	Grazed/Cut	1,313.95	1,313.95
43	1pc	Front wheel hub with bearing	Bent/Necessary	416.95	416.95
44	1pc	Front drive shaft	Bent	2,229.95	2,229.95
45	1pc	Front anti roll bar	Bent	398.95	398.95 X
46	1pc	Front anti roll bar link LH	Bent	103.75	103.75 X
47	1pc	Front steering rack assy	Bent/Jammed	4,921.65	4,921.65
48	1pc	Front steering rack crossmember	Dented/Bent	981.65	981.65 X
49	1pc	Front grille	Broken	414.30	414.30
50	1pc	Front grille logo	Necessary	112.60	112.60
51	2pcs	Front headlamp @ \$1,955.35	Broken	3,910.70	X 3,910.70
52	2pcs	Front headlamp HID bulb @ \$510.65	N/S Broken	1,021.30	510.65
53	2pcs	Front headlamp control unit RH @ \$970.85	Serviceable	1,941.70	-
54	2pcs	Front headlamp control unit LH @ \$970.85	Damaged	1,941.70	X 1,941.70
55	1pc	Front headlamp LED light LH	Broken	816.55	816.55
56	2pcs	Front headlamp top panel @ \$95.25	N/S Twisted	190.50	95.25
57	1pc	Front headlamp wire harness LH	Broken	241.65	241.65
58	1pc	Front headlamp spray nozzle LH	Broken	167.25	167.25
59	1pc	Air con condenser	Twisted	587.85	587.85
60	1pc	Air con discharge pipe	Serviceable	341.60	-
61	1pc	Air con suction pipe	Serviceable	321.50	-
62	1pc	Air con liquid pipe	Serviceable	211.40	-
63	1pc	Air intercooler	Dented	575.65	575.65
64	1pc	Radiator assy	Broken/Twisted	625.25	625.25
65	1pc	Radiator lower member	Missing	261.50	261.50
66	1pc	Radiator top hose	Serviceable	81.65	-
67	1pc	Radiator bottom hose	Serviceable	89.90	-

Constant Appraiser Services

Vehicle No : SKW 3851P

Our ref : CAS/18-09/002

7942

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>PARTS REPLACEMENT - LIST ITEMS (CONT'D)</u>			
68	1pc	Radiator auxiliary fan assy	Serviceable	1,371.65	-
69	1pc	Engine undercover	Torn	297.15	297.15
70	2pcs	Horn @ \$89.50	N/S Damaged	179.00	89.50
71	1pc	Washer tank	Deformed	202.55	202.55
72	1pc	Washer tank neck	Deformed	126.20	126.20
73	2pcs	Washer tank motor @ \$171.65	Damaged	343.30	343.30 X NH
74	1pc	Engine mounting RH	Serviceable	262.55	-
75	1pc	Engine mounting LH	Torn	422.45	422.45 X NH
76	1pc	Engine mounting rear	Torn	197.75	197.75 X NH
77	1pc	Rear bumper repair	Grazed/Deformed	1,056.55	R 1,056.55
78	1pc	Rear bumper reflector LH	Serviceable	81.55	-
79	2pcs	Rear bumper PDC sensor LH @ \$208.85	Damaged	417.70	X 417.70
80	1pc	Rear bumper side retainer LH	Broken	45.50	X 45.50 NH
81	1pc	Rear fender LH	Dented/Warped	1,632.85	1,632.85
82	1pc	Rear fender inner panel	Repair	1,020.65	-
83	1pc	Rear fender inner shield	Distorted	214.60	214.60
84	15pcs	Rear fender inner shield clip @ \$4.50	Necessary	67.50	67.50
85	1pc	Rear door LH	Dented/Warped	1,988.45	1,988.45
86	1pc	Rear door outer handle LH	Grazed/Jammed	159.50	X 159.50 NH
87	1pc	Rear door ¼ glass rubber LH	Necessary	89.15	89.15
88	1pc	Rear door glass outer moulding LH	Necessary	160.95	160.95
89	1pc	Rear door glass run channel LH	Necessary	251.10	X 251.10
90	1pc	Rear door glass regulator LH	Bent	391.60	X 391.60 NH
91	1pc	Rear door glass regulator motor LH	Damaged	365.50	X 365.50
92	1pc	Rear door inner lock LH	Bent/Jammed	411.25	X 411.25
93	1pc	Rear door inner board LH	Broken	971.65	X 971.65
94	1pc	Rear door weatherstrip LH	Necessary	231.50	231.50
95	1pc	Rear door checker LH	Bent	89.55	X 89.55 NH
96	2pcs	Rear door hinge LH @ \$85.00	Bent	170.00	X 170.00
97	1pc	Rear shock absorber LH	Bent	263.30	263.30
98	1pc	Rear top arm LH	Serviceable	287.75	-
99	1pc	Rear lower arm LH	Bent	289.75	289.75
100	1pc	Rear knuckle arm LH	Bent	765.75	765.75
101	1pc	Rear wheel sport rim LH	Grazed/Cut	1,313.95	1,313.95

Constant Appraiser Services

Vehicle No : SKW 3851P

Our ref : CAS/18-09/002

479.75

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – LIST ITEMS (CONT'D)</u>					
102	1pc	Rear wheel hub with bearing LH	Bent/Necessary	479.75	479.75
103	1pc	Rear trailing arm LH	Bent	448.55	X 448.55 NH
104	1pc	Rear anti roll bar	Serviceable	431.50	-
105	1pc	Rear anti roll bar link LH	Serviceable	103.75	-
			37262.11	59,192.23	49,436.71
		Less 10%	16%	(5,919.22)	(4,943.67)
		Sub total	33535.89	53,273.01	44,493.04
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>					
1	1pc	Rear tyre LH	Cut (60%)	450.00	X 270.00 NH
2	1pc	Front tyre LH	Cut (60%)	450.00	X 270.00 NH
3	4ltrs	Auto TX oil @ \$30.00	Necessary	120.00	80 120.00
4	1bot	Brake fluid	Necessary	40.00	40.00
5	1bot	Air con oil	Necessary	60.00	60.00
6	1bot	Radiator coolant	Necessary	60.00	60.00
		Sub total		54,453.01	45,313.04
<u>LABOUR & MISC. CHARGES</u>					
1		Towing charges		120.00	60.00
2		To remove, refix front undercarriage		650.00	300 450.00
3		To remove, refix rear undercarriage		350.00	100 200.00
4		To check wheel alignment		120.00	60 80.00
5		To check front & rear electrical wiring		120.00	50.00
6		To remove, refix A/C condenser & refill A/C gas		180.00	100 120.00
7		To respray undercoating		250.00	80 150.00
8		To remove, refix front & rear interior trims to assist repair		150.00	60 120.00
9		To remove, refix engine parts		300.00	X 150.00
10		To respray painting & etc		2,200.00	1,800.00
11		Panel beating, cut, weld, remove & replacing above parts		3,500.00	1600 2,400.00
		Grand total		62,393.01	50,893.04
Recommended cost of lump sum repair (To its pre-accident condition)				4310	40,750.00

Constant Appraiser Services

Vehicle No : SKW 3851P

Our ref : CAS/18-09/002

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$40,750.00** on a contractual basis. Under normal circumstances, the repair period would be about **12 (Twelve)** working days.

Yours faithfully,

Constant Appraiser Services



Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA

33535.89
240.00
4310.00

38,085.89
20%
30,468.71

48 - 30,400

12 days
=

repair limit 12k



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18014611/R1fb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN: TAN WANCONG

Date : 18-06-2019

Code : ASM



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMA 7651R	Veh. Inspected	SKW 3851P
Policy No.	VPX/P2154975	Coverage (\$)	0.00
Claim No.	S8M00R8Z	Excess (\$)	0.00
Assign From	TAN WANCONG	Assign Date	01/11/2018

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN GOLF A7 1.4	c.c	1395
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WVWZZZAUZFW357843	Colour	WHITE
Odometer	84926	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40ZR18	PIRELLI	6 mm
L/H Front Tyre	225/40ZR18	PIRELLI	6 mm
R/H Rear Tyre	225/40ZR18	PIRELLI	6 mm
L/H Rear Tyre	225/40ZR18	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.
REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	05/08/2018	Inspection Date	02/11/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 3851P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	REPLACED	991.50	991.50
1	FRONT BONNET LOCK	NOT CHANGED	261.45	-
1	FRONT BONNET LOCK CATCH	SERVICEABLE	112.50	-
1	FRONT BONNET DAMPER	SERVICEABLE	241.62	-
1	FRONT BONNET INSULATOR	NOT CHANGED	274.85	-
12	FRONT BONNET INSULATOR CLIP @ \$4.50	REPLACED	54.00	54.00
2	FRONT BONNET HINGE @ \$55.00	REPLACED	110.00	110.00
1	FRONT BONNET SEAL - CTR	REPLACED	48.85	48.85
2	FRONT BONNET SEAL @ \$48.85	REPLACED	97.70	97.70
1	FRONT BUMPER	REPLACED	1,076.45	1,076.45
6	FRONT BUMPER PDC SENSOR @ \$208.85	REPLACED 3PCS ONLY	1,253.10	626.55
1	FRONT BUMPER GRILLE	REPLACED	168.95	168.95
2	FRONT BUMPER SIDE GRILLE @ \$68.85	REPLACED	137.70	137.70
2	FRONT BUMPER FOG LAMP @ \$230.15	N/S REPLACED	460.30	230.15
1	FRONT BUMPER SPONGE	REPLACED	154.05	154.05
1	FRONT BUMPER REINFORCEMENT	REPLACED	581.95	581.95
2	FRONT BUMPER SIDE RETAINER @ \$58.85	REPLACED	117.70	117.70
1	FRONT BUMPER SPRAY NOZZLE COVER	REPLACED	28.15	28.15
1	FRONT FENDER LH	REPLACED	547.75	547.75
1	FRONT FENDER STAY	REPLACED	59.50	59.50
1	FRONT FENDER WHEEL HOUSING	REPAIRED SEE LABOUR	1,055.00	-
2	FRONT FENDER INNER SHIELD @ \$247.15	N/S REPLACED	494.30	247.15
30	FRONT FENDER INNER SHIELD CLIP @ \$4.50	REPLACED	135.00	135.00
2	FRONT FENDER INNER SHIELD EXTENSION @ \$89.95	REPLACED	179.90	179.90
1	FRONT DOOR LH	REPLACED	1,878.25	1,878.25
1	FRONT DOOR OUTER HANDLE	NOT CHANGED	182.60	-
1	FRONT DOOR SIDE MIRROR ASSY	REPLACED	908.60	908.60
1	FRONT DOOR GLASS OUTER MOULDING	REPLACED	180.26	180.26
1	FRONT DOOR GLASS RUN CHANNEL	NOT CHANGED	241.65	-

Report Ref No. CC4/ASM18014611/R1fb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR GLASS REGULATOR	NOT CHANGED	396.40	-
1	FRONT DOOR GLASS REGULATOR MOTOR	NOT CHANGED	365.50	-
1	FRONT DOOR INNER LOCK	NOT CHANGED	431.55	-
1	FRONT DOOR INNER BOARD	REPLACED	979.55	979.55
1	FRONT DOOR WEATHERSTRIP	REPLACED	241.65	241.65
1	FRONT DOOR CHECKER	NOT CHANGED	89.55	-
2	FRONT DOOR HINGE @ \$85.00	NOT CHANGED	170.00	-
1	FRONT SUPPORT PANEL	REPLACED	1,087.45	1,087.45
1	FRONT SHOCK ABSORBER LH	REPLACED	418.95	418.95
1	FRONT SHOCK ABSORBER TOP MOUNT	REPLACED	159.65	159.65
1	FRONT LOWER ARM	REPLACED	376.75	376.75
1	FRONT KNUCKLE ARM	REPLACED	616.45	616.45
1	FRONT WHEEL SPORT RIM	REPLACED	1,313.95	1,313.95
1	FRONT WHEEL HUB WITH BEARING	REPLACED	416.95	416.95
1	FRONT DRIVE SHAFT	REPLACED	2,229.95	2,229.95
1	FRONT ANTI ROLL BAR	NOT CHANGED	398.95	-
1	FRONT ANTI ROLL BAR LINK LH	NOT CHANGED	103.75	-
1	FRONT STEERING RACK ASSY	REPLACED	4,921.65	4,921.65
1	FRONT STEERING RACK CROSSMEMBER	NOT CHANGED	981.65	-
1	FRONT GRILLE	REPLACED	414.30	414.30
1	FRONT GRILLE LOGO	REPLACED	112.60	112.60
2	FRONT HEADLAMP @ \$1955.35	REPLACED 1PC ONLY	3,910.70	1,955.35
2	FRONT HEADLAMP HID BULB @ \$510.65	N/S REPLACED	1,021.30	510.65
2	FRONT HEADLAMP CONTROL UNIT RH @ \$970.85	SERVICEABLE	1,941.70	-
2	FRONT HEADLAMP CONTROL UNIT LH @ \$970.85	REPLACED 1PC ONLY	1,941.70	970.85
1	FRONT HEADLAMP LED LIGHT LH	REPLACED	816.55	816.55
2	FRONT HEADLAMP TOP PANEL @ \$95.25	N/S REPLACED	190.50	95.25
1	FRONT HEADLAMP WIRE HARNESS LH	REPLACED	241.65	241.65
1	FRONT HEADLAMP SPRAY NOZZLE LH	REPLACED	167.25	167.25
1	AIR CON CONDENSER	REPLACED	587.85	587.85
1	AIR CON DISCHARGE PIPE	SERVICEABLE	341.60	-
1	AIR CON SUCTION PIPE	SERVICEABLE	321.50	-

Report Ref No. CC4/ASM18014611/R1fb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR CON LIQUID PIPE	SERVICEABLE	211.40	-
1	AIR INTERCOOLER	REPLACED	575.65	575.65
1	RADIATOR ASSY	REPLACED	625.25	625.25
1	RADIATOR LOWER MEMBER	REPLACED	261.50	261.50
1	RADIATOR TOP HOSE	SERVICEABLE	81.65	-
1	RADIATOR BOTTOM HOSE	SERVICEABLE	89.90	-
1	RADIATOR AUXILIARY FAN ASSY	SERVICEABLE	1,371.65	-
1	ENGINE UNDERCOVER	REPLACED	297.15	297.15
2	HORN @ \$89.50	N/S REPLACED	179.00	89.50
1	WASHER TANK	REPLACED	202.55	202.55
1	WASHER TANK NECK	REPLACED	126.20	126.20
2	WASHER TANK MOTOR @ \$171.65	NOT CHANGED	343.30	-
1	ENGINE MOUNTING RH	SERVICEABLE	262.55	-
1	ENGINE MOUNTING LH	NOT CHANGED	422.45	-
1	ENGINE MOUNTING REAR	NOT CHANGED	197.75	-
1	REAR BUMPER	REPAIRED SEE LABOUR	1,056.55	-
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	81.55	-
2	REAR BUMPER PDC SENSOR LH @ \$208.85	REPLACED 1PC ONLY	417.70	208.85
1	REAR BUMPER SIDE RETAINER LH	NOT CHANGED	45.50	-
1	REAR FENDER LH	REPLACED	1,632.85	1,632.85
1	REAR FENDER INNER PANEL	REPAIRED SEE LABOUR	1,020.65	-
1	REAR FENDER INNER SHIELD	REPLACED	214.60	214.60
15	REAR FENDER INNER SHIELD CLIP @ \$4.50	REPLACED	67.50	67.50
1	REAR DOOR LH	REPLACED	1,988.45	1,988.45
1	REAR DOOR OUTER HANDLE LH	NOT CHANGED	159.50	-
1	REAR DOOR 1/4 GLASS RUBBER LH	REPLACED	89.15	89.15
1	REAR DOOR GLASS OUTER MOULDING LH	REPLACED	160.95	160.95
1	REAR DOOR GLASS RUN CHANNEL LH	NOT CHANGED	251.10	-
1	REAR DOOR GLASS REGULATOR LH	NOT CHANGED	391.60	-
1	REAR DOOR GLASS REGULATOR MOTOR LH	NOT CHANGED	365.50	-
1	REAR DOOR INNER LOCK LH	NOT CHANGED	411.25	-

Report Ref No. CC4/ASM18014611/R1fb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR DOOR INNER BOARD LH	NOT CHANGED	971.65	-
1	REAR DOOR WEATHERSTRIP LH	REPLACED	231.50	231.50
1	REAR DOOR CHECKER LH	NOT CHANGED	89.55	-
2	REAR DOOR HINGE LH @ \$85.00	NOT CHANGED	170.00	-
1	REAR SHOCK ABSORBER LH	REPLACED	263.30	263.30
1	REAR TOP ARM LH	SERVICEABLE	287.75	-
1	REAR LOWER ARM LH	REPLACED	289.75	289.75
1	REAR KNUCKLE ARM LH	REPLACED	765.74	765.75
1	REAR WHEEL SPORT RIM LH	REPLACED	1,313.95	1,313.95
1	REAR WHEEL HUB WITH BEARING LH	REPLACED	479.75	479.75
1	REAR TRAILING ARM LH	NOT CHANGED	448.55	-
1	REAR ANTI ROLL BAR	SERVICEABLE	431.50	-
1	REAR ANTI ROLL BAR LINK LH	SERVICEABLE	103.75	-
	LESS 10% DISCOUNT		-5,919.21	-3,707.95
			53,273.01	33,371.56
	SPECIAL NETT ITEMS			
1	REAR TYRE LH (SN)	NOT CHANGED	450.00	-
1	FRONT TYRE LH (SN)	NOT CHANGED	450.00	-
4	LTRS AUTO TX OIL @ \$30.00 (SN)	REPLACED	120.00	80.00
1	BOT BRAKE FLUID (SN)	REPLACED	40.00	40.00
1	BOT AIR CON OIL (SN)	REPLACED	60.00	60.00
1	BOT RADIATOR COOLANT (SN)	REPLACED	60.00	60.00
			1,180.00	240.00
	LABOUR			
	TOWING CHARGES.		120.00	60.00
	TO REMOVE, REFIX FRONT UNDERCARRIAGE.		650.00	300.00
	TO REMOVE, REFIX REAR UNDERCARRIAGE.		350.00	100.00
	TO CHECK WHEEL ALIGNMENT.		120.00	60.00
	TO CHECK FRONT & REAR ELECTRICAL WIRING.		120.00	50.00
	TO REMOVE, REFIX A/C CONDENSER & REFILL A/C GAS.		180.00	100.00
	TO RESPRAY UNDERCOATING.		250.00	80.00
	TO REMOVE, REFIX FRONT & REAR INTERIOR TRIMS TO ASSIST REPAIR.		150.00	60.00

Report Ref No. CC4/ASM18014611/R1fb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REFIX ENGINE PARTS.	NOT NECESSARY	300.00	-
	TO RESPRAY PAINTING & ETC.		2,200.00	1,600.00
	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER WHEEL HOUSING, REAR BUMPER AND REAR FENDER INNER PANEL.		3,500.00	1,900.00
			7,940.00	4,310.00
	GRAND TOTAL		62,393.01	37,921.56
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			30,300.00

Report Ref No. CC4/ASM18014611/R1fb3s2

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT NOT AGREED WITH OUR OFFER

MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.