

ASS. REC. BY:

REF:

CS/SPFI8014617 / Mgbez

Special Instruction:

Supervisor:

ASSIGNMENT (Office)

From (Person):

Perry He

of

SPF

Date/Time:

10082018 4:18pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

TP 982U

Insured:

63822763 / 8514276
Pension

at Workshop m/s

Ban Huck Hin

Tel:

6281 6520 / 6286 0515 Sunny

of

No. 6 Dafu Lane 4

Policy No:

Claim No:

HOMSPFETQ17300218

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

14082018

INDECO - MIKE 63822763

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

13062018 4:18pm

Person Contacted:

Raymond

Vehicle IN / OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	TP 982U
29/8/18 @ 5:07pm	revert to Perry by email.
	Material = \$19871.76; man hrs = 6.4hrs
	Exclude Material = \$1079.16; man hrs = 9 hrs

REF: SPF

ASSIGNMENT

From: _____ Date: 14082018

Estimated Cost: 00 TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: TP 982U

at Workshop m/s Bun Hock Him

of No. 6 Delta Lane A

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: TP 982U Yr Regn: /

Type: M.Car / 00 Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda C.C

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 52094 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JH2RC499K5M000022

Gen. Cond: Good / Fair / Poor / Burnt

Steering: 00 In order / Jammed / Leaked / Burnt or

Brake: 00 In order / Jammed / Leaked / Burnt or

Modi: Nil / 00 Rim / STD A/Rim or

Tyre Size: F: 120/70ZR17

R: 180/55ZR17 Dun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: 0 mm Rear: 0 mm

R/Bal. mm R/Bal. mm

L/Bal. mm L/Bal. mm

D.O.A. _____ D.O.I. 14/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S, O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
RECEIVED 05 OCT 2018	

Date/Time. File Pass to? : Preli. Report

1) 08/10 turner : Final Report

Date/Time. File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: 280

Transportation: _____

(\$ + RS. \$)

Photos: _____

Others: _____

TOTAL: 280

Add Fee: Site Insp (\$ _____)

Interview (\$ _____)

Tech. Invs (\$ _____)

Weekend (\$ _____)

Shiau Chan (LKKAuto)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Thursday, 4 October 2018 4:26 PM
To: Shiau Chan (LKKAuto)
Subject: RE: Appraisal Services for SPF vehicle at INDECO, BHH - HOMSPFETQ17300218 - TP982U

Hi Shiau Chan,

OK, pls send thank you.

Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Thursday, 4 October 2018 11:22 AM
To: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Subject: RE: Appraisal Services for SPF vehicle at INDECO, BHH - HOMSPFETQ17300218 - TP982U

Dear Sir/Madam,

Kindly advise whether we can submit our report accordingly to your good office.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Thursday, 6 September 2018 10:14 AM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO, BHH - HOMSPFETQ17300218 - TP982U

Thanks will update again.

Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Wednesday, 29 August 2018 5:07 PM
To: Perry HE (SPF) <Perry_HE@spf.gov.sg>; SUR <sur@lkkauto.com>
Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; assignments <assignments@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO, BHH - HOMSPFETQ17300218 - TP982U

Dear Perry,

Please refer to the attachment.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 27 August 2018 2:47 PM
To: 'Perry HE (SPF)' <Perry_HE@spf.gov.sg>; SUR <sur@lkkauto.com>
Cc: 'Wei Yea LIM (SPF)' <LIM_Wei_Yea@spf.gov.sg>; 'Kwee Huat TAN (SPF)' <TAN_Kwee_Huat@spf.gov.sg>; 'Kim Pang CHAY (SPF)' <CHAY_Kim_Pang@spf.gov.sg>; Ai Phing (LKKAuto) <aiphing@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO, BHH - HOMSPFETQ17300218 - TP982U

Dear Perry,

Thank you for your email.

Dear Shiau Chan,

FYNA. Our Ref: CS/SPF18014617/Uqb

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 29 August 2018 5:07 PM
To: 'Perry HE (SPF)'; SUR
Cc: 'Wei Yea LIM (SPF)'; 'Kwee Huat TAN (SPF)'; 'Kim Pang CHAY (SPF)'; assignments
Subject: RE: Appraisal Services for SPF vehicle at INDECO, BHH - HOMSPFETQ17300218 - TP982U
Attachments: TP982U Photo.pdf; TP982U.xls

Dear Perry,

Please refer to the attachment.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 27 August 2018 2:47 PM
To: 'Perry HE (SPF)' <Perry_HE@spf.gov.sg>; SUR <sur@lkkauto.com>
Cc: 'Wei Yea LIM (SPF)' <LIM_Wei_Yea@spf.gov.sg>; 'Kwee Huat TAN (SPF)' <TAN_Kwee_Huat@spf.gov.sg>; 'Kim Pang CHAY (SPF)' <CHAY_Kim_Pang@spf.gov.sg>; Ai Phing (LKKAuto) <aiphing@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO, BHH - HOMSPFETQ17300218 - TP982U

Dear Perry,

Thank you for your email.

Dear Shiau Chan,

FYNA. Our Ref: CS/SPF18014617/Uqb

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) [mailto:Perry_HE@spf.gov.sg]
Sent: Monday, 27 August, 2018 2:43 PM
To: assignments <assignments@lkkauto.com>
Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Ai Phing (LKKAuto) <aiphing@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO, BHH - HOMSPFETQ17300218 - TP982U

Hi,

Any update on this?

Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Perry HE (SPF)

Sent: Friday, 10 August 2018 4:17 PM

To: 'assignments' <assignments@lkkauto.com>

Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; 'Ai Phing (LKKAuto)' <aiphing@lkkauto.com>; 'Shiau Chan (LKKAuto)' <siewsc@lkkauto.com>; 'Veron Chen (LKKAuto)' <veronchen@lkkauto.com>; 'Janice Lee (LKKAuto)' <JaniceLee@lkkauto.com>

Subject: Appraisal Services for SPF vehicle at INDECO, BHH - HOMSPFETQ17300218 - TP982U

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at INDECO, BHH.

Vehicle No: TP982U

Parts:

- 1.1 BOLT ,FLANGE 10*25
- 1.2 BOLT 8X16
- 1.3 BOX SIDE LH
- 1.4 BOX SIDE RH
- 1.5 BRACKET CRASH BAR REAR LH
- 1.6 BRACKET CRASH BAR REAR RH
- 1.7 BRACKET SIDE BOX
- 1.8 COVER TAIL CENTRE
- 1.9 COWLING SINGLE SEAT
- 1.10 PLATE ANTENNA
- 1.11 CRASH BAR FRONT (LH/RH)
- 1.12 CRASH BAR REAR (LH/RH)
- 1.13 FRONT COWLING SET
- 1.14 PANEL METER
- 1.15 STAY FR COWLING
- 1.16 STAY L ENGINE GUARD
- 1.17 PIPE STEERING HANDLE
- 1.18 GRIP HANDLE SET (GPR) RH & LH
- 1.19 LEVER CLUTCH

- 1.20 LIGHT ASSY LH ROTARY PATROL LH
- 1.21 LIGHT ASSY RH ROTARY PATROL
- 1.22 LIGHT REVOLVING (BLUE)
- 1.23 METER ASSY COMBINATION
- 1.24 MUFFLER COMP
- 1.25 PACKING MUFFLER
- 1.26 PIPE L ENGINE GUARD CENTER
- 1.27 PIPE R ENGINE GUARD CENTER
- 1.28 TAIL LIGHT ASSY
- 1.29 WINDSHIELD
- 1.30 STICKER (TP) VISOR FRONT

Additional Parts

- 2.1 BASE PACKING FUEL TANK
- 2.2 MARK
- 2.3 O-RING (FUEL GAUGE)
- 2.4 STICKER (HONDA) LOGO LH
- 2.5 STICKER (HONDA) LOGO RH
- 2.6 STICKER TANK LINING
- 2.7 STRIPE L SIDE COVER
- 2.8 TANK FUEL ASSY
- 2.9 TANK GRIP LH
- 2.10 TANK GRIP RH

Labour (Man hours)

1.1	REPLACE ITEM 1.3	2 hrs
1.2	REPLACE ITEM 1.4	2 hrs
1.3	REPLACE ITEM 1.5	0.7 hr
1.4	REPLACE ITEM 1.6	0.7 hr
1.5	REPLACE ITEM 1.7	0.5 hr
1.6	REPLACE ITEM 1.8 - 1.10	3 hrs
1.7	REPLACE ITEM 1.11	2 hrs
1.8	REPLACE ITEM 1.12	2 hrs
1.9	REPLACE ITEM 1.13 - 1.15	3 hrs
1.10	REPLACE ITEM 1.16	1 hr
1.11	REPLACE ITEM 1.17 - 1.18	2 hrs
1.12	REPLACE ITEM 1.19	0.5 hr
1.13	REPLACE ITEM 1.20	1 hr
1.14	REPLACE ITEM 1.21	1 hr
1.15	REPLACE ITEM 1.22	1 hr
1.16	REPLACE ITEM 1.23	2 hrs
1.17	REPLACE ITEM 1.24 & 1.25	1 hr

1.18	REPLACE ITEM 1.26	2 hrs
1.19	REPLACE ITEM 1.27	2 hrs
1.20	REPLACE ITEM 1.28	1 hr
1.21	REPLACE ITEM 1.29	1 hr
1.22	REPAIR ALIGN - BRACKET LH & RH WINDSHIELD	2 hrs

Thank you.

Perry He Junyun
 Contract Management Engineer
 Automotive Engineering & Management Division
 Police Logistics Department
 Singapore Police Force
 DID: (65) 6478 4869 | HP: (65) 9191 5725



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Nivitha (LKK Auto)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Friday, 10 August 2018 4:17 PM
To: assignments
Cc: Wei Yea LIM (SPF); Kwee Huat TAN (SPF); Kim Pang CHAY (SPF); Ai Phing (LKKAuto); Shiau Chan (LKKAuto); Veron Chen (LKKAuto); Janice Lee (LKKAuto)
Subject: Appraisal Services for SPF vehicle at INDECO, BHH - HOMSPFETQ17300218 - TP982U

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at INDECO, BHH.

Vehicle No: TP982U

Parts:

- 1.1 BOLT ,FLANGE 10*25
- 1.2 BOLT 8X16
- 1.3 BOX SIDE LH *cu? ✓*
- 1.4 BOX SIDE RH
- 1.5 BRACKET CRASH BAR REAR LH *twi ✓*
- 1.6 BRACKET CRASH BAR REAR RH
- 1.7 BRACKET SIDE BOX
- 1.8 COVER TAIL CENTRE
- 1.9 COWLING SINGLE SEAT
- 1.10 PLATE ANTENNA
- 1.11 CRASH BAR FRONT (LH/RH)
- 1.12 CRASH BAR REAR (LH/RH)
- 1.13 FRONT COWLING SET
- 1.14 PANEL METER *cu ✓*
- 1.15 STAY FR COWLING
- 1.16 STAY L ENGINE GUARD
- 1.17 PIPE STEERING HANDLE
- 1.18 GRIP HANDLE SET (GPR) RH & LH
- 1.19 LEVER CLUTCH
- 1.20 LIGHT ASSY LH ROTARY PATROL LH
- 1.21 LIGHT ASSY RH ROTARY PATROL
- 1.22 LIGHT REVOLVING (BLUE)
- 1.23 METER ASSY COMBINATION
- 1.24 MUFFLER COMP
- 1.25 PACKING MUFFLER
- 1.26 PIPE L ENGINE GUARD CENTER
- 1.27 PIPE R ENGINE GUARD CENTER
- 1.28 TAIL LIGHT ASSY *3/20 ✓*
- 1.29 WINDSHIELD *3/20 ✓*
- 1.30 STICKER (TP) VISOR FRONT *neu ✓*

Additional Parts

- 2.1 BASE PACKING FUEL TANK
- 2.2 MARK
- 2.3 O-RING (FUEL GAUGE)
- 2.4 STICKER (HONDA) LOGO LH

- 2.5 STICKER (HONDA) LOGO RH
- 2.6 STICKER TANK LINING
- 2.7 STRIPE L SIDE COVER
- 2.8 TANK FUEL ASSY
- 2.9 TANK GRIP LH
- 2.10 TANK GRIP RH

Labour (Man hours)

1.1	REPLACE ITEM 1.3	2 hrs
1.2	REPLACE ITEM 1.4	2 hrs
1.3	REPLACE ITEM 1.5	0.7 hr
1.4	REPLACE ITEM 1.6	0.7 hr
1.5	REPLACE ITEM 1.7	0.5 hr
1.6	REPLACE ITEM 1.8 - 1.10	3 hrs
1.7	REPLACE ITEM 1.11	2 hrs
1.8	REPLACE ITEM 1.12	2 hrs
1.9	REPLACE ITEM 1.13 - 1.15	3 hrs
1.10	REPLACE ITEM 1.16	1 hr
1.11	REPLACE ITEM 1.17 - 1.18	2 hrs
1.12	REPLACE ITEM 1.19	0.5 hr
1.13	REPLACE ITEM 1.20	1 hr
1.14	REPLACE ITEM 1.21	1 hr
1.15	REPLACE ITEM 1.22	1 hr
1.16	REPLACE ITEM 1.23	2 hrs
1.17	REPLACE ITEM 1.24 & 1.25	1 hr
1.18	REPLACE ITEM 1.26	2 hrs
1.19	REPLACE ITEM 1.27	2 hrs
1.20	REPLACE ITEM 1.28	1 hr
1.21	REPLACE ITEM 1.29	1 hr
1.22	REPAIR ALIGN - BRACKET LH & RH WINDSHIELD	2 hrs

Thank you.

Perry He Junyun
 Contract Management Engineer
 Automotive Engineering & Management Division
 Police Logistics Department
 Singapore Police Force
 DID: (65) 6478 4869 | HP: (65) 9191 5725

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



Scope Of Work
Home Team Agency

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	Indeco Engineers Pte Ltd	VEH TYPE :	UNIT :	TP
VEH NO :	TP982U	MC	REPAIR TYPE:	ACCIDENT
VEH MAKE/MODEL:	HONDA VFR800P		Mileage:	52094

Reference No.	
MHA/SPF/2018/08-0017 1100009047	

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1 Scope Of Repairs						
1.1	BOLT_FLANGE 10*25	5.00	2	20%	6.00	12.00
1.2	BOLT 8X16	4.60	4	20%	5.52	22.08
1.3	BOX SIDE LH	1800.00	1	20%	2160.00	2160.00
1.4	BOX SIDE RH	1800.00	1	20%	2160.00	2160.00
1.5	BRACKET CRASH BAR REAR LH	122.00	1	20%	146.40	146.40
1.6	BRACKET CRASH BAR REAR RH	122.00	1	20%	146.40	146.40
1.7	BRACKET SIDE BOX	308.00	1	20%	369.60	369.60
1.8	COVER TAIL CENTRE	364.00	1	20%	436.80	436.80
1.9	COWLING SINGLE SEAT	318.00	1	20%	381.60	381.60
1.10	PLATE ANTENNA	68.20	1	20%	81.84	81.84
1.11	CRASH BAR FRONT (LH/RH)	288.00	2	20%	345.60	691.20
1.12	CRASH BAR REAR (LH/RH)	281.00	2	20%	337.20	674.40
1.13	FRONT COWLING SET	985.00	1	20%	1182.00	1182.00
1.14	PANEL METER	167.00	1	20%	200.40	200.40
1.15	STAY FR COWLING	409.00	1	20%	490.80	490.80
1.16	STAY L ENGINE GUARD	227.30	1	20%	272.76	272.76
1.17	PIPE STEERING HANDLE	235.00	1	20%	282.00	282.00
1.18	GRIP HANDLE SET (GPR) RH & LH	9.40	1	20%	11.28	11.28
1.19	LEVER CLUTCH	64.00	1	20%	76.80	76.80
1.20	LIGHT ASSY LH ROTARY PATROL LH	3340.00	1	20%	4008.00	4008.00
1.21	LIGHT ASSY RH ROTARY PATROL	3340.00	1	20%	4008.00	4008.00
1.22	LIGHT REVOLVING (BLUE)	2121.00	1	20%	2545.20	2545.20
1.23	METER ASSY COMBINATION	4091.00	1	20%	4909.20	4909.20
1.24	MUFFLER COMP	894.00	1	20%	1072.80	1072.80
1.25	PACKING MUFFLER	26.00	1	20%	31.20	31.20
1.26	PIPE L ENGINE GUARD CENTER	137.00	1	20%	164.40	164.40
1.27	PIPE R ENGINE GUARD CENTER	137.00	2	20%	164.40	328.80
1.28	TAIL LIGHT ASSY	455.00	1	20%	546.00	546.00
1.29	WINDSHIELD	455.00	1	20%	546.00	546.00
1.30	STICKER (TP) VISOR FRONT	11.40	1	20%	13.68	13.68
				20%	0.00	0.00
2 Additional Services						
2.1	BASE PACKING FUEL TANK		1	20%	0.00	0.00
2.2	MARK		2	20%	0.00	0.00
2.3	O-RING (FUEL GAUGE)		1	20%	0.00	0.00
2.4	STICKER (HONDA) LOGO LH		1	20%	0.00	0.00
2.5	STICKER (HONDA) LOGO RH		1	20%	0.00	0.00
2.6	STICKER TANK LINING		1	20%	0.00	0.00
2.7	STRIPE L SIDE COVER		1	20%	0.00	0.00
2.8	TANK FUEL ASSY		1	20%	0.00	0.00
2.9	TANK GRIP LH		1	20%	0.00	0.00
2.10	TANK GRIP RH		1	20%	0.00	0.00
				20%	0.00	0.00
Remarks:					Parts Total:	\$ 27,971.64
SPARE PARTS SUBJECTED TO AVAILABILITY						

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1 Scope Of Repairs				
1.1	REPLACE ITEM 1.3	61.80	2	123.60
1.2	REPLACE ITEM 1.4	61.80	2	123.60
1.3	REPLACE ITEM 1.5	61.80	0.7	43.26
1.4	REPLACE ITEM 1.6	61.80	0.7	43.26
1.5	REPLACE ITEM 1.7	61.80	0.5	30.90
1.6	REPLACE ITEM 1.8 - 1.10	61.80	3	185.40
1.7	REPLACE ITEM 1.11	61.80	2	123.60
1.8	REPLACE ITEM 1.12	61.80	2	123.60
1.9	REPLACE ITEM 1.13 - 1.15	61.80	3	185.40
1.10	REPLACE ITEM 1.16	61.80	1	61.80
1.11	REPLACE ITEM 1.17 - 1.18	61.80	2	123.60
1.12	REPLACE ITEM 1.19	61.80	0.5	30.90
1.13	REPLACE ITEM 1.20	61.80	1	61.80
1.14	REPLACE ITEM 1.21	61.80	1	61.80
1.15	REPLACE ITEM 1.22	61.80	1	61.80
1.16	REPLACE ITEM 1.23	61.80	2	123.60
1.17	REPLACE ITEM 1.24 & 1.25	61.80	1	61.80
1.18	REPLACE ITEM 1.26	61.80	2	123.60
1.19	REPLACE ITEM 1.27	61.80	2	123.60
1.20	REPLACE ITEM 1.28	61.80	1	61.80
1.21	REPLACE ITEM 1.29	61.80	1	61.80
1.22	REPAIR ALIGN - BRACKET LH & RH WINDSHIELD	61.80	2	123.60
2 Additional Services				
2.1	TRANSPORT CHARGES (SOR 8) (BILL UNDER MONTH END SOR BILLING)		2	
				Labour Total: \$ 2,064.12
				GRAND TOTAL : \$ 30,035.76

Contractor shall complete the entire repair within 5 working days upon quotation approved date.

Verification of Scope of Work					
Contractor QC		Vetted By:		Approved By:	
Name:	Gan Hup Tiong	Name:		Name:	
Date:	10/8/18	Date:		Date:	
Sign:		Sign:		Sign:	
Verification of Completed Repairs					
Contractor QC		Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager	
Name:		Name:		Name:	
Date:		Date:		Date:	
Sign:		Sign:		Sign:	
All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made					

7.4

Registration No. TP 982U

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	BOLT ,FLANGE 10*25	2	NECESSARY	\$6.00	\$12.00	
1.2	BOLT 8X16	4	NECESSARY	\$5.52	\$22.08	
1.3	BOX SIDE LH	1	CUT	\$2,160.00	\$2,160.00	
1.4	BOX SIDE RH	1	NOT NECESSARY	\$2,160.00		
1.5	BRACKET CRASH BAR REAR LH	1	BENT	\$146.40	\$146.40	
1.6	BRACKET CRASH BAR REAR RH	1	BENT	\$146.40	\$146.40	
1.7	BRACKET SIDE BOX	1	BENT	\$369.60	\$369.60	
1.8	COVER TAIL CENTRE	1	CRACKED	\$436.80	\$436.80	
1.9	COWLING SINGLE SEAT	1	CRACKED	\$381.60	\$381.60	
1.10	PLATE ANTENNA	1	NOT NECESSARY	\$81.84		
1.11	CRASH BAR FRONT (LH/RH)	2	O/S SERVICABLE N/S BENT	\$345.60	\$345.60	
1.12	CRASH BAR REAR (LH/RH)	2	O/S NOT NECESSARY N/S BENT	\$337.20	\$337.20	
1.13	FRONT COWLING SET	1	CRACKED	\$1,182.00	\$1,182.00	
1.14	PANEL METER	1	CRACKED	\$200.40	\$200.40	
1.15	STAY FR COWLING	1	BENT	\$490.80	\$490.80	
1.16	STAY L ENGINE GUARD	1	UNCONFIRM	\$272.76	\$272.76	
1.17	PIPE STEERING HANDLE	1	UNCONFIRM	\$282.00	\$282.00	
1.18	GRIP HANDLE SET (GPR) RH & LH	1	NOT NECESSARY	\$11.28		
1.19	LEVER CLUTCH	1	SERVICABLE	\$76.80		
1.20	LIGHT ASSY LH ROTARY PATROL LH	1	BROKEN	\$4,008.00	\$4,008.00	
1.21	LIGHT ASSY RH ROTARY PATROL	1	SERVICABLE	\$4,008.00		
1.22	LIGHT REVOLVING (BLUE)	1	CUT	\$2,545.20	\$2,545.20	
1.23	METER ASSY COMBINATION	1	DAMAGED	\$4,909.20	\$4,909.20	
1.24	MUFFLER COMP	1	DENTED / BENT	\$1,072.80	\$1,072.80	
1.25	PACKING MUFFLER	1	UNCONFIRM	\$31.20	\$31.20	
1.26	PIPE L ENGINE GUARD CENTER	1	UNCONFIRM	\$164.40	\$164.40	
1.27	PIPE R ENGINE GUARD CENTER	2	UNCONFIRM	\$164.40	\$328.80	
1.28	TAIL LIGHT ASSY	1	BROKEN	\$546.00	\$546.00	
1.29	WINDSHIELD	1	CRACKED	\$546.00	\$546.00	
1.30	STICKER (TP) VISOR FRONT	1	NECESSARY	\$13.68	\$13.68	

2.1	BASE PACKING FUEL TANK	1	UNCONFIRM			
2.2	MARK	2	UNCONFIRM			
2.3	O-RING (FUEL GAUGE)	1	UNCONFIRM			
2.4	STICKER (HONDA) LOGO LH	1	NECESSARY			
2.5	STICKER (HONDA) LOGO RH	1	NECESSARY			
2.6	STICKER TANK LINING	1	NECESSARY			
2.7	STRIPE L SIDE COVER	1	NECESSARY			
2.8	TANK FUEL ASSY	1	REPAIR			
2.9	TANK GRIP LH	1	NECESSARY			
2.10	TANK GRIP RH	1	NECESSARY			
3	SCOPE OF REPAIRS					
1.1	REPLACE ITEM 1.3					1
1.2	REPLACE ITEM 1.4					0.5
1.3	REPLACE ITEM 1.5					0.2
1.4	REPLACE ITEM 1.6					0
1.5	REPLACE ITEM 1.7					0.2
1.6	REPLACE ITEM 1.8 - 1.10					0.5
1.7	REPLACE ITEM 1.11					0.2
1.8	REPLACE ITEM 1.12					0.2
1.9	REPLACE ITEM 1.13 - 1.15					1
1.10	REPLACE ITEM 1.16		UNCONFIRM			1
1.11	REPLACE ITEM 1.17 - 1.18		UNCONFIRM			2
1.12	REPLACE ITEM 1.19					0
1.13	REPLACE ITEM 1.20					0.5
1.14	REPLACE ITEM 1.21					0
1.15	REPLACE ITEM 1.22					0.2
1.16	REPLACE ITEM 1.23		UNCONFIRM			2
1.17	REPLACE ITEM 1.24 & 1.25					0.5
1.18	REPLACE ITEM 1.26		UNCONFIRM			2
1.19	REPLACE ITEM 1.27		UNCONFIRM			2
1.20	REPLACE ITEM 1.28					0.2
1.21	REPLACE ITEM 1.29					0.2
1.22	REPAIR ALIGN - BRACKET LH & RH WINDSHIELD					1
COSTING		TOTAL PARTS COST			#####	
		TOTAL MAN-HOUR				15.4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18014617/Uqbe2	
CONTRACT MANAGEMENT SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333		Date : 01-11-2018	
ATTN : PERRY HE		Code : SPF3	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	TP 982U
Policy No.		Coverage (\$)	0.00
Claim No.	HOMSPFETQ17300218	Excess (\$)	0.00
Assign From	PERRY HE	Assign Date	10/08/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA VFR800P	c.c	781
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JH2RC499X5M000022	Colour	WHITE
Odometer	52094	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	120/70Z R17	DUNLOP	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	180/55Z R17	DUNLOP	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date		Inspection Date	14/08/2018
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		
5a. Remarks			



Registration No. TP 982U

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	BOLT ,FLANGE 10*25	2	NECESSARY	\$6.00	\$12.00	
1.2	BOLT 8X16	4	NECESSARY	\$5.52	\$22.08	
1.3	BOX SIDE LH	1	CUT	\$2,160.00	\$2,160.00	
1.4	BOX SIDE RH	1	NOT NECESSARY	\$2,160.00		
1.5	BRACKET CRASH BAR REAR LH	1	BENT	\$146.40	\$146.40	
1.6	BRACKET CRASH BAR REAR RH	1	BENT	\$146.40	\$146.40	
1.7	BRACKET SIDE BOX	1	BENT	\$369.60	\$369.60	
1.8	COVER TAIL CENTRE	1	CRACKED	\$436.80	\$436.80	
1.9	COWLING SINGLE SEAT	1	CRACKED	\$381.60	\$381.60	
1.10	PLATE ANTENNA	1	NOT NECESSARY	\$81.84		
1.11	CRASH BAR FRONT (LH/RH)	2	O/S SERVICABLE N/S BENT	\$345.60	\$345.60	
1.12	CRASH BAR REAR (LH/RH)	2	O/S NOT NECESSARY N/S BENT	\$337.20	\$337.20	
1.13	FRONT COWLING SET	1	CRACKED	\$1,182.00	\$1,182.00	
1.14	PANEL METER	1	CRACKED	\$200.40	\$200.40	
1.15	STAY FR COWLING	1	BENT	\$490.80	\$490.80	
1.16	STAY L ENGINE GUARD	1	UNCONFIRM	\$272.76	\$272.76	
1.17	PIPE STEERING HANDLE	1	UNCONFIRM	\$282.00	\$282.00	
1.18	GRIP HANDLE SET (GPR) RH & LH	1	NOT NECESSARY	\$11.28		
1.19	LEVER CLUTCH	1	SERVICABLE	\$76.80		
1.20	LIGHT ASSY LH ROTARY PATROL LH	1	BROKEN	\$4,008.00	\$4,008.00	
1.21	LIGHT ASSY RH ROTARY PATROL	1	SERVICABLE	\$4,008.00		

1.22	LIGHT REVOLVING (BLUE)	1	CUT	\$2,545.20	\$2,545.20	
1.23	METER ASSY COMBINATION	1	DAMAGED	\$4,909.20	\$4,909.20	
1.24	MUFFLER COMP	1	DENTED / BENT	\$1,072.80	\$1,072.80	
1.25	PACKING MUFFLER	1	UNCONFIRM	\$31.20	\$31.20	
1.26	PIPE L ENGINE GUARD CENTER	1	UNCONFIRM	\$164.40	\$164.40	
1.27	PIPE R ENGINE GUARD CENTER	2	UNCONFIRM	\$164.40	\$328.80	
1.28	TAIL LIGHT ASSY	1	BROKEN	\$546.00	\$546.00	
1.29	WINDSHIELD	1	CRACKED	\$546.00	\$546.00	
1.30	STICKER (TP) VISOR FRONT	1	NECESSARY	\$13.68	\$13.68	
2.1	BASE PACKING FUEL TANK	1	UNCONFIRM			
2.2	MARK	2	UNCONFIRM			
2.3	O-RING (FUEL GAUGE)	1	UNCONFIRM			
2.4	STICKER (HONDA) LOGO LH	1	NECESSARY			
2.5	STICKER (HONDA) LOGO RH	1	NECESSARY			
2.6	STICKER TANK LINING	1	NECESSARY			
2.7	STRIPE L SIDE COVER	1	NECESSARY			
2.8	TANK FUEL ASSY	1	REPAIR			
2.9	TANK GRIP LH	1	NECESSARY			
2.10	TANK GRIP RH	1	NECESSARY			
3	SCOPE OF REPAIRS					
1.1	REPLACE ITEM 1.3					1
1.2	REPLACE ITEM 1.4					0.5
1.3	REPLACE ITEM 1.5					0.2
1.4	REPLACE ITEM 1.6					0
1.5	REPLACE ITEM 1.7					0.2
1.6	REPLACE ITEM 1.8 - 1.10					0.5
1.7	REPLACE ITEM 1.11					0.2
1.8	REPLACE ITEM 1.12					0.2
1.9	REPLACE ITEM 1.13 - 1.15					1
1.10	REPLACE ITEM 1.16		UNCONFIRM			1
1.11	REPLACE ITEM 1.17 - 1.18		UNCONFIRM			2
1.12	REPLACE ITEM 1.19					0
1.13	REPLACE ITEM 1.20					0.5
1.14	REPLACE ITEM 1.21					0
1.15	REPLACE ITEM 1.22					0.2
1.16	REPLACE ITEM 1.23		UNCONFIRM			2
1.17	REPLACE ITEM 1.24 & 1.25					0.5
1.18	REPLACE ITEM 1.26		UNCONFIRM			2

1.19	REPLACE ITEM 1.27		UNCONFIRM			2
1.20	REPLACE ITEM 1.28					0.2
1.21	REPLACE ITEM 1.29					0.2
1.22	REPAIR ALIGN - BRACKET LH & RH WINDSHIELD					1
COSTING		TOTAL PARTS COST			\$20,950.92	
		TOTAL MAN-HOUR				15.4

Registration No. TP 982U

Vehicle Inspected By

CHUA KANG SENG
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.