



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

InvolvingTPVD OPEL COMBO VAN AZ (GZ9001T)

Date of Loss2 August 2018

Time of Loss13.30

Loss DescriptionWC7342D (INSD) C/W GZ9001T (TP)

Comment

Workshop Details

Total Rebate Amount

0

Nett Loss Amount\$18,000.00

Assigned WorkshopLKK AUTO CONSULTANTS PTE LTD (TP)

Days of work completion *

65



SERVICE REQUESTS

MESSAGES

CLAIMS

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details



Vehicle Registration#	GZ9001T	Purchase Date	<div>dd/mm/yyyy</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>01/11/2006</div> <div></div>
Mileage	<div>347552</div>	Age of Vehicle	11

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<div>2006</div>
Make	TPVD OPEL	<div>OPEL</div>
Model	COMBO VAN AZ	<div>COMBO VAN AZ</div>

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	VEDIYAPPAN GOPI	<div></div>
Date of Birth	10 May 1992	<div>dd/mm/yyyy</div> <div></div>
Age	26	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="W0L0XCF2563069302"/>
Engine No		<input type="text" value="Z17DTH01514043"/>
Engine Capacity		<input type="text" value="1686"/>
Sum Insured		<input type="text" value="0"/>
Market Value		<input type="text" value="18000"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="dd/mm/yyyy"/> 
License Expiration Date		<input type="text" value="dd/mm/yyyy"/> 
Address	TBC, Singapore	<input type="text" value=""/>
Address type	Personal Correspondence	<input type="text" value=""/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	<input type="text"/>
Marital status	Unknown	<input type="text"/>
Identification #	G3363749M	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

13/08/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

185/65R15

Rear Tyre Size

185/65R15

Front left side

WESTLAKE6mm

Rear left side

WESTLAKE6mm

Front right side

WESTLAKE6mm

Rear right side

WESTLAKE6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD		Ref: CS3/ASM18014627/Gz4be2		
8 SHENTON WAY #24-01		Date: 24-09-2018		
AXA TOWERS SINGAPORE 068811				
ATTN : JOHNNY YONG		Code: ASM		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	WC 7342D	Veh. Inspected	GZ 9001T	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00QXL	Excess (\$)	0.00	
Assign From	JOHNNY YONG	Assign Date	10/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	OPEL COMBO	c.c	1686	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	W0L0XCF2563069302	Colour	BLACK	
Odometer	347552 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	WEST LAKE	6 mm	
L/H Front Tyre	185/65 R15	WEST LAKE	6 mm	
R/H Rear Tyre	185/65 R15	WEST LAKE	6 mm	
L/H Rear Tyre	185/65 R15	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
5. General Information				
Accident Date	02/08/2018	Inspect Date / Time	13/08/2018 (05:00 PM)	
Survey held at	160 SIN MING DRIVE #08-12			
Repairer	-			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/ASM18014627/Gz4be2

Inspected By



XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.