

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG18014634/T1QD3S2**Date:** 04/10/2018REFERENCE

Insured/Claimant:	SOH POH GEOK	Policy No:	2100118528	
Date of Loss:	06/08/2018	Nature of Claim:	OD	Claim No: 4665936607SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN972C		
Make & Model:	DAIHATSU SIRION, 1.5 Sports (A)	Engine No:	2030440
Reg. Date:	03/02/2009 (Man. Year: 2007)	Chassis No:	JDAM303S001002898
Colour:	Green	Odometer:	59740 km
Engine Capacity:	1495 cc		
Market Value/New Car Price:	S\$8,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,015.22	1,523.13	1,492.09	49.49
Miscellaneous Items	0.00	0.00	0.00	
Total Labour	2,110.00	1,814.50	295.50	14.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,125.22	3,337.63	1,787.59	34.88
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	4,525.22	2,737.63	1,787.59	39.50
+ GST 7.00/7.00% (S\$)	316.77	191.63	125.14	39.51
Nett Amount (S\$)	4,841.99	2,929.26	1,912.73	39.50

INSPECTION

Date of Assignment:	15/08/2018		
Date Inspected:	14/08/2018	Inspected At:	Sin Tien Seng Pte Ltd (Kallang) 10 Kallang Way Singapore 349215
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REINFORCEMENT FRONT	Bent	235.56 F	*100.00 FL
2	1		*SUPPORT, FR BUMPER RH	Not Necessary	30.42 F	*- FL
3	1		*SUPPORT, FR BUMPER LH	Necessary	30.42 F	*30.42 FL
4	1		*COVER, FR BUMPER (SP)	Deformed	377.52 F	*377.52 FL
5	1		*BRCKT, FOG LAMP LH	Not Necessary	20.28 F	*- FL
6	1		*H-COVER FR BUMPER LH	Not Necessary	12.09 F	*- FL
7	1		*MOULDG, FR BUMPER LH	Cut	26.52 F	*26.52 FL
8	1		*GRILLE, FR BUMPER UPP	Not Necessary	55.38 F	*- FL
9	1		*GRILLE, FR BUMPER LWR	Not Necessary	62.40 F	*- FL
10	1		*SUPPORT RADIATOR RH	Not Necessary	73.32 F	*- FL
11	1		*SUPPORT RADIATOR LH	Not Necessary	72.54 F	*- FL
12	1		*SUPPORT RADIATOR TOP	Bent	45.24 F	*20.00 FL
13	1		*SUPPORT, HOOD LOCK	Bent	16.38 F	*16.38 FL
14	1		*HOOD	Bent	259.74 F	*120.00 FL
15	1		*LOCK HOOD	Bent	60.84 F	*60.84 FL
16	1		*SHIELD FENDER LH	Not Necessary	89.70 F	*- FL
17	1		*PANEL, FR FENDER, LH	Bent	152.88 F	*152.88 FL
18	1		*SEAL, FRT FENDER LH	Necessary	8.97 F	*8.97 FL
19	1		*EMBLEM, HOOD	Not Necessary	49.14 F	*- FL
20	1		*HEADLAMP SET, LH	Cracked	333.06 F	*333.06 FL
21	1		*CONDENSER W/RECEIVER	Bent	297.96 F	*208.80 FL
22	1		*HOSE, DISCHARGE	Not Necessary	294.84 F	*- FL
23	1		*TUBE, INLET	Not Necessary	241.02 F	*- FL
24	1		*R-COOLANT RCP 1L	Necessary	29.00 F	*14.40 FL
25	1		*SUNDRIES	Necessary	80.00 F	*73.50 FL
26	1		*FRONT NUMBER PLATE	Bent	40.00 F	*40.00 FL
27	1		*OPC NUMBER PLATE SEAL	Necessary	20.00 F	*20.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,015.22	1,603.29
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	80.16
Total Parts (\$\$)	3,015.22	1,523.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R / REPLACE FRONT HEADLAMP & REFOCUS HEADLIGHT.	New	30.00	30.00
2	R&R RADIATOR TO FACILITATE REPAIR.	New	40.00	40.00
3	R&R / REPLACE AIRCON CONDENSER & REFILL GAS.	New	120.00	120.00
4	CUT & WELD FRONT SUPPORT PANEL / PANEL BEAT REPLACE FRONT BUMPER / HOOD ETC.	New	900.00	800.00
5	SPRAY PAINT ON AFFECTED AREAS.	New	900.00	800.00
6	LTA DOCUMENTATION FOR OPC NUMBER PLATE.	New	120.00	120.00
Gross Labour Cost (\$)			2,110.00	1,910.00
- 0.00/5.00% Labour Discount (\$)			0.00	95.50
Gross Labour after Discount (\$)			2,110.00	1,814.50

Report was unsubmitted during this print-out.

< END OF ESTIMATES >