

ASS. REC. BY:

REF:

CS / MSG18014703 / Avd3 / n2

Special Instruction:

Surveyor
merimen

Adrian

ASSIGNMENT (Office)

From (Person):

Fievel F00

of

MSG

Date/Time:

14/8/18 @ 9:31am

Estimated Cost:

Bill to:

OD / (P) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKH 6608 K

Insured:

FBE 2719 Y

at Workshop m/s

Modern Automotive

Tel:

6748 4422

of

Blk 3023A Ubi Rd 1 # 01-61 3 01-58

Policy No:

MSD / VMT / 18-379905-CA

Claim No:

MSC / V / 18-001079

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/08/2018

CA / REV / REP. / REV 24 HRS

lup>

H.O.D. Endorsement:

Date/Time:

9:57am @ 4/8/18

Person Contacted:

Gree

Vehicle IN /

(OUT)

Date/Time

Action/Instruction

(✓)

Estimate

SKH 6608 K - x

FBE 2719 Y - x

15/8/18

Informed Fievel pending workshop est via merimen

4/10/18

@ 144pm final fig \$ 2688 confirmed with ms chin

(Reel 1476.40, 35/)

REF:

ASS. REC. BY: Adrian King**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKH66081K Yr Regn: 2018 MayType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Tucson c.c. 1591Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 8808 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHJ3812VJ4743970Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/55R18R: 225/55R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 15/08/18Survey held at ModernDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP MS14.

4/10/18 Send preli revised via merimen

RECEIVED 05 OCT 2018



Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2) 5/10 - typistDays Of Repair: 3Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos

Other

TOTAL

150

10

160

Report Format:

merimen

Lump Sum / L.B.I. (%)

2688/-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18014703/Avd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 14-08-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBE 2719Y	Veh. Inspected	SKH 6608K	
Policy No.	MSD/VMT/18-379905-CA	Coverage (\$)	0.00	
Claim No.	MSC/V/18-001079	Excess (\$)	0.00	
Assign From	MERIMEN (FIEVEL FOO)	Assign Date	14/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/08/2018	Inspection Date		
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 04 Oct 2018

Preliminary Advice

Insured Vehicle No	: FBE2719Y	Accident Date	: 08/08/2018
TP Vehicle No	: SKH6608K	Assignment Date	: 14/08/2018
Make	: HYUNDAI TUCSON	Est. Duration of Repair	: 3.00
Date of Inspection	: 15/08/2018		
Inspection At	: MODERN AUTOMOTIVE PTE LTD (HQ) BLK 3023A UBI ROAD 1, #01-61 & #01-58 SINGAPORE 408717		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,164.40
Revised Amount	:S\$	2,688.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,688.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Aug 2018		14 Aug 2018 09:31 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	RUSYAIID BIN SUKARMAN, ID: S9532673J, Tel: +6581577412, Email: syaidiow@gmail.com		
Main Claimant:	WONG ANSON, ID: S7525095I		
Vehicle Reg. No.:	SKH6608K	Date of Loss:	08/08/2018 17:00 - :59 [3 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-001079	Policy/Cover Note No.:	MSD/VMT/18-379905-CA (Third Party Only) Coverage: 05/03/2018 - 04/03/2019
Vehicle Reg. No. (Insured):	FBE2719Y	Policy No. (Claimant):	
		Excess:	
Repairer:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2018]		
Driver/Custodian (Insured):	RUSYAIID BIN SUKARMAN (22 / Male), NRIC: S9532673J, Tel: +6581577412		
Adj Asg. Remarks:	Liability 100%, SJE agree - LKK, Contact : Grace at 6748 4422		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

View Sent Message

This mail is associated with :

***SKH6608K (MSC/V/18-001079)**
[FBE2719Y]

TP
WONG ANSON
Aug 8 2018 5:00PM
[RUSYADI BIN SUKARMAN]
Modern Automotive Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 15/08/2018 15:18 PM.
To MSIG_FFWY1
Subject TP SURVEY SKH 6608K

Dear Fievel,

Please be informed that we have inspected the vehicle SKH 6608K on 15/8/2018.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 #01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

MSIG INSURANCE (S) PTE LTD

4 Shenton Way # 21 - 01

SGX Centre 2

Singapore 068807

Hot line : 6827 - 7660

Fax : 6225- 7402 (CLAIM)

Quotation

DATE : 15.08.2018

VEH NO : SKH6608K

MODEL : Hyundai Tuscon

DOA : 08.08.2018

YR REF : FBE2719Y

Attn : Motor Claim Dept

(pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SKH6608K (HYUNDAI TUSCON)

Item	Description	Qty	Amt
NO	LIST ITEMS		
1	Rear Bumper <i>Repr</i>	1	447.00 X
2	Rear Bumper Clips <i>new</i>	1	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>new</i>	2	70.00 X
4	Rear Bumper Lower Spoiler <i>del</i>	1	335.00 ✓
5	Rear Mudflap - LH <i>ut</i>	1	38.00 ✓
6	Rear Exhaust Pipe <i>Dented</i> 2132	1	1,282.00 ✓
7	Rear Exhaust Mounting <i>new</i> 170560	1	28.00 X
8	Rear wheel Rim - LH <i>ut</i> S-N: 750	1	1,188.00 750 (SN)
			\$ 3,418.00
Less 20%			(683.60)
			\$ 2,734.40

S/NETT ITEMS

1	Reverse Sensor <i>not new</i>	1 set	280.00 X
---	-------------------------------	-------	----------

Total parts \$ 3,014.40

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$ 400.00 200.
2	To putty and spray up paint works	\$ 400.00 200.
3	To check wiring system	\$ 50.00 30

RE : ESTIMATE FOR ACCIDENT REPAIR SKH6608K (HYUNDAI TUSCON)

4	To remove exhaust pipe	\$	150.00 80
5	To perform wheel alignment test	590 \$	150.00 80
		\$	1,150.00
	GRAND TOTAL	\$	4,164.40

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total 3045.60 (P/P)
03 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18014703/AVD3N2

Date: 09/10/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/MT/18-379905-CA	
Claimant Vehicle No :	SKH6608K	Insured Vehicle No :	FBE2719Y	
Date of Loss:	08/08/2018	Nature of Claim:	TP	Claim No: MSC/V/18-001079

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH6608K	Engine No:	G4FJJU433134
Make & Model:	HYUNDAI TUCSON, 1.6 GLS T-GDI DCT 2WD (A)	Chassis No:	KMHJ3812VJU743970
Reg. Date:	02/05/2018 (Man. Year: 2018)	Odometer:	8808 km
Colour:	Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,014.40	2,098.00	916.40	30.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	590.00	560.00	48.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,164.40	2,688.00	1,476.40	35.45
+ GST 7.00/7.00% (\$\$)	291.51	188.16	103.35	35.45
Nett Amount (\$\$)	4,455.91	2,876.16	1,579.75	35.45

INSPECTION

Date of Assignment:	14/08/2018	
Date Inspected:	15/08/2018	Inspected At: Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58 Singapore 408717
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Oct 2018)
Parts:	M1-SUV	HYUNDAI TUCSON 1.6 GLS T-GDI DCT 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKH6608K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	447.00 FL	*- FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	2		*REAR BUMPER SIDE HOLDER-LH & RH	Not Necessary	70.00 FL	*- FL
4	1		*REAR BUMPER LOWER SPOILER	Deformed	335.00 FL	*335.00 FL
5	1		*REAR MUDFLAP-LH	Cut	38.00 FL	*38.00 FL
6	1		*REAR EXHAUST PIPE	Dented	1,282.00 FL	*1,282.00 FL
7	1		*REAR EXHAUST MOUNTING	Not Necessary	28.00 FL	*- FL
8	1		*REAR WHEEL RIM-LH	Cut	950.40 FS	*750.00 FS
9	1		*SET REVERSE SENSOR	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,460.40	2,435.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	446.00	337.00
Total Parts (\$\$)	3,014.40	2,098.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items**There are no new miscellaneous items selected.****Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	400.00	200.00
2	TO PUTTY AND SPRAY UP PAINT WORKS	New	400.00	200.00
3	TO CHECK WIRING SYSTEM	New	50.00	30.00
4	TO REMOVE EXHAUST PIPE	New	150.00	80.00
5	TO PERFORM WHEEL ALIGNMENT TEST	New	150.00	80.00
Gross Labour Cost (S\$)			1,150.00	590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >