

23003200

ASS. REC. BY:

REF: CS3/MSH18008115/Urb-1

Special Instruction:

Surveyor

MUNU.

ASSIGNMENT (Office)

From (Person):

Monica Chung

of

MSH

Date/Time:

14082018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKX 7214Y

Insured:

SGK 8666K

at Workshop m/s

SAT motors

Tel:

91269987

of

24 Difu Lane 12

Policy No:

29001380TMP

Claim No:

557253

Sum Insured:

Excess:

D.O.A. 28042018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

04052018

H.O.D. Endorsement:

Date/Time: 03052018 2:51pm

Person Contacted:

Jonathan

Vehicle: ☒ OUT

Date/Time	Action/Instruction (X) Estimate	Do Not Finalize
	SKX 7214Y - X	
	SGK 8666K - X	Estimate Range & Repair Days?
	fat huan 04711-T6A-00022 \$677.60	
	Woodchip 33100-T6A-001 \$886.20	
	fat huan 60210-T6A-30022 \$537.80	

24/8/18 Sumat \$4513.16 S.H.

Red: \$7065.42, 61%.

RECEIVED 27 AUG 2018

PRS REP: MSLH

maxmen

ASSIGNMENT

From: DATE: 04/05/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKX 7214Y

at Workshop m/s SAT Motors

of 24 Delu Lane 12

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value:

IDAC Accident Report: Consistent?: Yes or No

GIA / R/S Report: Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

LA6622

Vehicle: IN / OUT

Date: Person Contacted:

Val No: SKX 7214Y Regn: 1215

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Odyssey 2356

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 43996 T/Radio: Insured / Std / NI / NA

Eng/No:

G/No: JHMR18806C 201035

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Jammed / Leaked / Burnt or

Brake: Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rm or

Tyre Size: F: 215/55R17 R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 2 mm R/Bal: 2 mm

L/Bal: 2 mm L/Bal: 2 mm

D.O.A: 28/4/18 D.O.I: 4/5/18

Survey held at

Des. of Damages: Frt / Rear / BS / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

PRS No settled. After repair 10/5/18

4-5/18

11/5/18 Submit PRS Report

RECEIVED 14 MAY 2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Other Fee

Other Fee

Other Fee

Other Fee

Other Fee

120

50

10

180

Report Format :

Lump Sum / L.B / IS

Add Fee:

☐ Site Insp. IS

☐ Interview IS

☐ Tech. Insp. IS

☐ Management IS

Catherine Chong (LKK Auto)

From: Monica Chung <Monica_Chung@sg.msig-asia.com>
Sent: Tuesday, 14 August, 2018 1:30 PM
To: assignments@lkkauto.com
Subject: TP SKX7214Y DOA - 28/04/18 Our Re:F 557253

Dear Catherine,

We have shared the documents for paper adjustment in Merimen.

Thanks.

Regards,

Monica Chung
Executive, Claims Services (Motor)
D: +65 6594 2552 | F: +65 6225 7402 | monica_chung@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 May 2018		03 May 2018 13:32 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		LEE POH HUA, ID: S7321885C							
Main Claimant:		TAN SIEW ENG, ID: S6930566J							
Vehicle Reg. No.:		SKX7214Y	Date of Loss:	28/04/2018 00:00 - :59 [28 Months and 5 Days From LTA Reg Date (Man Yr)]					
Claim Type:		TP / 557253	Policy/Cover Note No.:	29001380TMP Coverage: 29/08/2017 - 28/08/2018					
Vehicle Reg. No. (Insured):		SGK8666K	Policy No. (Claimant):						
			Excess:						
Repairer:		Sat Motors (HQ) 24 Defu Lane 12, 539131 Defu Lane - Tel:							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 04/05/2018]							
Adj Asg. Remarks:		TP disagree with SJE Assign LKK Auto Consultants							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

K. KRISHNA & PARTNERS

UEN 53131210X
GST Regn. No. M90371530C
Advocates & Solicitors
Commissioner for Oaths
& Notary Public

101 Cecil Street #24-03/04 Tong Eng Building, Singapore 069533.
Tel: 6323 3038 Fax: 6323 2120 (Not for service of Court Documents)
Email: kkrishna@singnet.com.sg



K. Krishnamoorthi
LLB (Hons) (London)
Barrister-at-Law (Gray's Inn)
B.Sc(Hons)(Est.Man)(S'pore)

S. Manohar
LLB (Hons) (S'pore)

557253

Vengadesh s/o Kumaravelu
LLB (Hons)

Our Ref : KK.AMM.17726.2018.wen
Your Ref: 557253

19th June 2018

M/s MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way #21-01
SGX Centre 2
Singapore 068807

**BY HAND
WITHOUT PREJUDICE**

Dear Sirs

ACCIDENT ON 28/04/2018 INVOLVING SKX 7214Y, SGK 8666K & SHC 7242L AT THE JUNCTION OF ANCHORVALE LINK & ANCHORVALE DRIVE

We act for Mdm Tan Siew Eng, who was the registered owner of motor vehicle no. **SKX 7214Y** which was involved in the aforesaid accident with motor vehicle nos. SGK 8666K & SHC 7242L.

We are instructed that the said motor vehicle no. **SGK 8666K** was insured by you at the material time.

We are further instructed that the aforesaid accident was caused solely by the negligence of your insured driver in the control management and driving of his vehicle. Accordingly, our client's vehicle was damaged and our client has been put to loss and expenses as follows:

1) Cost of repairs	\$ 9,200.00
2) Rental of vehicle (15 days x \$180 per day)	\$ 2,700.00
3) Survey fee	\$ 579.00
4) GIA fee	\$ 29.00
5) LTA search	\$ 7.49
6) Costs	\$ 963.00
7) Transport, Xerox, postages & other incidentals	\$ 107.00

\$13,585.49
=====

K. KRISHNA & PARTNERS

Advocates & Solicitors

- 2 -

We have been instructed to claim the said sum of **\$13,585.49**. In support of our client's claim, we enclose herewith the documents as follows:-

- i) photocopy of LTA search;
- ii) photocopy of accident reports;
- iii) photocopy of Repair bill;
- iv) photocopy of Rental Agreement & invoice;
- v) photocopy of Survey Report & bill; &
- vi) **59** colour damaged photos.

TAKE NOTICE that unless we receive your acknowledgement of receipt of this letter and its enclosures **within fourteen (14) days from the date hereof**, our client will have no alternative but to commence proceedings against your insured and/or his authorised driver without further reference or notice to you.

FURTHER, if you wish to conduct an inspection of our client's vehicle or to conduct a second inspection as the case may be, please let us have your written request **within seven (7) days of receipt of this letter of demand**. Please be reminded that our client shall enforce the above time lines strictly.

Please note that this claim is submitted without prejudice to our client's rights to claim damages for his/her personal injury as the case may be.

Yours faithfully

enc

cc Mr Lee Poh Hua
Block 302A Anchorvale Link
#15-58
Singapore 541302

CERTIFICATE OF POSTING

(We would advise you to report the accident to your insurers, M/s MSIG Insurance (Singapore) Pte Ltd, if you have not done so. We have forwarded all supporting documents to your insurers, M/s MSIG Insurance (Singapore) Pte Ltd. All supporting documents will be forwarded to you upon request. Please also notify us if you have a claim against our insured **within eight (8) weeks** from the date hereof.)

cc client

Enquire Vehicle & Owner Information (Vehicle No. SGK8666K As At 28 Apr 2018 / 15:40:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: SM.SAT.PRI.7214Y

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S7321885C

Owner Name: LEE POH HUA (LI BAOHUA)

Registered Address Type: HDB / HUDC

Registered Block/House No.: 302A

Registered Street Name: ANCHORVALE LINK

Registered Unit No.: # 15 - 58

Registered Building Name: -

Registered Postal Code: 541302

Current Vehicle Details

Vehicle No.: SGK8666K

Make Description/Model: TOYOTA / COROLLA ALTIS 1.6 AUTO

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

Thank you



Krishnamoorthi S/o Kolanthaveloo has successfully logged out.

Your last login date and time was 02 May 2018, 10:40:01.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount
1	Vehicle	SGK8666K	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49

Authorized Signature

SAT LEASING PTE LTD

Your preferred choice

24 Delu Lane 12, Singapore 539131
T: +65 6748 1141 F: +65 6749 1141
Email: sales@satmotors.com
Website: www.satmotors.com

Invoice Date: 17/5/2018
Invoice #: SI92
Sales Person / Contact no.:

Bill To :

NRIC / Passport No.:	S6930566J
Hirer's:	TAN SIEW ENG
Address:	BLK 307A ANCHORVALE RD #13-44
Postal Code:	541307

Details :

Car Plate:	SJP9421G	Reference:	
Make / Model:	Toyota Estima	Reference:	
Rental period:	30/4/18 - 17/05/18		
Type Of Rental:	15 Days		

Payment Details :

Being Payment For:							
Rental Period :	\$180.00	x	15	Days	\$	2,700.00	
Rental Deposit :							
Remarks :	Claim For SKX7214Y						
Total :						\$	2,700.00

Terms & Conditions:

The deposit will be used in the event of loss of or damage to the vehicle where the Renter will be fully liable on the cost of necessary repairs or replacement and the deposit will be credited towards the Owner. The Renter shall pay in for any excess amount for the rental or replacement cost if the deposit amount was insufficient. In the absence of damage or loss, the deposit will be return to the Renter after handing over the vehicle.
The Renter agree to compensate the Owner for the sum of deposit in the event of breach of contract.



SAT Leasing Pte Ltd
24 Defu Lane 12 Singapore 539131


Tel: 6748 1141 / Fax: 6749 1141
Email: satleasing@satmotors.com



VEHICLE RENTAL AGREEMENT

HIRER'S PARTICULARS	
Name: <u>THAN SIBU ENY</u>	
Address:	
Name & Address of Employer:	
IC / PP No: <u>S 64305667</u>	DL No:
Date of Birth:	Date of Issue/Expiry:
Nationality:	PL of Issue:
Occupation:	Driving Exp:
Tel No: (O) _____	(Home) _____ (HP) _____

2ND DRIVER'S PARTICULARS	
Name:	
Address:	
Name & Address of Employer:	
P No: _____	DL No: _____
Date of Birth:	Date of Issue/Expiry:
Nationality:	PL of Issue:
Occupation:	Driving Exp:
Tel No: (O) _____	(Home) _____ (HP) _____



A-Accidents C-Cracked D-Dents S-Scratches

VEHICLE'S PARTICULARS	
Vehicle No: <u>SP4426</u>	Repl. Vehicle No:
Make/Model: <u>TOYOTA GSTRIMA</u>	Make Model:
Mileage Out:	Mileage In:
Date Out: <u>30/4/18</u>	Date In:
Time Out:	Time In:
Hirer/Period Expiry	

RENTAL CHARGES	
Daily @ \$ _____	per day
Weekly @ \$ _____	per week
Monthly @ \$ _____	per month
Others @ \$ _____	
Delivery Service	
SUB TOTAL S\$ _____	

PETROL/DIESEL LEVEL						
OUT	E	1/4	1/2	3/4	F	
IN	E	1/4	1/2	3/4	F	
Extension of Rental						
Repairs/Damages						
Collection Service						
MISC						
GST @ 7%						
TOTAL CHARGES S\$ _____						

Security Deposit (Refundable after 3 working days)					
Advance Rental Paid By:					
CASH	NETS	CHEQUE	BILL	CARD	
Cheque/Card No:					
Expiry Date					
Amount Due/Refund					

<u>g.w. Jor.</u> x	<u>g.w. Jor.</u> x
Hirer's	Driver's
Signature & Stamp	Signature & Stamp

Refund	By
Received \$ \$ _____	Receiver _____ x

I/We have read and agree to the Terms & Conditions on both sides of this agreement. If I/We have presented a cheque/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my/our signature above will be considered to have been made on the cheque/credit card voucher. All information I/We have given SAT LEASING PTE LTD in connection with this agreement are true and accurate.

IMPORTANT

- 1) Only persons above 24 and below 65 years of age with 2 years driving experience, authorised, licensed and signing this agreement may drive the vehicle.
- 2) Vehicle is strictly for Singapore use only and may not be driven out of Singapore without prior consent of the company SAT LEASING PTE LTD.
- 3) Use of the vehicle for illegal purpose (for instance: In connection with theft, drug peddling or trafficking, smuggling is strictly prohibited).
- 4) Additional drivers are required to register with us before they are allowed to drive the vehicle. Otherwise, he/she will not be protected by the Insurance cover.
- 5) The hirer shall be liable for excess charges for any late return of the rate shown per hour or per day.
- 6) In case of accident, the hirer shall report to the owner immediately, if there is bodily injuries, a police report must be made within 24 hours.
- 7) No refund will be given for early return of vehicle.
- 8) The hirer is responsible for the first \$2,500 excess to the THIRD PARTY DAMAGE OR INJURY claims and/or also the first \$2,500 excess to the FIRST PARTY DAMAGE, property of SAT LEASING PTE LTD, upon payment for each and every accident/damage.

RETURN OF VEHICLE - The Hirer/Driver is required to sign in the column 'Signature of Hirer/Driver'. Failing which the day and time inserted below shall be deemed to be the day and time the vehicle is returned to SAT LEASING PTE LTD and the same shall be accepted as conclusive evidence of the same and shall not be challenged or questioned on any account whatsoever.

Date In	Time In	Mileage In	Checked By	Remarks	Signature of Hirer/Driver



ALLIN AUTOMOTIVE APPRAISERS

Block 805D, Keat Hong Close. #13-88 Singapore 684805

INVOICE

Bill To: AUTO MEGA MALL PTE. LTD.
24, DEFU LANE 12
SINGAPORE 539131
On behalf of TAN TEE YONG

Invoice No : ALLIN-05-0044

Date : 09.05.2018

Being:		
Survey Fees (including 59 photographs and transport charges)		\$ 579.00
Singapore Dollars : Five Hundred And Seventy Nine Only.		\$ 579.00
Our Reference No. : ALLIN-05-0184		
Vehicle No. : SKX7214Y		

SURVEYED WITHOUT PREJUDICE



Appraiser Name:
Lim Chang Liang, Jonathan



ALLIN AUTOMOTIVE APPRAISERS
Block 805D, Keat Hong Close. #13-88 Singapore 684805

TAN TEE YONG
c/o Auto Mega Mall Pte Ltd
24, Defu Lane 12
Singapore 539131

Report No : ALLIN-05-184
Date : 09.05.2018

Reference

Requested by : Workshop, owner's behalf
Date of Request : 30/4/2018
Date of Accident : 28/4/2018
Date of Inspection : 30/4/2018
Inspected at : Auto Mega Mall Pte Ltd
24, Defu Lane 12
Singapore 539131

Vehicle Details

Vehicle No.	: SKX7214Y	Make & Model	: HONDA ODYSSEY
Year Make	: 2015	Colour	: RED
Engine No.	: K24W72010314	Chassis No.	: JHMRC1880G201035
Engine Capacity	: 2,356cc	Mileage	:
Air-Con	: YES	Radio/CD/Cassette	: YES
Seat Belt	: YES	Rims	: SPORT

General Condition of Vehicle

General Condition	: GOOD	Modification	: NIL
Brakes	: SERVICEABLE	Handbrake	: SERVICEABLE
Steering	: SERVICEABLE		

<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Rim</u>	<u>Tread Balance</u>
Front Right	YOKOHAMA	215 /55 R17	SPORT	70%
Front Left	YOKOHAMA	215 /55 R17	SPORT	70%
Rear Right	YOKOHAMA	215 /55 R17	SPORT	70%
Rear Left	YOKOHAMA	215 /55 R17	SPORT	70%

Assessment

	<u>Repairer's Estimate</u>	<u>Recommendation</u>
Spare Parts	\$ 8,639.08	\$ 6,911.26
Labour Charges	\$ 2,040.00	\$ 1632.00
Paint Work	\$ 900.00	\$ 720.00
Towing Charges	\$	
Total	\$ 11,579.08	\$ 9,263.26

Recommend Lum Sum Repairs
Reduction

: \$ 9,263.26
: \$ 2,315.82

Estimated Period Required for Repair

: 12 Days



ALLIN AUTOMOTIVE APPRAISERS
Block 805D, Keat Hong Close. #13-88 Singapore 684805

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SKX7214Y
Chassis No: JHMRC1880G201035
Engine No: K24W72010314

Report No : ALLIN-05-184

Date : 09.05.2018

Replacement of Damaged Parts

S/No.	Quantity	Description	Condition / Remarks	Repairer's Estimates	My Recommendation
1	1	Front Bumper	Damaged	\$ 928.12	\$ 742.50
2	1	Front Bumper Lower Grille Garnish	Damaged	\$ 108.75	\$ 87.00
3	1	Front Grille	Damaged	\$ 301.14	\$ 240.91
4	2	Grille Moulding	Damaged	\$ 249.40	\$ 199.52
5	1	Front Bumper Fog Lamp Garnish	Damaged	\$ 56.45	\$ 45.16
6	1	Front Bumper Bracket	Necessary	\$ 39.90	\$ 31.92
7	1	Front Support Panel Left	Damaged	\$ 618.82	\$ 495.06
8	1	Wiper Tank Reservoir	Damaged	\$ 95.21	\$ 76.17
9	1	Headlamp	Damaged	\$ 1,214.09	\$ 971.27
10	1	Headlamp Retainer	Necessary	\$ 43.34	\$ 34.67
11	1	Wheel Arc Cowling	Deformed	\$ 162.07	\$ 129.66
12	1	Lower Engine Garnish	Necessary	\$ 232.80	\$ 186.24
13	1	Fender Inner Panel	Damaged	\$ 588.37	\$ 470.70
14	1	Front Right side Fender	Damaged	\$ 788.22	\$ 630.58
15	1	Rims	Damaged	\$ 1,200.00	\$ 960.00
16	1	Air Con Condenser	Damaged	\$ 455.70	\$ 364.56
17	1	Bonnet Hinge	Impacted	\$ 215.70	\$ 172.56
18	1	Bonnet Stand	Impacted	\$ 95.00	\$ 76.00
19	1	Lower Arm	Impacted	\$ 355.70	\$ 284.56
20	1	Front Right Absorber	Impacted	\$ 890.30	\$ 712.24
				\$ 8,639.08	\$ 6,911.26

Total (Parts): \$ 8,639.08 Less 20% \$ 6,911.26

Labour Charges

21	To fix & dismantle and remove damaged parts and affected Front Right affected damaged portion.	\$ 800.00	\$ 640.00
22	To apply anti rust coat and affected areas	\$ 60.00	\$ 48.00
23	To check wiring	\$ 80.00	\$ 64.00
24	Welding and cutting of affected panels, including chassis alignment.	\$ 1,000.00	\$ 800.00
25	Spray painting for Front Right affected parts.	\$ 900.00	\$ 720.00
26	To apply waterproofing sealer on affected panels	\$ 100.00	\$ 80.00
Total Labour:		\$ 2,940.00	\$ 2,352.00

Total cost of repairs (Total cost of parts + Total Labour Cost) \$11,579.08

\$ 9,263.26

Done o/s not nls

394.45
- 20%
3153.16
1360

4513.16



ALLIN AUTOMOTIVE APPRAISERS

Block 805D, Keat Hong Close. #13-88 Singapore 684805

Vehicle No: SKX7214Y

Report No.: ALLIN-05-184

Point of Impact

Recommendation

The vehicle was inspected thoroughly based on the repairer's estimate against the actual damages found on the vehicle. My findings and recommendation are listed as per attached.

My adjusted amount for the cost of repair is \$9,263.26

Conclusion

The repairer has agreed to undertake repairs at a lump sum of \$9,200.00 corresponding to labour charges, spray painting and replacement of parts.

SURVEYED WITHOUT PREJUDICE



Appraiser Name:
Lim Chang Liang, Jonathan

Vehicle ident no.
SKX 7214 Y

Date
10.5.18 16:24
Odometer reading: km/miles
44023

			Before	Target Data		Actual
Rear axle	Camber	left	-1°48'			-1°49'
		right	-1°37'	-1°00'	+/-0°45'	-1°36'
		cross	-0°11'	0°00'	+/-0°45'	-0°13'
	Toe	left	0°16'			0°16'
		right	0°00'	0°05'	+0°05' -0°03'	0°00'
		total	0°15'	0°10'	+0°10' -0°05'	0°16'
	Geometrical driving axis		0°08'	0°00'		0°08'
Front axle	Camber	left	-0°21'			-0°29'
		right	0°25'	0°00'	+/-0°45'	0°31'
		cross	-0°46'	0°00'	+/-0°45'	-1°00'
	Caster	left	4°56'			4°56'
		right	5°19'	4°40'	+/-0°45'	5°19'
		cross	-0°23'	0°00'		-0°23'
	SAI	left	12°23'			12°30'
		right	12°28'			12°21'
		cross	-0°05'	0°00'		0°09'
	Track differential angle		left			
		right				
Toe	left	-0°42'			-0°02'	
	right	-0°40'	0°00'	+/-0°05'	-1°2'	
	total	-1°22'	0°00'	+/-0°10'	-1°22'	
Setback			0°00'			
Max steering lock	left steer	left		-41°00'	+/-2°00'	
		right		33°00'	+/-2°00'	
	right steer	left		33°00'	+/-2°00'	
		right		-41°00'	+/-2°00'	

Vehicle ident no.
SKX 7214 Y

Date
10.5.18 16:24

Odometer reading km/miles
44023

			Before	Target Data		Actual
Rear axle	Camber	left	-1°48'	-1°00'	+/-0°45'	-1°51'
		right	-1°37'			-1°32'
		cross	-0°11'	0°00'	+/-0°45'	-0°19'
	Toe	left	0°16'	0°05'	+0°05' -0°03'	0°15'
		right	0°00'			0°00'
		total	0°15'	0°10'	+0°10' -0°05'	0°15'
	Geometrical driving axis		0°08'	0°00'		0°08'
	Camber	left	-0°21'	0°00'	+/-0°45'	-0°32'
		right	0°25'			0°26'
		cross	-0°46'	0°00'	+/-0°45'	-0°57'
Front axle	Caster	left	4°56'	4°40'	+/-0°45'	4°56'
		right	5°19'			5°19'
		cross	-0°23'	0°00'		-0°23'
	SAI	left	12°23'			12°33'
		right	12°28'			12°26'
		cross	-0°05'	0°00'		0°06'
	Track differential angle		left			
			right			
	Toe	left	-0°42'	0°00'	+/-0°05'	0°00'
		right	-0°40'			0°00'
		total	-1°22'	0°00'	+/-0°10'	0°00'
	Setback			0°00'		
	Max steering lock	left steer	left	-41°00'	+/-2°00'	
		right steer	right	33°00'	+/-2°00'	
		left steer	left	33°00'	+/-2°00'	
		right steer	right	-41°00'	+/-2°00'	



































...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 May 2018		03 May 2018 13:32 Edit Adj Rpt	S\$4,513.16 Edit Estimates	S\$4,513.16 View Rpt		Pending for Survey Report Cancel Case






















Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LEE POH HUA , ID: S7321885C								
Main Claimant:	TAN SIEW ENG , ID: S6930566J								
Vehicle Reg. No.:	SKX7214Y	Date of Loss:	28/04/2018 00:00 - :59 [28 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 557253	Policy/Cover Note No.:	29001380TMP Coverage: 29/08/2017 - 28/08/2018						
Vehicle Reg. No. (Insured):	SGK8666K	Policy No. (Claimant):							
		Excess:							
Repairer:	Sat Motors (HQ) 24 Defu Lane 12, 539131 Defu Lane - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 04/05/2018]								
Adj Asg. Remarks:	TP disagree with SJE Assign LKK Auto Consultants								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKX7214Y (557253)
[SGK8666K]
TP
TAN SIEW ENG
Apr 28 2018 12:00AM
[LEE POH HUA]
Sat Motors

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/05/18 18:12	Accident Statement Addm. #1 <small>From: SC - Reg. No: SGK8666K, Claimant: LEE POH HUA (LI BAOHUA)</small>	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
2	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
3	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
4	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
5	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
6	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
7	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
8	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
9	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
10	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
11	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
12	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
13	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
14	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
15	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
16	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
17	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
18	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
19	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
20	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
21	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
22	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
23	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
24	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
25	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
26	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
27	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
28	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
29	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
30	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
31	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
32	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
33	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
35	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
36	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
37	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
38	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
39	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
40	08/05/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
41	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	16/05/18 11:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
88	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	16/05/18 12:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/05/18 11:31	TP PRI Request	 Load PDF	
2	03/05/18 11:35	TP reject SJE- assign LKK	 Load PDF	
3	03/05/18 11:36	TP PRI Request Email	 Load PDF	
4	10/05/18 18:15	SKX7214Y e-file report From: SC - Reg. No: SGK8666K, Claimant: LEE POH HUA (LI BAOHUA)	 Load PDF	
5	10/05/18 18:15	SHC7242L e-file report From: SC - Reg. No: SGK8666K, Claimant: LEE POH HUA (LI BAOHUA)	 Load PDF	
6	03/08/18 17:27	lod and supporting documents	 Load PDF	
7	03/08/18 17:29	survy report.	 Load PDF	
8	14/08/18 13:24	SURVEY PHOTOS1	 Load PDF	
9	14/08/18 13:24	SURVEY PHOTOS2	 Load PDF	
10	14/08/18 13:24	SURVEY PHOTOS3	 Load PDF	
11	14/08/18 13:24	SURVEY PHOTOS4	 Load PDF	
12	14/08/18 13:24	SURVEY PHOTOS5	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/08/18 14:56	COLOUR PHOTO	 Load PDF	
2	27/08/18 14:56	PRS Invoice	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18008115/URBE2-1

Date: 27/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29001380TMP

Claimant Vehicle No : SKX7214Y

Insured Vehicle No : SGK8666K

Date of Loss: 28/04/2018

Nature of Claim: TP

Claim No: 557253

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKX7214Y

Make & Model: HONDA ODYSSEY, 2.4 EXV-S CVT SR (A)

Engine No: K24W72010314

Reg. Date: 23/12/2015 (Man. Year: 2015)

Chassis No: JHMRC1880GC201035

Colour: Red

Odometer: 43996 km

Engine Capacity: 2356 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Yokohama 8 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,639.08	3,153.16	5,485.92	63.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	1,360.00	1,580.00	53.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,579.08	4,513.16	7,065.92	61.02
+ GST 7.00/7.00% (S\$)	810.54	315.92	494.62	61.02
Nett Amount (S\$)	12,389.62	4,829.08	7,560.54	61.02

INSPECTION

Date of Assignment: 03/05/2018

Date Inspected: 04/05/2018

Inspected At:

Sat Motors (HQ)

24 Defu Lane 12

Singapore 539131

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Aug 2018)
Parts:	M1-SUV	HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX7214Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	928.12 F	*677.60 FL
2	1		*FRONT BUMPER LOWER GRILLE GARNISH	Torn	108.75 F	*108.75 FL
3	1		*FRONT GRILLE	Cracked	301.14 F	*301.14 FL
4	2		*GRILLE MOULDING	Necessary	249.40 F	*249.40 FL
5	1		*FRONT BUMPER FOG LAMP GARNISH	Twisted	56.45 F	*56.45 FL
6	1		*FRONT BUMPER BRACKET	Bent	39.90 F	*39.90 FL
7	1		*FRONT SUPPORT PANEL LEFT	Not Necessary	618.82 F	*- FL
8	1		*WIPER TANK RESERVOIR	Deformed	95.21 F	*95.21 FL
9	1		*HEADLAMP	Cracked	1,214.09 F	*1,214.09 FL
10	1		*HEADLAMP RETAINER	Cracked	43.34 F	*43.34 FL
11	1		*WHEEL ARC COWLING	Torn	162.07 F	*162.07 FL
12	1		*LOWER ENGINE GARNISH	Not Necessary	232.80 F	*- FL
13	1		*FENDER INNER PANEL	Repair	588.37 F	*- FL
14	1		*FRONT RIGHT SIDE FENDER	Buckled	788.22 F	*537.80 FL
15	1		*RIMS	Not Changed	1,200.00 F	*- FL
16	1		*AIR CON CONDENSER	Punctured	455.70 F	*455.70 FL
17	1		*BONNET HINGE	Not Necessary	215.70 F	*- FL
18	1		*BONNET STAND	Not Necessary	95.00 F	*- FL
19	1		*LOWER ARM	Not Changed	355.70 F	*- FL
20	1		*FRONT RIGHT ABSORBER	Not Changed	890.30 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	8,639.08	3,941.45
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	788.29
Total Parts (\$\$)	8,639.08	3,153.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO FIX & DISMANTLE AND REMOVE DAMAGED PARTS AND AFFECTED FRONT RIGHT AFFECTED DAMAGED PORTION }	New	800.00	0.00
2	WELDING AND CUTTING OF AFFECTED PANELS, INCLUDING CHASSIS ALIGNMENT }	New	1,000.00	600.00
3	TO APPLY ANTI RUST COAT AND AFFECTED AREAS	New	60.00	30.00
4	TO CHECK WIRING	New	80.00	30.00
5	SPRAY PAINTING FOR FRONT RIGHT AFFECTED PARTS	New	900.00	700.00
6	TO APPLY WATERPROOFING SEALER ON AFFECTED PANELS	New	100.00	0.00
Gross Labour Cost (\$\$)			2,940.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >