

2209/2000

ASS. REC. BY:

REF:

CS/FCI18014740/Urbn2

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

cus

Terene Jan

of

FCI

Date/Time:

14/8/18 @ 6.43pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJK 6992X

Insured:

SHC 7526T

at Workshop m/s

Progressive Auto

Tel:

68444620

of

No. 1, Kelci Bkt Ave 6 #02-48

Policy No:

Claim No:

D18006033MF5H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(Ds)

H.O.D. Endorsement:

Date/Time:

9:39am @ 15/8/18

Person Contacted:

Mandy

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SJK 6992X - X
	SHC 7526T - X
14/8/18 @ 4:21pm	revised to name by email.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / 19 / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: *SJK 6992*at Workshop m/s *PA Kelci*

of: _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection:

Est. or Market Value: *106.*

IDAC Accident Rpt: _____ Consistent?: Yes or No

CA / PR Seen: *✓* Consistent?: Yes or NoEst. Repairs: *8* days: Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 6973

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

*rental car per month 1400k. 2 mth. 19 day.**25/8/18 LTA 6973 net 3027 conf.rmd L/S \$3000 with MR way (Ref # 6954.88, 69%)*

RECEIVED 30 AUG 2018

(EST)

MV: 10.000 LTA: 6973. NV: 3027

Date/Time, File Pass to?

☐ : Prell. Report*30/8 12/15/18*☐ : Final Report

Date/Time, File Return to?

2)

Report Format: *TP*Lump Sum / I.B.A. (\$) *3000*Days Of Repair: *8*Resurvey No. of Trip: *1*

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$1

Photos

Others

TOTAL

*170**50**50**102**372**Fc1*Veh No: *SJK 6992X* Yr Regn: *30/10 08*Type: *CA* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Move:Truck / Trailer of: *CA*Make: *Honda Fit Skyroof* *1339*Colour: *Silver* A/C: Insured / Std / NI / NoSp. Reading: *130715* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *6E61106400*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: *CA* / STD A/Rim orTyre Size: F: *185/55R15*

R: _____

BS / DJN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. *6* mmL/Bal. *6* mmD.O.A. *11/8/18*

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roach or

Rear & Lf

The U/C / Chassis frame / Body Structure affected due to collision.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18014740/Uqb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 14-08-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7526T	Veh. Inspected	SJK 6992X
Policy No.		Coverage (\$)	0.00
Claim No.	D18006033MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	14/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	11/08/2018	Inspection Date	14/08/2018
Survey held at	PROGRESSIVE AUTO PTE LTD NO.1 KAKI BUKIT AVE 6 #02-48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006033MFSH

Date: 15 August 2018

Our Ref: CS/FCI18014740/Uqb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJK 6992X

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/08/2018 at the premises of M/s PROGRESSIVE AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>9,754.88</u>
Revised Estimate Amount	: S\$ <u>6,250.16</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the rear & front portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	13-08-2018	Our Ref No. D18006033MFSH
Accident Date	11-08-2018	Claim Type. Third Party
Insured Vehicle	SHC7526T	Third Party Vehicle. SJK6992X
Survey Location	NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48/50	
Contact Person.	MANDY SIN	
Contact No.	68444620/ 0	Fax No. 68444625
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PROGRESSIVE AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 15 August 2018 4:21 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006033MFSH/1
Attachments: CSFC118014740Uqb.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SJK 6992X.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 15 August 2018 9:43 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006033MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 14 August 2018 6:42 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; cwsmotorclaims@msfirstcapital.com.sg
Subject: PRI: SURVEY ASSESSMENT - D18006033MFSH/1

Please find below link to download document
[Jobsheet_D18006033MFSH_TPD1.pdf](#)

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.



Honda Fit

Price Range ▼

Depreciation ▼

2008 ▼

Vehicle Type ▼

Home » Used Cars » Rydecity Automobiles Pte Ltd » Honda Fit 1.3A G

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Honda Fit 1.3A G

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Car Details

Price \$9,300**Depreciation** -**Reg Date** 16-Sep-2008
(1mth COE left)**Manufactured** 2008**Mileage** -**Transmission** Auto**Engine Cap** 1,339 cc**Road Tax** \$590 /yr**Power** 73.0 kW (97 bhp)
View specs of the Honda Fit (2008-2013)**Curb Weight** 1,010 kg**Features** -**Accessories** -**COE** -**OMV** \$11,782**ARF** \$11,782**Dereg Value** \$5,891 as of today (change)**No. of Owners** 3**Type of Veh** Hatchback**Category** PARF Car**Availability** Available

Add to Shortlist

Add to Compare

Add a Note

Compare



Seller Infor

Company

Address

Contact Perso

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0501N
Vehicle Details	
Vehicle No.:	SJK6992X
Vehicle to be Exported:	Yes
Intended De-registration Date:	14 Aug 2018
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G SKYROOF A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	L13A4118028
Chassis No.:	GE61106400
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$13,493.00
Original Registration Date:	30 Oct 2008
First Registration Date:	30 Oct 2008
Transfer Count:	4
Actual ARF Paid:	\$13,493.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2018
PARF Rebate Amount:	\$6,746.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$10,989.00
COE Rebate Amount:	\$227.00
Total Rebate Amount:	\$6,973.00

The information contained herein is correct as at 14 Aug 2018

OK

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
 TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg
 GST:200712509E RCB NO:200712509E

*Not Allowed
 2/5/18 3000/
 14/8/18
 Take photo after repair
 Sdy*

M/S : FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

TEL: 6507 3848 FAX: 6507 3849

ATTN: Motor Claim Department

Your Ref No: SJK6992X

Claim Type: Third Party

Accident Date: 11-08-2018

TP Veh Reg No: SHC7526T

Estimate No: EST0000682

Date: 11 Aug 2018

Policy No: 5100668867

Veh Reg No: SJK6992X

Make/Model: HONDA FIT

Chassis No: GE61106400

Engine No: L13A4118028

Reg. Date: 30-10-2008

Estimate Repair Cost to Vehicle No :SJK6992X

Description	U/Price	Quantity	List Price SS	Amount SS
SJK6992X HONDA FIT				
List Price				
1 Rear Boot <i>300/500</i>	660.7000	1 PC	660.70	✓
2 Rear Boot Lock <i>20/50</i>	242.8000	1 PC	242.80	✓
3 Rear Boot Lock Catch <i>11</i>	86.5000	1 PC	86.50	X
4 Rear Boot Rubber <i>twi</i>	68.9000	1 PC	68.90	X
5 Rear Boot Inner Cover Board <i>11</i>	125.6000	1 PC	125.60	✓
6 Rear End Panel <i>300/500</i>	276.5000	1 PC	276.50	✓
7 Rear End Panel Top Garnish <i>twi</i>	110.1000	1 PC	110.10	✓
8 Rear Spare Tyre Panel <i>11</i>	737.0000	1 PC	737.00	X
9 Rear Spare Tyre Top Cover Board <i>mayah</i>	204.6000	1 PC	204.60	✓
10 Rear Tail Lamp <i>one</i>	246.8000	2 PC	493.60	✓
11 Rear Bumper <i>20</i>	470.2000	1 PC	470.20	✓
12 Rear Bumper Side Retainer <i>300</i>	22.7000	2 PC	45.40	✓
13 Rear Bumper Towing Cover <i>70.11</i>	14.2000	1 PC	14.20	✓
14 Rear Boot Cover Clips <i>11</i>	5.5000	4 PC	22.00	✓
15 Rear Boot Emblem <i>F.1</i>	16.2000	1 PC	16.20	✓
16 Rear Windscreen Seal <i>11</i>	52.2000	1 PC	52.20	✓
17 Front Bonnet <i>11</i>	464.4000	1 PC	464.40	X
18 Front Bonnet Hinges <i>11</i>	38.6000	2 PC	77.20	X
19 Front Bonnet Lock <i>11</i>	45.2000	1 PC	45.20	X
20 Front Support Panel <i>11</i>	360.3000	1 PC	360.30	X
21 Front Head Lamp <i>11</i>	529.7000	2 PC	1,059.40	X
22 Front Grille <i>11</i>	116.2000	1 PC	116.20	X
23 Front Bumper <i>20</i>	523.5000	1 PC	523.50	✓
24 Front Bumper Reinforcement <i>300</i>	160.2000	1 PC	160.20	✓
25 Front Bumper Side Retainer <i>300</i>	13.1000	2 PC	26.20	✓
26 Front Head Lamp Lower Bracket <i>11</i>	35.1000	2 PC	70.20	X
27 Front Bumper Lower Grille <i>twi</i>	89.2000	1 PC	89.20	✓
28 Front Battery Top Cover <i>11</i>	35.2000	1 PC	35.20	X
29 Front Grille Emblem <i>11</i>	16.2000	1 PC	16.20	X
30 Front Aircon Condenser <i>pan/300</i>	786.2000	1 PC	786.20	✓
			7,456.10	
			Less 20%	1,491.22
				5,964.88
Special Net				
31 Rear Bumper Sensor <i>sketch</i>	300.0000	<i>1 PC</i>	300.00	200
32 Rear Windscreen Gum <i>11</i>	80.0000	1 PC	80.00	40
33 Front Number Plate <i>300</i>	50.0000	1 PC	50.00	40

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg

GST:200712509E RCB NO:200712509E

M/S : FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 6507 3848

FAX: 6507 3849

ATTN: Motor Claim Department

Your Ref No: SJK6992X

Claim Type: Third Party

Accident Date: 11-08-2018

TP Veh Reg No: SHC7526T

Estimate No: EST0000682

Date: 11 Aug 2018

Policy No: 5100668867

Veh Reg No: SJK6992X

Make/Model: HONDA FIT

Chassis No: GE61106400

Engine No: L13A4118028

Reg. Date: 30-10-2008

Estimate Repair Cost to Vehicle No :SJK6992X

Description	U/Price	Quantity	List Price	Amount
			SS	SS
			430.00	430.00
Labour				
34 Panel Beating	1,800.000	1 PC	1,800.00	1200
35 Check Wiring	80.0000	1 PC	80.00	30
36 Rust Proofing	80.0000	1 PC	80.00	✓
37 To Remove & Replace Air Con Condenser and Change Gas	160.0000	1 PC	160.00	100
38 To Remove & Refit Windscreen	160.0000	1 PC	160.00	120
39 To Remove & Replace Bumper Sensor	80.0000	1 PC	80.00	60
40 Spray Painting	1,000.000	1 PC	1,000.00	980
			3,360.00	3,360.00
Total			SS 9,754.88	

TOTAL: SINGAPORE DOLLAR NINE THOUSAND SEVEN HUNDRED FIFTY FOUR AND CENTS EIGHTY EIGHT ONLY

For PROGRESSIVE AUTO PTE LTD

AUTHORISED SIGNATURE



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18014740/Uqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7526T	Veh. Inspected	SJK 6992X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006033MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	14/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT SKYROOF (A)	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	GE61106400	Colour	SILVER	
Odometer	130725	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	185/55 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	185/55 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	185/55 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/08/2018	Inspection Date	14/08/2018	
Survey held at	PROGRESSIVE AUTO PTE LTD NO.1 KAKI BUKIT AVE 6 #02-48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 6992X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT	BADLY DENTED	660.70	660.70
1	REAR BOOT LOCK	DENTED / JAMMED	242.80	242.80
1	REAR BOOT LOCK CATCH	NOT NECESSARY	86.50	-
1	REAR BOOT RUBBER	TWISTED	68.90	68.90
1	REAR BOOT INNER COVER BOARD	NOT NECESSARY	125.60	-
1	REAR END PANEL	BADLY DENTED	276.50	276.50
1	REAR END PANEL TOP GARNISH	TWISTED	110.10	110.10
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	737.00	-
1	REAR SPARE TYRE TOP COVER BOARD	WARPED	204.60	204.60
2	REAR TAIL LAMP @\$246.80	CRACKED	493.60	493.60
1	REAR BUMPER	DENTED	470.20	470.20
2	REAR BUMPER SIDE RETAINER @\$22.70	BENT	45.40	45.40
1	REAR BUMPER TOWING COVER	TORN	14.20	14.20
4	REAR BOOT COVER CLIPS @\$5.50	NECESSARY	22.00	22.00
1	REAR BOOT EMBLEM FIT	NECESSARY	16.20	16.20
1	REAR WINDSCREEN SEAL	NECESSARY	52.20	52.20
1	FRONT BONNET	TO REPAIR SEE LABOUR	464.40	-
2	FRONT BONNET HINGES @\$38.60	NOT NECESSARY	77.20	-
1	FRONT BONNET LOCK	NOT NECESSARY	45.20	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	360.30	-
2	FRONT HEAD LAMP @\$529.70	NOT NECESSARY	1,059.40	-
1	FRONT GRILLE	NOT NECESSARY	116.20	-
1	FRONT BUMPER	DENTED	523.50	523.50
1	FRONT BUMPER REINFORCEMENT	BENT	160.20	160.20
2	FRONT BUMPER SIDE RETAINER @\$13.10	BENT	26.20	26.20
2	FRONT HEAD LAMP LOWER BRACKET @\$35.10	NOT NECESSARY	70.20	-
1	FRONT BUMPER LOWER GRILLE	TWISTED	89.20	89.20
1	FRONT BATTERY TOP COVER	NOT NECESSARY	35.20	-
1	FRONT GRILLE EMBLEM	NOT NECESSARY	16.20	-

Report Ref No. CS/FCI18014740/Uqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT AIRCON CONDENSER	BENT / PUNCTURE	786.20	786.20
	LESS 20% DISCOUNT		-1,491.22	-852.54
			5,964.88	3,410.16
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER SENSOR (SN)	SHORTED	300.00	200.00
1	REAR WINDSCREEN GUM (SN)	NECESSARY	80.00	40.00
1	FRONT NUMBER PLATE (SN)	BENT	50.00	40.00
			430.00	280.00
	<u>LABOUR</u>			
	PANEL BEATING INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE PANEL, FRONT BONNET AND FRONT SUPPORT PANEL.		1,800.00	1,200.00
	CHECK WIRING.		80.00	30.00
	RUST PROOFING.		80.00	80.00
	TO REMOVE & REPLACE AIR CON CONDENSER AND CHANGE GAS.		160.00	100.00
	TO REMOVE & REFIT WINDSCREEN.		160.00	120.00
	TO REMOVE & REPLACE BUMPER SENSOR.		80.00	50.00
	SPRAY PAINTING.		1,000.00	980.00
			3,360.00	2,560.00
GRAND TOTAL			9,754.88	6,250.16
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CS/FC118014740/Uqbn2

MARKET VALUE: \$10,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$6,973.00=NETT VALUE: \$3,027.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.