

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AXA	DATE	: 13/08/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: GBD9049G		
MODEL	: NISSAN NV350		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>			
DATE	: 8-Aug-18		
TIME	: 13:40HRS		
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Dented.</i>	1	\$ 2,150.90	\$ 2,150.90
2	REAR BUMPER <i>Del</i>	1	\$ 690.00	\$ 690.00
3	REAR BUMPER STEP PANEL <i>N/A</i>	1	\$ 288.60	\$ 288.60

2840.50
1988.63

TOTAL PRICE \$ 3,129.50
LESS 30% \$ 938.85
SUB TOTAL PRICE \$ 2,190.65

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE LOGO	1	\$ 73.20	\$ 73.20
2	TAIL GATE EMBLEM 'NV350'	1	\$ 80.00	\$ 80.00
3	TAIL GATE EMBLEM 'URVAN'	1	\$ 77.40	\$ 77.40
4	TAIL GATE TOP LOCK	1	\$ 320.80	\$ 320.80
5	TAIL GATE CATCH	1	\$ 89.70	\$ 89.70
6	TAIL GATE WEATHER STRIP	1	\$ 219.30	\$ 219.30
7	REAR BUMPER SIDE RETAINER	2	\$ 62.30	\$ 124.60

8	REAR BUMPER AIR VENT <i>new</i>	1	\$ 98.80	\$ 98.80	<i>+</i>
9	REAR END PANEL (OUTER) <i>Dented</i>	1	\$ 355.30	\$ 355.30	<i>✓</i>
10	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 191.10	\$ 191.10	<i>-</i>
11	TAIL LAMP <i>cracked</i>	1	\$ 374.40	\$ 374.40	<i>-</i>

1402.6
1262.34

281.70

TOTAL PRICE \$ 2,004.60
LESS 10% \$ 200.46
SUB TOTAL PRICE \$ 1,804.14

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	TAIL GATE INNER SEAL <i>new</i>	1	\$ 120.00	\$ 120.00	<i>+</i>
2	TAILGATE STICKER 70KM/H <i>3 new</i>	1	\$ 30.00	\$ 30.00	<i>10</i>
3	TAILGATE STICKER 8PAX	1	\$ 30.00	\$ 30.00	<i>10</i>
4	TAIL GATE WINDSCREEN SEALANT <i>3 new</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
5	TAIL GATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	<i>30</i>
6	REAR BUMPER CLIPS(SET) <i>new</i>	1	\$ 35.00	\$ 35.00	<i>30</i>
7	REAR END PANEL SEALANT (OUTER) <i>new</i>	1	\$ 120.00	\$ 120.00	<i>60</i>
8	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	<i>200</i>

370

TOTAL \$ 695.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$1,200.00	<i>800</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$1,000.00	<i>700</i>	
3	TUFF COAT	\$150.00	<i>40</i>	
4	WIRING CHECK	\$120.00	<i>30</i>	
5	TRANSFER TAILGATE MECHANISM	\$100.00	<i>80</i>	
6	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>✓</i>	
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$120.00	<i>50</i>	

TOTAL

\$2,810.00

1820

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	4,689.79
TOTAL LABOUR COST	:	\$	2,810.00
TOTAL REPAIR COST	:	\$	7,499.79

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian King
13/08/18
05 Days

total: 5440.87
2/5: 4.3K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: