



Tanpura

REF:

LPc

ASSIGNMENT

CoE 2023 April

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD/TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

\$23K

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR. Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

9

days

Res.: \_\_\_\_\_

Yes or No

Lump Sum: \_\_\_\_\_

%

3 Val: \_\_\_\_\_

Yes or No

CA / REV / REP. / 24 HRS

WP

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Ms. Mary

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Battery needs

\$5K

Veh No: GW2334U Yr Regn: 2003 April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: \_\_\_\_\_

Tofa Lease  
\$4000

CS 284

Colour: \_\_\_\_\_

A/C

Insured / Std / NI / NA

Sp Reading: \_\_\_\_\_

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

CR 425005104

Gen Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size: \_\_\_\_\_

F: \_\_\_\_\_

165 R13

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: \_\_\_\_\_

6

mm

R/Bal: \_\_\_\_\_

5

mm

L/Bal: \_\_\_\_\_

6

mm

L/Bal: \_\_\_\_\_

6

mm

D.O.A. \_\_\_\_\_

D.O.I. \_\_\_\_\_

13/8/18 @ 1540

Survey held at \_\_\_\_\_

Wan May

Bnt BTH

Des. of Damages: \_\_\_\_\_

Frnt

Rear

O/S

NI

U/C

Rooftop

or

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Insp (\$

☐

: Weekend (\$

Survey Fee:

Transportation

\$ - RS - SI

Photos

Other

TOTAL

R(\$6,018.60/55%)

## Woon Meng Motor Pte Ltd

Office : 140 Upper Bukit Timah Road, #03-15 Beauty World Plaza, Singapore 588176

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

( Email Address : woonmeng @singnet.com.sg )

Co Reg No. 200603678M

GST Reg No. 20-0603678M

### Estimate

To : Lonpac Insurance Bhd  
Motor Claims Dept

### TP CLAIM

Date : 13 Aug 2018

Dear Sirs :

Fax : 68968706

### RE : ESTIMATE COST FOR TOYOTA LIEACE 5DR - GW2334U

ACCIDENT INVOLVING GW2334U,GBC6243L & XD5923Z ON 06/08/2018

| <u>ITEMS</u>                   | <u>DESCRIPTION</u>                    | <u>QTY</u> | <u>PRICE</u>         |
|--------------------------------|---------------------------------------|------------|----------------------|
| 1                              | Front bonnet.                         | 1pc        | \$ 180.00 <i>bt</i>  |
| 2                              | Front bonnet lock.                    | 1pc        | \$ 60.00 <i>bt</i>   |
| 3                              | Front bonnet hinge @\$30ea.           | 2pcs       | \$ 60.00 <i>bt</i>   |
| 4                              | Front bonnet side rubber o/s.         | 1pc        | \$ 30.00 <i>cut</i>  |
| 5                              | Air cleaner box.                      | 1pc        | \$ 180.00 <i>car</i> |
| 6                              | Front wiper garnish.                  | 1pc        | \$ 155.00 <i>de</i>  |
| 7                              | Front fender @\$155ea                 | 2pcs       | \$ 310.00 <i>bt</i>  |
| 8                              | Front fender lamp @\$28ea             | 2pcs       | \$ 56.00 <i>car</i>  |
| 9                              | Front fender garnish o/s.             | 1pc        | \$ 65.00 <i>de</i>   |
| 10                             | Front mudflat @\$15ea                 | 1pc        | \$ 30.00 <i>xm</i>   |
| 11                             | Front fender side mirror garnish n/s. | 1pc        | \$ 32.00 <i>car</i>  |
| 12                             | Front door n/s.                       | 1pc        | \$ 320.00 <i>bt</i>  |
| 13                             | Front door hinge n/s @\$45ea          | 2pcs       | \$ 90.00 <i>car</i>  |
| 14                             | Front door chek n/s.                  | 1pc        | \$ 35.00 <i>xm</i>   |
| 15                             | Front door lock n/s.                  | 1pc        | \$ 62.00 <i>xm</i>   |
| 16                             | Front bumper beam.                    | 1pc        | \$ 50.00 <i>bt</i>   |
| 17                             | Front bumper.                         | 1pc        | \$ 165.00 <i>mis</i> |
| 18                             | Front bumper reinforcement.           | 1pc        | \$ 58.00 <i>bt</i>   |
| <b>Balance Carried Forward</b> |                                       |            | \$ 1,938.00          |

\$ 1,938.00

|                                |                                      |       |    |                 |               |
|--------------------------------|--------------------------------------|-------|----|-----------------|---------------|
| 19                             | Front bumper fog lamp cover @\$55ea. | 2pcs  | \$ | 110.00          | mis           |
| 20                             | Front headlamp @\$85ea               | 2pcs  | \$ | 170.00          | cur           |
| 21                             | Front headlamp grille @\$58ea        | 2pcs  | \$ | 116.00          | cur           |
| 22                             | Front side lamp @\$65ea              | 2pcs  | \$ | 130.00          | out           |
| 23                             | Front center grille.                 | 1pc   | \$ | 95.00           | mis           |
| 24                             | Emblem.                              | 1pc   | \$ | 98.00           | up            |
| 25                             | Clips @\$1ea.                        | 10pcs | \$ | 10.00           | all           |
| 26                             | Front support panel.                 | 1pc   | \$ | 230.00          | bt            |
| 27                             | Front support bace panel.            | 1pc   | \$ | 40.00           | bt            |
| 28                             | Front radiator.                      | 1pc   | \$ | 250.00          | cur           |
| 29                             | Front radistor fan cowlng.           | 1pc   | \$ | 105.00          | cur           |
| 30                             | Front radiator fan blade.            | 1pc   | \$ | 80.00           | jun           |
| 31                             | Front radiator fan motor.            | 1pc   | \$ | 195.00          | jun           |
| 32                             | Front air con condenser.             | 1pc   | \$ | 230.00          | bt            |
| 33                             | Front wheel house@\$250ea            | 2pcs  | \$ | 500.00          | LH-XR, RH-250 |
| 34                             | Horn.                                | 1pc   | \$ | 60.00           | del           |
| 35                             | Wiper tank.                          | 1pc   | \$ | 90.00           | del           |
| 36                             | Spare tank.                          | 1pc   | \$ | 115.00          | del           |
| 37                             | Fuel box.                            | 1pc   | \$ | 250.00          | cur           |
| 38                             | Top hose.                            | 1pc   | \$ | 55.00           | x un          |
| 39                             | Discharge hose.                      | 1pc   | \$ | 105.00          | bt            |
| 40                             | Suction hose.                        | 1pc   | \$ | 120.00          | bt            |
| 41                             | Air con valve.                       | 1pc   | \$ | 50.00           | x un          |
| 42                             | Air con dryer.                       | 1pc   | \$ | 50.00           | del           |
| 43                             | Front windscreen glass.              | 1pc   | \$ | 320.00          | cur           |
| 44                             | Front windscreen moulding.           | 1pc   | \$ | 40.00           | del           |
| 45                             | Nozzle @\$55ea.                      | 2pcs  | \$ | 110.00          | x un          |
| 46                             | Engine mounting @\$58ea.             | 2pcs  | \$ | 116.00          | x un          |
| 47                             | Idler pulley                         | 1pc   | \$ | 55.00           | x un          |
| 48                             | Timing belt.                         | 1pc   | \$ | 50.00           | x un          |
| 49                             | Fuel filter.                         | 1pc   | \$ | 45.00           | fun           |
|                                |                                      |       | \$ | 5,928.00        |               |
|                                |                                      |       | \$ | 1,185.60        |               |
| <b>Balance Carried Forward</b> |                                      |       | \$ | <b>7,113.60</b> |               |

**Balance Carried Forward****\$ 7,113.60**

|    |                           |     |    |                    |      |
|----|---------------------------|-----|----|--------------------|------|
| 50 | Front windscreen sealant. | 1pc | \$ | 40.00              | nl ✓ |
| 51 | Front ERP bracket.        | 1pc | \$ | 15.00              | nl ✓ |
| 52 | Coolant.                  | 1pc | \$ | 35.00              | nl ✓ |
| 53 | Front number plate.       | 1pc | \$ | 25.00              | nl ✓ |
|    |                           |     |    | <b>\$ 7,228.60</b> |      |

**Labour Charge & Misc**

|                                                      |        |           |                  |           |
|------------------------------------------------------|--------|-----------|------------------|-----------|
| Towing fee.                                          |        | \$        | 60.00            | ✓         |
| To remove, repair, replace & install damaged parts.  | }<br>} | \$        | 1,300.00         | 1000      |
| To R & R front radiator.                             |        | \$        | 120.00           | 100.      |
| To R & R air con system.top up air con gas.          |        | \$        | 150.00           | 100       |
| To remove & install door mechanism and for function. | }<br>} | \$        | 100.00           | 60.       |
| To remove & replace front windscreen glass.          |        | \$        | 150.00           | 120. nl ✓ |
| To repair & straighten chassis.                      |        | \$        | 350.00           | xun.      |
| To R & R wiring.                                     |        | \$        | 60.00            | 40        |
| To putty & spray painting.                           |        | \$        | 1,500.00         | 1200.     |
| <b>Total</b>                                         |        | <b>\$</b> | <b>11,018.60</b> |           |

All prices quoted are subjected to 7% GST

This is a computer generated document. No signature is required.

**LKK Auto Consultants hence notify****The Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4/5/5000  
9dys

# Woon Meng Motor Pte Ltd

Office : 140 Upper Bukit Timah Road, #03-15 Beauty World Plaza, Singapore 588176

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

( Email Address : woonmeng @singnet.com.sg )

Co Reg No. 200603678M

GST Reg No. 20-0603678M

## Estimate

*hong pai insurance*

**TP CLAIM**

To : India International Insurance Pte Ltd  
Motor Claims Dept

Date : 02 Jan 2015

Dear Sirs :

Fax : 6224 4174

**RE : ESTIMATE COST FOR TOYOTA LIEACE 5DR - GY3123U**  
**ACCIDENT INVOLVING GY3123U & SHB8382P ON 29/12/2014**

| <u>ITEMS</u>                   | <u>DESCRIPTION</u>                              | <u>QTY</u> | <u>PRICE</u> |
|--------------------------------|-------------------------------------------------|------------|--------------|
| 1                              | Front bonnet. <i>bt</i>                         | 1pc        |              |
| 2                              | Front bonnet lock. <i>bt</i>                    | 1pc        |              |
| 3                              | Front bonnet hinge @\$53.ea. <i>bt</i>          | 2pcs       |              |
| 4                              | Front bonnet side rubber o/s. <i>wt</i>         | 1pc        |              |
| 5                              | Air cleaner box. <i>ae</i>                      | 1pc        |              |
| 6                              | Front wiper garnish. <i>de</i>                  | 1pc        |              |
| 7                              | Front fender @\$ <i>bt</i>                      | 2pcs       |              |
| 8                              | Front fender lamp @\$ ?                         | 2pcs       |              |
| 9                              | Front fender garnish o/s. <i>de</i>             | 1pc        |              |
| 10                             | Front mudflat @\$ <i>x</i>                      | 1pc        |              |
| 11                             | Front fender side mirror garnish n/s. <i>ae</i> | 1pc        |              |
| 12                             | Front door n/s. <i>bt</i>                       | 1pc        |              |
| 13                             | Front door hinge n/s @\$ ?                      | 2pcs       |              |
| 14                             | Front door chek n/s. ?                          | 1pc        |              |
| 15                             | Front door lock n/s. <i>x</i>                   | 1pc        |              |
| 16                             | Front bumper beam. <i>bt</i>                    | 1pc        |              |
| 17                             | Front bumper. <i>wt</i>                         | 1pc        |              |
| 18                             | Front bumper reinforcement. <i>bt</i>           | 1pc        |              |
| <b>Balance Carried Forward</b> |                                                 |            | \$ -         |

### Balance Carried Forward

|                         |                                            |              |
|-------------------------|--------------------------------------------|--------------|
| 19                      | Front bumper retainer @\$38ea. <i>del</i>  | 2pcs         |
| 20                      | Front bumper fog lamp cover @\$ <i>mis</i> | 2pcs         |
| 21                      | Front headlamp @\$ <i>del</i>              | 2pcs         |
| 22                      | Front headlamp grille @\$ <i>del</i>       | 2pcs         |
| 23                      | Front side lamp @\$ <i>del</i>             | 2pcs         |
| 24                      | Front center grille. <i>mis</i>            | 2pcs         |
| 25                      | Emblem. <i>del</i>                         | 1pc          |
| 26                      | Clips @\$5ea. <i>del</i>                   | 10pcs        |
| 27                      | Front support panel. <i>bt</i>             | 1pc          |
| 28                      | Front support base panel. <i>bt</i>        | 1pc          |
| 29                      | Front radiator. <i>del</i>                 | 1pc          |
| 30                      | Front radiator fan cowling. <i>del</i>     | 1pc          |
| 31                      | Front radiator fan blade. <i>del</i>       | 1pc          |
| 32                      | Front radiator fan motor. <i>del</i>       | 1pc          |
| 33                      | Front air con condenser. <i>del</i>        | 1pc          |
| 34                      | Front wheel house @\$ <i>LH-RH, RH-bt</i>  | 2pcs         |
| 35                      | Horn. <i>del</i>                           | 1pc          |
| 36                      | Wiper tank. <i>del</i>                     | 1pc          |
| 37                      | Spare tank. <i>del</i>                     | 1pc          |
| 38                      | Fuel box. <i>del</i>                       | 1pc          |
| 39                      | Top hose. <i>?</i>                         | 1pc          |
| 40                      | Discharge hose. <i>bt</i>                  | 1pc          |
| 41                      | Suction hose. <i>bt</i>                    | 1pc          |
| 42                      | Air con valve. <i>?</i>                    | 1pc          |
| 43                      | Air con dryer. <i>del</i>                  | 1pc          |
| 44                      | Front windscreen glass. <i>del</i>         | 1pc          |
| 45                      | Front windscreen moulding. <i>del</i>      | 1pc          |
| 46                      | Nozzle @\$ <i>?</i>                        | 2pcs         |
|                         |                                            | \$ -         |
| Add 20%                 |                                            | \$ -         |
| 47                      | Front windscreen sealant. <i>del</i>       | 1pc \$ 40.00 |
| 48                      | Front ERP bracket. <i>del</i>              | 1pc \$ 15.00 |
| 49                      | Coolant. <i>del</i>                        | 1pc \$ 35.00 |
| 50                      | Front number plate. <i>mis</i>             | 1pc \$ 25.00 |
| Balance Carried Forward |                                            | \$ -         |

## Balance Carried Forward

### Labour Charge & Misc

Towing fee.

To remove, repair, replace & install damaged

1000

To numbering logo.

X

To R & R front radiator.

100

To R & R air con system. top up air con gas.

900

To remove & replace front windscreen glass.

120

To repair & straighten chassis.

200 putu

To remove & install door mechanism }  
and for function. }

60

To R & R wiring.

40

To putty & spray painting.

1200

**Total**

\$ -

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495749  
-wp-  
13/8/18 @ 4pm  
Resurvey after repair  
sur @ 11am to 6pm  
Repair limit \$5000  
of days.

## Nivitha (LKK Auto)

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Friday, 10 August 2018 4:45 PM  
**To:** admin-d@lkkauto.com  
**Cc:** MT\_Claim\_SG; Heng Sew Sow  
**Subject:** FW: Accident involving GW2334U, GBC6243L & XD5923Z On 06.08.18  
**Attachments:** 20180810162122.pdf

Our Ref: 18/18/18/VC00/020817

9.22am @ 13/8/18  
Ms. Heng  
vehicle in  
suro faufich

Dear Nivitha,

Please proceed to conduct the survey as requested.

Our insured has yet to lodge a report.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

-----Original Message-----

From: Heng Sew Sow [mailto:woonmeng@singnet.com.sg]

Sent: Friday, 10 August, 2018 4:40 PM

To: GERALD POH WEE BIN

Subject: Accident involving GW2334U, GBC6243L & XD5923Z On 06.08.18

Dear Gerald

We refer to the above accident

Kindly be advised that we will be assisting our client, owner of vehicle no:

GW2334U, to submit a third party claim against your insured vehicle. We would like to proceed with direct settlement.

Please arrange for your surveyor to liaise with us for an inspection on our client's Vehicle at your earliest convenience.

Location : 50, Bukit Batok St 23, # 01- 06 Midview Building ( S ) 659578 ( Vehicle in )

Thank you.

Best Regards,

Heng Sew Sow (Ms)

Woon Meng Motor Pte Ltd

Tel: 6316 1131/51

Fax: 6316 7050

**Mei Kwan (LKKAUTO)**

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Friday, 17 August, 2018 2:18 PM  
**To:** Mei Kwan (LKKAUTO)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: Accident involving GW2334U, GBC6243L & XD5923Z On 06.08.18  
**Attachments:** 17082018141524.pdf  
  
**Categories:** HMK

Dear Mei Kwan,

Attached a copy of insured's GIA report for your attention.

Best Regards  
Gerald Poh  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]  
**Sent:** Friday, 17 August, 2018 1:57 PM  
**To:** GERALD POH WEE BIN  
**Cc:** MT\_Claim\_SG; Admin A; Joy Irene (LKKAUTO); Asher Sng (LKKAUTO); Hsiao Tong (LKKAUTO)  
**Subject:** RE: Accident involving GW2334U, GBC6243L & XD5923Z On 06.08.18

**Your ref:** 18/18/18/VC00/020817  
**LKK ref:** CC4/LPC18014759/T1ja3

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: GW 2334U

Date of survey: 13/08/2018

We have not authorized repairs.

Please note that the estimated cost of repair is incomplete – no parts price.

We will revert to you on preliminary advice in due course.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Please take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

*To check availability of the case handler, you may contact the undersigned.*

Thank you,  
Best Regards,

We refer to the above accident

Kindly be advised that we will be assisting our client, owner of vehicle no: GW2334U, to submit a third party claim against your insured vehicle. We would like to proceed with direct settlement.

Please arrange for your surveyor to liaise with us for an inspection on our client's Vehicle at your earliest convenience.

Location : 50, Bukit Batok St 23, # 01- 06 Midview Building ( S ) 659578 ( Vehicle in )

Thank you.

Best Regards,  
Heng Sew Sow (Ms)  
Woon Meng Motor Pte Ltd  
Tel: 6316 1131/51  
Fax: 6316 7050

---

This email has been checked for viruses by AVG.  
<https://www.avg.com>



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                |                               |            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------|------------|-------------------------------------------------------------------------------------|
| LONPAC INSURANCE BHD                                                                                                                   |                                                                                                | Ref : CC4/LPC18014759/T1ja3s2 |            |                                                                                     |
| 300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555                                                                              |                                                                                                | Date : 06-03-2019             |            |  |
|                                                                                                                                        |                                                                                                | Code : LPC2                   |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                |                               |            |                                                                                     |
| Insured Veh.                                                                                                                           | GBC 6243L                                                                                      | Veh. Inspected                | GW 2334U   |                                                                                     |
| Policy No.                                                                                                                             | Z/18/VC00/101452                                                                               | Coverage (\$)                 | 0.00       |                                                                                     |
| Claim No.                                                                                                                              | 18/18/18/VC00/020817                                                                           | Excess (\$)                   | 0.00       |                                                                                     |
| Assign From                                                                                                                            | GERALD POH                                                                                     | Assign Date                   | 10/08/2018 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                |                               |            |                                                                                     |
| Make & Model                                                                                                                           | TOYOTA LITEACE                                                                                 | c.c                           | 2184       |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                                                         | Year of Reg.                  | 2003       |                                                                                     |
| Chassis No.                                                                                                                            | CR425005104                                                                                    | Colour                        | WHITE      |                                                                                     |
| Odometer                                                                                                                               | -                                                                                              | Steering                      | IN ORDER   |                                                                                     |
| Brakes                                                                                                                                 | IN ORDER                                                                                       | Modification                  | NIL        |                                                                                     |
| General                                                                                                                                | GOOD                                                                                           |                               |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                |                               |            |                                                                                     |
|                                                                                                                                        | Size                                                                                           | Make                          | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                         | 165 R13                                                                                        | BRIDGESTONE                   | 6 mm       |                                                                                     |
| L/H Front Tyre                                                                                                                         | 165 R13                                                                                        | BRIDGESTONE                   | 6 mm       |                                                                                     |
| R/H Rear Tyre                                                                                                                          | 165 R13                                                                                        | BRIDGESTONE                   | 6 mm       |                                                                                     |
| L/H Rear Tyre                                                                                                                          | 165 R13                                                                                        | BRIDGESTONE                   | 6 mm       |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                |                               |            |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.<br>DAMAGES SEE DETAILS.                                                            |                                                                                                |                               |            |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                                                |                               |            |                                                                                     |
| Accident Date                                                                                                                          | 06/08/2018                                                                                     | Inspection Date               | 13/08/2018 |                                                                                     |
| Survey held at                                                                                                                         | WOON MENG MOTOR PTE LTD<br>50 BUKIT BATOK ST 23<br>#01-06 MIDVIEW BUILDING<br>SINGAPORE 659578 |                               |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                |                               |            |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                |                               |            |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                                |                               |            |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                                | <b>9 Working Days</b>         |            |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GW 2334U

| Qty | Description of Parts                        | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---------------------------------------------|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>          |                      |                           |                   |
| 1   | FRONT BONNET (WCP)                          | BENT                 | 180.00                    | 180.00            |
| 1   | FRONT BONNET LOCK (WCP)                     | BENT                 | 60.00                     | 60.00             |
| 2   | FRONT BONNET HINGE @ \$30.00 (WCP)          | BENT                 | 60.00                     | 60.00             |
| 1   | FRONT BONNET SIDE RUBBER O/S (WCP)          | CUT                  | 30.00                     | 30.00             |
| 1   | AIR CLEANER BOX (WCP)                       | CRACKED              | 180.00                    | 180.00            |
| 1   | FRONT WIPER GARNISH (WCP)                   | DEFORMED             | 155.00                    | 155.00            |
| 2   | FRONT FENDER @ \$155.00 (WCP)               | BENT                 | 310.00                    | 310.00            |
| 2   | FRONT FENDER LAMP @ \$28.00 (WCP)           | NOT NECESSARY        | 56.00                     | -                 |
| 1   | FRONT FENDER GARNISH O/S (WCP)              | DEFORMED             | 65.00                     | 65.00             |
| 1   | FRONT MUDFLAT @ \$15.00 (WCP)               | NOT NECESSARY        | 30.00                     | -                 |
| 1   | FRONT FENDER SIDE MIRROR GARNISH N/S (WCP)  | CRACKED              | 32.00                     | 32.00             |
| 1   | FRONT DOOR N/S (WCP)                        | BENT                 | 320.00                    | 320.00            |
| 2   | FRONT DOOR HINGE N/S @ \$45.00 (WCP)        | TO REPAIR SEE LABOUR | 90.00                     | -                 |
| 1   | FRONT DOOR CHEK N/S (WCP)                   | NOT NECESSARY        | 35.00                     | -                 |
| 1   | FRONT DOOR LOCK N/S (WCP)                   | NOT NECESSARY        | 62.00                     | -                 |
| 1   | FRONT BUMPER BEAM (WCP)                     | BENT                 | 50.00                     | 50.00             |
| 1   | FRONT BUMPER (WCP)                          | MISSING              | 165.00                    | 165.00            |
| 1   | FRONT BUMPER REINFORCEMENT (WCP)            | BENT                 | 58.00                     | 58.00             |
| 2   | FRONT BUMPER FOG LAMP COVER @ \$55.00 (WCP) | MISSING              | 110.00                    | 110.00            |
| 2   | FRONT HEADLAMP @ \$85.00 (WCP)              | CRACKED              | 170.00                    | 170.00            |
| 2   | FRONT HEADLAMP GRILLE @ \$58.00 (WCP)       | CRACKED              | 116.00                    | 116.00            |
| 2   | FRONT SIDE LAMP @ \$65.00 (WCP)             | CRACKED              | 130.00                    | 130.00            |
| 1   | FRONT CENTER GRILLE (WCP)                   | MISSING              | 95.00                     | 95.00             |
| 1   | EMBLEM (WCP)                                | NECESSARY            | 98.00                     | 98.00             |
| 10  | CLIPS @ \$1.00 (WCP)                        | NECESSARY            | 10.00                     | 10.00             |
| 1   | FRONT SUPPORT PANEL (WCP)                   | BENT                 | 230.00                    | 230.00            |
| 1   | FRONT SUPPORT BACE PANEL (WCP)              | BENT                 | 40.00                     | 40.00             |
| 1   | FRONT RADIATOR (WCP)                        | CRACKED              | 250.00                    | 250.00            |
| 1   | FRONT RADIATOR FAN COWLING (WCP)            | CRACKED              | 105.00                    | 105.00            |
| 1   | FRONT RADIATOR FAN BLADE (WCP)              | JAMMED               | 80.00                     | 80.00             |

Report Ref No. CC4/LPC18014759/T1ja3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

| Qty | Description of Parts                                                                                                           | Condition                                 | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------|---------------------------|-------------------|
| 1   | FRONT RADIATOR FAN MOTOR (WCP)                                                                                                 | JAMMED                                    | 195.00                    | 195.00            |
| 1   | FRONT AIR CON CONDENSER (WCP)                                                                                                  | BENT                                      | 230.00                    | 230.00            |
| 2   | FRONT WHEEL HOUSE @ \$250.00 (WCP)                                                                                             | N/S TO REPAIR<br>SEE LABOUR / O/S<br>BENT | 500.00                    | 250.00            |
| 1   | HORN (WCP)                                                                                                                     | DENTED                                    | 60.00                     | 60.00             |
| 1   | WIPER TANK (WCP)                                                                                                               | DEFORMED                                  | 90.00                     | 90.00             |
| 1   | SPARE TANK (WCP)                                                                                                               | DEFORMED                                  | 115.00                    | 115.00            |
| 1   | FUEL BOX (WCP)                                                                                                                 | CRACKED                                   | 250.00                    | 250.00            |
| 1   | TOP HOSE (WCP)                                                                                                                 | NOT NECESSARY                             | 55.00                     | -                 |
| 1   | DISCHARGE HOSE (WCP)                                                                                                           | BENT                                      | 105.00                    | 105.00            |
| 1   | SUCTION HOSE (WCP)                                                                                                             | BENT                                      | 120.00                    | 120.00            |
| 1   | AIR CON VALVE (WCP)                                                                                                            | NOT NECESSARY                             | 50.00                     | -                 |
| 1   | AIR CON DRYER (WCP)                                                                                                            | DENTED                                    | 50.00                     | 50.00             |
| 1   | FRONT WINDSCREE GLASS (WCP)                                                                                                    | CRACKED                                   | 320.00                    | 320.00            |
| 1   | FRONT WINDSCREEN MOULDING (WCP)                                                                                                | NECESSARY                                 | 40.00                     | 40.00             |
| 2   | NOZZLE @ \$55.00 (WCP)                                                                                                         | NOT NECESSARY                             | 110.00                    | -                 |
| 2   | ENGINE MOUNTING @ \$58.00 (WCP)                                                                                                | NOT NECESSARY                             | 116.00                    | -                 |
| 1   | IDLER PULLEY (WCP)                                                                                                             | NOT NECESSARY                             | 55.00                     | -                 |
| 1   | TIMING BELT (WCP)                                                                                                              | NOT NECESSARY                             | 50.00                     | -                 |
| 1   | FUEL FILTER (WCP)                                                                                                              | NOT NECESSARY                             | 45.00                     | -                 |
|     | COST PLUS 20%                                                                                                                  |                                           | 1,185.60                  | 984.80            |
|     |                                                                                                                                |                                           | 7,113.60                  | 5,908.80          |
|     | <b><u>SPECIAL NETT ITEMS</u></b>                                                                                               |                                           |                           |                   |
| 1   | FRONT WINDSCREEN SEALANT (SN)                                                                                                  | NECESSARY                                 | 40.00                     | 40.00             |
| 1   | FRONT ERP BRACKET (SN)                                                                                                         | NECESSARY                                 | 15.00                     | 15.00             |
| 1   | COOLANT (SN)                                                                                                                   | NECESSARY                                 | 35.00                     | 35.00             |
| 1   | FRONT NUMBER PLATE (SN)                                                                                                        | MISSING                                   | 25.00                     | 25.00             |
|     |                                                                                                                                |                                           | 115.00                    | 115.00            |
|     | <b><u>LABOUR</u></b>                                                                                                           |                                           |                           |                   |
|     | TOWING FEE.                                                                                                                    |                                           | 60.00                     | 60.00             |
|     | TO REMOVE, REPAIR, REPLACE & INSTALL DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR HINGE N/S AND N/S FRONT WHEEL HOUSE. |                                           | 1,300.00                  | 1,000.00          |

Report Ref No. CC4/LPC18014759/T1ja3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty                                                                  | Description of Parts                                 | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|----------------------------------------------------------------------|------------------------------------------------------|---------------|---------------------------|-------------------|
|                                                                      | TO R&R FRONT RADIATOR.                               | NOT NECESSARY | 120.00                    | 100.00            |
|                                                                      | TO R&R AIR CON SYSTEM. TOP UP AIR CON GAS.           |               | 150.00                    | 100.00            |
|                                                                      | TO REMOVE & INSTALL DOOR MECHANISM AND FOR FUNCTION. |               | 100.00                    | 60.00             |
|                                                                      | TO REMOVE & REPLACE FRONT WINDSCREEN GLASS.          |               | 150.00                    | 120.00            |
|                                                                      | TO REPAIR & STRAIGHTEN CHASSIS.                      |               | 350.00                    | -                 |
|                                                                      | TO R&R WIRING.                                       |               | 60.00                     | 40.00             |
|                                                                      | TO PUTTY & SPRAY PAINTING.                           |               | 1,500.00                  | 1,200.00          |
|                                                                      |                                                      |               | 3,790.00                  | 2,680.00          |
| GRAND TOTAL                                                          |                                                      |               | 11,018.60                 | 8,703.80          |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) |                                                      |               |                           | 5,000.00          |

Report Ref No. CC4/LPC18014759/T1ja3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.