


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6393K
Ref. No : TAX/08/18/2034
Reg. Date : 26/01/2012
Vehicle Type : TAXI
Make : SSANGYONG
Model : RODIUS-SV270
Name of Driver : LOH SIEW LOONG
Type of Accident : CHAIN COLLISION
Date / Time of Accident : 08/08/2018 08:50:00 AM
Accident Reported Date / Time : 08/08/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024097455
Special Instruction to ARC, if any :
GBD8641C - CHINA TAIPING -LKK
Prepared Date : 08/08/2018 11:21:18 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KPTV0B1FSCP066705

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,690.00	0.00
Total Spray Painting Charges :	2,365.00	0.00
Total Material Charges :	6,988.23	6,988.23
Other Charges :	820.00	0.00
TOTAL :	11,863.23	0.00
Lum Sum Total :	11,850.00	0.00
No. of Repair Days :	10.00 <i>7.00</i>	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	08/08/2018 08:13:52 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 08/08/2018 08:13:52 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	845.00 600	0.00
TO REPAIR REAR PORTION	845.00 400	0.00
Total Labour	1,690.00 1,000	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	473.00 200	0.00
TO REPSRAY FRONT HOOD	473.00 200	0.00
TO RESPRAY FRONT FENDER LH	473.00 200	0.00
TO REPSRAY REAR BUMPER	473.00 200	0.00
TO RESPRAY TAIL GATE	473.00 200	0.00
Total Spray Painting & Panel Beating	2,365.00 1,000	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00 50	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00 X 00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00 20	0.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00 30	0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00 30	0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00 50	0.00
TO REPLACE SUNDRY PARTS	100.00 X 00	0.00
TO WASH AND VACUUM	60.00 X 00	0.00
Total Other Costs	820.00	0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NAZ LKIC

10/8/18 1030

LIS

7 days

After Repair Photo

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
7871A21000	FRONT		FRT BUMPER ASSY	1	1,187.50	10.00	1,068.75	Replace	Replace	No <i>CRD</i>
	FRONT		FRT BUMPER CLIP	6	8.25	10.00	44.55	Replace	Replace	No <i>rec</i>
7872121010	BODY		ABSORBER-ENERGY FRT BUMPER	1	67.16	10.00	60.44	Replace	Replace	No ?
5715021000	COMMON		MBR ASSY - FRT END LWR INR	1	256.15	10.00	230.53	Replace	Replace	No ?
5714021000	COMMON		MBR ASSY - FRT END LWR OTR	1	360.58	10.00	324.52	Replace	Replace	No ?
			NUMBER PLATE HOLDER	1	60.00	10.00	54.00	Replace	Replace	No <i>BT</i>
	REAR		NUMBER PLATE	1	30.00	0.00	30.00	Replace	Replace	No <i>CRD</i>
	FRONT		FRONT NUMBER PLATE FRAME	1	35.00	0.00	35.00	Replace	Replace	No <i>BT</i>
6101021001	COMMON		PNL ASSY-HOOD	1	1,050.67	10.00	945.60	Replace	Replace	No ?
6181021000	BODY		HINGE ASSY - HOOD LH	1	46.44	10.00	41.80	Replace	Replace	No ?
6182021000	BODY		HINGE ASSY - HOOD RH	1	46.44	10.00	41.80	Replace	Replace	No ?
8310121501	FRONT		LAMP ASSY HEAD LH	1	787.08	10.00	708.37	Replace	Replace	No <i>scr</i>
5181121010	FRONT		Frt Fender Assy LH	1	651.77	10.00	586.59	Replace	Replace	No ?
7881A21000	REAR		Rear Bumper Assy	1	925.27	10.00	832.74	Replace	Replace	No <i>XR</i>
	COMMON		REAR BUMPER CLIP	6	4.25	10.00	22.95	Replace	Replace	No <i>xrr</i>
7882121000	BODY		ABSORBER ENERGY RR BUMPER	1	111.73	10.00	100.56	Replace	Replace	No ?
	REAR		REVERSE SENSOR	1	165.10	10.00	148.59	Replace	Replace	No <i>xsv</i>
8390121100	BODY		LAMP ASSY, REFLEX REFLECTOR LH	1	10.52	10.00	9.47	Replace	Replace	No ?
8390221100	BODY		LAMP ASSY, REFLEX REFLECTOR RH	1	10.52	10.00	9.47	Replace	Replace	No ?
6401121000	REAR		REAR TAILGATE ASSY	1	1,355.08	10.00	1,219.57	Replace	Replace	No <i>DD</i>
6480121000	REAR		Rear Tailgate Hinge	2	23.12	10.00	41.62	Replace	Replace	No ?
7141021000	BODY		LATCH ASSY, T/GATE	1	59.98	10.00	53.98	Replace	Replace	No ?
7143021000	BODY		LIFTER ASSY, T/GATE LH	1	65.18	10.00	58.66	Replace	Replace	No ?
7144021000	REAR		LIFTER ASSY, T/GATE RH	1	65.18	10.00	58.66	Replace	Replace	No ?
7141521030	BODY		STRIKER ASSY, T/GATE	1	9.89	10.00	8.90	Replace	Replace	No ?
7145021031	REAR		WEATHER STRIP T/GATE OPENING	1	97.67	10.00	87.90	Replace	Replace	No ?
	COMMON		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace	No <i>rec</i>
			EMBLEM REAR	1	48.94	10.00	44.05	Replace	Replace	No <i>rec</i>
	COMMON		STICKER PRESTIGE	1	60.00	0.00	60.00	Replace	Replace	No <i>rec</i>

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
8379021001	REAR		LAMP ASSY-LICENSE PLATE	1	49.25	10.00	44.32	Replace	Replace	No <i>X na</i>
8360121201	REAR		COMBI LAMP ASYS-RR T/GATE LH	1	288.57	10.00	259.71	Replace	Replace	No <i>X snc</i>
8360221201	REAR		COMBI LAMP ASYS-RR T/GATE RH	1	288.57	10.00	259.71	Replace	Replace	No <i>?</i>
7963021002	REAR		Garnish assy-T/gate ctr	1	300.19	10.00	270.17	Replace	Replace	No <i>?</i>
7381021002ABU	Body		Trim assy-T/gate lwr	1	199.92	10.00	179.93	Replace	Replace	No <i>?</i>
7383021000ABU	Body		Trim assy-T/gate upr	1	47.17	10.00	42.45	Replace	Replace	No <i>?</i>
	REAR		REAR NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace	No <i>X na</i>
	REAR		REAR NUMBER PLATE FRAME	1	35.00	0.00	35.00	Replace	Replace	No <i>X na</i>
8360121301	REAR		COMBI LAMP ASSY-RR QTR LH	1	288.57	10.00	259.71	Replace	Replace	No <i>X snc</i>
8360221301	REAR		COMBI LAMP ASSY-RR QTR RH	1	203.46	10.00	183.11	Replace	Replace	No <i>?</i>
TOTAL MATERIALS							8,552.21	8,552.18		
TOTAL MATERIALS(Discounted)							6,988.23	6,988.23		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									