

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120**Our File No:** CC3/AIG18014822/AVBS2**Date:** 04/12/2018REFERENCE

Insured/Claimant:	TAN SHEN LEK	Policy No:	1800088788	
Date of Loss:	07/08/2018	Nature of Claim:	OD	Claim No: 5369147792SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD1109P	Engine No:	CVK063736
Make & Model:	AUDI A4, 2.0 (A)	Chassis No:	WAUZZZF40JA186949
Reg. Date:	01/08/2018 (Man. Year: 2018)	Odometer:	855 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$150,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,092.00	1,525.60	2,566.40	62.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,252.00	1,602.00	650.00	28.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,344.00	3,127.60	3,216.40	50.70
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	5,744.00	2,527.60	3,216.40	56.00
+ GST 7.00/7.00% (S\$)	402.08	176.93	225.15	56.00
Nett Amount (S\$)	6,146.08	2,704.53	3,441.55	56.00

INSPECTION

Date of Assignment:	15/08/2018		
Date Inspected:	15/08/2018	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER	Deformed	1,907.00 FS	*1,525.60 FS
2	1		*FIXING PARTS FOR BUMPER	Not Necessary	63.00 FS	*- FS
3	1		*SECURING STRIP	Not Necessary	191.00 FS	*- FS
4	1		*SPOILER	Not Necessary	216.00 FS	*- FS
5	2		*REAR LIGHT REFLECTOR - LH/RH	Not Necessary	70.00 FS	*- FS
6	1		*BUMPER CARRIER	Not Necessary	786.00 FS	*- FS
7	2		*SEAL	Not Necessary	24.00 FS	*- FS
8	2		*GUIDE SECTION - LH/RH	Not Necessary	76.00 FS	*- FS
9	2		*GUIDE SECTION - LH/RH	Not Necessary	38.00 FS	*- FS
10	2		*SENSOR - REAR INNER / OUTER	Not Necessary	421.00 FS	*- FS
11	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **4,092.00** **1,525.60**

LKK Auto Consultants Pte Ltd/SMD1109P/04/12/2018 08:02

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER.	New	900.00	500.00
3	TO RESPRAY REAR BUMPER.	New	800.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (\$\$)			2,252.00	1,602.00

LKK Auto Consultants Pte Ltd/SMD1109P/04/12/2018 08:02

< END OF ESTIMATES >