

1/1/2018

INS. CASE OWNER:

CC 6 UR 1801 4841, A 1832

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

4/8/18

Date / Time:

14/8/18

Registered in Merimen:

15/8/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SFT 9508B

Name of Insured:

UR

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

4/8/18

Is driver the owner?

(YES / NO)

Nature of Accident:

if NO, Driver Name / Age: UM 7m WDEI

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

74060075756

Policy No.:

999995145

Make / Model:

TUGOTW

Place of Accident:

WORTH POINT 4512W

OI GIA REPORT: YES NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Green Forest



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

11/8/18
JDN

SLX 5717K

SFT 9508B-X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

201 4-9-18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Cal

Final Liability:

SS

%

(Agreed / Assessed)

BOLA S/N No. : 28d

If NO or B 28, Ass. Lia:

100

Repair Cost:

SS

4,815

Loss of Rental (LOR):

SS

900

(S

x

days)

X100

Loss of Use (LOU):

SS

(S

x

days)

Loss of Income (LOI):

SS

-

(S

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

5,715

Global Sum SS:

5,700

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Cal

Payee 1:

SS

5,700.XV

Name 1:

GREEN FOREST AUTOMOBILE PTE LTD

Payee 2: (Strike if N.A.)

SS

X

Name 2:

X

Payee 3: (Strike if N.A.)

SS

X

Name 3:

X

RECEIVED 18 OCT 2018

COPY SENT

VIDEO OF MOVING
INVESTIGATION JUNE 18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLX5317K

Yr Regn:

2009, March.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Vios

C.C. 1497

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

202753

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR053HY9305105292

Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/60R15

R:

195/60R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

14/08/18.

Survey held at

Green Forest.

Des. of Damages Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TPAG.

L/S \$4,500/-

MV: 11.51K

PV: 6.9K

Nett: 4.6K.

R (\$10,822.15 / 717.)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC6/LCR18014841/Ajb3	
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120			Date : 15-08-2018	
			Code : LCR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKZ 9508B	Veh. Inspected	SLX 5317K	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	15/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/08/2018	Inspection Date	14/08/2018	
Survey held at	GREEN FOREST AUTOMOBILE 8 KAKI BUKIT AVENUE 4 #05-25 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

LUMENS AUTO PTE LTD
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BIKIT
Singapore 415875

TPLCR
Joy.

15th AUGUST 2018

Accident date: 11th AUGUST 2018

Estimated repair cost for vehicle no: SLX5317K TOYOTA VIOS '09

S/n	Qty	Items/Nett	U/price	Amount
1	1	Rear tail Lamp-LH <i>coated</i>		\$283.75 ✓
2	2	Rear tail lamp clips <i>new</i>	\$6.50	\$26.00 <i>10</i>
3	1	Rear Bumper <i>deformed</i>		\$381.40 ✓
4	4	Rear Bumper Clips <i>new</i>	\$6.50	\$26.00 ✓
5	1	Rear Bumper Side Bracket -LH <i>new</i>		\$132.45 <i>82.5</i>
6	1	Rear Bumper Reverse Sensor <i>new</i>		\$300.00 ✗
7	1	Rear Bumper Bracket -LH <i>new</i>	\$105.00	\$105.00 ✗
8	1	Rear Fender-LH <i>Distorted</i>		\$972.00 ✓
9	1	Rear Fender Inner Trim Board <i>3 new</i>		\$312.40 ✗
10	5	Rear Fender Inner Trim Board Clips <i>new</i>	\$6.50	\$65.00 ✗
11	1	Rear R/H fender air-duct <i>new</i>		\$161.80 ✗
12	1	Rear L/H Door <i>Dented</i>		\$981.40 ✓
13	1	Rear L/H Door Protector <i>deformed</i>		\$131.25 ✓
14	1	Rear L/H Door Inner Lock <i>new</i>		\$289.90 ✗
15	1	Rear L/H Door Inner Trim Board <i>3 new</i>		\$372.40 ✗
16	1	Rear L/H Door Inner Gear Motor Assy <i>new</i>		\$372.40 ✗
17	2	Rear L/H Door Hinge <i>new</i>	\$131.25	\$262.50 ✗
18	1	Front L/H door <i>Dented</i>		\$971.45 ✓
19	1	Front L/H Door Protector <i>deformed</i>		\$161.40 ✓
20	1	Front L/H door inner lock <i>new</i>		\$289.90 ✗
21	1	Front L/H door inner trim board <i>new</i>		\$372.40 ✗
22	1	Front L/H Door Side Mirror		\$281.55 ✗
23	1	Front L/H Door Inner Gear Motor Assy <i>new</i>		\$372.40 ✗
24	1	Front head lamp-LH <i>new</i>		\$481.00 ✓
25	1	Front Bumper <i>Distorted</i>		\$561.00 ✓

26	1	Front Bumper Side Bracket-LH <i>New</i>		\$131.10	38.40
27	5	Front Bumper Clips <i>New</i>	\$5.00	\$32.50	✓
28	1	Front Bumper Number Plate <i>New</i>		\$50.00	✓
29	1	Front Bumper emblem logo <i>New</i>		\$61.00	✓
30	1	Front Bumper Grille <i>Del</i>		\$182.25	✓
31	1	Front Bumper Grille Chrome <i>New</i>		\$128.30	X
32	1	Front Bumper Reinforcement <i>Bent</i>		\$351.44	✓
33	1	Front Support Panel <i>Repair</i>		\$81.00	X
34	1	Front Support Panel Side Cover-LH <i>2nd</i>	\$100.00	\$100.00	X
35	10	Front Support Panel Side Cover Clips <i>New</i>		\$10.00	X
36	1	Front fender-LH <i>Distorted</i>		\$301.50	✓
37	1	Front fender cowling-LH <i>Del</i>		\$180.00	✓
38	1	Front fender cowling clips <i>New</i>			30
39	1	Front Tyre LH <i>Replaced</i>	240 160(SW)		
40	1	Front Wheel Lin LH <i>nt</i>	580 100(SW)	\$11.00	

Labour charges

To remove & refix cushion

6077.35

3.20.580

\$1 / 60

To remove & re-fix reverse sensor

4558.01

\$1 / 50

To remove & refix petrol tank

\$1 / 80

To remove & Refix front & rear LH door

Bitting

\$1 / 160

Wheel alignment (computer)

\$120 / 80

To check wiring

2980

\$6 / 30

Towing charges

\$100 / 60

Tuff kote

\$120 / 60

Panel beating

\$1,000 / 1200

Spray painting

\$1,000 / 1200

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display "Damaged" (if any) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal:-

\$4

\$15,322.75

16/02/15

total: 8118.01

H/S: ASK

OT days

Joy Irene (LKKAUTO)

From: chan pick yuen <chris_chanbebe@hotmail.com>
Sent: Friday, 7 September 2018 7:42 PM
To: Admin A
Cc: Joy Irene (LKKAUTO)
Subject: SLX5317K & SKZ9508B DOA 11.08.2018
Attachments: VIDEO-2018-08-20-18-24-39.mp4; SD.pdf; SLX 5317K - GIA report (SAS2454709).pdf

Dear Sir / Mdm ,

Enclosed is our invoice , LOA , rental bill .
As request following :

1. RC \$4815 (\$4500 + 7% GST) -As agreed
2. LOR \$1350 (\$150 X 9 DAYS - 7 Days recommend + 1 day waiting PRS + 1 day weekend
- 3.

@ 100%

Total \$ 6165/- . (cut in with attachment video camera)

Please let us have your offer soon . Thanks

Regards,
Chris Chan Pick Yuen
Green Forest Automobile Pte Ltd
8 Kaki Bukit Avenue 4, #05-25,
Premier@Kaki Bukit, Singapore 415875
HP: 92712214

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Aug 2018 Edit Reg		14 Aug 2018 00:00 Edit Adj Rpt	S\$4,500.00 Edit Estimates	S\$4,500.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Main Claimant:	LUMENS AUTO PTE LTD, Co. Reg. No.: 201426961K		
Vehicle Reg. No.:	SLX5317K	Date of Loss:	11/08/2018 15:00 - :59 [112 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3406007523SG	Policy/Cover Note No.:	0999994768 (Comprehensive)
Vehicle Reg. No. (Insured):	SKZ9508B	Policy No. (Claimant):	5087588097-01
		Excess:	
Repairer:	Green Forest Automobile Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #05-25, Premier@Kaki Bukit, Singapore 415875, 415875 Kaki Bukit - Tel: 92712214		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tee, Chee-Wah] Chee-Wah.Tee@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 27/08/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLX5317K (3406007523SG)
[SKZ9508B]**

TP

LUMENS AUTO PTE LTD

Aug 11 2018 3:00PM

[LCRF PTE LTD]

Green Forest Automobile Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Video			1 per page ▼ ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	21/08/18 16:53	IVF FROM TPV		Load MOV
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	04/10/18 15:37	Video - Accident oiv		Load MP4
Letters/Correspondences			1 per page ▼ ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit
Photos/Images			3 per page ▼ ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	03/09/18 17:20	General View		Load JPG ☒
2	03/09/18 17:20	General View		Load JPG ☒
3	03/09/18 17:20	General View		Load JPG ☒
4	03/09/18 17:20	General View		Load JPG ☒
5	03/09/18 17:20	General View		Load JPG ☒
6	03/09/18 17:20	General View		Load JPG ☒
7	03/09/18 17:20	General View		Load JPG ☒
8	03/09/18 17:20	General View		Load JPG ☒
9	03/09/18 17:20	General View		Load JPG ☒
10	03/09/18 17:20	General View		Load JPG ☒
11	03/09/18 17:20	General View		Load JPG ☒
12	03/09/18 17:20	General View		Load JPG ☒
13	03/09/18 17:20	General View		Load JPG ☒
14	03/09/18 17:20	General View		Load JPG ☒
15	03/09/18 17:20	General View		Load JPG ☒
16	03/09/18 17:20	General View		Load JPG ☒
17	03/09/18 17:20	General View		Load JPG ☒
18	03/09/18 17:20	General View		Load JPG ☒
19	03/09/18 17:20	General View		Load JPG ☒
20	03/09/18 17:20	General View		Load JPG ☒
21	03/09/18 17:20	General View		Load JPG ☒
22	03/09/18 17:20	General View		Load JPG ☒
23	03/09/18 17:20	General View		Load JPG ☒
24	03/09/18 17:20	General View		Load JPG ☒
25	03/09/18 17:20	General View		Load JPG ☒
26	03/09/18 17:20	General View		Load JPG ☒

Video			1 per page ▾	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
27	03/09/18 17:20	General View	 Load JPG	✓
28	03/09/18 17:20	General View	 Load JPG	✓
29	03/09/18 17:20	General View	 Load JPG	✓
30	03/09/18 17:20	General View	 Load JPG	✓
31	03/09/18 17:20	General View	 Load JPG	✓
32	03/09/18 17:20	General View	 Load JPG	✓
33	03/09/18 17:20	General View	 Load JPG	✓
34	03/09/18 17:20	General View	 Load JPG	✓
35	03/09/18 17:20	General View	 Load JPG	✓
36	03/09/18 17:20	General View	 Load JPG	✓
37	03/09/18 17:20	General View	 Load JPG	✓
38	03/09/18 17:20	General View	 Load JPG	✓
39	03/09/18 17:20	General View	 Load JPG	✓
40	03/09/18 17:20	General View	 Load JPG	✓
41	03/09/18 17:20	General View	 Load JPG	✓
42	03/09/18 17:20	General View	 Load JPG	✓
43	03/09/18 17:20	General View	 Load JPG	✓
44	03/09/18 17:20	General View	 Load JPG	✓
45	03/09/18 17:20	General View	 Load JPG	✓
46	03/09/18 17:20	General View	 Load JPG	✓
47	03/09/18 17:20	General View	 Load JPG	✓
48	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
49	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
50	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
51	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
52	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
53	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
54	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
55	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
56	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
57	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
58	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
59	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
60	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
61	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
62	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
63	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
64	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
65	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
66	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
67	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
68	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
69	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
70	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
71	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
72	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
73	03/09/18 17:21	Reinspection Photo	 Load JPG	✓
74	03/09/18 17:21	Reinspection Photo	Load JPG	✓

Video			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
75	03/09/18 17:21	Reinspection Photo	Load JPG	✓
76	03/09/18 17:21	Reinspection Photo	Load JPG	✓
77	03/09/18 17:21	Reinspection Photo	Load JPG	✓
78	03/09/18 17:21	Reinspection Photo	Load JPG	✓
79	03/09/18 17:21	Reinspection Photo	Load JPG	✓
80	03/09/18 17:21	Reinspection Photo	Load JPG	✓
81	03/09/18 17:21	Reinspection Photo	Load JPG	✓
82	03/09/18 17:21	Reinspection Photo	Load JPG	✓
83	03/09/18 17:21	Reinspection Photo	Load JPG	✓
84	03/09/18 17:21	Reinspection Photo	Load JPG	✓
85	03/09/18 17:21	Reinspection Photo	Load JPG	✓
86	03/09/18 17:21	Reinspection Photo	Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/08/18 17:09	TP GIA REPORT	Load PDF	
2	19/10/18 14:12	AUTHORISATION TO ACT	Load PDF	
3	19/10/18 14:12	LETTER TO OI	Load PDF	
4	19/10/18 14:12	RELEASE VOUCHER	Load PDF	
5	19/10/18 14:12	RENTAL MILEAGE	Load PDF	
6	19/10/18 14:12	RENTAL RECEIPT	Load PDF	
7	19/10/18 14:12	WORKSHOP INVOICE	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	16/08/18 11:30	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKZ9508B (Insd veh)	Model:	TOYOTA VIOS 1.5 E (A)
	SLX5317K (TP veh)		
Date of Accident:	11/08/2018		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	17,336.30
Final Repair Cost	:	\$	5,700.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	9 days
LTA / GIA Search Fee	:	\$	_____
Others:	:	\$	_____
	:	\$	_____
Final Settlement Sum (GLOBAL SUM)	:	\$	5,700.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 100 _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown

1)	Green Forest Automobile Pte Ltd	:	\$	5,700.00
2)		:	\$	

NUR SHAQILAH BTE ABDOL WAHAB

19 Oct
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18014841/AJB3S2
Date: 19/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994768
Claimant Vehicle No: SLX5317K Insured Vehicle No: SKZ9508B
Date of Loss: 11/08/2018 Nature of Claim: TP Claim No: 3406007523SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX5317K
Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 1NZX880415
Reg. Date: 16/03/2009 (Man. Year: 2009) Chassis No: MR053HY9305105292
Colour: White Odometer: 202753 km
Engine Capacity: 1497 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60R15 Rear Tyre Size: 195/60R15
Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,182.15	5,274.70	6,907.45	56.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,020.00	2,980.00	1,040.00	25.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,202.15	8,254.70	7,947.45	49.05
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	16,202.15	4,500.00	11,702.15	72.23
+ GST 7.00/7.00% (S\$)	1,134.15	315.00	819.15	72.23
Nett Amount (S\$)	17,336.30	4,815.00	12,521.30	72.23
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
Nett Liability (S\$)		5,715.00		
Global Sum Settlement (S\$)		5,700.00		

INSPECTION

Date of Assignment: 14/08/2018
Date Inspected: 14/08/2018 Inspected At: Green Forest Automobile Pte Ltd (HQ)
Singapore 415875
Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL LAMP - LH	Cracked	283.75 F	*283.75 FL
2	2		*REAR TAIL LAMP CLIPS	Necessary	26.00 F	*10.00 FL
3	1		*REAR BUMPER	Deformed	381.40 F	*381.40 FL
4	4		*REAR BUMPER CLIPS	Necessary	26.00 F	*26.00 FL
5	1		*REAR BUMPER SIDE BRACKET - LH	Necessary	132.45 F	*88.50 FL
6	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	300.00 F	*- FL
7	1		*REAR BUMPER BRACKET - LH	Not Necessary	105.00 F	*- FL
8	1		*REAR FENDER - LH	Distorted	972.00 F	*972.00 FL
9	1		*REAR FENDER INNER TRIM BOARD	Not Necessary	312.40 F	*- FL
10	5		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	65.00 F	*- FL
11	1		*REAR R/H FENDER AIR-DUCT	Not Necessary	161.80 F	*- FL
12	1		*REAR L/H DOOR	Dented	981.40 F	*981.40 FL
13	1		*REAR L/H DOOR PROTECTOR	Deformed	131.25 F	*131.25 FL
14	1		*REAR L/H DOOR INNER LOCK	Not Necessary	289.90 F	*- FL
15	1		*REAR L/H DOOR INNER TRIM BOARD	Not Necessary	372.40 F	*- FL
16	1		*REAR L/H DOOR INNER GEAR MOTOR ASSY	Not Necessary	372.40 F	*- FL
17	2		*REAR L/H DOOR HINGE	Not Necessary	262.50 F	*- FL
18	1		*FRONT L/H DOOR	Dented	971.45 F	*971.45 FL
19	1		*FRONT L/H DOOR PROTECTOR	Deformed	161.40 F	*161.40 FL
20	1		*FRONT L/H DOOR INNER LOCK	Not Necessary	289.90 F	*- FL
21	1		*FRONT L/H DOOR INNER TRIM BOARD	Not Necessary	372.40 F	*- FL
22	1		*FRONT L/H DOOR SIDE MIRROR	Not Necessary	281.85 F	*- FL
23	1		*FRONT L/H DOOR INNER GEAR MOTOR ASSY	Not Necessary	372.40 F	*- FL
24	1		*FRONT HEAD LAMP - LH	Cut	481.40 F	*481.40 FL
25	1		*FRONT BUMPER	Distorted	561.40 F	*561.40 FL
26	1		*FRONT BUMPER SIDE BRACKET - LH	Necessary	131.10 F	*38.40 FL
27	5		*FRONT BUMPER CLIPS	Necessary	32.50 F	*32.50 FL
28	1		*FRONT BUMPER NUMBER PLATE	Not Necessary	50.00 F	*- FL
29	1		*FRONT BUMPER EMBLEM LOGO	Necessary	61.00 F	*61.00 FL
30	1		*FRONT BUMPER GRILLE	Deformed	182.25 F	*182.25 FL
31	1		*FRONT BUMPER GRILLE CHROME	Not Necessary	128.30 F	*- FL
32	1		*FRONT BUMPER REINFORCEMENT	Bent	381.45 F	*381.45 FL
33	1		*FRONT SUPPORT PANEL	Repair	881.40 F	*- FL
34	1		*FRONT SUPPORT PANEL SIDE COVER - LH	Not Necessary	187.25 F	*- FL
35	10		*FRONT SUPPORT PANEL SIDE COVER CLIPS	Not Necessary	65.00 F	*- FL
36	1		*FRONT FENDER - LH	Distorted	301.50 F	*301.50 FL
37	1		*FRONT FENDER COWLING - LH	Deformed	182.55 F	*182.55 FL
38	1		*FRONT FENDER COWLING CLIPS	Necessary	50.00 F	*30.00 FL
39	1		*FRONT TYRE LH	Punctured	300.00 FS	*180.00 FS
40	1		*FRONT WHEEL RIM LH	Cut	580.00 FS	*400.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	12,182.15	6,839.60
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,564.90
Total Parts (\$\$)	12,182.15	5,274.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX CUSHION.	New	150.00	60.00
2	TO REMOVE & RE-FIX REVERSE SENSOR.	New	100.00	50.00
3	TO REMOVE & REFIX PETROL TANK.	New	120.00	80.00
4	TO REMOVE & REFIX FRONT & REAR LH DOOR FITTINGS.	New	250.00	160.00
5	WHEEL ALIGNMENT (COMPUTER)	New	120.00	80.00
6	TO CHECK WIRING.	New	60.00	30.00
7	TOWING CHARGES.	New	100.00	60.00
8	TUFF KOTE.	New	120.00	60.00
9	PANEL BEATING.	New	1,400.00	1,200.00
10	SPRAY PAINTING.	New	1,600.00	1,200.00
Gross Labour Cost (S\$)			4,020.00	2,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >