

[illegible]

ASS. REC. BY:

REF: LPC1Kennerth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Trans Cob

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02h days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC5529E Yr Regn: 08, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or A)Make: Renault Latitude c.c. 1995Colour: White / Red A/C: Insured / Std / NI / NASp. Reading 503823 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF1ABL15AUC 278870Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Mil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16Lig R: Lay

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 11/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Frt

The UIC / Chasals frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/8 File pass to Cartier6/1/18 34506

(Red: \$78,128.42 / 95%)

6/1/18 34500 (Red: \$78,128.42 / 96%)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

\$ - RS - SI

Fixtures

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC3/LPC18014852/Kfb3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 15-08-2018		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GZ 9538L	Veh. Inspected	SHC 5529Z	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	15/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/08/2018	Inspection Date	14/08/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1 #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/LPC18014852/Kfb3

Date: 15.08.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC5529Z

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14.08.2018 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	81,578.42
Revised Estimate Amount	: S\$	3,450.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
N/S Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 3878K

Vehicle Details

Vehicle No.: SHC5529Z
Vehicle to be Exported: Yes
Intended De-registration Date: 13 Aug 2018
Vehicle Make: RENAULT
Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour: Red
Manufacturing Year: 2014
Engine No.: M9R8839C001886
Chassis No.: VF1ABL15AUC278870
Maximum Power Output: 127.0 kW (170 bhp)
Open Market Value: \$19,998.00
Original Registration Date: 15 Aug 2014
First Registration Date: 15 Aug 2014
Transfer Count: 0
Actual ARF Paid: \$12,498.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 14 Aug 2022
PARF Rebate Amount: \$9,373.00

Intended COE Rebate Details

COE Expiry Date: 14 Aug 2022
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 8
PQP Paid: \$50,088.00
COE Rebate Amount: \$25,060.00
Total Rebate Amount: \$34,433.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 Aug 2018

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5529Z**AAD1808-082***Not Authorized
L1 Smg @ 3450h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5529Z

VF1ABL15AUC278870

RENAULT

LATITUDE

11.8.2018

LONPAC**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>belong to me</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75 ✓
3	1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68 ✓
4	1	BUMPER RETAINER FRT LH	\$	<i>DIS</i> 151.41 ✓
5	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88
6	1	BUMPER RETAINER FRT RH	\$	<i>SL</i> 150.77
7	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88
8	1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83
9	1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.21
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21
12	1	BUMPER BEAM FRT	\$	<i>SL</i> 914.08
13	1	TOW COVER FRT	\$	<i>SL</i> 28.61
14	1	RADIATOR GRILLE	\$	<i>SL</i> 1,707.78
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36
16	1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 1,353.75
17	1	FRAME FULL SUPPORT PANEL	\$	<i>SL</i> 615.90
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>SL</i> 89.79
19	1	FRONT BRACE PANEL	\$	<i>SL</i> 177.22
20	1	HORN	\$	<i>SL</i> 314.17
21	1	HORN BRACKET	\$	<i>SL</i> 40.45
22	1	HEADLAMP LH	\$	<i>me</i> 1,184.43 ✓
23	1	HEADLAMP RH	\$	<i>SL</i> 1,184.43 X
24	1	HEADLAMP PANEL FRT LH	\$	<i>SL</i> 152.15 X
25	1	HEADLAMP PANEL FRT RH	\$	<i>SL</i> 152.15 X
26	1	BONNET	\$	<i>SL</i> 1,941.63 X
27	1	BONNET INSULATOR	\$	<i>SL</i> 405.73 X
28	1	BONNET STRUT LH	\$	<i>SL</i> 88.61 X

14116.08

Trans-cab Auto Services Pte Ltd**AAD1808-082**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5529Z

29	1	BONNET STRUT RH	\$	88.61	X
30	1	BONNET HINGE LH	\$	348.31	X
31	1	BONNET HINGE RH	\$	348.31	X
32	1	BONNET LOCK	\$	305.48	X
33	1	BONNET CABLE	\$	119.19	X
34	1	BONNET CABLE COVER	\$	161.03	X
35	1	BONNET SEAL OUTER	\$	92.36	X
36	1	BONNET SEAL INNER	\$	157.28	X
37	1	FENDER PANEL FRT LH	\$	783.83	✓
38	1	WHEELARCH FRT LH	\$	278.84	}
39	1	FENDER BRACKET LOWER LH	\$	15.79	
40	1	FENDER INSULATOR LH	\$	130.84	
41	1	FENDER INSULATOR RH	\$	130.84	
42	1	WIPER RESERVOIR	\$	348.25	
43	1	WIPER RESERVOIR NECK	\$	136.11	
44	1	WIPER RESERVOIR MOTOR	\$	270.06	
45	1	AIR CLEANER LOWER	\$	271.26	
46	1	AIR CLEANER HOSE	\$	76.14	
47	1	BASE BATTERY TRAY	\$	363.40	
48	1	AIR CLEANER BOX	\$	464.20	
49	1	TURBO DUCT	\$	1,027.80	
50	1	A/C HEATER VALVE	\$	484.50	
51	1	SUBFRAME OUTER FRT	\$	2,652.45	
52	1	SUBFRAME BRACKET OUTER LH	\$	92.36	
53	1	ENGINE UNDERTRAY	\$	564.98	
54	1	A/C CONDENSER	\$	2,020.37	
55	1	A/C CONDENSER GARNISH LH UPPER	\$	39.67	
56	1	A/C CONDENSER GARNISH RH UPPER	\$	39.67	
57	1	A/C CONDENSER GARNISH LH	\$	58.81	
58	1	A/C CONDENSER GARNISH RH	\$	59.60	
59	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	208.39	}
60	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	658.72	
61	1	A/C PIPE COMPRESSOR	\$	334.29	
62	1	A/C PIPE	\$	658.72	
63	1	A/C COMPRESSOR	\$	2,684.61	
77	1	AIR COOLER	\$	792.60	
78	1	AIR INTERCOOLER HOSE (LONG)	\$	1,014.13	
79	1	AIR INTERCOOLER HOSE (Short)	\$	375.14	

12856-94

Trans-cab Auto Services Pte Ltd**AAD1808-082**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5529Z

80	1	TRANSMISSION COOLER	\$	1,219.30
81	1	TRANSMISSION COOLER PAD	\$	17.96
82	1	RADIATOR	\$	1,202.20
83	2	RADIATOR STUD UPPER	\$	14.41
84	2	RADIATOR BUSH UPPER	\$	50.12
85	2	RADIATOR MTG LOWER	\$	55.85
86	1	RADIATOR FAN COWLING	\$	820.54
87	1	RADIATOR FAN MOTOR LH	\$	967.36
88	1	RADIATOR FAN MOTOR RH	\$	1,479.46
89	1	RADIATOR TANK	\$	324.62
90	1	RADIATOR HOSE UPPER	\$	240.56
91	1	RADIATOR HOSE LOWER	\$	491.18
92	1	RADIATOR TANK HOSE	\$	61.18
93	1	AUTO COMPUTER	\$	5,032.17
94	1	INJECTION COMPUTER	\$	4,706.30
95	1	RHD HYDRAULIC POWER(RQCK&PINION)	\$	5,154.52
96	1	STEERING PUMP ELECTRIC L70Y	\$	2,306.90
97	1	STEERING PINION RACK L70Y	\$	4,413.11
98	1	DOOR PANEL FRT LH	\$	2,844.66
99	1	LOWER ARM LH L70Y	\$	685.76
100	1	KUNCKLE ARM LH L70Y	\$	846.98
101	1	ABSORBER FRT LH L70Y	\$	360.54
102	1	AIR CLEANER BOX	\$	464.20
103	1	AIR CLEANER HOSE	\$	175.85
104	1	DOOR HARNESS WIRE LH	\$	2,670.00
105	1	DOOR MIRROR ASSY LH	\$	1,483.40
106	1	DOOR PANEL FRT LH	\$	2,844.66
TOTAL			\$	70,862.14
10%			\$	7,086.21
			\$	63,775.92

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00 X
2	1SET	BUMPER CLIP FRT	\$	66.00 ✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	12.00 X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	10.50 X
5	1	BUMPER BRACKET CLIP FRT RH	\$	12.00 X

Trans-cab Auto Services Pte Ltd

AAD1808-082

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5529Z

6	1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	}
7	1	TOW COVER FRT	\$	sn	14.50	
8	1SET	RADAIOR GRILLE SCREW	\$	nn	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	
13	1	Windscreen moulding	\$	nn	100.00	
14	1SET	Front licence plate with holder	\$	sn	80.00	
15	1	Front left tyre	\$	sn	330.00	
16	1	Front left tyre rim	\$	sn	380.00	}
17	1	FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00	
18	1	FRONT DOOR STICKER 'Chassis'	\$	nn	50.00	

TOTAL	\$	1,402.50
TOTAL PARTS	\$	65,178.42

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 5,400.00 *400*

Towing Fees.

\$ nn 120.00 X

To apply paint protection system (PPS) maintain and enhancement

\$ nn 380.00 X

Putty and spray painting of the affected portion.

\$ 6,000.00 *600*

To rust-proofing of the affected areas.

\$ 170.00 *300*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

To check steering geometry and computer wheel alignment

\$ nn 220.00 X

Trans-cab Auto Services Pte Ltd

AAD1808-082

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5529Z

To transfer of tire, rim and on wheel balancing.	\$	~ 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	~ 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00 X
To lift-up engine with gear box and refit.	\$	~ 440.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	~ 440.00 X
To remove and refit air bag system and reset.	\$	~ 480.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	~ 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	~ 380.00 X
To replace, refix and top up coolant for radiator	\$	~ 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	~ 170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	~ 170.00 X

TOTAL \$ 16,400.00**Over All Total \$ 81,578.42****Repair Days (LUMP SUM)****20 DAYS**

2 1/2 days

84138 63

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Shu Pei (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 20 August 2018 9:00 AM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: Direct Settlement - Accident Involving GZ9538L (OI : LPC - TBA) AND SHC5529Z (TP : LKK REF - CC3/LPC18014852/Kfb3) on 11.08.2018
Attachments: 20082018085646.pdf

Our Ref :18/18/18/VC05/020835

Dear Shu Pei,

Attached copy of insured's GIA report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, 15 August, 2018 5:07 PM
To: GERALD POH WEE BIN; ericwoo; ONG LI LI
Cc: MT_Claim_SG; Admin A; Poh Kin (LKKAUTO)
Subject: Direct Settlement - Accident Involving GZ9538L (OI : LPC - TBA) AND SHC5529Z (TP : LKK REF - CC3/LPC18014852/Kfb3) on 11.08.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHC 5529Z at M/s Trans-cab Auto Services Pte Ltd.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP's GIA report

Our case handler in-charge is Poh Kin and he can be contacted at DID: 6841-2132.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

• Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Friday, 30 November 2018 2:38 PM
To: 'claims'; 'Jasmine Tan'
Cc: 'Ng Wai Yin'; Admin A
Subject: Our Ref: CC3/LPC18014852/Kfb3; Your Ref: SHC 5529Z
(DOA:11/08/2018)

Importance: High

WITHOUT PREJUDICE

Our Ref: CC3/LPC18014852/Kfb3
Your Ref: SHC 5529Z (DOA:11/08/2018)


Dear Sir/Madam,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GZ 9538L AND SHC 5529Z ALONG ARAB STREET ON
11/08/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is unclear for the above mentioned case. There is no conclusive evidence yet to substantiate either party's version. Below is a copy of our insured's accident report statement for your perusal.

Date of accident: 11-07-18 Time: 1200 Location: Alad St
 Veh A: 3349 SBL Veh B: 546 SBL No of pass: 1 Weather: Clear/dry Rain/Wet
 SKETCH PLAN



DETAILED CIRCUMSTANCES OF THE ACCIDENT

I was driving along Arac Street on the left most lane
when all of a sudden van to which was on my right,
swerved to my lane and hit into my vehicle right side

Video by: Wale Isang Case-5017MCASH

- * We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request the CCTV footage / accident scene photos / evidence in order to seek further instruction from our principal.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Poh Kin (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Monday, 3 December 2018 2:21 PM
To: Poh Kin (LKKAUTO)
Cc: Admin A; claims@transcab.com.sg
Subject: RE: Our Ref: CC3/LPC18014852/Kfb3; Your Ref: AAD1808-082 (SHC 5529Z - DOA:11/08/2018)

Categories: clear

WITHOUT PREJUDICE


Dear Poh Kin

We regret to inform that we do not have video/photo for this case.

However enclosed our driver statement for your attention.

Brief Details.

On the 11/08/2018 at around 6pm, I was driving my taxi (SHC 5529 Z) along Arab Street alone and time, I was driving towards Sungei Road. However just before this Queen Street Bus Terminal, out of sudden, there was this van (GZ 9538 L) which overtook me on my left side, catching me off-guard. I applied my emergency braking but however the front right side (mud guard area) of the said van the onto the front left part of my taxi. I then alighted to exchange particulars with the other driver before driving off. It was only after the accident I felt pain to my neck and lower back to which I sought treatment from Mount Alvernia Hospital on the 13/08/2018 to which I was given outpatient treatment. I am then lodging this report for insurance claim(s) and also to notify the Traffic Police of this accident. My taxi installed with an in-car recording device but however it did not capture this accident as the memory full. That is all for now.



Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message

Poh Kin (LKKAuto)

From: Poh Kin (LKKAUTO)
Sent: Friday, 30 November 2018 2:38 PM
To: 'claims'; 'Jasmine Tan'
Cc: 'Ng Wai Yin'; Admin A
Subject: Our Ref: CC3/LPC18014852/Kfb3; Your Ref: SHC 5529Z
(DOA:11/08/2018)

Importance: High

WITHOUT PREJUDICE

Our Ref: CC3/LPC18014852/Kfb3
Your Ref: SHC 5529Z (DOA:11/08/2018)


Dear Sir/Madam,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GZ 9538L AND SHC 5529Z ALONG ARAB STREET ON 11/08/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is unclear for the above mentioned case. There is no conclusive evidence yet to substantiate either party's version. Below is a copy of our insured's accident report statement for your perusal.

Date of accident: 11-02-18 Time: 1200 Location: Arad 84
 Veh A: G293 32L Veh B: Sus 5539 No of pass: 1 Weather: Clear/dry Rain/Wet
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT:

I was driving along Arava Street on the left most lane
when out of a address van to which was on my right,
swerved to my lane and hit into my vehicle right side

Page 2: Will being said - 501706284

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request the CCTV footage / accident scene photos / evidence in order to seek further instruction from our principal.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."


Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC3/LPC18014852/Kha3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 15-01-2020		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GZ 9538L	Veh. Inspected	SHC 5529Z	
Policy No.	Z18VC05000346	Coverage (\$)	0.00	
Claim No.	18/18/18/VC05/020835	Excess (\$)	0.00	
Assign From		Assign Date	14/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC278870	Colour	METALLIC WHITE / RED	
Odometer	503823	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	9 mm	
L/H Front Tyre	215/60 R16	GITI	9 mm	
R/H Rear Tyre	215/60 R16	LING LONG	8 mm	
L/H Rear Tyre	215/60 R16	LING LONG	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/08/2018	Inspection Date	14/08/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2.500 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5529Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER FRT	BUCKLED / MTG CRACKED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT LH	DISTORTED	151.41	151.41
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH	SERVICEABLE	150.77	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.21	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	TOW COVER FRT	SERVICEABLE	28.61	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE "RENAULT"	SERVICEABLE	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	-
1	HORN	SERVICEABLE	314.17	-
1	HORN BRACKET	TO REPAIR SEE LABOUR	40.45	-
1	HEADLAMP LH	MTG CRACKED	1,184.43	1,184.43
1	HEADLAMP RH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	BONNET	TO REPAIR SEE LABOUR	1,941.63	-

Report Ref No. CC3/LPC18014852/Kha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET STRUT LH	SERVICEABLE	88.61	-
1	BONNET STRUT RH	SERVICEABLE	88.61	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK	SERVICEABLE	305.48	-
1	BONNET CABLE	SERVICEABLE	119.19	-
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	BONNET SEAL INNER	SERVICEABLE	157.28	-
1	FENDER PANEL FRT LH	BENT	783.83	783.83
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	WIPER RESERVOIR	SERVICEABLE	348.25	-
1	WIPER RESERVOIR NECK	SERVICEABLE	136.11	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	270.06	-
1	AIR CLEANER LOWER	SERVICEABLE	271.26	-
1	AIR CLEANER HOSE	SERVICEABLE	76.14	-
1	BASE BATTERY TRAY	SERVICEABLE	363.40	-
1	AIR CLEANER BOX	SERVICEABLE	464.20	-
1	TURBO DUCT	SERVICEABLE	1,027.80	-
1	A/C HEATER VALVE	SERVICEABLE	484.50	-
1	SUBFRAME OUTER FRT	SERVICEABLE	2,652.45	-
1	SUBFRAME BRACKET OUTER LH	SERVICEABLE	92.36	-
1	ENGINE UNDERTRAY	SERVICEABLE	564.98	-
1	A/C CONDENSER	SERVICEABLE	2,020.37	-
1	A/C CONDENSER GARNISH LH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH RH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH LH	SERVICEABLE	58.81	-
1	A/C CONDENSER GARNISH RH	SERVICEABLE	59.60	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	A/C PIPE CONDENSER TO COMPRESSOR	SERVICEABLE	208.39	-
1	A/C PIPE CONDENSER TO EXPENSION VALVE	SERVICEABLE	658.72	-
1	A/C PIPE COMPRESSOR	SERVICEABLE	334.29	-
1	A/C PIPE	SERVICEABLE	658.72	-
1	A/C COMPRESSOR	SERVICEABLE	2,684.61	-
1	AIR COOLER	SERVICEABLE	792.60	-
1	AIR INTERCOOLER HOSE (LONG)	SERVICEABLE	1,014.13	-
1	AIR INTERCOOLER HOSE (SHORT)	SERVICEABLE	375.14	-
1	TRANSMISSION COOLER	SERVICEABLE	1,219.30	-
1	TRANSMISSION COOLER PAD	SERVICEABLE	17.96	-
1	RADIATOR	SERVICEABLE	1,202.20	-
2	RADIATOR STUD UPPER	SERVICEABLE	14.41	-
2	RADIATOR BUSH UPPER	SERVICEABLE	50.12	-
2	RADIATOR MTG LOWER	SERVICEABLE	55.85	-
1	RADIATOR FAN COWLING	SERVICEABLE	820.54	-
1	RADIATOR FAN MOTOR LH	SERVICEABLE	967.36	-
1	RADIATOR FAN MOTOR RH	SERVICEABLE	1,479.46	-
1	RADIATOR TANK	SERVICEABLE	324.62	-
1	RADIATOR HOSE UPPER	SERVICEABLE	240.56	-
1	RADIATOR HOSE LOWER	SERVICEABLE	491.18	-
1	RADIATOR TANK HOSE	SERVICEABLE	61.18	-
1	AUTO COMPUTER	SERVICEABLE	5,032.17	-
1	INJECTION COMPUTER	SERVICEABLE	4,706.30	-
1	RHD HYDRAULIC POWER (RACK & PINION)	SERVICEABLE	5,154.52	-
1	STEERING PUMP ELECTRIC L70Y	SERVICEABLE	2,306.90	-
1	STEERING PINION RACK L70Y	SERVICEABLE	4,413.11	-
1	DOOR PANEL FRT LH	TO REPAIR SEE LABOUR	2,844.66	-
1	LOWER ARM LH L70Y	SERVICEABLE	685.76	-
1	KNUCKLE ARM LH L70Y	NOT NECESSARY	846.98	-
1	ABSORBER FRT LH L70Y	SERVICEABLE	360.54	-
1	AIR CLEANER BOX	SERVICEABLE	464.20	-
1	AIR CLEANER HOSE	SERVICEABLE	175.85	-

Report Ref No. CC3/LPC18014852/Kha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR HARNESS WIRE LH	SERVICEABLE	2,670.00	-
1	DOOR MIRROR ASSY LH	SERVICEABLE	1,483.40	-
1	DOOR PANEL FRT LH	TO REPAIR SEE LABOUR	2,844.66	-
	LESS 10% DISCOUNT		-7,370.68	-337.91
			66,336.13	3,041.18
	<u>SPECIAL NETT ITEMS</u>			
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NOT NECESSARY	52.00	-
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN)	SERVICEABLE	14.50	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	-
1	FRONT LEFT TRYE (SN)	SERVICEABLE	330.00	-
1	FRONT LEFT TRYE RIM (SN)	SERVICEABLE	380.00	-
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	FRONT DOOR STICKER "CHASSIS" (SN)	NECESSARY	50.00	15.00
			1,402.50	141.00
	<u>LABOUR</u>			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT,FRAME FULL SUPPORT BRACKET,FRONT BRACE PANEL,HORN BRACKET,HEADLAMP PANEL FRT LH,HEADLAMP PANEL FRT RH,BONNET,BONNET HINGE LH,BONNET HINGE RH AND DOOR PANEL FRT LH.		5,400.00	400.00

Report Ref No. CC3/LPC18014852/Kha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	660.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	NOT NECESSARY	440.00	-
	TO REMOVE AND RENEW POWER STEERING PUMP,OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.	NOT NECESSARY	480.00	-
	TO DROP DIESEL TANK,PIPES,HOSES TO FACILITATE BODYWORK REPAIR,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER.	NOT NECESSARY	380.00	-
	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			16,400.00	1,110.00
	GRAND TOTAL		84,138.63	4,292.18
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,450.00



Report Ref No. CC3/LPC18014852/Kha3n2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.