

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC4/ASM18014859/T1pa3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN		Date: 17-08-2020 Code: ASM			
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	FU 8852Z	Veh. Inspected	SHD 1138P	
	Policy No.	AN3164101	Coverage (\$)	0.00	
	Claim No.	S8M00S3B	Excess (\$)	0.00	
	Assign From		Assign Date	15/08/2018	
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI 130	c.c	1582	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	TMAD281UVHJ119093	Colour	SILVER	
	Odometer	217453	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	MAXXIS	6 mm	
	L/H Front Tyre	195/65 R15	MAXXIS	6 mm	
	R/H Rear Tyre	195/65 R15	MAXXIS	6 mm	
	L/H Rear Tyre	195/65 R15	MAXXIS	6 mm	
4.	·				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	13/08/2018	Inspection Date	15/08/2018	
	Survey held at				
	23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				