

ASS. REC. BY:

REP:

CS/FCE18014874/K1td3

n2
Special Instruction:

Surveyor: kalvin

ASSIGNMENT (Office)

From (Person): Lurene kw

of FCE

Date/Time: 15/8/18 @ 9:57am

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 6930R

Insured: SHB 3420X

at Workshop m/s Premier Automotive

Tel: 6544 6682

of 23 Chengsi South Ave 2 #03-02

Policy No: Claim No: D18606094MP8H

Sum Insured: Excess:

Make of Veh: D.O.A. 11/08/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS (up) H.O.D. Endorsement:

Date/Time: 10:00am @ 15/8/18 Person Contacted: Wee Dck Vehicle (IN) DUT

Date/Time	Action/Instruction (✓) Estimate	
	SHC 6930R - NSI INC 18014657/K1tb	DoA: 11/8/2018
	SHB 3420X - NSI INC 18014657/K1tb	DoA: 11/8/18
17/8	Revert via preli via email	

(08/11/13)

Director: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp. Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHC 6930R Yr Regn: 16 Oct 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA Optima c.c. 1685

Colour: Silver A/C: Ins / Std / NI / NA

Sp. Reading: 311379 T/Radio: Ins / Std / NI / NA

Eng/No: _____

C/No: KNAHM 414 MF 5 659313

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In / Jammed / Leaked / Burnt or

Brake: In / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD R / Rim or

Tyre Size: F: 205 / 65 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxxis

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 11/8/8 D.O.I. 15/8/8

Survey held at Premier

Des. of Damages: Frt / Rear / N/S / N/S / UIC / Rooftop or

N/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
27/8/8	Checked ups \$2950 / 4 Pp. (Red: 43431, 50%)

FCZ
PIP

RECEIVED 27 AUG 2018

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: 4

1) 27/8 Typist

: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

2) _____

Add Fee: : Site Insp (\$ _____) S + RS, SI

Transportation:

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$ 2950)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

TOTAL

150
50
50
31
281



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18014874/K1td3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 15-08-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 3420X	Veh. Inspected	SHC 6930R
Policy No.		Coverage (\$)	0.00
Claim No.	D18006094MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	15/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	11/08/2018	Inspection Date	15/08/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your Ref: D18006094MFSH

Date: 17/8/2018

Our Ref: CS/FCI18014874/K1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6930R

Please be informed that we had conducted the inspection of the abovementioned vehicle 15/8/2018 at the premises of M/s Premier and have the following to report: -

Workshop Estimate Amount	: S\$ <u>7,483.00</u>
Revised Estimate Amount	: S\$ <u>3,608.10</u>
"Check" Items Amount	: S\$ <u>1,187.20</u>
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the n/s rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kalvin

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	14-08-2018	Our Ref No. D18006094MFSH
Accident Date	11-08-2018	Claim Type. Third Party
Insured Vehicle	SHB3420X	Third Party Vehicle. SHC6930R
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	GOH WEE DEK	
Contact No.	62148880/ 65446682	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	16 Oct 2015 / 08:47:49	Receipt No.:	AACCK001-AX239-151016-000005
Asset Type:	Vehicle	Transaction Amount:	\$68,676.00
Asset ID:	SHC6930R	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20151016084749433156		
Vehicle No.:	SHC6930R		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	16 Oct 2015		
Original Registration Date:	16 Oct 2015		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5639313		
Engine No.:	D4FDEH313522		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2015		
Open Market Value:	\$22,212.00		
Minimum PARF Benefit:	\$13,858.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	16 Oct 2015 08:47:49		
COE No.:	2015101601003621H		
COE Expiry Date:	15 Oct 2023		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$45,439.00		
Lifespan Expiry Date:	15 Oct 2023		

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

14-Aug-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6930 R

1 pc	Rear bumper	— ca	\$	696.00
1 pc	Rear bumper n/s side bracket	✓ ca	\$	29.00
1 pc	Rear n/s fender	X rpr	\$	1,208.00
1 pc	Rear n/s fender innershield	✓ tm	\$	120.00
1 pc	Rear windscreen moulding	X n	\$	87.00
1 pc	Rear n/s door	— dnd	\$	791.00
1 pc	n/s rocker panel garnish	— ca	\$	286.00
1 pc	Rear n/s rim	X su — hnd	\$	246.00
1 pc	Rear n/s wheel cover	—	\$	116.00
1 pc	Rear n/s lower arm	X su X su	\$	351.00
1 pc	Rear n/s shock absorber	X su	\$	313.00
1 pc	Rear n/s trailing arm	X su	\$	157.00
1 pc	Rear n/s upper arm	X su	\$	84.00
1 pc	Rear n/s assist arm	X su	\$	163.00
			\$	<u>4,647.00</u>
			Less 10%	\$ 464.70
				<u>\$ 4,182.30</u>

Front n/s Door X repair

S/NETT

1 set	Rear bumper clips	— nca	\$	48.00
1 set	Rear fender innershield clips	X n	\$	28.00
1 pc	Sealant	X n	\$	50.00
	Door sticks	— n		
	Fender sock	— n		
	Sundry		\$	50.00
	To dismantle / refit reverse sensor to new bumper and reset to the same		\$	120.00 30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 50
	To dismantle n/s rear underramp		\$	250.00 600 X n
	To dismantle and refit the rear windscreen		\$	120.00 X n
	To dismantle and refit the inner component of the rear n/s door into new shell door		\$	150.00 50

\$100
\$60.

20
~~50.00~~

14-Aug-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6930 R

To labour charge for dismantle and renew the accident damaged parts. To cut/weld and heat on the rear n/s fender. Including knock-out, straighten, repair, reshape and adjust of the same

\$ ~~950.00~~⁶⁰⁰

To putty and spray painting on rear bumper, rear n/s fender, rear n/s door, n/s rocker panel garnish

\$ ~~1,000.00~~^{2,900}

To apply rustproofing on the repaired and replaced panels.

\$ ~~180.00~~⁵⁰

\$ 7,323.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

7468.30

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalin (0004

15/8/18 1115 hrs.

4 Dags.

P/P

Betox Paint photo.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18014874/K1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 28-08-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 3420X	Veh. Inspected	SHC 6930R
Policy No.		Coverage (\$)	0.00
Claim No.	D18006094MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	15/08/2018
2. Vehicle Particulars & Condition			
Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KNAGM414MF5639313	Colour	SILVER
Odometer	311379	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/65 R16	MAXXIS	7 mm
L/H Front Tyre	205/65 R16	MAXXIS	7 mm
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/08/2018	Inspection Date	15/08/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6930R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	CRACKED	696.00	696.00
1	REAR BUMPER N/S SIDE BRACKET	CRACKED	29.00	29.00
1	REAR N/S FENDER	TO REPAIR SEE LABOUR	1,208.00	-
1	REAR N/S FENDER INNERSHIELD	TORN	120.00	120.00
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	87.00	-
1	REAR N/S DOOR	DENTED	791.00	791.00
1	N/S ROCKER PANEL GARNISH	CRACKED	286.00	286.00
1	REAR N/S RIM	SERVICEABLE	246.00	-
1	REAR N/S WHEEL COVER	GRAZED	116.00	116.00
1	REAR N/S LOWER ARM	SERVICEABLE	351.00	-
1	REAR N/S SHOCK ABSORBER	SERVICEABLE	313.00	-
1	REAR N/S TRAILING ARM	SERVICEABLE	157.00	-
1	REAR N/S UPPER ARM	SERVICEABLE	84.00	-
1	REAR N/S ASSIST ARM	SERVICEABLE	163.00	-
1	FRONT N/S DOOR (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-464.70	-203.80
			4,182.30	1,834.20
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET REAR FENDER INNERSHIELD CLIPS (SN)	NOT NECESSARY	28.00	-
1	SEALANT (SN)	NOT NECESSARY	50.00	-
1	DOOR STICKER (SN)	NECESSARY	100.00	100.00
1	FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			336.00	228.00
LABOUR				
	TO DISMANTLE/REFIT REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO DISMANTLE N/S REAR UNDERCARRIAGE.	NOT NECESSARY	250.00	-
	TO DISMANTLE AND REFIT THE REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	TO DISMANTLE AND REFIT THE INNER COMPONENT OF THE REAR N/S DOOR INTO NEW SHELL DOOR.		150.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS TO CUT/WELD AND HEAT ON THE REAR N/S FENDER, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME. INCLUSIVE OF THE REPAIR OF REAR N/S FENDER AND FRONT N/S DOOR.		950.00	600.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER, REAR N/S FENDER, REAR N/S DOOR, N/S ROCKER PANEL GARNISH.		1,000.00	900.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		180.00	50.00
			2,950.00	1,680.00
	GRAND TOTAL		7,468.30	3,742.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,950.00

Report Ref No. CS/FCI18014874/K1td3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.