Barreya		REF: CSI/LPO	c18014876/B gb sm	Special Instruction;		
From (Person); Estimated Cost	Ong li Li	of UC	GNMENT (Office)  Date/Time: 14087018	Third Parties:		
	¥1	Surveyor:				
	pection / Evalua			Workshop:		
To Inspect Vehicle No: SLV 31723 Insured: SJC 12547				L.		
at Workshop m	1/sAl\su	vell more	Tel:			
of	25 D	efu lare 9.				
Policy No:			Claim No: 18/18/18/VI	PUS/020796		
Sum Insured:			Excess:			
Make of Veh: _			D.O.A.			
Client's Record)						
Date/Time: _	Confin	med with	Vehicle IN/OUT Final Fig,days (Re	d \$/_%; Originaldays)		
	Action/Instruction		The state of the s	0033)		
	CIN SERT	X				
	The state of the s	NA / DNC/11/02/4/837/W		DA: 01-12-2011		
	Already che	cleed with mortae	1, change \$120\$ Ar	paper survey.		
	U		0	1		
				myerte		
		D	L/3 2100/2			
		Керац	days 4	Vactor'		
				20/8/20		
Para(1) : P	arts found no	t replaced (To	highlight R or UB, LI	R. Etc)		
			,	,		
D (2) 6						
Para(2) : C	Comments on o	consistency of da	mages (Parts Not Consiste	ent:NC)		
			AUG 2018			
	71	ECEIVEDES	100 2010			
				1		
Para(3) · N	Vett Value					
Para(3) : N	Nett Value					
Para(3) : N	Vett Value Market Value	:	Inspected/	Fee Charged: Date:		
Para(3) : N	Market Value	:	Inspected/ Evaluated by:	Basic & Add 294		
Para(3) : N						
Para(3) : N	Market Value Salvage Value			Basic & Add Transport Photos Others		
Para(3): N	Market Value Salvage Value Nett Value		Evaluated by:	Basic & Add Transport Photos Others Total		
	Market Value Salvage Value Nett Value	ile Pass to typen-		Basic & Add Transport Photos Others		

## Shiau Chan (LKKAuto)

From:

ONG LI LI < llong@lonpac.com>

Sent:

Tuesday, 14 August 2018 11:09 AM

To:

SUR

Cc:

MT\_Claim\_SG

Subject:

RE: Our Ref: 18/18/18/VP05/020796

Attachments:

SLV3172J- estimate.pdf

### Dear Sir/Mdm

In addition to my email below, we understand that only Tailgate & rear bumper have been repaired.

We look forward to hearing from you.

Thanks, Regards, Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel: (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: ONG LI LI

Sent: Tuesday, 14 August, 2018 10:59 AM

To: 'SUR' (sur@lkkauto.com)

Cc: MT Claim SG

Subject: Our Ref: 18/18/18/VP05/020796

#### Dear Sir/Mdm

May I have your surveyor's comment on the attached marked estimate (COR & no. of repair days)?

Thanks, Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel: (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

# **Allswell Motor Traders**

25 Defu Lane 9. Singapore 539266

Tel: +65 6679 1146

emailtben.@allstvellmotsr.com.t/z

Estimate repair

Vehicle No. Make & Model

Chassis No.

Date of survey

(3rd party claim against NTUC Insumed SJC1254T

By paint

Toli C H

ate repair
e No. : SU/31727 Submitted by 8/18:

COE expiry Engine No.

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	Rigy toulgate V	01	\$1A140	DD/953/30	
9	Reon Junaper	01		DOV 762.70	
03	Bud panyel P	01	申612-0	RX	to repair
04	Windstreen moulding	8]	4145-0	NEC/145.00	T.
Zo	Fender ky war are?	01		NNX	
06	RH End point (bumper) P	0	#294.3	RX	* repair
	Special nett				
61	Clos for bunner @ \$4.00x4	01	416.00	NEC / 16.00	
0>-	Scalant for undserven	Ol	4) 80.00	NECV 50.00	40km
	A glasse Bassa A gr				
_	Calaur Description	-	-		
01	Diswantle / Assembly of	DI	\$260-0	200.60	250 =
- 01	afferted paints	- 01			
63	Dismonte I Assembly of tallgate	01	株150-D	120.00	12012
	undscreen				
03	Stray painting of all affected	01	牌900·0	400.00	4501
	paids mellidian anti-rust paint				-
04	. Panul brahing of end panel	10	申160.0	100.00	Refer Labour
	3 1 1	Total	5417.5	2707.00	
	The survey of th	143		2100:00	
	*			1	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

ed to be repaired, then was



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: 18/18/18/VP05/020796

Date: 23rd August 2018

Our Ref; CS1/LPC18014876/BqbS2

#### M/s Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555 (The Motor Claims Department)

Dear Sir / Madam,

# EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLV 3172J INSURED VEHICLE: SJC 1254T

We thank you for your instruction on 14/08/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLV 3172J 1686K from M/s Allswell Motor Traders.
- b) Colour damaged vehicle photographs of SLV 3172J.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

Information Recorded: -

Registration Number : SLV 3172J

Make & Model

: Honda Vezel

- We recommend that the repairs of the entire damage require about <u>4 (Four)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



#### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 3172J

Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
LACEMENT OF PARTS			
R TAILGATE	DENTED	1,414.00	953.30
R BUMPER	DENTED	1,190.10	762.70
PANEL	TO REPAIR SEE LABOUR	612.00	-
DSCREEN MOULDING	NECESSARY	145.00	145.00
DER RH REAR ARC	NOT NECESSARY	196.10	-
ND PANEL (BUMPER)	TO REPAIR SEE LABOUR	294.30	-
S 20% DISCOUNT	NO HOSSI POGLOO	_	-372.20
		3,851.50	1,488.80
CIAL NETT ITEMS			
S FOR BUMPER @ \$44.00 (SN)	NECESSARY	16.00	16.00
LANT FOR WINDSCREEN (SN)	NECESSARY	80.00	50.00
		96.00	66.00
OUR			
MANTLE / ASSEMBLY OF AFFECTED PARTS. USIVE OF THE REPAIR OF END PANEL AND RH END EL (BUMPER).		260.00	200.00
MANTLE / ASSEMBLY OF TAILGATE WINDSCREEN.		150.00	120.00
AY PAINTING OF ALL AFFECTED PARTS INCLUDING I-RUST PAINT.		900.00	400.00
EL BEATING OF END PANEL.		160.00	100.00
		1,470.00	820.00
ND TOTAL		5,417.50	2,374.80
	L DED COST OF LUMP SUM REPAIRS		L 5,417.50

RECOMMENDED COST OF LUMP SUM REPAIRS	1,900.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS1/LPC18014876/BqbS2

LIM TEOW GUAN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.