

2/01/2008

ASS. REC. BY:

REF:

CS/ICS18014862/Ald3

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Janice Goh

of

ECICS

Date/Time:

15/8/18 @ 11:10am

Estimated Cost:

Bill to:

☒ OD

TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

812 1570K

Insured:

at Workshop m/s:

1st Autoworks

Tel:

8292 5595

of

23 Kelki Bukit Ave 4 #04-01

Policy No.:

DMPC 18003224

Claim No.:

MPC 18A00170600

Sum Insured:

Excess:

\$500.00

Make of Veh.:

(Client's Record)

D.O.A.:

05/08/2018

CA / ☒ REV

/ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:20pm @ 15/8/18

Person Contacted:

Karlvin

Vehicle:

☒ IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

812 1570K - (CA/ICS18014419/Kca3

DoA: 5/8/18

A/B-

Revert via menmen

A/B@

A4111111 authorise by Jeffery Chew

A/B@

5:57pm Email to Kelvin, Euhaimi authorise repair
excess \$500-

ASSIGNMENT

From: _____ Date: 15/08/18

Estimated Cost: _____

☒ P / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLZ 1570K

at Workshop n/s First Autowork

of 23 Kaki Bkt Ave 4 # 04-01

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$500.00

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark. The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 888 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLZ1570K Yr Regn: 2018 / Apr

Type: ☒ M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Opel Crossland c.c. 1199

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 5917 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W0V7D9ED7J4146284

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16
R: 205/60R16

☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: _____ Rear: _____

R/Bal: 06 mm R/Bal: 06 mm

L/Bal: 06 mm L/Bal: 06 mm

D.O.A. _____ D.O.I. 15/08/18

Survey held at 1st Autowork

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction ECICS.

MV: 1151K
PV: 46.6K
Nett: 68.41K

RECEIVED 29 NOV 2018

Part by Part \$46,271.60 (Red: 36265.60: 43%)

Date/Time, File Pass to? ☐ : Preli. Report
29/11/2018 ☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 10

Resurvey No. of Trip: 1

Survey Fee: 450

Transportation: _____

Photos _____

Others 10

TOTAL 460

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Report Format: Db

Lump Sum / (B): (\$ 46,271.60)

Catherine Chong (LKK Auto)

From: motorsurvey <motorsurvey@ecics.com.sg>
Sent: Wednesday, 15 August, 2018 11:10 AM
To: vincent.sim@alpinemotors.sg; 'assignments'
Cc: suhaimi@alpinemotors.sg; Kelvin Chew; motorsurvey
Subject: RE: SLZ1570K - OPEL CROSSLAND 1.2- OWN DAMAGED CLAIM - ECICS- DOA- 5-8-2018
Attachments: SLZ1570K - OWN DAMAGED.PDF; SLZ1570K- OPEL _ESTIMATE 2 (1).jpg; SLZ1570K- OPEL _ESTIMATE 2 (2).jpg; SLZ1570K- OPEL _ESTIMATE 3.jpg

Hi Vincent

Thank you for your email.

We will appoint LKK for the OD survey.

Aside to LKK

Please assist to arrange OD survey.
Policy excess \$500.00.

Our claim no is DMPC1800322H/JG

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

From: Vincent Sim [mailto:vincent.sim@alpinemotors.sg]
Sent: Tuesday, 14 August, 2018 1:58 PM
To: motorsurvey; Janice Goh Siew Geok (ECICS, Claims)
Cc: suhaimi@alpinemotors.sg; Kelvin Chew
Subject: SLZ1570K - OPEL CROSSLAND 1.2- OWN DAMAGED CLAIM - ECICS- DOA- 5-8-2018

Dear Janice,
Kindly dispatch surveyor for the above , take note this is a Opel -under Auto Germany. which we do not input estimate inside merimen
vehicle is located at ;
Person in charge :-
Suhaimi , Kelvin – 82925595 H/P.
68441985 – office phone
E-mail ;
suhaimi@alpinemotors.sg

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Janice Goh

Date: 15 Nov 2018

Preliminary Advice

Vehicle No	: SLZ1570K	Accident Date	: 05/08/2018
Make	: OPEL COMBO	Policy No.	: -
Assignment Date	: 15/08/2018	Excess	: S\$1,000.00
Date of Inspection	: 15/08/2018	Est. Duration of Repair	: 10.00
Inspection At	: 1ST AUTOWORKS PTE LTD (HQ) 23 KAKI BUKIT AVE 4, #04-01 SINGAPORE 415933		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	82,537.20	inclusive supplementary \$15,237.00
Revised Amount	:S\$	46,271.60	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	46,271.60	

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	115,000.00
COE / PARF Rebate	:S\$	53,047.00
Salvage Value	:S\$	
Margin for Repair	:S\$	61,953.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Denise Tay (LKKAUTO)

From: Janice Goh Siew Geok (ECICS, Claims) <Janice_Goh@ecics.com.sg>
Sent: Thursday, 22 November 2018 10:57 AM
To: Denise Tay (LKKAUTO)
Subject: Our ref DMPC1800322H/JG ; Vehicle no SLZ1570K ; DOA 5.8.2018

Hi Denise

Please advise what was the reason for the increase from 33k to 46.2k? Why take nearly 3 months to advise the increase?

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

		
---	---	---

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Denise Tay (LKKAuto)

To: Janice Goh Siew Geok (ECICS, Claims)
Subject: RE: Our ref DMPC1800322H/JG ; Vehicle no SLZ1570K ; DOA 5.8.2018

Dear Janice,

The increase in repair cost due to supplementary parts & parts opined to be repaired initially were consequently replace. The replacement of the parts were due to these items being observed from view during the initial inspection.

Please refer to the computation:

Revised : \$17,500.50 (after 10%)
Confirm check item : \$5759.10 (after 10%)
s/nett: \$145
Supplementary: \$15,237 (after 10%)
Labour: \$7630/-
Total: \$46,271.60

intinally
The supp list was given to us without
part prices. ~~According to repair, the~~
~~Part prices were not available~~

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

A complete supp list was & only
provided to us by the repair
together with their final

From: Janice Goh Siew Geok (ECICS, Claims) <Janice_Goh@ecics.com.sg>
Sent: Tuesday, 27 November 2018 9:10 AM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: RE: Our ref DMPC1800322H/JG ; Vehicle no SLZ1570K ; DOA 5.8.2018

bill.

Hi Denise

Any update?

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg

Kelvin.chew@alpinemotors.sg

Add;
First Autoworks Pte Ltd
23, Kaki Bukit Ave 4
#04-01 (South Wing)
singapore 415933
(Vicom Building)
tel; 6844-1985

Auto Germany Pte Ltd

Regards,
Vincent Sim- Claims Dept

vincent.sim@alpinemotors.sg

65113022 ext 343

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

☐	☐	☐
--------------------------	--------------------------	--------------------------

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ECICS LTD		Ref : CS/ICS18014882/Atd3		
10 EUNOS ROAD 8 SINGAPORE POST CENTRE #09-04A SINGAPORE		Date : 15-08-2018		
		Code : ICS		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SLZ 1570K
Policy No.		Coverage (\$)		0.00
Claim No.		Excess (\$)		500.00
Assign From JANICE GOH		Assign Date		15/08/2018
2. Vehicle Particulars & Condition				
Make & Model		c.c		0
Engine No. HIDDEN		Year of Reg.		
Chassis No.		Colour		
Odometer -		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 05/08/2018		Inspection Date 15/08/2018		
Survey held at 1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING) SINGAPORE 415933				
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 17 August 2018 5:57 PM
To: 'Kelvin.chew@alpinemotors.sg'
Subject: FW: SLZ 1570K / OD / ECICS

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Friday, 17 August 2018 5:54 PM
To: 'suhaيمي@firstautoworks.com.sg' <suhaيمي@firstautoworks.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: SLZ 1570K / OD / ECICS

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLZ 1570K (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLZ1570K (DMPC1800322H)**

OD

Aug 5 2018 12:00AM

[~]

1st Autoworks Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From ECICS Limited (HQ) (ECICS), sent on 17/08/2018 17:41 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$33097.40) - SLZ1570K - Claim Handler: Janice Goh

Approved: 33097.40.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 16 Aug 2018

Preliminary Advice

Vehicle No	: SLZ1570K	Accident Date	: 05/08/2018
Make	: AUDI A3	Policy No.	: -
Assignment Date	: 15/08/2018	Excess	: S\$0.00
Date of Inspection	: 15/08/2018	Est. Duration of Repair	: 10.00
Inspection At	: 1ST AUTOWORKS PTE LTD (HQ) 23 KAKI BUKIT AVE 4, #04-01 SINGAPORE 415933		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	67,300.20	
Revised Amount	:S\$	27,278.90	
Check Items (Estimated)	:S\$	5,818.50	5759.10
Total	:S\$	33,097.40	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	115,000.00
COE / PARF Rebate	:S\$	53,047.00
Salvage Value	:S\$	
Margin for Repair	:S\$	61,953.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 16 Aug 2018

Preliminary Advice

Vehicle No	: SLZ1570K	Accident Date	: 05/08/2018
Make	: AUDI A3	Policy No.	: -
Assignment Date	: 15/08/2018	Excess	: S\$0.00
Date of Inspection	: 15/08/2018	Est. Duration of Repair	: 10.00
Inspection At	: 1ST AUTOWORKS PTE LTD (HQ) 23 KAKI BUKIT AVE 4, #04-01 SINGAPORE 415933		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	67,300.20	
Revised Amount	:S\$	27,273.90	27,278.90
Check Items (Estimated)	:S\$	5,818.50	
Total	:S\$	33,092.40	33,097.40
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	115,000.00
COE / PARF Rebate	:S\$	53,047.00
Salvage Value	:S\$	
Margin for Repair	:S\$	61,953.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2402B
Vehicle Details	
Vehicle No.:	SLZ1570K
Vehicle to be Exported:	No
Intended De-registration Date:	16 Aug 2018
Vehicle Make:	OPEL
Vehicle Model:	CROSSLAND X B12XHT AT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	10XVA10924806
Chassis No.:	W0V7D9ED7J4146284
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$21,172.00
Original Registration Date:	25 Apr 2018
First Registration Date:	25 Apr 2018
Transfer Count:	0
Actual ARF Paid:	\$21,641.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Apr 2028
PARF Rebate Amount:	\$16,230.00
Intended COE Rebate Details	
COE Expiry Date:	24 Apr 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$38,000.00
COE Rebate Amount:	\$36,817.00
Total Rebate Amount:	\$53,047.00

The information contained herein is correct as at 16 Aug 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2402B
Vehicle Details	
Vehicle No.:	SLZ1570K
Vehicle to be Exported:	Yes
Intended De-registration Date:	16 Aug 2018
Vehicle Make:	OPEL
Vehicle Model:	CROSSLAND X B12XHT AT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	10XVA10924806
Chassis No.:	W0V7D9ED7J4146284
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$21,172.00
Original Registration Date:	25 Apr 2018
First Registration Date:	25 Apr 2018
Transfer Count:	0
Actual ARF Paid:	\$21,641.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Apr 2028
PARF Rebate Amount:	\$16,230.00
Intended COE Details	
COE Expiry Date:	24 Apr 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$38,000.00
COE Rebate Amount:	\$30,400.00
Total Rebate Amount:	\$46,630.00

The information contained herein is correct as at 16 Aug 2018

OK



SELL BY CONSIGNMENT

SELL DIRECT AT THE PRICE YOU WANT

NO SALE = NO CHARGES!

[SEARCH](#)

 to

[Advanced Search](#)

Home > New Cars > Crossland X Search Results

Crossland X Search Results (1 vehicles)

Sort by [Model \(Ascending\)](#)

15 results/page

Car Model	Price	Dealer	Built in	User Rating
Opel Crossland X				
 ☐ 1.2 Turbo Classic (A)	\$129,777	Auto Germany	Spain	★★★★☆ 1 User Review
☐ 1.2 Turbo Enjoy (A)	\$132,777 \$12,200 /yr (8)	* 18.5km/l 109bhp 6-speed (A)		Promotion
☐ 1.2 Turbo Innovation (A)	\$139,777 \$12,700 /yr (8)	* 18.5km/l 109bhp 6-speed (A)		Editor's Review
Car Model	Price	Dealer	Built in	User Rating

15 results/page

[Home](#) |
 [New Cars](#) |
 [Used Cars](#) |
 [Sell My Car](#) |
 [Directory](#) |
 [Products](#) |
 [Insurance](#) |
 [Article](#) |
 [Forum](#) |
 [Resources](#)

sgCarMart is the number one car site for buying Singapore cars, including new cars, parallel import cars & used cars. View all new cars, such as Toyota, Honda, Nissan, Volkswagen, Mitsubishi & more. We have new car dealers comprising parallel importers, authorised car distributors, and used car dealers. Find new car price lists, new car launches, new car promotions, new car reviews, latest car news & car advice. Also join our car discussion and forum discussion for car reviews, importing news & motoring guides. Visit our partner sites who have job openings for Singapore jobs, Singapore classifieds, motor and real estate properties for sale.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or correct. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com



[About Us](#) |
 [Careers](#) |
 [Contact Us](#) |
 [Sitemap](#) |
 [Terms of Service](#) |
 [Privacy Policy](#) |
 [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/08/2018 12:50
Date Of Accident	05/08/2018 09:00
Exact Location Of Accident	CLEMENTI AVE 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ1570K
Insured/Policyholder	
Name Of Registered Owner	FRANK CHIN ZHAN SHENG
NRIC No	S8812402B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94798162
Alternative Phone No	OFFICE-94798162

Vehicle Particulars

Manufacturer	OPEL
Model	CROSSLAND 1.2
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	CN 17579

Driver

Name of Driver	FRANK CHIN ZHAN SHENG
NRIC No	S8812402B
Date Of Birth	13/04/1988
Occupation	INDOOR
Date Of Driving Pass	07/04/2009
Driving Experience	9 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94798162
Fax Number	
Contact Number	OFFICE-94798162
Email Address	NOEMAIL

Address	282A SENGKANG EAST
Postcode	541282
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SCZ8083K
Vehicle Make/Model/Colour	M/BENZ
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLM4564C
Vehicle Make/Model/Colour	MAZDA

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

5. SKETCH PLAN



6. DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was tracking element the 6. type is moderate
 there was a tree-cutting event on inner lane
 suddenly the car in front of me stop (SLZ 11570 K)
 I brake hard, but it did not stop in time &
 cause the accident, my vehicle was damaged badly
 as the air bag was deployed

DECLARATION

I/we declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name
 NRAC/IRG No:

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

- 1 - Please report exactly the details of the accident to speed up the claim process.
- 2 - This form must be completed by the Policyholder and/or the Authorized Driver.
- 3 - Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or WITHHOLDING of material facts may allow insurance companies to repudiate policy liability.
- 4 - The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 - Any false reporting may be referred to the Police for investigation.
- 6 - The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 - By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B - Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
SUBC/NIN No:



MOTOR COVER NOTE

Motor Vehicles (Third-Party Risks Compensation) Act (Chapter 189)
 Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
 Road Transport Act, 1967 (Malaysia)
 Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia)
 And any subsequent revisions to the above Acts and Agreement

The Insured mentioned in the Schedule having proposed for insurance in respect of the Motor Vehicle described in the Schedule, is hereby HELD COVERED under the terms of the Company's usual form of Motor Policy applicable thereto for the period mentioned in the Schedule unless the cover be terminated by the Company by notice in writing in which case the insurance will terminate and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

TYPE	
COVER NOTE NO.	17578
Agency Name	Alpine Insurance Agency Pte Ltd
Agency Code	AR060602
Has Purchased	MALAYAN BANKING BERHAD
Chassis No.	W0V7D9ED7J4146254
Engine No.	10XVA10024556
1. Make Mark and Registration Number of Vehicle :	SLZ154DK
2. Name of Policyholder :	Frank Chin Zhan Sheng
3. Effective Date of the Commencement of Insurance :	25 APRIL 2018
Date of Expiry of Insurance :	24 APRIL 2019
4. Details of Vehicle Make and Description of Vehicle Year of Manufacture Engine Capacity	OPEL CROSSLAND X 1.2 2018 1100 cc
5. Cover Type Excess	COMPREHENSIVE 1,000.00
6. Value (\$)	AS PER MARKET VALUE
7. Type of Plant	OPEL WORKSHOPS

(We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1967 (Malaysia))

Issued By : Alpine Insurance Agency Pte Ltd on 24/04/2018 5:44 PM

Issued By :

Chief Executive Officer

NOTE

This Cover Note is only valid for 60 days from the date of issue, unless renewed by the Certificate of Insurance issued by ECICS Limited.

If policy is cancelled when less than three months on risk will be charged subject to minimum of \$200.00 (inclusive of GST)

An administrative fee of \$226.75 (inclusive of GST) will be charged for retaining old registration number of vehicle.




ECICS Insurance Agency Pte Ltd, 11, Jalan Duta, Duta, 11000 Kuala Lumpur, Malaysia
 Tel: 603-2111 1111, Fax: 603-2111 1112, Email: info@ecics.com.my, website: www.ecics.com.my

Driving License



Identification Card



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2402B

Vehicle Details

Vehicle No.: SLZ1570K
Vehicle to be Exported: No
Intended De-registration Date: 13 Aug 2018
Vehicle Make: OPEL
Vehicle Model: CROSSLAND X B12XHT AT
Primary Colour: White
Manufacturing Year: 2018
Engine No.: 10XVA10924806
Chassis No.: W0V7D9ED7J4146284
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$21,172.00
Original Registration Date: 25 Apr 2018
First Registration Date: 25 Apr 2018
Transfer Count: 0
Actual ARF Paid: \$21,641.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 24 Apr 2028
PARF Rebate Amount: \$16,230.00

Intended COE Rebate Details

COE Expiry Date: 24 Apr 2028
COE Category: E - Open - all except motorcycle
COE Period(Years): 10
QP Paid: \$38,000.00
COE Rebate Amount: \$36,849.00
Total Rebate Amount: \$53,079.00

The information contained herein is correct as at 13 Aug 2018

OK

EFFECTIVE PERIOD: 19 APRIL - 9 MAY 2012



COMMERCIAL MODELS		FUEL CONSUMPTION (l/100km Combined)	CO ₂ EMISSIONS (g/km)	ROAD TAX	RETAIL PRICE (incl. GST)
	Connect 1.6T (114kW)	5.3	103	\$210	\$40,700*
	Vivaro 1.6T	6.3	130	\$210	\$49,900*

THESE

Repair Estimate



Date :13/08/2018

Reference: OPEL
Make: CROSSLAND

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SLZ1570K
CHASSIS NO.: W0V7D9ED7J4146284
ENGINE NO.: 10XVA10924806

Name of insured :FRANK CHINZHAN SHENG
Date of accident.: 05/08/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET <i>Perfected</i>	\$ 1,580.00
2	1	FRT BONNET DAMPER <i>new</i>	\$ 200.00
3	1	FRT BONNET INSULATOR	\$ 308.00
4	10	FRT BONNET INSULATOR CLIP <i>3x replaced</i>	\$ 65.00
5	1	FRT BONNET LOCK <i>new</i>	\$ 206.00
6	1	FRT BONNET LOCK CABLE <i>new</i>	\$ 147.00
7	2	FRT BONNET STOPPED <i>new</i>	\$ 13.00
8	1	FRT BONNET HINGE LH <i>Best</i>	\$ 162.00
9	1	FRT BONNET HINGE RH <i>Best</i>	\$ 162.00
10	1	FRT FENDER RH <i>Repair</i>	\$ 758.00
11	1	FRT FENDER BRACKET RH <i>3x new</i>	\$ 108.00
12	1	FRT FENDER INNERSHIELD RH	\$ 194.00
13	1	FRT FENDER WHEELARCH GARNISH RH <i>new</i>	\$ 142.00
14	20	FRT FENDER WHEELARCH CLIP <i>new</i>	\$ 130.00
15	20	FRT FENDER INNERSHIELD CLIP <i>new</i>	\$ 130.00
16	1	FRT FENDER LH <i>Repair</i>	\$ 758.00
17	1	FRT FENDER BRACKET LH <i>3x new</i>	\$ 108.00
18	1	FRT FENDER INNERSHIELD LH	\$ 230.00
20	1	FRT FENDER WHEELARCH GARNISH LH	\$ 142.00
21	1	FRT BUMPER <i>Displaced</i>	\$ 1,669.00
22	1	FRT BUMPER TOW COVER <i>Missing</i>	\$ 90.00
23	1	FRT BUMPER LOWER <i>Behind</i>	\$ 940.00
24	10	FRT BUMPER CLIP <i>new</i>	\$ 65.00
25	1	FRT BUMPER SIDE RETAINER LH <i>3x new</i>	\$ 166.00
26	1	FRT BUMPER SIDE RETAINER RH	\$ 166.00
27	1	FRT BUMPER TOP CENTRE BRACKET <i>Best</i>	\$ 368.00
28	1	FRT BUMPER SPONGE UPP <i>cracked</i>	\$ 194.00
29	1	FRT BUMPER REINFORCEMENT, IMPACT BAR UPP <i>Best</i>	\$ 896.00
30	1	FRT BUMPER SPONGE LOW <i>cracked</i>	\$ 154.00
32	1	FRT BUMPER LOW LIP <i>new</i>	\$ 196.00
33	1	FRT BUMPER FOG LAMP COVER RH <i>new</i>	\$ 182.00
34	1	FRT BUMPER FOG LAMP RH <i>new</i>	\$ 366.00
35	1	FRT BUMPER FOG LAMP COVER LH <i>3x new</i>	\$ 182.00
36	1	FRT BUMPER FOG LAMP LH <i>new</i>	\$ 366.00
37	1	FRT GRILLE BASE <i>cracked</i>	\$ 270.00
38	1	FRT GRILLE CHROME MLDG RH <i>3x new</i>	\$ 258.00
39	1	FRT GRILLE CHROME MLDG LH <i>1 new</i>	\$ 258.00

40	1	FRT GRILLE LOGO	new	\$	326.00	✓
41	1	FRT GRILLE BASE COVER	new	\$	248.00	✓
42	1	RH HEADLAMP	new	\$	1,254.00	✓
45	1	LH HEADLAMP	new	\$	1,254.00	✓
51	1	FRT CHASSIS PANEL LH	Repair	\$	2,278.00	✓
52	1	FRT CHASSIS PANEL RH	Repair	\$	2,278.00	✓
53	1	A/C CONDENSER	new	\$	1,644.00	✓
54	2	A/C CONDENSER TOP BRACKET	new	\$	36.00	✓
59	1	A/C CONDENSER AIRGUIDE RH	new	\$	108.00	✓
60	1	A/C CONDENSER AIRGUIDE LH	new	\$	108.00	✓
61	1	A/C PIPE (condenser to compressor)	new	\$	260.00	✓
62	1	A/C PIPE (cooling coil to condenser)	new	\$	620.00	✓
63	1	A/C COMPRESSOR	new	\$	2,334.00	✓
64	1	ALTERNATOR	new	\$	2,884.00	✓
65	1	ALTERNATOR BELT	new	\$	138.00	✓
66	1	TURBO INTAKE COOLER	new	\$	940.00	✓
73	1	TURBO ASSY	new	\$	5,272.00	✓
74	1	FRT INTAKE AIR DUCT (to resonator box)	new	\$	178.00	✓
75	1	FRT INTAKE RESONATOR BOX	new	\$	76.00	✓
76	1	AUTO TRANSMISSION FLUID COOLER	new	\$	1,491.00	✓
78	1	RADIATOR	new	\$	1,286.00	✓
82	1	RADIATOR TOP HOSE, INLET	new	\$	58.00	✓
83	1	RADIATOR LOW HOSE, OUTLET	new	\$	188.00	✓
84	1	RADIATOR FAN COWLING ASSY	new	\$	1,034.00	✓
86	1	EXHAUST CATALYTIC CONVERTER	new	\$	3,238.00	✓
89	1	RR ENGINE MOUNTING	new	\$	240.00	✓
90	1	RH ENGINE MOUNTING	new	\$	294.00	✓
91	1	LH ENGINE MOUNTING	new	\$	274.00	✓
92	1	FRT WINDSCREEN WITH MLDG	new	\$	1,327.00	✓
93	1	WIPER WASHER TANK	new	\$	272.00	✓
94	1	WIPER WASHER TANK NECK	new	\$	56.00	✓
95	2	WIPER WASHER TANK PUMP	new	\$	102.00	✓
96	1	FRT WIPER GARNISH	new	\$	374.00	✓
97	1	FRT AIR BAG SENSOR	Activated	\$	198.00	✓
99	1	FRT DRIVER STEERING AIR BAG	Activated	\$	2,902.00	✓
102	1	AIR BAG CONTROL UNIT	Activated	\$	690.00	✓
103	1	FRT DRIVER SEAT BELT RH	Activated	\$	721.00	✓
104	1	FRT DRIVER SEAT BELT PRETENSIONER RH	Activated	\$	362.00	✓
105	1	FRT DRIVER SEAT BELT BUCKLE RH	Activated	\$	526.00	✓
106	1	FRT DRIVER SEAT BELT LH	Activated	\$	744.00	✓
107	1	FRT DRIVER SEAT BELT PRETENSIONER LH	Activated	\$	362.00	✓
108	1	FRT DRIVER SEAT BELT BUCKLE LH	Activated	\$	526.00	✓
109	1	RR RH PASSENGER SEAT BELT	Activated	\$	721.00	✓
110	1	RR RH PASSENGER SEAT BELT BUCKLE	Activated	\$	526.00	✓
111	1	RR LH PASSENGER SEAT BELT	Activated	\$	721.00	✓
112	1	RR LH PASSENGER SEAT BELT BUCKLE	Activated	\$	526.00	✓
113	1	FRT ENGINE LOW SUBFRAME	new	\$	2,104.00	✓
114	1	FRT KNUCKLE ARM WITH BEARING RH	new	\$	778.00	✓
116	1	FRT LOW ARM RH	new	\$	778.00	✓
117	1	FRT SHOCK ABSORBER RH	new	\$	444.00	✓

Parts Total: \$ 58,428.00
Less 10%: \$ 5,842.80
Total: \$ 52,585.20

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts	\$ 5,200.00
2	Carry out spray painting on affected area, FRT BUMPER, FRT BONNET, FRT SUPPORT PANEL, FRT CHASSIS PANEL RH, FRT CHASSIS PANEL LH, FRT FENDER RH, FRT FENDER LH, FRT DOOR RH, FRT DOOR LH	\$ 5,500.00
3	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 220.00
4	To remove and refit engine to facilitate repairs	\$ 660.00
5	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 600.00
6	To conduct chassis alignment of vehicle	\$ 350.00
7	To remove and replace RHF under carriage parts	\$ 440.00
8	To conduct 4 wheel alignment	\$ 220.00
9	To remove and replace dashboard system and internal wiring	\$ 660.00
10	To conduct reset of air bag light on	\$ 350.00
11	Remove and refit front windscreen	\$ 220.00

2600

3300

120

X

X

X

X

X

X

X

Labour Total : \$ 14,420.00

Others**Other Description**

No.	Other Description	Price (SGD)
1	FRT NUMBER PLATE	\$ 65.00
2	RADIATOR COOLANT	\$ 80.00
3	FRT WINDSCREEN INNER SEAL	\$ 40.00
4	FRT WINDSCREEN SEALANT	\$ 65.00
5	FRT IU BRACKET	\$ 45.00

Other Total: 295.00

TOTAL: 67,300.20
GST (7%): 4,711.01

GRAND TOTAL : 72,011.21

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor

To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lim
P/P 15/08/18

Not Authorised
Excess \$500.

10 days

2534.20

VEHICLE NO:

SL7 1570k

[illegible]

Repair Estimate

Date :13/08/2018

Reference: OPEL
Make: CROSSLAND

Wir lieben Autos.

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SLZ1570K
CHASSIS NO.: W0V7D9ED7J4146284
ENGINE NO.: 10XVA10924806

Name of insured :FRANK CHINZHAN SHENG
Date of accident.: 05/08/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET <i>sent</i>	\$ 1,580.00
2	1	FRT BONNET DAMPER <i>new</i>	\$ 200.00
3	1	FRT BONNET INSULATOR <i>2 new</i>	\$ 308.00
4	10	FRT BONNET INSULATOR CLIP <i>new</i>	\$ 65.00
5	1	FRT BONNET LOCK <i>new</i>	\$ 206.00
6	1	FRT BONNET LOCK CABLE <i>new</i>	\$ 147.00
7	2	FRT BONNET STOPPED <i>new</i>	\$ 13.00
8	1	FRT BONNET HINGE LH <i>sent</i>	\$ 162.00
9	1	FRT BONNET HINGE RH <i>sent</i>	\$ 162.00
10	1	FRT FENDER RH <i>new</i>	\$ 758.00
11	1	FRT FENDER BRACKET RH <i>new</i>	\$ 108.00
12	1	FRT FENDER INNERSHIELD RH	\$ 194.00
13	1	FRT FENDER WHEELARCH GARNISH RH <i>new</i>	\$ 142.00
14	20	FRT FENDER WHEELARCH CLIP <i>new</i>	\$ 130.00
15	20	FRT FENDER INNERSHIELD CLIP <i>new</i>	\$ 130.00
16	1	FRT FENDER LH <i>new</i>	\$ 758.00
17	1	FRT FENDER BRACKET LH <i>new</i>	\$ 108.00
18	1	FRT FENDER INNERSHIELD LH	\$ 230.00
20	1	FRT FENDER WHEELARCH GARNISH LH	\$ 142.00
21	1	FRT BUMPER <i>Disrupted</i>	\$ 1,669.00
22	1	FRT BUMPER TOW COVER <i>Missing</i>	\$ 90.00
23	1	FRT BUMPER LOWER <i>new</i>	\$ 940.00
24	10	FRT BUMPER CLIP <i>new</i>	\$ 65.00
25	1	FRT BUMPER SIDE RETAINER LH <i>new</i>	\$ 166.00
26	1	FRT BUMPER SIDE RETAINER RH <i>new</i>	\$ 166.00
27	1	FRT BUMPER TOP CENTRE BRACKET <i>sent</i>	\$ 368.00
28	1	FRT BUMPER SPONGE UPP <i>new</i>	\$ 194.00
29	1	FRT BUMPER REINFORCEMENT, IMPACT BAR UPP <i>sent</i>	\$ 896.00
30	1	FRT BUMPER SPONGE LOW	\$ 154.00
32	1	FRT BUMPER LOW LIP <i>new</i>	\$ 196.00
33	1	FRT BUMPER FOG LAMP COVER RH	\$ 182.00
34	1	FRT BUMPER FOG LAMP RH <i>new</i>	\$ 366.00
35	1	FRT BUMPER FOG LAMP COVER LH	\$ 182.00
36	1	FRT BUMPER FOG LAMP LH <i>new</i>	\$ 366.00
37	1	FRT GRILLE BASE <i>new</i>	\$ 270.00
38	1	FRT GRILLE CHROME MLDG RH <i>new</i>	\$ 258.00
39	1	FRT GRILLE CHROME MLDG LH <i>new</i>	\$ 258.00

40	1	FRT GRILLE LOGO	NEA	\$	326.00	✓
41	1	FRT GRILLE BASE COVER	Canled	\$	248.00	✓
42	1	RH HEADLAMP	Canled	\$	1,254.00	✓
45	1	LH HEADLAMP	Canled	\$	1,254.00	✓
51	1	FRT CHASSIS PANEL LH	Repair	\$	2,278.00	✓
52	1	FRT CHASSIS PANEL RH		\$	2,278.00	✓
53	1	A/C CONDENSER	Sealed	\$	1,644.00	✓
54	2	A/C CONDENSER TOP BRACKET	Bent	\$	36.00	✓
59	1	A/C CONDENSER AIRGUIDE RH	Canled	\$	108.00	✓
60	1	A/C CONDENSER AIRGUIDE LH	Canled	\$	108.00	✓
61	1	A/C PIPE (condenser to compressor)	?	\$	260.00	?
62	1	A/C PIPE (cooling coil to condenser)	?	\$	620.00	?
63	1	A/C COMPRESSOR	NEA	\$	2,334.00	+
64	1	ALTERNATOR	NEA	\$	2,884.00	+
65	1	ALTERNATOR BELT	NEA	\$	138.00	+
66	1	TURBO INTAKE COOLER	Bent	\$	940.00	+
73	1	TURBO ASSY	NEA	\$	5,272.00	+
74	1	FRT INTAKE AIR DUCT (to resonator box)	?	\$	178.00	?
75	1	FRT INTAKE RESONATOR BOX	?	\$	76.00	?
76	1	AUTO TRANSMISSION FLUID COOLER	?	\$	1,491.00	?
78	1	RADIATOR	Distorted	\$	1,286.00	✓
82	1	RADIATOR TOP HOSE, INLET	NEA	\$	58.00	+
83	1	RADIATOR LOW HOSE, OUTLET	NEA	\$	188.00	+
84	1	RADIATOR FAN COWLING ASSY	?	\$	1,034.00	?
86	1	EXHAUST CATALYTIC CONVERTER	NEA	\$	3,238.00	+
89	1	RR ENGINE MOUNTING	?	\$	240.00	+
90	1	RH ENGINE MOUNTING	NEA	\$	294.00	+
91	1	LH ENGINE MOUNTING		\$	274.00	+
92	1	FRT WINDSCREEN WITH MLDG	NEA	\$	1,327.00	+
93	1	WIPER WASHER TANK	?	\$	272.00	+
94	1	WIPER WASHER TANK NECK	NEA	\$	56.00	+
95	2	WIPER WASHER TANK PUMP		\$	102.00	+
96	1	FRT WIPER GARNISH	NEA	\$	374.00	+
97	1	FRT AIR BAG SENSOR	Activated	\$	198.00	✓
99	1	FRT DRIVER STEERING AIR BAG	Activated	\$	2,902.00	✓
102	1	AIR BAG CONTROL UNIT	Activated	\$	690.00	✓
103	1	FRT DRIVER SEAT BELT RH	Activated	\$	721.00	✓
104	1	FRT DRIVER SEAT BELT PRETENSIONER RH	Activated	\$	362.00	✓
105	1	FRT DRIVER SEAT BELT BUCKLE RH	?	\$	526.00	?
106	1	FRT DRIVER SEAT BELT LH	Activated	\$	744.00	✓
107	1	FRT DRIVER SEAT BELT PRETENSIONER LH	?	\$	362.00	✓
108	1	FRT DRIVER SEAT BELT BUCKLE LH	?	\$	526.00	?
109	1	RR RH PASSENGER SEAT BELT	Activated	\$	721.00	✓
110	1	RR RH PASSENGER SEAT BELT BUCKLE	?	\$	526.00	?
111	1	RR LH PASSENGER SEAT BELT	Activated	\$	721.00	✓
112	1	RR LH PASSENGER SEAT BELT BUCKLE	?	\$	526.00	?
113	1	FRT ENGINE LOW SUBFRAME	?	\$	2,104.00	+
114	1	FRT KNUCKLE ARM WITH BEARING RH	NEA	\$	778.00	+
116	1	FRT LOW ARM RH	NEA	\$	778.00	+
117	1	FRT SHOCK ABSORBER RH		\$	444.00	+

Parts Total: \$ 58,428.00
Less 10%: \$ 5,842.80
Total: \$ 52,585.20

Labour

No.	Labour Description	Price (SGD)	
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts	\$ 5,200.00	2600
2	Carry out spray painting on affected area, FRT BUMPER, FRT BONNET, FRT SUPPORT PANEL, FRT CHASSIS PANEL RH, FRT CHASSIS PANEL LH, FRT FENDER RH, FRT FENDER LH, FRT DOOR RH, FRT DOOR LH	\$ 5,500.00	3300
3	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 220.00	120
4	To remove and refit engine to facilitate repairs	\$ 660.00	X
5	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 600.00	✓
6	To conduct chasis alignment of vehicle	\$ 350.00	X.
7	To remove and replace RHF under carriage parts	\$ 440.00	X
8	To conduct 4 wheel alignment	\$ 220.00	X
9	To remove and replace dashboard system and internal wiring	\$ 660.00	✓
10	To conduct reset of air bag light on	\$ 350.00	✓
11	Remove and refit front windscreen	\$ 220.00	X

Labour Total : \$ 14,420.00

Others

No.	Other Description	Price (SGD)	
1	FRT NUMBER PLATE <i>Coated</i>	\$ 65.00	✓
2	RADIATOR COOLANT <i>new</i>	\$ 80.00	✓
3	FRT WINDSCREEN INNER SEAL <i>2</i>	\$ 40.00	+
4	FRT WINDSCREEN SEALANT <i>1</i>	\$ 65.00	+
5	FRT IU BRACKET	\$ 45.00	+

Other Total: 295.00

TOTAL: 67,300.20
GST (7%): 4,711.01

GRAND TOTAL : 72,011.21

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor

Adrian Lim
P/P 15/08/18
Not Authorised
Excess \$500.
10 days.

8-16930
R-19449
CE-6399
L-7690



Wir leben Autos.

FINALIZE

ECICS LIMITED

GST Ref. No: 20-0000274-Z

Vehicle No: SLZ1570K
Chassis No: W0V7D9ED7J4146284
Engine No: 10XVA10924806
Date of accident :05/08/2018

Invoice No:

Invoice Date:

DESCRIPTION AMOUNT SGD

Parts

No.	Qty.	Description	Price (SGD)
1	1	FRT BONNET	\$ 1,580.00
2	1	FRT BONNET INSULATOR	\$ 308.00
3	10	FRT BONNET INSULATOR CLIP	\$ 65.00
4	1	FRT BONNET LOCK	\$ 206.00
5	1	FRT BONNET HINGE LH	\$ 162.00
6	1	FRT BONNET HINGE RH	\$ 162.00
7	20	FRT FENDER WHEELARCH CLIP	\$ 65.00
8	1	FRT BUMPER	\$ 1,669.00
9	1	FRT BUMPER TOW COVER	\$ 90.00
10	1	FRT BUMPER LOWER	\$ 940.00
11	10	FRT BUMPER CLIP	\$ 65.00
12	1	FRT BUMPER SIDE RETAINER LH	\$ 166.00
13	1	FRT BUMPER SIDE RETAINER RH	\$ 166.00
14	1	FRT BUMPER TOP CENTRE BRACKET	\$ 368.00
15	1	FRT BUMPER SPONGE UPP	\$ 194.00
16	1	FRT BUMPER REINFORCEMENT , IMPACK BAR , UPP	\$ 896.00
17	1	FRT BUMPER SPONGE LOW	\$ 154.00
18	1	FRT BUMPER FOG LAMP RH	\$ 366.00
19	1	FRT GRILLE BASE	\$ 270.00
20	1	FRT GRILLE BASE COVER	\$ 248.00
21	1	RH HEADLAMP	\$ 1,254.00
22	1	LH HEADLAMP	\$ 1,254.00
23	1	A/C CONDENSER	\$ 1,644.00
24	2	A/C CONDENSER TOP BRACKET	\$ 36.00
25	1	A/C CONDENSER AIRGUIDE RH	\$ 108.00
26	1	A/C CONDENSER AIRGUIDE LH	\$ 108.00
27	1	TURBO INTAKECOOLER	\$ 940.00
28	1	FRT INTAKE RESONATOR BOX	\$ 76.00
29	1	AUTO TRANSMISSION FLUID COOLER	\$ 1,491.00
30	1	RADIATOR	\$ 1,286.00
31	1	RADIATOR FAN COWLING ASSY	\$ 1,034.00

32	1	FRT AIR BAG SENSOR	\$	198.00
33	1	FRT DRIVER STEERING AIR BAG	\$	2,902.00
34	1	AIR BAG CONTROL UNIT	\$	690.00
35	1	FRT DRIVER SEAT BELT RH	\$	721.00
36	1	FRT DRIVER SEAT BELT PRETENSIONER RH	\$	362.00
37	1	FRT DRIVER SEAT BELT BUCKLE RH	\$	526.00
38	1	FRT DRIVER SEAT BELT LH	\$	744.00
39	1	FRT DRIVER SEAT BELT PRETENSIONER LH	\$	362.00
40	1	FRT DRIVER SEAT BELT BUCKLE LH	\$	526.00
41	1	RR RH PASSENGER SEAT BELT	\$	721.00
42	1	RR LH PASSENGER SEAT BELT	\$	721.00

Supplementary

1	1	STEERING CLOCK SPRING	\$	1,203.00
2	1	FRT DASHBOARD ASSY	\$	3,420.00
3	1	FRT BUMPER WIRE HARNESS	\$	314.00
4	2	FRT BUMPER PARKING SENSOR	\$	492.00
5	1	RADIATOR SUPPORT PANEL	\$	512.00
6	1	RADIATOR LOW SUPPORT PANEL	\$	442.00
7	1	FRT HEADLAMP LOW BRACKET RH	\$	154.00
8	1	FRT HEADLAMP LOW BRACKET LH	\$	154.00
9	3	FRT BRACE PANEL	\$	270.00
10	1	FRT PASSENGER AIR BAG LH	\$	2,902.00
11	1	A/C CONDENSOR AIR GUIDE UPP RH	\$	108.00
12	1	A/C CONDENSOR AIR GUIDE UPP LH	\$	108.00
13	1	FRT DASHBOARD WIRE HARNESS	\$	2,395.00
14	1	RR RH FENDER INNER TRIM BOARD	\$	553.00
15	1	RR SEAT BELT WIRE HARNESS	\$	3,601.00
16	1	FRT BUMPER LOW REINFORCEMENT	\$	302.00

Total: \$ 42,774.00
Less 10%: \$ 4,277.40
Parts Total: \$ 38,496.60

Labour

No.		Price (SGD)
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIRED / REPLACEMENT PARTS.	\$ 2,600.00
2	CARRY OUT SPRAY PAINTING OF ACCIDENT AFFECTED AREA. FRT BUMPER, FRT BONNET, FRT SUPPORT PANEL, FRT CHASSIS PANEL RH, FRT CHASSIS PANEL LH, FRT FENDER RH, FRT DOOR RH, FRT DOOR LH	\$ 3,300.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	\$ 120.00

4		TO REMOVE AND REFIT AIRCON CONDENSOR , VACUUM , REFILL AND CHECK AIR CON GAS SYSTEM	\$	600.00
5		TO REMOVE AND REPLACE DASHBOARD SYSTEM AND INTERNAL WIRING	\$	660.00
6		TO CONDUCT RESET OF AIR BAG LIGHT ON	\$	350.00

Labour Total : \$ 7,630.00

Other

<u>No.</u>			<u>Price (SGD)</u>
1	1	FRONT NUMBER PLATE	\$ 65.00
2	1	RADIATOR COOLANT	\$ 80.00

Other Total : \$ 145.00

Total : \$ 46,271.60

Excess: \$ 500.00

GST (7%) : \$ 3,204.01

Grand Total : \$ 48,975.61

Yours Faithfully,

Kelvin Chew
Service Advisor

Tel: 68441985 Fax:68445185

Please check and finalize with me

...CLAIM SUBFOLDER...(Pending for Survey Report)

Midnight Accident

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est. Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Aug 2018 16:32 Edit Reg		15 Aug 2018 00:00 Edit Adj Rpt	S\$46,271.60 Edit Estimates	S\$46,271.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	ID: S88124028, Email: noemail@gmail.com		
Vehicle Reg. No.:	SLZ1570K	Date of Loss:	05/08/2018 00:00 - :59 [3 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / DMPC1800322H	Policy/Cover Note No.:	MPC18A00170600 (Comprehensive)
		Excess:	S\$500.00
Repairer:	1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01, 415933 Kaki Bukit - Tel: 68441985		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Janice Goh - 6303 0182]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 27/08/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- ECICS (28/11/2018): Alert - Adj Mandate Approved (S\$46271.60) - SLZ1570K - Claim Handler: Janice Goh
- ECICS (17/08/2018): Alert - Adj Mandate Approved (S\$33097.40) - SLZ1570K - Claim Handler: Janice Goh

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLZ1570K (DMPC1800322H)

OD

Aug 5 2018 12:00AM

[-]

1st Autoworks Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/08/18 08:07	Adjuster Immediate Advice	 Load HTM	☐
2	17/08/18 17:29	Adjuster Immediate Advice	 Load HTM	☐
3	15/11/18 11:34	Adjuster Immediate Advice	 Load HTM	☐
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/08/18 08:44	General View	 Load JPG	☒
2	17/08/18 08:44	General View	 Load JPG	☒
3	17/08/18 08:44	General View	 Load JPG	☒
4	17/08/18 08:44	General View	 Load JPG	☒
5	17/08/18 08:44	General View	 Load JPG	☒
6	17/08/18 08:44	General View	 Load JPG	☒
7	17/08/18 08:44	General View	 Load JPG	☒
8	17/08/18 08:44	General View	 Load JPG	☒
9	17/08/18 08:44	General View	 Load JPG	☒
10	17/08/18 08:44	General View	 Load JPG	☒
11	17/08/18 08:44	General View	 Load JPG	☒
12	17/08/18 08:44	General View	 Load JPG	☒
13	17/08/18 08:44	General View	 Load JPG	☒
14	17/08/18 08:44	General View	 Load JPG	☒
15	17/08/18 08:44	General View	 Load JPG	☒
16	17/08/18 08:44	General View	 Load JPG	☒
17	17/08/18 08:44	General View	 Load JPG	☒
18	17/08/18 08:44	General View	 Load JPG	☒
19	17/08/18 08:44	General View	 Load JPG	☒
20	17/08/18 08:44	General View	 Load JPG	☒
21	17/08/18 08:44	General View	 Load JPG	☒
22	17/08/18 08:44	General View	 Load JPG	☒
23	17/08/18 08:44	General View	 Load JPG	☒
24	17/08/18 08:44	General View	 Load JPG	☒
25	17/08/18 08:44	General View	 Load JPG	☒
26	17/08/18 08:44	General View	 Load JPG	☒
27	17/08/18 08:44	General View	 Load JPG	☒
28	17/08/18 08:44	General View	 Load JPG	☒
29	17/08/18 08:44	General View	 Load JPG	☒
30	17/08/18 08:44	General View	 Load JPG	☒
31	17/08/18 08:44	General View	 Load JPG	☒
32	17/08/18 08:44	General View	 Load JPG	☒
33	17/08/18 08:44	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
34	17/08/18 08:44	General View	 Load JPG	☒
35	17/08/18 08:44	General View	 Load JPG	☒
36	17/08/18 08:44	General View	 Load JPG	☒
37	17/08/18 08:44	General View	 Load JPG	☒
38	17/08/18 08:44	General View	 Load JPG	☒
39	17/08/18 08:44	General View	 Load JPG	☒
40	17/08/18 08:44	General View	 Load JPG	☒
41	17/08/18 08:44	General View	 Load JPG	☒
42	17/08/18 08:44	General View	 Load JPG	☒
43	17/08/18 08:44	General View	 Load JPG	☒
44	17/08/18 08:44	General View	 Load JPG	☒
45	17/08/18 08:44	General View	 Load JPG	☒
46	17/08/18 08:44	General View	 Load JPG	☒
47	17/08/18 08:44	General View	 Load JPG	☒
48	17/08/18 08:44	General View	 Load JPG	☒
49	17/08/18 08:44	General View	 Load JPG	☒
50	17/08/18 08:44	General View	 Load JPG	☒
51	17/08/18 08:44	General View	 Load JPG	☒
52	17/08/18 08:44	General View	 Load JPG	☒
53	17/08/18 08:44	General View	 Load JPG	☒
54	17/08/18 08:44	General View	 Load JPG	☒
55	17/08/18 08:44	General View	 Load JPG	☒
56	17/08/18 08:44	General View	 Load JPG	☒
57	17/08/18 08:44	General View	 Load JPG	☒
58	17/08/18 08:44	General View	 Load JPG	☒
59	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
60	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
61	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
62	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
63	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
64	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
65	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
66	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
67	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
68	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
69	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
70	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
71	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
72	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
73	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
74	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
75	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
76	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
77	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
78	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
79	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
80	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
81	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
82	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
83	14/11/18 18:37	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
85	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
86	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
87	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
88	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
89	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
90	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
91	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
92	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
93	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
94	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
95	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
96	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
97	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
98	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
99	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
100	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
101	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
102	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
103	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
104	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
105	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
106	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
107	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
108	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
109	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
110	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
111	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
112	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
113	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
114	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
115	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
116	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
117	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
118	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
119	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
120	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
121	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
122	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
123	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
124	14/11/18 18:37	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/11/18 10:33	SUPPLEMENTARY	 Load PDF	
No	Finalized On	ECICS Limited (HQ)	Thumbnail	Print
1	17/08/18 17:06	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One
Singapore 038987

Our File No: CS/ICS18014882/ATD3E2

Date: 20/12/2018

REFERENCE

Insured/Claimant: - Policy No: MPC18A00170600
Date of Loss: 05/08/2018 Nature of Claim: OD Claim No: DMPC1800322H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ1570K**
Make & Model: OPEL COMBO, 1.2 D (M) Engine No: 10XVA10924806
Reg. Date: 25/04/2018 (Man. Year: 2018) Chassis No: W0V7D9ED7J4146284
Colour: White Odometer: 5917 km
Engine Capacity: 1199 cc
Market Value/New Car Price: S\$115,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	68,117.20	38,641.60	29,475.60	43.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,420.00	7,630.00	6,790.00	47.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	82,537.20	46,271.60	36,265.60	43.94
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	82,037.20	45,771.60	36,265.60	44.21
+ GST 7.00/7.00% (S\$)	5,742.60	3,204.01	2,538.59	44.21
Nett Amount (S\$)	87,779.80	48,975.61	38,804.19	44.21

INSPECTION

Date of Assignment: 15/08/2018
Date Inspected: 15/08/2018 Inspected At: 1st Autoworks Pte Ltd (HQ)
23 Kaki Bukit Ave 4, #04-01
Singapore 415933
Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 20 Dec 2018)	
Parts:	N/A	OPEL COMBO 1.2 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ1570K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET	Dented	1,580.00 FL	*1,580.00 FL
2	1		*FRT BONNET DAMPER	Not Necessary	200.00 FL	*- FL
3	1		*FRT BONNET INSULATOR	Crumpled	308.00 FL	*308.00 FL
4	10		*FRT BONNET INSULATOR CLIP	Necessary	65.00 FL	*65.00 FL
5	1		*FRT BONNET LOCK	Damaged	206.00 FL	*206.00 FL
6	1		*FRT BONNET LOCK CABLE	Not Necessary	147.00 FL	*- FL
7	1		*FRT BONNET HINGE LH	Bent	162.00 FL	*162.00 FL
8	1		*FRT BONNET HINGE RH	Bent	162.00 FL	*162.00 FL
9	1		*FRT FENDER RH	Repair	758.00 FL	*- FL
10	1		*FRT FENDER BRACKET RH	Not Necessary	108.00 FL	*- FL
11	1		*FRT FENDER INNERSHIELD RH	Not Necessary	194.00 FL	*- FL
12	1		*FRT FENDER WHEELARCH GARNISH RH	Not Necessary	142.00 FL	*- FL
13	1		*FRT FENDER WHEELARCH CLIP	Necessary	130.00 FL	*65.00 FL
			(20PCS)			
14	20		*FRT FENDER INNERSHIELD CLIP	Not Necessary	130.00 FL	*- FL
15	1		*FRT FENDER LH	Repair	758.00 FL	*- FL
16	1		*FRT FENDER BRACKET LH	Not Necessary	108.00 FL	*- FL
17	1		*FRT FENDER INNERSHIELD LH	Not Necessary	230.00 FL	*- FL
18	1		*FRT FENDER WHEELARCH GARNISH LH	Not Necessary	142.00 FL	*- FL
19	1		*FRT BUMPER	Distorted	1,669.00 FL	*1,669.00 FL
20	1		*FRT BUMPER TOW COVER	Missing	90.00 FL	*90.00 FL
21	1		*FRT BUMPER LOWER	Deformed	940.00 FL	*940.00 FL
22	10		*FRT BUMPER CLIP	Necessary	65.00 FL	*65.00 FL
23	1		*FRT BUMPER SIDE RETAINER LH	Necessary	166.00 FL	*166.00 FL
24	1		*FRT BUMPER SIDE RETAINER RH	Necessary	166.00 FL	*166.00 FL
25	1		*FRT BUMPER TOP CENTRE BRACKET	Bent	368.00 FL	*368.00 FL
26	1		*FRT BUMPER SPONGE UPP	Cracked	194.00 FL	*194.00 FL
27	1		*FRT BUMPER REINFORCEMENT, IMPACT BAR UPP	Bent	896.00 FL	*896.00 FL
28	1		*FRT BUMPER SPONGE LOW	Cracked	154.00 FL	*154.00 FL
29	1		*FRT BUMPER LOW LIP	Not Necessary	196.00 FL	*- FL
30	1		*FRT BUMPER FOG LAMP COVER RH	Not Necessary	182.00 FL	*- FL
31	1		*FRT BUMPER FOG LAMP RH	Cracked	366.00 FL	*366.00 FL
32	1		*FRT BUMPER FOG LAMP COVER LH	Not Necessary	182.00 FL	*- FL
33	1		*FRT BUMPER FOG LAMP LH	Not Necessary	366.00 FL	*- FL
34	1		*FRT GRILLE BASE	Cracked	270.00 FL	*270.00 FL
35	1		*FRT GRILLE CHROME MLDG RH	Not Necessary	258.00 FL	*- FL
36	1		*FRT GRILLE CHROME MLDG LH	Not Necessary	258.00 FL	*- FL
37	1		*FRT GRILLE LOGO	Not Necessary	326.00 FL	*- FL
38	1		*FRT GRILLE BASE COVER	Cracked	248.00 FL	*248.00 FL
39	1		*RH HEADLAMP	Cracked	1,254.00 FL	*1,254.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*LH HEADLAMP	Cracked	1,254.00 FL	*1,254.00 FL
41	1		*FRT CHASSIS PANEL LH	Repair	2,278.00 FL	*- FL
42	1		*FRT CHASSIS PANEL RH	Repair	2,278.00 FL	*- FL
43	1		*A/C CONDENSER	Dented	1,644.00 FL	*1,644.00 FL
44	2		*A/C CONDENSER TOP BRACKET	Bent	36.00 FL	*36.00 FL
45	1		*A/C CONDENSER AIRGUIDE RH	Cracked	108.00 FL	*108.00 FL
46	1		*A/C CONDENSER AIRGUIDE LH	Cracked	108.00 FL	*108.00 FL
47	1		*A/C PIPE (CONDENSER TO COMPRESSOR)	Not Necessary	260.00 FL	*- FL
48	1		*A/C PIPE (COOLING COIL TO CONDENSER)	Not Necessary	620.00 FL	*- FL
49	1		*A/C COMPRESSOR	Not Necessary	2,334.00 FL	*- FL
50	1		*ALTERNATOR	Not Necessary	2,884.00 FL	*- FL
51	1		*ALTERNATOR BELT	Not Necessary	138.00 FL	*- FL
52	1		*TURBO INTAKECOOLER	Bent	940.00 FL	*940.00 FL
53	1		*TURBO ASSY	Not Necessary	5,272.00 FL	*- FL
54	1		*FRT INTAKE AIR DUCT (TO RESONATOR BOX)	Not Necessary	178.00 FL	*- FL
55	1		*FRT INTAKE RESONATOR BOX	Cracked	76.00 FL	*76.00 FL
56	1		*AUTO TRANSMISSION FLUID COOLER	Necessary	1,491.00 FL	*1,491.00 FL
57	1		*RADIATOR	Distorted	1,286.00 FL	*1,286.00 FL
58	1		*RADIATOR TOP HOSE, INLET	Not Necessary	58.00 FL	*- FL
59	1		*RADIATOR LOW HOSE, OUTLET	Not Necessary	188.00 FL	*- FL
60	1		*RADIATOR FAN COWLING ASSY	Dented	1,034.00 FL	*1,034.00 FL
61	1		*EXHAUST CATALYTIC CONVERTER	Not Necessary	3,238.00 FL	*- FL
62	1		*RR ENGINE MOUTING	Not Necessary	240.00 FL	*- FL
63	1		*RH ENGINE MOUTING	Not Necessary	294.00 FL	*- FL
64	1		*LH ENGINE MOUTING	Not Necessary	274.00 FL	*- FL
65	1		*FRT WINDSCREEN WITH MLDG	Not Necessary	1,327.00 FL	*- FL
66	1		*WIPER WASHER TANK	Not Necessary	272.00 FL	*- FL
67	1		*WIPER WASHER TANK NECK	Not Necessary	56.00 FL	*- FL
68	2		*WIPER WASHER TANK PUMP	Not Necessary	102.00 FL	*- FL
69	1		*FRT WIPER GARNISH	Not Necessary	374.00 FL	*- FL
70	1		*FRT AIR BAG SENSOR	Activated	198.00 FL	*198.00 FL
71	1		*FRT DRIVER STEERING AIR BAG	Activated	2,902.00 FL	*2,902.00 FL
72	1		*AIR BAG CONTROL UNIT	Activated	690.00 FL	*690.00 FL
73	1		*FRT DRIVER SEAT BELT RH	Activated	721.00 FL	*721.00 FL
74	1		*FRT DRIVER SEAT BELT PRETENSIONER RH	Activated	362.00 FL	*362.00 FL
75	1		*FRT DRIVER SEAT BELT BUCKLE RH	Activated	526.00 FL	*526.00 FL
76	1		*FRT DRIVER SEAT BELT LH	Activated	744.00 FL	*744.00 FL
77	1		*FRT DRIVER SEAT BELT PRETENSIONER LH	Activated	362.00 FL	*362.00 FL
78	1		*FRT DRIVER SEAT BELT BUCKLE LH	Activated	526.00 FL	*526.00 FL
79	1		*RR RH PASSENGER SEAT BELT	Activated	721.00 FL	*721.00 FL
80	1		*RR RH PASSENGER SEAT BELT BUCKLE	Not Necessary	526.00 FL	*- FL
81	1		*RR LH PASSENGER SEAT BELT	Activated	721.00 FL	*721.00 FL
82	1		*RR LH PASSENGER SEAT BELT BUCKLE	Not Necessary	526.00 FL	*- FL
83	1		*FRT ENGINE LOW SUBFRAME	Not Necessary	2,104.00 FL	*- FL
84	1		*FRT KNUCKLE ARM WITH BEARING RH	Not Necessary	778.00 FL	*- FL
85	1		*FRT LOW ARM RH	Not Necessary	778.00 FL	*- FL
86	1		*FRT SHOCK ABSORBER RH	Not Necessary	444.00 FL	*- FL
87	1		*FRT NUMBER PLATE	Cracked	65.00 FS	*65.00 FS
88	1		*RADIATOR COOLANT	Necessary	80.00 FS	*80.00 FS
89	1		*FRT WINDSCREEN INNER SEAL	Not Necessary	40.00 FS	*- FS
90	1		*FRT WINDSCREEN SEALANT	Not Necessary	65.00 FS	*- FS
91	1		*FRT IU BRACKET	Not Necessary	45.00 FS	*- FS
92	1		*STEERING CLOCK SPRING	Activated	1,203.00 FL	*1,203.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
93	1		*FRT DASHBOARD ASSY	Torn	3,420.00 FL	*3,420.00 FL
94	1		*FRT BUMPER WIRE HARNESS	Damaged	314.00 FL	*314.00 FL
95	2		*FRT BUMPER PARKING SENSOR	Damaged	492.00 FL	*492.00 FL
96	1		*RADIATOR SUPPORT PANEL	Distorted	512.00 FL	*512.00 FL
97	1		*RADIATOR LOW SUPPORT PANEL	Bent	442.00 FL	*442.00 FL
98	1		*FRT HEADLAMP LOW BRACKET RH	Cracked	154.00 FL	*154.00 FL
99	1		*FRT HEADLAMP LOW BRACKET LH	Cracked	154.00 FL	*154.00 FL
100	3		*FRT BRACE PANEL	Bent	270.00 FL	*270.00 FL
101	1		*FRT PASSENGER AIR BAG LH	Activated	2,902.00 FL	*2,902.00 FL
102	1		*A/C CONDENSER AIR GUIDE RH	Cracked	108.00 FL	*108.00 FL
103	1		*A/C CONDENSER AIR GUIDE LH	Missing	108.00 FL	*108.00 FL
104	1		*FRT DASHBOARD WIRE HARNESS	Burst	2,395.00 FL	*2,395.00 FL
105	1		*RR RH FENDER INNER TRIM BOARD LOW	Cracked	553.00 FL	*553.00 FL
106	1		*RR SEAT BELT WIRE HARNESS	Burst	3,601.00 FL	*3,601.00 FL
107	1		*FRT BUMPER LOW REINFORCEMENT	Damaged	302.00 FL	*302.00 FL
108	2		*FRT BONNET STOPPED	Not Necessary	13.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$)	75,653.00	42,919.00
- List Item Discount on L Items 10.00/10.00% (S\$)	7,535.80	4,277.40
Total Parts (S\$)	68,117.20	38,641.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CARRY OUT SPRAY PAINTING ON AFFECTED AREA, FRT BUMPER, FRT BONNET, FRT SUPPORT PANEL, FRT CHASSIS PANEL RH, FRT CHASSIS PANEL LH, FRT FENDER RH, FRT FENDER LH, FRT DOOR RH, FRT DOOR LH	New	5,500.00	3,300.00
2	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	220.00	120.00
3	TO REMOVE AND REFIT ENGINE TO FACILITATE REPAIRS	New	660.00	0.00
4	TO REMOVE AND REFIT AIRCON CONDENSOR, VACUUM, REFILL AND CHECK AIR CON GAS SYSTEM	New	600.00	600.00
5	TO CONDUCT CHASSIS ALIGNMENT OF VEHICLE	New	350.00	0.00
6	TO REMOVE AND REPLACE RHF UNDER CARRIAGE PARTS	New	440.00	0.00
7	TO CONDUCT 4 WHEEL ALIGNMENT	New	220.00	0.00
8	TO REMOVE AND REPLACE DASHBOARD SYSTEM AND INTERNAL WIRING	New	660.00	660.00
9	TO CONDUCT RESET OF AIR BAG LIGHT ON	New	350.00	350.00
10	REMOVE AND REFIT FRONT WINDSCREEN	New	220.00	0.00
11	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR REPLACEMENT PARTS	New	5,200.00	2,600.00
Gross Labour Cost (S\$)			14,420.00	7,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >