



Your Ref : S8M00RV9

Date: 24th August 2018

Our Ref : CS/ASM18014884/R1qd3s2

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01

AXA Tower

Singapore 068811

(The Motor Claims Department)

Attn: Kitty Teo

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SJR 3122Z
ACCIDENT ON 12/08/2018**

Instruction was received to inspect the vehicle Reg. No. SJR 3122Z. The inspection was conducted on 16/08/2018 at the premises of M/s Elite AM Pte. Ltd., 280 Woodlands Industrial Park E5 #01-17 Harvest @ Woodlands Singapore 757322.

The following vehicle information was recorded:

Registration Number	: SJR 3122Z
Make/Model	: Honda Fit 1.3G A
Year of Registration	: 2009
Body Colour	: Grey
Chassis Number	: GE61157715
Engine Capacity	: 1339 cc
Speedometer Reading	: 157741 km

The vehicle sustained damages at the front portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$	14,000.00
Less: LTA Reimbursement Value (RV)	(S\$	8,264.00)
Nett Liability	S\$	5,736.00
		=====

Vehicle Inspected By:

MRB

MOHD. RASUL BIN MOHD YUNUS

AMSOE, AMIRTE, AMSAE-A, M. MATAI

Automotive Assessor



K.K. LAU

MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AMCATARI(CAN), M. MATA(USA), M. MATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.