

ASS. REC. BY:

REF: TMI / CC3 / TMI18014908 / Kad3 n2

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop nvs Trans Cob

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. ME000409


Claims No. M1804060

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHTD 162A Yr Regn: 09, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude c.c. 1.995

Colour: M. White / Red A/C: Insured / Std / NI / NA

Sp. Reading: 401570 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VF1ABL15AUC - 289545

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: MF / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or GIA

Front: 8 mm

Rear: 8 mm

R/Bal. 8 mm

R/Bal. 8 mm

L/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 14/8/18

D.O.I. 15/8/18

Survey held at \_\_\_\_\_

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

& 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
16/8	File pass to Catherine SHTD 162A - CC3 / TMI18014908 / Kad3 n2 GBC 6209L - X
16/8/18 @ 1.45pm	Enrol GIA, police report & estimate to TMI.
	<u>Q13917-16 (Red \$97431.12, 88%)</u>

RECEIVED 03 OCT 2010

Date/Time, File Pass to?  : Prell. Report  
 : Final Report

Date/Time, File Return to?

Days Of Repair: 5  
Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ )  
 : Interview (\$ )  
 : Tech Invs (\$ )  
 : Weekend (\$ )

Survey Fee:	
Transportation:	250
S - RS, SI	10
Fixtars	
Others	
TOTAL	260

Report Format: MER-TP  
Lump Sum / I.B.I: (\$ 13917-16)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TOKIO MARINE INSURANCE SINGAPORE LTD Ref : CC3/TMI18014908/Kqd3

20 MCCALLUM STREET #09-01  
TOKIO MARINE CENTRESINGAPORE 069046

Date : 16-08-2018



Code : TMI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 6209L	Veh. Inspected	SHD 162A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	16/08/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	15/08/2018	Inspection Date	15/08/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO 2 ANG MO KIO ST 63 SINGAPORE 569111		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 16 August 2018 1:45 PM  
**To:** motorclaims@tokiomarine.com.sg  
**Cc:** SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD DOA: 14/08/2018, SHD 162A (TP VEHICLE), GBC 6209L (OI VEHICLE)  
**Attachments:** SHD162 PR.pdf; SHD162 GIA-.pdf; SHD162 EST-.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle **SHD 162A** M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63, SINGAPORE 569111.

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/08/2018 15:05
Date Of Accident	14/08/2018 07:50
Exact Location Of Accident	SLE TOWARDS CTE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD162A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	TEO QUAY LAI
NRIC No	S7314895B
Date Of Birth	29/04/1973
Occupation	OUTDOOR
Date Of Driving Pass	22/06/1993
Driving Experience	25 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-83078838
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 645 HOUGANG AVENUE 8 #02-313
Postcode	530645
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHOKKALINGAM PONNAMBALAM GENDER: : MALE

### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOGANG N.P.C
Police Station Address	ROAD: 60 HOUGANG AVE 9 SINGAPORE 538775 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

REFER TO POLICE REPORT

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

### Details of Witness 1

Name	CHOKKALINGAM PONNAMBALAM
Phone Number	84989480
Email Address	

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC6209L
Vehicle Make/Model/Colour	LORRY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE

Name of Driver	LIM ENG KHENG
NRIC/Passport Number	S1336117G
Contact Number	83184115
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	YN280M
Vehicle Make/Model/Colour	LORRY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	GANESAN NATARJAN
NRIC/Passport Number	G2459189T
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	TEO QUAY LAI
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHD162A
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

## Sketch Plan Pg. 1

### SKETCH PLAN


#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20180814/2082

1 of 4

Police Station Of Origin:  
Hougang N.P.C  
60 Hougang Avenue 9 SINGAPORE 538775  
Tel No: 1800-4890999

Report No. T/20180814/2082

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 14/08/2018 14:02	Vide Report No.:	Station Diary No.: 95
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: TEO QUAY LAI		Address: APT BLK 645 HOUGANG AVENUE 8 #02-313 SINGAPORE 530645	
ID Type / ID No.: NRIC NO / S7314895B		Contact No.:	Mobile: 83078838
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 45	Date of Birth: 29/04/1973	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: TRANSCAB DRIVER		Driving Licence Information: Class: 3	Date of Expiry:

**General Information of the Accident**

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 14/08/2018 07:50	Type of Location: Flyover
Location: Along Road 1 SELETAR EXPRESSWAY				
SLE towards CTE near to exit of Woodland Avenue 2				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC6209L	Lorry					6
SHD162A	Car				Slightly Damaged	1
YN280M	Lorry				No Damage	6



**SINGAPORE  
POLICE FORCE**



T/20180814/2082

2 of 4

Police Station Of Origin:  
Hougang N.P.C  
60 Hougang Avenue 9 SINGAPORE 538775  
Tel No: 1800-4890999

Report No. T/20180814/2082

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	LIM ENG KHENG	ID No.	S1336117G
Related Vehicle	GBC6209L (Lorry)	Contact No.	83184115
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	TEO QUAY LAI	ID No.	S7314895B
Related Vehicle	SHD162A (Car)	Contact No.	83078838
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	14/08/2018	Date Discharge	14/08/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight
<b>Passenger</b>			
Name	CHOKKALINGAM PONNAMBALAM	ID No.	S7860744J
Related Vehicle	SHD162A (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



**SINGAPORE  
POLICE FORCE**



T/20180814/2082

3 of 4

Police Station Of Origin:  
Hougang N.P.C  
60 Hougang Avenue 9 SINGAPORE 538775  
Tel No: 1800-4890999

Report No. T/20180814/2082

**CONTINUATION OF REPORT**

<b>Driver</b>			
Name	GANESAN NATARJAN	ID No.	G2459189T
Related Vehicle	YN280M (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 14/08/2018 at about 0750hrs, I was driving my taxi (SHD162A) with a passenger on board. We were travelling in the 2nd left lane along SLE at a slow pace (60 km/hr) as it was during the peak period. I was talking to my passenger on board when suddenly I felt an impact from the rear of my vehicle. I managed to control my vehicle slightly and come to stop but my vehicle still managed to collide the vehicle (YN280M) in front of me. I came down and made a check and realized that a lorry bearing plate number GBC6209L had collided with the rear of my vehicle. As a result my rear bumper and boot was damaged. We all took photos of the incident and exchange particulars before leaving. My passenger informed that he was feeling fine at that point in time.

After I dropped off my passenger, I begin to feel pain in my lower back. As such, I made my way to Khoo Teck Puat Hospital and after the check by the doctor, I was given 3 days of MC.

As such, I made my way to Hougang NPC to lodge a traffic accident report. I wish to inform that there was no in-vehicle camera in my taxi.



**SINGAPORE  
POLICE FORCE**



T/20180814/2082

4 of 4

Police Station Of Origin:  
Hougang N.P.C  
60 Hougang Avenue 9 SINGAPORE 538775  
Tel No: 1800-4890999

Report No. T/20180814/2082

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /  
Sgt 2 KOH YEW WEI

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
14/08/2018 14:02

Officer In Charge Of Case:  
TP / GIA /  
Staff Sgt WONG SIEU LUI  
Contact No.: 65476151

Classification Of Case:

Authentication Stamp  
NP168



Signature: \_\_\_\_\_

SN 085

Singapore Police Force

# Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111  
 Tel No. : 6287 6666 Fax No. : 6257 1330  
 CO./GST Reg. No. 201019626G

**SHD 162A**

AAD1808-102

*Not withain  
 Primary B4 paint @ 13917-16*

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :

**SHD 162A**  
 VF1ABL15AUC281545  
 RENAULT  
 LATITUDE  
 14.8.2018  
**TOKIO MARINE**

PART		LIST
1	1 BUMPER COVER REAR	\$ <i>Bu</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$ <i>Da</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$ <i>D11</i> 113.47 ✓
4	1 BUMEP R BRACKET SIDE RH REAR	\$ <i>Su</i> 135.97 X
5	1 BUMEP R RETAINER RH REAR	\$ <i>Su</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$ <i>Su</i> 43.61 X
7	1 BUMEP R BRACKET SIDE LH REAR	\$ <i>Su</i> 135.97 X
8	1 BUMEP R RETAINER LH REAR	\$ <i>Su</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$ <i>CM</i> 43.61 ✓
10	1 BUMPER BEAM REAR	\$ <i>B1</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$ <i>B1</i> 225.95 ✓
12	1 BUMPER BEAM BRACKET RH REAR	\$ <i>R</i> 225.95 X
13	1 BOOT REAR	\$ <i>B1</i> 2,872.68 ✓
14	1 BOOT FINISHER	\$ <i>Wap</i> 470.06 ✓
15	1 BOOT WHEATERSTRIP	\$ <i>D11/ Cw</i> 323.05 ✓
16	1 BOOT REFLECTOR LAMP LH	\$ <i>CM</i> 493.35 ✓
17	1 BOOT REFLECTOR LAMP RH	\$ <i>CM</i> 493.35 ✓
18	1 BOOT BADGE 'RENAULT'	\$ <i>Nu</i> 225.36 ✓
19	1 BOOT BADGE	\$ <i>Nu</i> 225.36 ✓
20	1 BOOT STRUT LH	\$ <i>Su</i> 276.08
21	1 BOOT STRUT RH	\$ <i>Su</i> 276.08
22	1 BOOT HINGE LH	\$ <i>R</i> 367.84
23	1 BOOT HINGE RH	\$ <i>R</i> 367.84
24	1 BOOT INNER TRIM	\$ <i>Su</i> 586.45 } X
25	1 BOOT SWITCH	\$ <i>Su</i> 168.13
26	1 BOOT LOCK	\$ <i>R</i> 202.67
27	1 BOOT LOCK CATCH	\$ <i>R</i> 74.40
28	2 LICENCE PLATE LAMP	\$ <i>Su</i> 50.52
29	2 BOOT RUBBER PLUG	\$ <i>Su</i> 221.81

# Trans-cab Auto Services Pte Ltd

AAD1808-102

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

## SHD 162A

30	1 DOOR PANEL REAR LH	\$	R	2,844.66	}	
31	1 FENDER PANEL INNER TRIM REAR LH	\$	S	671.45		
32	1 FENDER PANEL REAR LH	\$	R	3,299.13		
33	1 WHEELARCH REAR LH	\$	S	543.47		
34	1 FENDER PANEL INNER TRIM REAR RH	\$	S	671.45		
35	1 FENDER PANEL REAR RH	\$	R	3,299.13		
36	1 WHEELARCH REAR RH	\$	S	543.47	}	
37	1 TAILLAMP RH	\$	MJC	552.55		✓
38	1 TAILLAMP PANEL RH	\$	R	986.70	X	
39	1 TAILLAMP LH	\$	MJC	552.55	✓	
40	1 TAILLAMP PANEL LH	\$	R	986.70	X	
41	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77	✓	
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	S	404.56	X	
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	}	
44	1 SPARE WHEEL PANEL TRIM	\$	S	612.21		
45	1 EXHAUST REAR	\$	R	7,489.05		
46	1 EXHAUST CAP REAR	\$	S	230.49		
47	1 FUEL FLAP L70Y	\$	S	343.57		
48	1 BUMPER COVER FRT	\$	S	1,259.42		
49	1 BUMPER SPOILER FRT	\$	S	181.75		
50	1 BUMPER ABSORBER FRT	\$	S	394.68		
51	1 BUMPER RETAINER FRT LH	\$	S	151.41		}
52	1 BUMPER SUPPORT FRT	\$	S	123.88		
53	1 BUMPER RETAINER FRT RH	\$	S	150.77	}	
54	1 BUMPER SUPPORT FRT	\$	S	123.88		
55	1 BUMPER UNDERTRAY FRT	\$	S	472.83		
56	1 BUMPER GRILLE LOWER FRT	\$	S	266.80		
57	1 BUMPER FOG LAMP GRILLE LH	\$	S	207.21		
58	1 BUMPER FOG LAMP GRILLE RH	\$	S	207.21		
59	1 BUMPER BEAM FRT	\$	R	914.08		
60	1 TOW COVER FRT	\$	S	28.61		
61	1 RADIATOR GRILLE	\$	CM	1,707.78	✓	
62	1 RADIATOR GRILLE BADGE 'RENAULT'	\$	N	225.36	✓	
63	1 RADIATOR GRILLE FRAME	\$	S	1,353.75	X	
64	1 FRAME FULL SUPPORT PANEL	\$	S	615.90	X	
65	1 FRAME FULL SUPPORT BRACKET	\$	R	89.79	X	
66	1 FRONT BRACE PANEL	\$	R	177.22	X	
67	1 HORN	\$	S	314.17	X	
68	1 HORN BRACKET	\$	R	40.45	X	

**Trans-cab Auto Services Pte Ltd**

AAD1808-102

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 162A**

69	1 HEADLAMP LH	\$	Su 1,184.43
70	1 HEADLAMP RH	\$	Su 1,184.43
71	1 HEADLAMP PANEL FRT LH	\$	N 152.15
72	1 HEADLAMP PANEL FRT RH	\$	N 152.15
73	1 BONNET	\$	N 1,941.63
74	1 BONNET INSULATOR	\$	Su 405.73
75	1 BONNET STRUT LH	\$	Su 88.61
76	1 BONNET STRUT RH	\$	Su 88.61
77	1 BONNET HINGE LH	\$	N 348.31
78	1 BONNET HINGE RH	\$	N 348.31
79	1 BONNET LOCK	\$	N 305.48
80	1 BONNET CABLE	\$	Su 119.19
81	1 BONNET CABLE COVER	\$	Su 161.03
82	1 BONNET SEAL OUTER	\$	Su 92.36
83	1 BONNET SEAL INNER	\$	Su 157.28
84	1 FENDER PANEL FRT LH	\$	N 783.83
85	1 WHEELARCH FRT LH	\$	Su 278.84
86	1 FENDER BRACKET LOWER LH	\$	Su 15.79
87	1 FENDER INSULATOR LH	\$	Su 130.84
88	1 FENDER PANEL FRT RH	\$	N 783.83
89	1 WHEELARCH FRT RH	\$	Su 278.84
90	1 FENDER BRACKET LOWER RH	\$	N 15.79
91	1 FENDER INSULATOR RH	\$	Su 130.84
92	1 AIR CLEANER LOWER	\$	Su 271.26
93	1 AIR CLEANER HOSE	\$	Su 76.14
94	1 BASE BATTERY TRAY	\$	Su 363.40
95	1 AIR CLEANER BOX	\$	Su 464.20
96	1 TURBO DUCT	\$	Su 1,027.80
97	1 A/C HEATER VALVE	\$	Su 484.50
98	1 SUBFRAME OUTER FRT	\$	Su 2,652.45
99	1 SUBFRAME BRACKET OUTER LH	\$	Su 92.36
100	1 ENGINE UNDERTRAY	\$	Su 564.98
101	1 A/C CONDENSER	\$	Su 2,020.37
102	1 A/C CONDENSER GARNISH LH UPPER	\$	Su 39.67
103	1 A/C CONDENSER GARNISH RH UPPER	\$	Su 39.67
104	1 A/C CONDENSER GARNISH LH	\$	Su 58.81
105	1 A/C CONDENSER GARNISH RH	\$	Su 59.60
106	1 A/C PIPE CONDENSER TO COMPRESSOR	\$	Su 208.39

X

**Trans-cab Auto Services Pte Ltd**

**AAD1808-102**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 162A**

107	1 A/C PIPE CONDENSER TO EXPENSION VALVE	\$	S <sub>h</sub>	658.72
108	1 A/C PIPE COMPRESSOR	\$	S <sub>h</sub>	334.29
109	1 A/C PIPE	\$	S <sub>h</sub>	658.72
110	1 A/C COMPRESSOR	\$	S <sub>h</sub>	2,684.61
111	1 AIR COOLER	\$	S <sub>h</sub>	792.60
112	1 AIR INTERCOOLER HOSE (LONG)	\$	S <sub>h</sub>	1,014.13
113	1 AIR INTERCOOLER HOSE (Short)	\$	S <sub>h</sub>	375.14
114	1 TRANSMISSION COOLER	\$	S <sub>h</sub>	1,219.30
115	1 TRANSMISSION COOLER PAD	\$	S <sub>h</sub>	17.96
116	1 RADIATOR	\$	S <sub>h</sub>	1,202.20
117	2 RADIATOR STUD UPPER	\$	S <sub>h</sub>	14.41
118	2 RADIATOR BUSH UPPER	\$	S <sub>h</sub>	50.12
119	2 RADIATOR MTG LOWER	\$	S <sub>h</sub>	55.85
120	1 RADAITOR FAN COWLING	\$	S <sub>h</sub>	820.54
121	1 RADIATOR FAN MOTOR LH	\$	S <sub>h</sub>	967.36
122	1 RADIATOR FAN MOTOR RH	\$	S <sub>h</sub>	1,479.46
123	1 RADIATOR TANK	\$	S <sub>h</sub>	324.62
124	1 RADIATOR HOSE UPPER	\$	S <sub>h</sub>	240.56
125	1 RADIATOR HOSE LOWER	\$	S <sub>h</sub>	491.18
126	1 RADIATOR TANK HOSE	\$	S <sub>h</sub>	61.18
127	1 AUTO COMPUTER	\$	S <sub>h</sub>	5,032.17
128	1 INJECTION COMPUTER	\$	S <sub>h</sub>	4,706.30
129	1 RHD HYDRAULIC POWER(ROCK&PINION)	\$	S <sub>h</sub>	5,154.52
130	1 STEERING PUMP ELECTRIC L70Y	\$	S <sub>h</sub>	2,306.90
131	1 STEERING PINION RACK L70Y	\$	S <sub>h</sub>	4,413.11

X

<b>TOTAL</b>	<b>\$</b>	<b>100,711.96</b>
<b>10%</b>	<b>\$</b>	<b>10,071.20</b>
	<b>\$</b>	<b>90,640.76</b>

**Special Nett**

1	1SET PARKING AID	\$	Short	700.00	Good
2	1SET REAR BUMPER CLIP	\$	na	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X

# Trans-cab Auto Services Pte Ltd

AAD1808-102

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

## SHD 162A

7 1SET BUMPR RETAINER CLIP LH RR	\$	na	20.00	X
8 1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9 1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10 1 EXHAUST MOUNTING REAR	\$	Sm	17.82	X
11 1SET BOOT FINISHER CLIP	\$	na	24.20	✓
12 1 BOOT STICKER "Trans-cab"	\$	na	30.00	✓
13 1 BOOT STICKER "6555-3333"	\$	na	30.00	✓
14 1 BOOT INNER TRIM CLIP	\$	na	45.00	X
15 1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
16 1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
17 1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X
18 1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X
19 1 TAILLAMP CLIP RH	\$	na	5.00	✓
20 1 TAILLAMP CLIP LH	\$	na	5.00	✓
21 2 REAR WINDSCREEN SELANT	\$	na	80.00	X
22 1 WINDSCREEN MOULDING	\$	na	100.00	X
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	X
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sm	385.00	X
25 1 SPARE TYRE	\$	Sm	330.00	X
26 1SET RADIATOR GRILLE FRAME CLIP	\$	na	52.00	✓
27 1SET BUMPER CLIP FRT	\$	na	66.00	} X
28 1 BUMPER BRACKET CLIP FRT LH	\$	na	12.00	
29 1 BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
30 1 BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
31 1 BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
32 1 TOW COVER FRT	\$	Sm	14.50	
33 1SET RADIATOR GRILLE SCREW	\$	na	16.00	
34 1SET BUMPER GRILLE LOWER CLIP	\$	na	69.00	
35 1SET FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
36 2 FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
37 2 FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	
38 1 Windscreen moulding	\$	na	100.00	
39 1SET Front licence plate with holder	\$	Sm	80.00	

**TOTAL \$ 2,787.52**

**TOTAL PARTS \$ 93,428.28**

**Trans-cab Auto Services Pte Ltd**

AAD1808-102

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 162A

**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	6601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	7001
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	na 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	4 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	na 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	4 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	4 170.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X

**Trans-cab Auto Services Pte Ltd**

AAD1808-102

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 162A

To transfer of rear door fittings, attachment and perform water seepage test.	\$	na	380.00	X
Towing Fees.	\$	na	120.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	na	380.00	X
To rust-proofing of the affected areas.	\$	na	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
To check steering geometry and computer wheel alignment	\$	na	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	na	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	201
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	na	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4	380.00	X
To lift-up engine with gear box and refit.	\$	4	440.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	4	440.00	X
To remove and refit air bag system and reset.	\$	4	480.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	4	380.00	X

**Trans-cab Auto Services Pte Ltd**

**AAD1808-102**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 162A**

To vacuum, replace, refix and recharge air condenser	\$	~ 380.00	X
To replace, refix and top up coolant for radiator	\$	↪ 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	↪ 170.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	↪ 170.00	X
<b>TOTAL</b>	<b>\$</b>	<b>17,920.00</b>	

**Over All Total \$ 111,348.28**

**(PART-BY-PART)**

**Repair Days**

*20 DAYS*  
*5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

## LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18014908/KQD3N2  
Date: 22/10/2018

#### REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	ME000409
Claimant Vehicle No :	SHD162A	Insured Vehicle No :	GBC6209L
Date of Loss:	14/08/2018	Nature of Claim:	TP
		Claim No:	M1804060

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD162A	Engine No:	M9R8839C002519
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Chassis No:	VF1ABL15AUC281545
Reg. Date:	10/09/2015 (Man. Year: 2015)	Odometer:	401570 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Giti 8 mm

*The above values represent the remaining tyre treads depth*

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	93,428.27	12,297.16	81,131.11	86.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,920.00	1,620.00	16,300.00	90.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>111,348.27</b>	<b>13,917.16</b>	<b>97,431.11</b>	<b>87.50</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>7,794.38</b>	<b>974.20</b>	<b>6,820.18</b>	<b>87.50</b>
<b>Nett Amount (S\$)</b>	<b>119,142.65</b>	<b>14,891.36</b>	<b>104,251.29</b>	<b>87.50</b>

#### INSPECTION

Date of Assignment:	16/08/2018	
Date Inspected:	15/08/2018	Inspected At:
		Trans Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63 Singapore 569111
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

Reference	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 19 Oct 2018)
<b>Parts:</b> 143	RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD162A)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1	*BUMPER LOWER REAR	Dented	768.84 FL	*768.84 FL
3	1	*BUMPER BRACKET CTR REAR	Distorted	113.47 FL	*113.47 FL
4	1	*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1	*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1	*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1	*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1	*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1	*BUMPER REFLECTOR LH	Cracked	43.61 FL	*43.61 FL
10	1	*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1	*BUMPER BEAM BRACKET LH REAR	Bent	225.95 FL	*225.95 FL
12	1	*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1	*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
14	1	*BOOT FINISHER	Warped	470.06 FL	*470.06 FL
15	1	*BOOT WEATHERSTRIP	Distorted/Cut	323.05 FL	*323.05 FL
16	1	*BOOT REFLECTOR LAMP LH	Cracked	493.35 FL	*493.35 FL
17	1	*BOOT REFLECTOR LAMP RH	Cracked	493.35 FL	*493.35 FL
18	1	*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
19	1	*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
20	1	*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1	*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1	*BOOT HINGE LH	Repair	367.84 FL	*- FL
23	1	*BOOT HINGE RH	Repair	367.84 FL	*- FL
24	1	*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1	*BOOT SWITCH	Serviceable	168.13 FL	*- FL
26	1	*BOOT LOCK	Repair	202.67 FL	*- FL
27	1	*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
28	2	*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	2	*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1	*DOOR PANEL REAR LH	Repair	2,844.66 FL	*- FL
31	1	*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL	*- FL
32	1	*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
33	1	*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
34	1	*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL
35	1	*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
36	1	*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
37	1	*TAILLAMP RH	Mtg Cracked	552.55 FL	*552.55 FL
38	1	*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
39	1	*TAILLAMP LH	Mtg Cracked	552.55 FL	*552.55 FL
40	1	*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
41	1	*OUTER PANEL REAR (END PANEL)	Bent	1,471.77 FL	*1,471.77 FL
42	1	*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*- FL
43	1	*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	2,189.88 FL	*- FL
44	1	*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*EXHAUST REAR	Repair	7,489.05 FL	*-FL
46	1	*EXHAUST CAP REAR	Serviceable	230.49 FL	*-FL
47	1	*FUEL FLAP L70Y	Serviceable	343.57 FL	*-FL
48	1	*BUMPER COVER FRT	Serviceable	1,259.42 FL	*-FL
49	1	*BUMPER SPOILER FRT	Serviceable	181.75 FL	*-FL
50	1	*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*-FL
51	1	*BUMPER RETAINER FRT LH	Serviceable	151.41 FL	*-FL
52	1	*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*-FL
53	1	*BUMPER RETAINER FRT RH	Serviceable	150.77 FL	*-FL
54	1	*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*-FL
55	1	*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*-FL
56	1	*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*-FL
57	1	*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*-FL
58	1	*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*-FL
59	1	*BUMPER BEAM FRT	Repair	914.08 FL	*-FL
60	1	*TOW COVER FRT	Serviceable	28.61 FL	*-FL
61	1	*RADIATOR GRILLE	Cracked	1,707.78 FL	*1,707.78 FL
62	1	*RADIATOR GRILLE BADGE RENAULT	Dented	225.36 FL	*225.36 FL
63	1	*RADIATOR GRILLE FRAME	Serviceable	1,353.75 FL	*-FL
64	1	*FRAME FULL SUPPORT PANEL	Serviceable	615.90 FL	*-FL
65	1	*FRAME FULL SUPPORT BRACKET	Repair	89.79 FL	*-FL
66	1	*FRONT BRACE PANEL	Repair	177.22 FL	*-FL
67	1	*HORN	Serviceable	314.17 FL	*-FL
68	1	*HORN BRACKET	Repair	40.45 FL	*-FL
69	1	*HEADLAMP LH	Serviceable	1,184.43 FL	*-FL
70	1	*HEADLAMP RH	Serviceable	1,184.43 FL	*-FL
71	1	*HEADLAMP PANEL FRT LH	Repair	152.15 FL	*-FL
72	1	*HEADLAMP PANEL FRT RH	Repair	152.15 FL	*-FL
73	1	*BONNET	Repair	1,941.63 FL	*-FL
74	1	*BONNET INSULATOR	Serviceable	405.73 FL	*-FL
75	1	*BONNET STRUT LH	Serviceable	88.61 FL	*-FL
76	1	*BONNET STRUT RH	Serviceable	88.61 FL	*-FL
77	1	*BONNET HINGE LH	Repair	348.31 FL	*-FL
78	1	*BONNET HINGE RH	Repair	348.31 FL	*-FL
79	1	*BONNET LOCK	Repair	305.48 FL	*-FL
80	1	*BONNET CABLE	Serviceable	119.19 FL	*-FL
81	1	*BONNET CABLE COVER	Serviceable	161.03 FL	*-FL
82	1	*BONNET SEAL OUTER	Serviceable	92.36 FL	*-FL
83	1	*BONNET SEAL INNER	Serviceable	157.28 FL	*-FL
84	1	*FENDER PANEL FRT LH	Repair	783.83 FL	*-FL
85	1	*WHEELARCH FRT LH	Serviceable	278.84 FL	*-FL
86	1	*FENDER BRACKET LOWER LH	Serviceable	15.79 FL	*-FL
87	1	*FENDER INSULATOR LH	Serviceable	130.84 FL	*-FL
88	1	*FENDER PANEL FRT RH	Repair	783.83 FL	*-FL
89	1	*WHEELARCH FRT RH	Serviceable	278.84 FL	*-FL
90	1	*FENDER BRACKET LOWER RH	Repair	15.79 FL	*-FL
91	1	*FENDER INSULATOR RH	Serviceable	130.84 FL	*-FL
92	1	*AIR CLEANER LOWER	Serviceable	271.26 FL	*-FL
93	1	*AIR CLEANER HOSE	Serviceable	76.14 FL	*-FL
94	1	*BASE BATTERY TRAY	Serviceable	363.40 FL	*-FL
95	1	*AIR CLEANER BOX	Serviceable	464.20 FL	*-FL
96	1	*TURBO DUCT	Serviceable	1,027.80 FL	*-FL
97	1	*A/C HEATER VALVE	Serviceable	484.50 FL	*-FL
98	1	*SUBFRAME OUTER FRT	Serviceable	2,652.45 FL	*-FL
99	1	*SUBFRAME BRACKET OUTER LH	Serviceable	92.36 FL	*-FL
100	1	*ENGINE UNDERTRAY	Serviceable	564.98 FL	*-FL
101	1	*A/C CONDENSER	Serviceable	2,020.37 FL	*-FL
102	1	*A/C CONDENSER GARNISH LH UPPER	Serviceable	39.67 FL	*-FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
103	1	*A/C CONDENSER GARNBISH RH UPPER	Serviceable	39.67 FL	*- FL
104	1	*A/C CONDENSER GARNBISH LH	Serviceable	58.81 FL	*- FL
105	1	*A/C CONDENSER GARNBISH RH	Serviceable	59.60 FL	*- FL
106	1	*A/C PIPE CONDENSER TO COMPRESSOR	Serviceable	208.39 FL	*- FL
107	1	*A/C PIPE CONDENSER TO EXPENSION VALVE	Serviceable	658.72 FL	*- FL
108	1	*A/C PIPE COMPRESSOR	Serviceable	334.29 FL	*- FL
109	1	*A/C PIPE	Serviceable	658.72 FL	*- FL
110	1	*A/C COMPRESSOR	Serviceable	2,684.61 FL	*- FL
111	1	*AIR COOLER	Serviceable	792.60 FL	*- FL
112	1	*AIR INTERCOOLER HOSE (LONG)	Serviceable	1,014.13 FL	*- FL
113	1	*AIR INTERCOOLER HOSE (SHORT)	Serviceable	375.14 FL	*- FL
114	1	*TRANSMISSION COOLER	Serviceable	1,219.30 FL	*- FL
115	1	*TRANSMISSION COOLER PAD	Serviceable	17.96 FL	*- FL
116	1	*RADIATOR	Serviceable	1,202.20 FL	*- FL
117	2	*RADIATOR STUD UPPER	Serviceable	14.41 FL	*- FL
118	1	*RADIATOR BUSH UPPER	Serviceable	50.12 FL	*- FL
119	1	*RADIATOR MTG LOWER	Serviceable	55.85 FL	*- FL
120	1	*RADIATOR FAN COWLING	Serviceable	820.54 FL	*- FL
121	1	*RADIATOR FAN MOTOR LH	Serviceable	967.36 FL	*- FL
122	1	*RADIATOR FAN MOTOR RH	Serviceable	1,479.46 FL	*- FL
123	1	*RADIATOR TANK	Serviceable	324.62 FL	*- FL
124	1	*RADIATOR HOSE UPPER	Serviceable	240.56 FL	*- FL
125	1	*RADIATOR HOSE LOWER	Serviceable	491.18 FL	*- FL
126	1	*RADIATOR TANK HOSE	Serviceable	61.18 FL	*- FL
127	1	*AUTO COMPUTER	Serviceable	5,032.17 FL	*- FL
128	1	*INJECTION COMPUTER	Serviceable	4,706.30 FL	*- FL
129	1	*RHD HYDRAULIC POWER (ROCK & PINION)	Serviceable	5,154.52 FL	*- FL
130	1	*STEERING PUMP ELECTRIC L70Y	Serviceable	2,306.90 FL	*- FL
131	1	*STEERING PINION RACK L70Y	Serviceable	4,413.11 FL	*- FL
132	1	*SET PARKING AID	Shorted	700.00 FS	*600.00 FS
133	1	*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
134	1	*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
135	1	*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
136	1	*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
137	1	*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
138	1	*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
139	1	*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
140	1	*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
141	1	*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
142	1	*SET BOOT FINISHER CLIP	Necessary	24.20 FS	*24.20 FS
143	1	*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
144	1	*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
145	1	*BOOT INNER TRIM TRIM	Not Necessary	45.00 FS	*- FS
146	1	*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
147	1	*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
148	1	*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
149	1	*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
150	1	*TAILLAMP CLIP RH	Necessary	5.00 FS	*5.00 FS
151	1	*TAILLAMP CLIP LH	Necessary	5.00 FS	*5.00 FS
152	2	*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
153	1	*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
154	1	*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
155	1	*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
156	1	*SPARE TRYE	Serviceable	330.00 FS	*- FS
157	1	*SET RADIATOR GRILLE FRAME CLIP	Necessary	52.00 FS	*52.00 FS
158	1	*SET BUMPER CLIP FRT	Not Necessary	66.00 FS	*- FS
159	1	*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
160	1	*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS

Report was unsubmitted during this print-out.

## Adjuster Report

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
161	1	*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
162	1	*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
163	1	*TOW COVER FRT	Serviceable	14.50 FS	*- FS
164	1	*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*- FS
165	1	*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
166	1	*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
167	2	*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
168	2	*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
169	1	*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
170	1	*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>103,499.47</b>	<b>13,562.27</b>
- List Item Discount on L Items 10.00/10.00% (S\$)	10,071.20	1,265.11
<b>Total Parts (S\$)</b>	<b>93,428.27</b>	<b>12,297.16</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	660.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,200.00	700.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	-
7	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	-
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST }	New	170.00	60.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST }	New	170.00	-
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANELINSULATION PADDING	New	380.00	-
11	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	-
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
14	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
15	TOWING FEES	New	120.00	-
16	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	-
17	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	-
18	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	-
19	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
20	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	-
21	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
22	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK	New	380.00	-
23	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	-
24	TO LIFT UP ENGINE WITH GEAR BOX AND REFIT	New	440.00	-
25	TO REMOVE AND RENEW POWER STEERING PUMP,OIL COOLER PIPE AND FINAL CHECKING AND TESTING	New	440.00	-
26	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET	New	480.00	-
27	TO DROP DIESEL TANK,PIPES,HOSES TO FACILITATE BODYWORK REPAIR,FINAL CHECKING AND TESTING	New	380.00	-

Report was unsubmitted during this print-out.

## Adjuster Report

No	Particulars	Lab.Type	Repairer's	Amount
28	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER	New	380.00	-
29	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	-
30	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER	New	170.00	-
31	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	-
<b>Gross Labour Cost (S\$)</b>			<b>17,920.00</b>	<b>1,620.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >