

PERFECT WERKZ

Block 25 Kaki Bukit Road 4 #06-51 Synergy@KB Singapore 417800
 HP: 92712214 Fax: (65) 69664526 ROC : 53364512C

GOH CHONG PHENG
 Bk 25 Kaki Bukit Rd 4
 # 05-26 SYNERGY @KB
 Singapore 417800

15th August 2018

TRAXA

Joy

ZNE100288362

Accident date: 14 August 2018

Estimated repair cost for vehicle no: SGF2695S Toyota Wish 1.8 A

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dented</i>		\$950.00
2	2	Rear Boot Lid Hinges <i>2 new</i>	\$187.70	\$375.40 +
3	2	Rear Boot Lid shock absorber	\$232.00	\$464.00 +
4	1	Rear boot lid emble logo <i>new</i>		\$74.10
5	1	Rear Boot Lid Inner Lock <i>Dented</i>		\$549.10 385
6	1	Rear boot lid inner rubber <i>new</i>		\$276.10
7	1	Rear Boot Lid center moulding <i>2 new</i>		\$613.80 x
8	2	Rear Boot Lid center moulding side clips	\$8.50	\$17.00 x
9	1	Rear Boot Lid Number Plate <i>Dented</i>		\$50.00
10	2	Rear Boot Lid Number Plate Lamp <i>new</i>	\$135.10	\$270.20 x
11	1	Rear Boot Lid Inner Trim board <i>new</i>		\$680.00 +
12	1	Rear Boot Lid Inner lock side cover <i>new</i>		\$68.00 +
13	1	Rear boot lid windscreen seal <i>new</i>		\$310.10 255.30
14	2	Rear tail lamp <i>2 new</i>	\$640.10	\$1,280.20 +
15	4	Rear tail lamp clips <i>new</i>	\$8.50	\$34.00 +
16	2	Rear tail lamp panel	\$320.00	\$640.00 +
17	1	Rear End Panel outer <i>Dented</i>		\$740.00 581.50
18	1	Rear End Panel inner <i>new</i>		\$580.00 +
19	1	Rear End Panel Top Garnish <i>not new</i>		\$403.40 x
20	1	Rear spare tire lock <i>new</i>		\$536.10 +
21	2	Rear fender inner trim board <i>new</i>	\$870.00	\$1,740.00 +
22	1	Rear floor panel top cover		\$535.77 +
23	1	Rear floor panel sealant		\$120.00 +
24	2	Rear floor panel side cover <i>new</i>	\$225.50	\$451.00 +
25	1	Rear floor panel inner garnish		\$682.70 x
26	1	Rear floor panel inner trim		\$503.10 +

27	1	Rear Bumper <i>deformed</i>		\$1,077.00 <i>575</i>
28	2	Rear Bumper side reflector <i>new</i>	\$83.10	\$166.20 <i>x</i>
29	2	Rear Bumper Side Bracket <i>new</i>	\$55.60	\$111.20 <i>✓</i>
30	1	Rear Bumper reverse sensor <i>Damaged</i>		\$350.00 <i>200 (800)</i>
31	2	Rear Bumper Bracket <i>new</i>	\$68.40	\$136.80 <i>+</i>
32	8	Rear bumper clips <i>new</i>	\$6.50	\$52.00 <i>30</i>
33	1	rear exhaust		\$971.10 <i>x</i>
34	1	rear exhaust aluminium cover <i>new</i>		\$212.15 <i>x</i>
35	1	rear bumper lower air cond pipe		\$288.00 <i>+</i>

Subtotal :- \$16,308.52

3298.60 S.N. 200

2473.85

labour charges

To remove & refix front air-con pipe & top up gas

\$180.00 *x*

To Check Wiring System

~~\$80.00~~ *30*

Tuff Kote

~~\$150.00~~ *50*

To Remove & refix cushion

~~\$150.00~~ *60*

To Remove & refix rear exhaust

1960

\$220.00 *+*

To Remove & refix rear windscreen

\$120.00 *✓*

Gum

\$50.00 *✓*

To Remove & refix reverse Sensor

~~\$100.00~~ *50*

Towing charges

\$100.00 *+*

Panel beating

~~\$1,400.00~~ *80*

Spray painting

~~\$1,400.00~~ *80*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal :- \$3,950.00

Total:- \$20,258.52

total: 4633.85

L/s: 3.7K *✓*

06 days