

EDV00001

ASS. REC. BY:

REP:

CS3/AXA18014949/Uzad3¹⁵²

Special Instruction:

Surveyor:
Meimien

Marcus

ASSIGNMENT (Office)

From (Person):

Vale oh

of

AXA

Date/Time:

15/8/18 @ 4:08pm

Estimated Cost:

Bill to:

OD / (IP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMA 4680B

Insured:

SHF 745H

at Workshop m/s

Apex Motoring

Tel:

9619 4055 / 9725 5585

of

Blk 14 Sin Ming Ind. #01-11

Policy No:

P1680520

Claim No:

C0474 227

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14/08/2018

Insp: 25 KB Rd 4 # 01-55

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

16/8/18 @ 10:47am

Person Contacted:

Mr. Lim

Vehicle

IN OUT

Date/Time	Action/Instruction (X) Estimate
	SMA 4680B - X
	SHF 745H - (ca) AXA 16018594 / H1ha3s2 DOA: 29/9/16
17/8/18	Dismantled.
21/8/18	After Repair



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS3/AXA18014949/Uz4d3

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 16-08-2018



Code : AXA2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHF 745H	Veh. Inspected	SMA 4680B
Policy No.	P1680520	Coverage (\$)	0.00
Claim No.	C0474227	Excess (\$)	0.00
Assign From	MERIMEN (VALE OH)	Assign Date	16/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/08/2018	Inspection Date	16/08/2018
Survey held at	APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGAPORE 417800.		

5a. Remarks

<p>A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.</p>
--

...CLAIM SUBFOLDER...(New Assignment)

PRI

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	
Main	14 Aug 2018		15 Aug 2018 16:08 Assign				New Assignment Cancel Case

Main
Reference
Claim Details
Documents
[Show All](#)

[\[Created by insurer\]](#)

CLAIM SUBFOLDER DETAILS

Insured:	TRANS-CAB SERVICES PTE LTD		
Main Claimant:	TBC		
Vehicle Reg. No.:	SMA4680B	Date of Loss:	14/08/2018 16:00 - :59
Claim Type:	TP / C0474227	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHF745H	Policy No. (Claimant):	
		Excess:	S\$5,000.00
Repairer:	Apex Motoring (HQ) Block 14 Sin Ming Industrial #01-11 Sin Ming Road, 575658 Sin Ming - Tel: 9619 4055		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Vale Oh - 6880 4897]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/08/2018]		
Adj Asg. Remarks:	Please conduct PRI.		

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

- AXA_SG (15/08/2018): WP/ PRI Assignment - C0474227/P1680520

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)



14/08/2018

AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way
#27-01 AXA Tower
Singapore 068811
Fax : 6880 4838

Dear Sirs

**ACCIDENT BETWEEN VEHICLE NO. SMA 4680 B AND VEHICEL NO. SHF 745 H
ON 14/08/2018 @ 1607 HRS**

We are the appointed repair workshop of vehicle no. **SMA 4680 B**

We understand that you are the insurer of vehicle no. **SHF 745 H**

The owner of vehicle number **SMA 4680 B** has authorised us to carry out the repairs to his vehicle which was damaged by your insured's vehicle. The owner intends to make a claim against your insured and/or insured's authorised driver for the accident which is caused wholly and/or contributed by your insured and/or your insured's authorised driver's negligence.

We hereby give you notice of the accident and an opportunity to inspect the damaged to the vehicle prior to the commencement of the repairs.

The vehicle is now at our workshop awaiting for your inspection at the following address: 25 Kaki Bukit Road 4 #01-55 Synergy @ KB Singapore 417800.

Please email 10 surveyor list to peijie@expresscar.com.sg
Mobile No. 9725 5585 Mr Lee

Yours faithfully

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Aug 2018		15 Aug 2018 16:08 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: -		
Main Claimant:	TBC		
Vehicle Reg. No.:	SMA4680B	Date of Loss:	14/08/2018 16:00 - :59 [343 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0474227	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHF745H	Policy No. (Claimant):	
		Excess:	S\$5,000.00
Repairer:	Apex Motoring (HQ) Block 14 Sin Ming Industrial #01-11 Sin Ming Road, 575658 Sin Ming - Tel: 9619 4055		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Vale Oh - 6880 4897]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 27/08/2018]		
Adj Asg. Remarks:	Please conduct PRI.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AXA_SG (15/08/2018): **WP/ PRI Assignment - C0474227/P1680520**

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMA4680B (C0474227)**
[SHF745H]
TP
TBC
Aug 14 2018 4:00PM
[TRANS-CAB SERVICES PTE LTD]
Apex Motoring

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View	View in Browser ▼
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
2	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
3	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
4	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
5	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
6	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
7	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
8	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
9	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
10	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
11	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
12	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
13	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
14	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
15	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
16	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
17	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
18	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
19	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
20	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
21	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
22	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
23	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
24	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
25	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
26	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
27	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
28	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
29	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
30	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
31	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
32	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
33	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
34	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>
35	18/08/18 11:45	General View		Load JPG <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	18/08/18 11:45	General View		<input checked="" type="checkbox"/>
37	18/08/18 11:45	General View		<input checked="" type="checkbox"/>
38	18/08/18 11:45	General View		<input checked="" type="checkbox"/>
39	18/08/18 11:45	General View		<input checked="" type="checkbox"/>
40	18/08/18 11:45	General View		<input checked="" type="checkbox"/>
41	28/08/18 11:52	Dismantled Parts		<input checked="" type="checkbox"/>
42	28/08/18 11:52	Dismantled Parts		<input checked="" type="checkbox"/>
43	28/08/18 11:52	Dismantled Parts		<input checked="" type="checkbox"/>
44	28/08/18 11:52	Dismantled Parts		<input checked="" type="checkbox"/>
45	28/08/18 11:52	Dismantled Parts		<input checked="" type="checkbox"/>
46	28/08/18 11:52	Dismantled Parts		<input checked="" type="checkbox"/>
47	28/08/18 11:52	Dismantled Parts		<input checked="" type="checkbox"/>
48	28/08/18 11:52	Dismantled Parts		<input checked="" type="checkbox"/>
49	28/08/18 11:52	Dismantled Parts		<input checked="" type="checkbox"/>
50	28/08/18 11:52	Dismantled Parts		<input checked="" type="checkbox"/>
51	28/08/18 11:52	Dismantled Parts		<input checked="" type="checkbox"/>
52	28/08/18 11:52	Dismantled Parts		<input checked="" type="checkbox"/>
53	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
54	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
55	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
56	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
57	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
58	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
59	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
60	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
61	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
62	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
63	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
64	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
65	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
66	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
67	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
68	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
69	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
70	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
71	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
72	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
73	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
74	28/08/18 11:52	Photo After Spray		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	14/08/18 13:43	CO_CLAIMANT		<input type="checkbox"/>
2	14/08/18 13:50	EMAIL TO WORKSHOP		<input type="checkbox"/>
3	15/08/18 15:54	SHF745H GIA REPORT		<input type="checkbox"/>
4	15/08/18 16:05	FRM TP		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AXA18014949/UZ4D3S2

Date: 25/10/2018

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1680520
Claimant Vehicle No :	SMA4680B	Insured Vehicle No :	SHF745H
Date of Loss:	14/08/2018	Nature of Claim:	TP
		Claim No:	C0474227

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA4680B	Engine No:	HIDDEN
Make & Model:	TOYOTA PRIUS HYBRID, 1.5 (A)	Chassis No:	ZVW400029142
Reg. Date:	01/01/1990 (Man. Year: 1990)	Odometer:	21435 km
Colour:	Grey		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	15/08/2018		
Date Inspected:	16/08/2018	Inspected At:	Apex Motoring (HQ) Block 14 Sin Ming Industrial #01-11 Sin Ming Road Singapore 575658
Estimated Period of Repair:	6.0 days		

Adjuster: MARCUS CHUA

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Oct 2018)

Parts: 144 TOYOTA PRIUS HYBRID 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMA4680B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >