



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 8 2016 ISUZU LT434P 7.8 SMT ISUXXX
(PC5748M)

Date of Loss 11 August 2018

Time of Loss 14.30

Loss Description PC5748M (INSD) C/W TREE & KERB

Comment

Workshop Details

Total Rebate Amount 27990

Nett Loss Amount \$222,010.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion * 201



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# PC5748M

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

18/04/2017



Mileage

72957

Age of Vehicle

1

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATIONManufacturing
Year

2016

2016

Make

ISUZU LT434P 7.8
SMT

ISUZU

Model

ISUXXX

LT434P 7.8 SMT

Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Driver Name

KWEK YONG LEE ADDISON

Date of Birth

18 May 1961

dd/mm/yy



Age

57

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No	JALLT434PH7000006	ALLT434PH7000006
Engine No	6HK1692281	6HK1692281
Engine Capacity		7790
Sum Insured	0	0
Market Value	0	250000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	14	
Driver License #		
License Type		
License Issue Date	1 January 2005	dd/mm/ 
License Expiration Date		dd/mm/ 
Address	BLK 174C HOUGANG, AVENUE 1 #08-1559, 533174, Singapore	
Address type	Personal Correspondence	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	
Marital status	Unknown	
Identification #	S1511302B	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

16/08/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

3000

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

11R22.5

Rear Tyre Size

11R22.5(D)

Front left side

BRIDGESTONE8mm

Rear left side

BRIDGESTONE8/8mm

Front right side

BRIDGESTONE8mm

Rear right side

BRIDGESTONE8/8mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			FRONT BUMPER ASSY			Damaged	4600		10		4140	Reviewing	
		2	1			FRONT BUMPER STRUCTURAL FRAME ASSY			Bent	1400		10		1260	Reviewing	
		3	2			FRONT BUMPER SPOT LAMP (*CHECK) (\$560.00)				0		10		0	Reviewing	
		4	1			FRONT CROSS MEMBER			Bent	1100		10		990	Reviewing	
		5	1			O/S FRONT HEADLAMP			Damaged	960		10		864	Reviewing	
		6	1			N/S FRONT HEADLAMP (*CHECK) (\$960.00)				0		10		0	Reviewing	
		7	1			FRONT CENTRE PANEL			Deformed	2100		10		1890	Reviewing	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		8	1			FRONT CENTRE PANEL CHROME MOULDING			Deformed	310		10		279	Reviewing	
		9	1			FRONT TOP PANEL			Cracked	3600		10		3240	Reviewing	
		10	1			FRONT PANEL STRUCTURAL FRAME ASSY			Bent	2400		10		2160	Reviewing	
		11	1			FRONT TOP VISOR PANEL			Damaged	2200		10		1980	Reviewing	
		12	1			SET FRONT TOP VISOR PANEL BRACKET			Bent	320		10		288	Reviewing	
		13	2			FRONT WIPER ARM			Damaged	280		10		504	Reviewing	
		14	2			FRONT WIPER BLADE			Serviceable	0	0	0	0	0	Deny	
		15	1			O/S FRONT WIPER ARM CAP			Missing	26		10		23.4	Reviewing	
		16	1			N/S FRONT WIPER ARM CAP			Serviceable	0	0	0	0	0	Deny	
		17	1			FRONT WIPER MOTOR			Serviceable	0	0	0	0	0	Deny	
		18	1			FRONT WIPER LINKAGE ASSY			Serviceable	0	0	0	0	0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		19	1			O/S FRONT WIPER NOZZLE			Cut	10		10		9	Reviewing	
		20	1			N/S FRONT WIPER NOZZLE			Serviceable	0	0	0	0	0	Deny	
		21	1			FRONT MAIN WINDSCREEN GLASS (*CHECK) (\$7,000.00)				0		10		0	Reviewing	
		22	1			O/S FRONT ELECTRICAL WING MIRROR ASSY			Cracked	2900		10		2610	Reviewing	
		23	1			N/S FRONT ELECTRICAL WING MIRROR ASSY			Repair	0	0	0	0	0	Deny	
		24	1			FRONT VISOR PANEL			Serviceable	0	0	0	0	0	Deny	
		25	1			SET FRONT VISOR PANEL BRACKET			Serviceable	0	0	0	0	0	Deny	
		26	1			FRONT TOP WINDSCREEN GLASS (*CHECK) (\$4,200.00)				0		10		0	Reviewing	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		TO TOW SUBJECT VEHICLE (TWO TRIPS). (*CHECK) (\$500.00)	0	0	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		2		TO REMOVE DAMAGED FRONT SHOCK ABSORBERS AND REFIT NEW INCLUDING CARRYING OUT FRONT WHEEL ALIGNMENT. (*CHECK) (\$600.00)	0	0	0	Reviewing	
		3		TO REMOVE DAMAGED FRONT MAIN WINDSCREEN GLASS AND REFIT NEW. (*CHECK) (\$600.00)	0	0	0	Reviewing	
		4		TO REMOVE DAMAGED FRONT TOP WINDSCREEN GLASS AND REFIT NEW. (*CHECK) (\$500.00)	0	0	0	Reviewing	
		5		TO REMOVE FRONT DASHBOARD PANEL SO AS TO ENABLE REPAIR TO BE CARRIED OUT AND REFIT SAME. (*CHECK) (\$500.00)	0	0	0	Reviewing	
		6		TO CHECK WIRING SYSTEM AND ADJUST HEADLAMP ALIGNMENT	50	0	0	Reviewing	
		7		TO SUPPLY AND SPRAY INSULATION FOAM ON ALL AFFECTED ACCIDENT PARTS	500	0	0	Reviewing	
		8		TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER, FRONT CENTRE PANEL, FRONT PANEL, FRONT VISOR PANEL, WING MIRROR CASING AND ALL AFFECTED ACCIDENT PARTS. (MULTI COLOUR)	2000	0	0	Reviewing	

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		9	TO CUT OFF DAMAGED FRONT STRUCTURAL FRAMES AND WELD NEW. TO JACK / KNOCK / STRAIGHTEN ALL NECESSARY PARTS INCLUDING REPAIRING AND CHANGING OF ALL DAMAGED PARTS AND ALIGN SAME	2000	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	(REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$15,750.00 NETT)	Reviewing			
		2	DAYS OF REPAIR : 10 DAYS	Reviewing			
		3	FRONT MAIN WINDSCREEN GUM	Reviewing	200	NECESSARY	

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		4	FRONT TOP WINDSCREEN GUM	Reviewing		(*CHECK) (\$400.00)	
		5	FRONT NUMBER PLATE ASSY	Reviewing	35	BROKEN	
		6	ERP BRACKET	Reviewing		(*CHECK) (\$120.00)	
		7	FRONT SHOCK ABSORBER - 2PCS	Reviewing		(*CHECK) (\$1,082.00)	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition		Taxes & Ratio		Parts & Labour		Miscellaneous		Summary	
Claim Amount		\$22,022.40				Claim Amount				\$22,022.40			
CATEGORY		ESTIMATE				REVISED AMOUNT							
Spare Parts		\$20,237.40				\$20,237.40							
Labour		\$4,550.00				\$4,550.00							
Miscellaneous		\$235.00				\$235.00							
Excess		-\$3,000.00				-\$3,000.00							
Submit for Review													