

**SMC AUTO ENGINEERING WORKS**

Invoice/Ref No: YP5749K180710

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 52889066B . Tel: 6741-1731 . Fax: 6744-5746. Email: smc_eplow@yahoo.com.sg

Estimate

Customer

Name: AXA Insurance Singapore Pte Ltd

Date: 16-08-18

Address: Motor Claims Department

Vehicle No: XE2601S

8 Shenton Way #27-01

Model/Make Iveco Stralis

AXA Tower

Singapore 068811

My2013 AT440S36T/P (Euro V)

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Bumper	\$ 3,666.46	
2	Front LH Lower Bumper Garnish	\$ 1,946.40	
3	Front LH Bumper Signal Lamp	\$ 274.58	X
4	Front LH Step Panel Lower	\$ 1,670.00	
5	Front LH Step Panel Top	\$ 2,360.00	X
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 800.00	
	To putty & spray painting & including touch up paint on accident affected areas	\$ 600.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 11,317.44

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



P-7132-86
102
6419.57

M/s SMC Auto Engrg Ws

not allowed
LKH
M/s 45750
3 sh.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: