

ASS. REC. BY:

REF:

CS/AIG/8015018/GV03

Special Instruction:

M/V Vendor:

Mithoo Singh

ASSIGNMENT (Office)

AIG

Date/Time: 17/8/18 @ 9:13am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

818 6458E

Insured:

SLK 632B

at Workshop n/s:

Ah Cheng Motor

Tel:

64835434

of

Blk 10 AMK Ind. Park 2A #03-16

Policy No:

099999 4765

Claim No:

3736467480 SG

Sum Insured:

Excess:

Make of Veh:

D.O.A

13/8/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

hps

H.O.D. Endorsement:

Date/Time:

11:34am @ 17/8/18

Person Contacted:

Diana

Vehicle

IN OUT

Date/Time

Action/Instruction

(✓) - limit

818 6458E - CC3/AIG 09025257/Cwq/n

D.O.A: 8/11/2009

818 632B-x

16/10/18

LS \$5000 confirmed by email (Recd 14,745.90, 75b)

(08/11/13) wef

ASS. SEC. BY:

REF:

AIG

8083H

ASSIGNMENT

From:

Date: 17/8/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJS6458E

at Workshop m/s

Ah Chang Motor

of BIK10, AMK Ind. Park 2A #03-16

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$12K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

lup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJS6458E

Yr Regn:

27 Aug 2009

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA cerato Forte 1591

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading:

212995

T/Radio: Insured / Std / NI / NA

Eng/No:

KNAFW41MA 5114831

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F: 215/45 R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

17-08-18

Survey held at

W/S

4:20pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/8 estimate given later. repair limit \$4000 - \$5000.

RECEIVED 17 OCT 2018

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

6

1)

☐

Final Report

Resurvey No. of Trip:

1

Date/Time, File Return to?

2)

17/10 - typist

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

merimen

Lump Sum / I.B.I: (\$

5000)

250

20

270



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG18015018/Gvd3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 17-08-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 632B	Veh. Inspected	SJS 6458E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MITHOOSINGH	Assign Date	17/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	13/08/2018	Inspection Date	17/08/2018
Survey held at	AH CHANG MOTOR SERVICE CENTRE BLK 10 ANG MO KIO IND PARK 2A AMK AUTOPOINT #03-16 SINGAPORE 568047		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Aug 2018 Edit Reg		17 Aug 2018 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K			
Main Claimant:	-			
Vehicle Reg. No.:	SJS6458E	Date of Loss:	13/08/2018 00:00 - :59	
Claim Type:	TP / 3736467480SG	Policy/Cover Note No.:	0999994765 (Comprehensive)	
Vehicle Reg. No. (Insured):	SLK632B	Policy No. (Claimant):		
Excess:				
Repairer:	Ah Chang Motor Service Centre (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A, ANG MO KIO POINT #03-16, 568047 Ang Mo Kio - Tel: 64835434			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Gan, Angie-GL] Anglegeokling.Gan@aig.com			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 29/08/2018]			
Claimant's Solicitor:	CHEONGHOH LAW CORPORATION - Tel: 63378700			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (20/08/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 17 October 2018 8:58 AM
To: 'ACM Chang'; SUR
Subject: RE: SJS 6458E-DOA: 13/8/2018

Dear Diana,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ACM Chang <acm.chang@outlook.com>
Sent: Tuesday, 16 October 2018 11:38 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: SJS 6458E-DOA: 13/8/2018

Dear Veron

We confirm on the repair amount of \$5000, but not on the 6 working days.

We will follow on our rental bill for that.

We will entrust our Lawyer to handle the case.

Your understanding is much appreciated.

Thank you

Diana

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Monday, October 15, 2018 3:06 PM
To: SUR; ACM Chang
Subject: SJS 6458E-DOA: 13/8/2018

Dear Sir/Madam,

WITHOUT PREJUDICE

Offer Lump Sum \$5,000/- (Max) @ 6 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

- Pre repair inspection request - SJS6458E VS SLK632B (OI) DOA 13/08/2018

From: Mithoosingh, Aashweenjeetkaur
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi
Sent: 17/8/2018 9:13:33 AM
Attachments: 80725 (Notice of Accident).pdf

Hi,

Please refer to the enclosed request from **Cheonghoh Law Corporation**.

Claim no : 3736467480SG003
Case Owner : ANGIE GEOK LING GAN

If you have any queries/concerns, please let us know.
Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks and regards,

Aashweenjeet Kaur (Aashween)
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Cheong Hoh Lee [mailto:mail@cheonghoh.sg]
Sent: Thursday, August 16, 2018 6:05 PM
To: Mithoosingh, Aashweenjeetkaur
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi
Subject: Re: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLK632B AND SJS6458E ON 13/08/2018; Our ref: LCH.my/AMK10-80725.18

Dear All,

We refer to the above matter and your email of even date.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your 10 appointed surveyors as stated in your aforesaid letter.

Our client hereby nominate surveyor from Marcus Chua of LKK Auto Consultants Pte Ltd named in paragraph 2 serial no 1 of your said email for the pre-repair survey ("PRS") of the damages to our client's vehicle arising out of the above mentioned accident.

Please be informed that our client's vehicle, SJS 6458 E is currently laying at our client's workshop, Ah Chang Motor Service Centre, Blk 10 Ang Mo Kio Industrial Park 2A, Ang Mo kio Point #03-16 Singapore 568047.

Kindly proceed to do the needful.

Regards,
Melody
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 6337 8700
Fax: 6337 3700

SJS 7436L
SJV 7905J

On Aug 16, 2018, at 1:39 PM, Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com> wrote:

<logo.jpeg>

<lock.gif>

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2018-08-23 13:39 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved

<SecureMessageAtt.html>

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: mail@cheonghoh.sg

To: Aashweenjeetkaur.Mithoosingh@aig.com

Cc: Lily.Tan@aig.com , Andy-SY.Fong@aig.com , Baljit.Kaur@aig.com , Lee-

Ying.Chin@aig.com , NoorManesa.AbuKassim@aig.com , Imran.Ishak@aig.com , ShengYang.Lim@aig.com , Syazairdina.Azian@aig.com , yokeshi.chan@aig.com

Subject: Re: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLK632B AND SJS6458E ON 13/08/2018; Our ref: LCH.my/AMK10-80725.18

Date: Thu, 16 Aug 2018 10:05:20 +0000

Dear All,

We refer to the above matter and your email of even date.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your 10 appointed surveyors as stated in your aforesaid letter.

Our client hereby nominate surveyor from Marcus Chua of LKK Auto Consultants Pte Ltd named in paragraph 2 serial no 1 of your said email for the pre-repair survey ("PRS") of the damages to our client's vehicle arising out of the above mentioned accident.

Please be informed that our client's vehicle, SJS 6458 E is currently laying at our client's workshop, Ah Chang Motor Service Centre, Blk 10 Ang Mo Kio Industrial Park 2A, Ang Mo Kio Point #03-16 Singapore 568047.

Kindly proceed to do the needful.

Regards,
Melody
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 6337 8700
Fax: 6337 3700

On Aug 16, 2018, at 1:39 PM, Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com> wrote:

<logo.jpeg>

<lock.gif>

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2018-08-23 13:39 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

<SecureMessageAtt.html>

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8083H
Vehicle Details	
Vehicle No.:	SJS6458E
Vehicle to be Exported:	No
Intended De-registration Date:	20 Aug 2018
Vehicle Make:	KIA
Vehicle Model:	CERATO FORTE 1.6 AT SX ABS D/AB 2WD 4DR
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	G4FC9H285374
Chassis No.:	KNAFW411MA5114831
Maximum Power Output:	92.7 kW (124 bhp)
Open Market Value:	\$14,195.00
Original Registration Date:	27 Aug 2009
First Registration Date:	27 Aug 2009
Transfer Count:	0
Actual ARF Paid:	\$12,214.00
OPC Cash Rebate Details	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Aug 2019
PARF Rebate Amount:	\$6,717.00
Intended COE Rebate Details	
COE Expiry Date:	26 Aug 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$0.00
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$6,717.00

The information contained herein is correct as at 20 Aug 2018

OK



AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
 Email: acm.chang@outlook.com / FB: www.facebook.com/AcmServiceCentre
 Tel / Fax: (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

SJS6458E Kia Cerato

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper assy / ee	\$ 760.00
2	2	Front bumper retainer / M6C	\$ 98.00
3	2	Front bumper bracket / BT	\$ 96.00
4	1	Front bumper reinforcement / BT	\$ 287.00
5	1	Front bumper lower grille / ee	\$ 127.00
6	1	Front bumper sponge / CPA	\$ 172.00
7	1	Front bumper left fog lamp X NN	\$ 252.00
8	1	Front bumper right fog lamp / SCR	\$ 252.00
9	1	Front left fog lamp garnish X NN	\$ 162.00
10	1	Front right fog lamp garnish / CA	\$ 162.00
11	1	Front grille with emblem / CPA	\$ 169.00
12	1	Front left headlamp / CA	\$ 685.00
13	1	Front right headlamp / CA	\$ 685.00
14	1	Front bonnet assy / BT	\$ 870.00
15	1	Front bonnet inner seal / M6C	\$ 112.00
16	2	Front bonnet rubber stopper X	\$ 36.00
17	1	Front bonnet insulator X NN	\$ 182.00
18	2	Front bonnet hinges X	\$ 220.00
19	1	Front bonnet lock mechanism / BT	\$ 108.00
20	2	Front horn X	\$ 178.00
21	1	Front left fender X NN	\$ 687.00
22	1	Front right fender X	\$ 687.00
23	1	Front left fender inner cowl X	\$ 118.00
24	1	Front right fender inner cowl X	\$ 118.00
25	1	Front support panel assy / BT	\$ 989.00
26	1	Front support panel top garnish X NN	\$ 126.00
27	1	Front air intake duct / ee	\$ 164.00
28	1	Front wiper tank X NN	\$ 87.00
29	1	Front wiper top garnish X NN	\$ 270.00
30	1	Front radiator assy / BT	\$ 1,233.00
31	1	Front radiator fan assy with motor / CPA	\$ 764.00
32	1	Front radiator expansion tank X NN	\$ 122.00
33	2	Front radiator top mounting X NN	\$ 66.00
34	1	Front air-con condenser assy / BT	\$ 1,296.00
35	2	Front air-con condenser rubber mounting X NN	\$ 66.00
36	1	Front air-con compressor assy X NN	\$ 845.00
Less 10%			\$ 13,251.00
			\$ 1,325.10
			\$ 11,925.90

5159.7
 10% = 4643.73

575
 18
 18
 173
 40
 79
 158.1
 27
 467
 467
 771.6
 20
 58
 373
 42
 632
 316
 696



AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
 Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
 Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

SJS6458E Kia Cerato

			Estimated Parts Price	
No	Qty	Parts Description		
<u>Special Nett Items</u>				
1	1	Front bumper lower spoiler / cut	\$ 750.00	120
2	6	Front bumper lower spoiler clips / nbc.	\$ 30.00	/
3	1	Front bumper lower spoiler sealant X N N	\$ 60.00	X
4	10	Front bumper clips /	\$ 50.00	40
5	4	Front grille clips / nbc	\$ 20.00	/
6	8	Front bonnet insulator clips /	\$ 30.00	/
7	4	Front left fog lamp garnish clips X n n	\$ 20.00	X
8	4	Front right fog lamp garnish clips / nbc	\$ 20.00	/
9	6	Front left fender inner cowling clips X	\$ 30.00	X
10	6	Front right fender inner cowling clips X n n	\$ 30.00	X
11	4	Front support panel top garnish clips X	\$ 20.00	X
12	1	Front radiator coolant /	\$ 80.00	40
13	1	Front air-con gas /	\$ 80.00	20
14	1	Front no plate with garnish (off peak) / nbc.	\$ 120.00	/
			<u>\$ 1,340.00</u>	
Total parts			\$ 13,265.90	440



AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
 Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
 Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

SJS6458E Kia Cerato

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 2,500.00	600
2	To putty and spray painting front portion.	\$ 2,500.00	600
3	To check wiring and focus front headlamp.	\$ 50.00	30
4	To remove and install air con system to facilitate the repair and refill gas.	\$ 180.00	60
5	To remove and install cooling system to facilitate the repair and check for leakage.	\$ 180.00	40
6	To remove and install front bonnet lock mechanism.	\$ 80.00	X NN
7	To apply anti rust proofing to front affected area.	\$ 150.00	60
8	To remove and install front air con compressor assy.	\$ 150.00	X NN
9	To repair, straighten and align both front door panel.	\$ 450.00	X NN
10	Towing accident vehicle to workshop.	\$ 120.00	40
11	To remove and install rear off-peak no plate and tow vehicle to LTA inspection.	\$ 120.00	X NN
Total labour :		\$ 6,480.00	1430

Total parts : \$ 13,265.90

Total labour : \$ 6,480.00

Total repair cost : \$ 19,745.90

Chao Qip . - 8288 0282 .

Lump Sum Repair .

6 Days .

After repair photos.

[Signature]
23/8/8.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6513.73

2%: 5000

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18015018/GVD3N2
Date: 18/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 09999994765
Claimant: SJS6458E Insured Vehicle No: SLK632B
Vehicle No: SJS6458E Nature of Claim: TP Claim No: 3736467480SG
Date of Loss: 13/08/2018

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJS6458E
Make & Model: KIA CERATO FORTE, 1.6 A/T ABS AB 2WD 4DR (A) Engine No: G4FC9H285374
Reg. Date: 27/08/2009 (Man. Year: 2009) Chassis No: KNAFW411MA5114831
Colour: Black Odometer: 212995 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	13,265.90	5,083.73	8,182.17	61.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,480.00	1,430.00	5,050.00	77.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,745.90	6,513.73	13,232.17	67.01
Approved Total (Overridden) (\$\$)		5,000.00		
(\$\$)	19,745.90	5,000.00	14,745.90	74.68
+ GST 7.00/7.00% (\$\$)	1,382.21	350.00	1,032.21	74.68
Nett Amount (\$\$)	21,128.11	5,350.00	15,778.11	74.68

INSPECTION

Date of Assignment: 17/08/2018
Date Inspected: 17/08/2018 Inspected At: Ah Chang Motor Service Centre (HQ)
10 ANG MO KIO INDUSTRIAL PARK
2A, ANG MO KIO POINT #03-16
Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER ASSY	Deformed	760.00 FL	*575.00 FL
2	2	*FRONT BUMPER RETAINER	Necessary	98.00 FL	*18.00 FL
3	2	*FRONT BUMPER BRACKET	Bent	96.00 FL	*18.00 FL
4	1	*FRONT BUMPER REINFORCEMENT	Bent	287.00 FL	*173.00 FL
5	1	*FRONT BUMPER LOWER GRILLE	Deformed	127.00 FL	*40.00 FL
6	1	*FRONT BUMPER SPONGE	Cracked	172.00 FL	*79.00 FL
7	1	*FRONT BUMPER LEFT FOG LAMP	Not Necessary	252.00 FL	*- FL
8	1	*FRONT BUMPER RIGHT FOG LAMP	Scratched	252.00 FL	*158.10 FL
9	1	*FRONT LEFT FOG LAMP GARNISH	Not Necessary	162.00 FL	*- FL
10	1	*FRONT RIGHT FOG LAMP GARNISH	Cut	162.00 FL	*27.00 FL
11	1	*FRONT GRILLE WITH EMBLEM	Cracked	169.00 FL	*169.00 FL
12	1	*FRONT LEFT HEADLAMP	Cut	685.00 FL	*467.00 FL
13	1	*FRONT RIGHT HEADLAMP	Cut	685.00 FL	*467.00 FL
14	1	*FRONT BONNET ASSY	Bent	870.00 FL	*771.60 FL
15	1	*FRONT BONNET INNER SEAL	Necessary	112.00 FL	*20.00 FL
16	2	*FRONT BONNET RUBBER STOPPER	Not Necessary	36.00 FL	*- FL
17	1	*FRONT BONNET INSULATOR	Not Necessary	182.00 FL	*- FL
18	2	*FRONT BONNET HINGES	Not Necessary	220.00 FL	*- FL
19	1	*FRONT BONNET LOCK MECHANISM	Bent	108.00 FL	*58.00 FL
20	2	*FRONT HORN	Not Necessary	178.00 FL	*- FL
21	1	*FRONT LEFT FENDER	Not Necessary	687.00 FL	*- FL
22	1	*FRONT RIGHT FENDER	Not Necessary	687.00 FL	*- FL
23	1	*FRONT LEFT FENDER INNER COWLING	Not Necessary	118.00 FL	*- FL
24	1	*FRONT RIGHT FENDER INNER COWLING	Not Necessary	118.00 FL	*- FL
25	1	*FRONT SUPPORT PANEL ASSY	Bent	989.00 FL	*373.00 FL
26	1	*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	126.00 FL	*- FL
27	1	*FRONT AIR INTAKE DUCT	Deformed	164.00 FL	*42.00 FL
28	1	*FRONT WIPER TANK	Not Necessary	87.00 FL	*- FL
29	1	*FRONT WIPER TOP GARNISH	Not Necessary	270.00 FL	*- FL
30	1	*FRONT RADIATOR ASSY	Bent	1,233.00 FL	*632.00 FL
31	1	*FRONT RADIATOR FAN ASSY WITH MOTOR	Cracked	764.00 FL	*376.00 FL
32	1	*FRONT RADIATOR EXPANSION TANK	Not Necessary	122.00 FL	*- FL
33	2	*FRONT RADIATOR TOP MOUNTING	Not Necessary	66.00 FL	*- FL
34	1	*FRONT AIR-CON CONDENSER ASSY	Bent	1,296.00 FL	*696.00 FL
35	2	*FRONT AIR-CON CONDENSER RUBBER MOUNTING	Not Necessary	66.00 FL	*- FL
36	1	*FRONT AIR-CON COMPRESSOR ASSY	Not Necessary	845.00 FL	*- FL
37	1	*FRONT BUMPER LOWER SPOILER	Cut	750.00 FS	*120.00 FS
38	6	*FRONT BUMPER LOWER SPOILER CLIPS	Necessary	30.00 FS	*30.00 FS
39	1	*FRONT BUMPER LOWER SPOILER SEALANT	Not Necessary	60.00 FS	*- FS
40	10	*FRONT BUMPER CLIPS	Necessary	50.00 FS	*40.00 FS
41	4	*FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
42	8	*FRONT BONNET INSULATOR CLIPS	Necessary	30.00 FS	*30.00 FS
43	4	*FRONT LEFT FOG LAMP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
44	4	*FRONT RIGHT FOG LAMP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
45	6	*FRONT LEFT FENDER INNER COWLING CLIPS	Not Necessary	30.00 FS	*- FS
46	6	*FRONT RIGHT FENDER INNER COWLING CLIPS	Not Necessary	30.00 FS	*- FS
47	4	*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
48	1	*FRONT RADIATOR COOLANT	Necessary	80.00 FS	*40.00 FS
49	1	*FRONT AIR-CON GAS	Necessary	80.00 FS	*20.00 FS
50	1	*FRONT NO PLATE WITH GARNISH (OFF PEAK)	Necessary	120.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 14,591.00 5,599.70

- List Item Discount on L Items 10.00/10.00% (S\$) 1,325.10 515.97

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	13,265.90 5,083.73

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN FRONT AFFECTED AREA AND REPLACE FRONT DAMAGED PARTS	New	2,500.00	600.00
2	TO PUTTY AND SPRAY PAINTING FRONT PORTION	New	2,500.00	600.00
3	TO CHECK WIRING AND FOCUS FRONT HEADLAMP	New	50.00	30.00
4	TO REMOVE AND INSTALL AIR CON SYSTEM TO FACILITATE THE REPAIR AND REFILL GAS	New	180.00	60.00
5	TO REMOVE AND INSTALL COOLING SYSTEM TO FACILITATE THE REPAIR AND CHECK FOR LEAKAGE	New	180.00	40.00
6	TO REMOVE AND INSTALL FRONT BONNET LOCK MECHANISM	New	80.00	-
7	TO APPLY ANTI RUST PROOFING TO FRONT AFFECTED AREA	New	150.00	60.00
8	TO REMOVE AND INSTALL FRONT AIR CON COMPRESSOR ASSY	New	150.00	-
9	TO REPAIR,STRAIGHTEN AND ALIGN BOTH FRONT DOOR PANEL	New	450.00	-
10	TOWING ACCIDENT VEHICLE TO WORKSHOP	New	120.00	40.00
11	TO REMOVE AND INSTALL REAR OFF-PEAK NO PLATE AND TOW VEHICLE TO LTA INSPECTION	New	120.00	-
Gross Labour Cost (S\$)			6,480.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >