

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGA 4493X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAIL LAMP RH	REPLACED	179.60	179.60
3	REAR TAIL LAMP CLIP RH	REPLACED	19.50	19.50
1	REAR BUMPER	REPLACED	528.60	528.60
2	REAR BUMPER SIDE RETAINER RH / LH	REPLACED	64.00	64.00
1	REAR WINDSCREEN GLASS MOULDING	REPLACED	64.00	64.00
1	REAR FENDER RH	REPAIRED SEE LABOUR	822.00	-
1	REAR SHOCK ABSORBER RH	NOT NECESSARY	216.00	-
1	REAR WHEEL HUB C/W BEARING RH	NOT NECESSARY	291.00	-
	LESS 10% DISCOUNT		-	-85.57
			2,184.70	770.13
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN GLASS SEALANT (SN)	NOT NECESSARY	70.00	-
1	REAR BUMPER LOWER SPOILER (SN)	REPLACED	800.00	400.00
1	REAR SPORT RIM RH (SN)	REPLACED	650.00	250.00
			1,520.00	650.00
<u>LABOUR</u>				
	TO STRAIGHTEN AND PANEL BEATING REAR RH TAIL LAMP INNER PANEL AND REAR FRAME MEMBERS. TO CUT / WELD REAR RH FENDER. TO REMOVE AND REFIT ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER RH.		1,400.00	700.00
	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS.		1,000.00	700.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	30.00
	TO RUST PROOF AFFECTED AREAS.		120.00	30.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT LINING, UPHOLSTERY, CUSHION SEATS, GARNISH, FITTINGS, ETC. TO ASSIST REPAIR.		200.00	60.00
	TO REMOVE, REFIT REAR RH SPORT RIM/ TYRE AND BALANCING.		50.00	30.00
	TO REMOVE AND REFIT REAR SUSPENSION SYSTEM.	NOT NECESSARY	400.00	-

Report Ref No. CS/AIG18015078/T1sbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT ELECTRONIC WHEEL ALIGNMENT TEST.		180.00	60.00
			3,580.00	1,610.00
GRAND TOTAL			7,284.70	3,030.13
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CS/AIG18015078/T1sbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.