



## Shirley Hiew (LKK Auto)

**From:** Wui, Shawnkaijye <Shawnkaijye.Wui@aig.com>  
**Sent:** Tuesday, 16 October 2018 11:49 AM  
**To:** Shirley Hiew (LKK Auto)  
**Cc:** SUR; Reports (LKKAuto)  
**Subject:** RE: <Re-inspection Report>Your Ref :0110659909SG-003 \*Our Ref: CS/AIG18015078/T1sbe2

Dear Shirley,

Noted and thanks.

Please assist to amend report based on comment.

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGA 4493X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR TAIL LAMP RH	REPLACED	179.60	179.60
3	REAR TAIL LAMP CLIP RH	REPLACED	19.50	19.50
1	REAR BUMPER	REPLACED	528.60	528.60
2	REAR BUMPER SIDE RETAINER RH / LH	REPLACED	64.00	64.00
1	REAR WINDSCREEN GLASS MOULDING	REPLACED	64.00	64.00
1	REAR FENDER RH	REPAIRED SEE LABOUR	822.00	-
1	REAR SHOCK ABSORBER RH	NOT NECESSARY	216.00	-
1	REAR WHEEL HUB C/W BEARING RH	NOT NECESSARY	291.00	-
LESS 10% DISCOUNT			-	-85.57

Thanks and Regards,  
Shawn Wui  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1959 | Fax +(65) 6835 7416

[Shawnkaijye.Wui@aig.com](mailto:Shawnkaijye.Wui@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

---

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]  
**Sent:** Monday, October 15, 2018 6:58 PM  
**To:** Wui, Shawnkaijye  
**Cc:** SUR; Reports (LKKAuto)  
**Subject:** RE: <Re-inspection Report>Your Ref :0110659909SG-003 \*Our Ref: CS/AIG18015078/T1sbe2

Dear Shawn,

We refer to your below email above matter.

According to our surveyor, usually when fender is repaired, it is not necessary to remove the rear windscreen, item not allowed for replace.

From the photos, it shows that the damage is minor and its impact is not direct as it's a side swipe case base on the accident report. It is unlikely that the undercarriage will be damage, therefore not necessary to replace, item not allowed.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]

**Sent:** Thursday, 11 October 2018 10:23 AM

**To:** 'Wui, Shawnkaiye' <[Shawnkaiye.Wui@aig.com](mailto:Shawnkaiye.Wui@aig.com)>

**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Reports (LKKAuto) <[report@lkkauto.com](mailto:report@lkkauto.com)>

**Subject:** RE: <Re-inspection Report>Your Ref :0110659909SG-003 \*Our Ref: CS/AIG18015078/T1sbe2

Dear Shawn,

We will check & revert.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Wui, Shawnkaiye [<mailto:Shawnkaiye.Wui@aig.com>]

**Sent:** Thursday, 11 October 2018 8:55 AM

**To:** Reports (LKKAuto) <[report@lkkauto.com](mailto:report@lkkauto.com)>

**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** RE: <Re-inspection Report>Your Ref :0110659909SG-003 \*Our Ref: CS/AIG18015078/T1sbe2



Dear Elaine,

Refer to the adjustment.

Please advise me,

When fender was classified as repaired, it the rear windscreen glass moulding necessary whereby no cutting of fender, no removal of rear windscreen.

For shock absorber RH and rear wheel hub c/w bearing RH, are these two items has been replaced or not necessary?

PRS photo	Re-inspection Photo
 <p>18/19: 1st Inspection view</p>	

It seems like there is no replacement.

Kindly revert to me as soon as possible.

Thanks and Regards,  
**Shawn Wui**  
**AIG**  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1959 | Fax +(65) 6835 7416

[Shawnkaijye.Wui@aig.com](mailto:Shawnkaijye.Wui@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

**From:** Reports (LKKAUTO) [<mailto:report@lkkauto.com>]

**Sent:** Wednesday, October 10, 2018 4:26 PM

**To:** Wui, Shawnkaijye

**Cc:** SUR

**Subject:** <Re-inspection Report>Your Ref :0110659909SG-003 \*Our Ref: CS/AIG18015078/T1sbe2

Your Ref : 0110659909SG-003  
Our Ref : CS/AIG18015078/T1sbe2

Dear Shawn Wui,

We refer to the above matter.

Enclosed herewith the re-inspection report and our note of charge for your necessary action.

Thank you.

Best Regards,

**Elaine | Reports**

**LKK Auto Consultants Pte.Ltd.**

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: [report@lkkauto.com](mailto:report@lkkauto.com)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# PAIR Automotive Consultancy

Regs. No: 32988974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel: 64531173, Fax: 64536131

Consultants: Vehicle appraisal & inspection, accident investigation, expert witness

Report No: 0097-18-EMAm

31 July 2018

## ACCIDENT VEHICLE SURVEY REPORT

Lim Ying Ping  
c/o 160 Sin Ming Drive #03-19 Sin Ming Autocity  
Singapore 575722

### VEHICLE INFORMATION:

Vehicle Reg No.:	SGA4493X	Odometer:	116865km
Make & Model:	Kia Cerato Forte 16SX AT	Colour:	Red
Chassis number:	KNAFW411MA5242742	Date of accident:	01/04/2018
Year of Regn.:	12/10/2010	Date inspected:	16/04/2018
Repairer at:	EM Solution Pte Ltd	Date inspected (After Repair):	20/04/2018
	160 Sin Ming Drive #03-19 Sin Ming Autocity		
	Singapore 575722		

### STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

### TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	5mm/Michelin	5mm/Michelin	215/45R17
Rear:	5mm/Michelin	5mm/Michelin	215/45R17

### POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear RH portion.  
Please see details as described in the Annex for parts and labour.

### REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

## Parts and Labour Assessment

Report No: 0097-18-EMAm Vehicle No: SGA4493X

Description of part	Qty	Condition as inspected	Repairer's estimate	Our adjustment
Rear tail lamp RH	1	fractured	179.60	179.60
Rear tail lamp clip RH	3	necessary	19.50	19.50
Rear bumper	1	fractured	528.60	528.60
Rear bumper side retainer RH/LH	2	necessary	64.00	64.00
Rear windscreen glass moulding	1	necessary	64.00	nn X 64.00
Rear fender RH	1	buckled	822.00	Rx 822.00
Rear shock absorber RH	1	bent	216.00	nn X 216.00
Rear wheel hub c/w bearing RH	1	jammed	291.00	nn X 291.00

Subtotal before discount 2,184.70 2,184.70 855.30

Percentage discount 0% and 10% 0.00 218.47

Sub total 1 2,184.70 1,966.23 770.13

Rear windscreen glass sealant	1	necessary	70.00	nn X 70.00
Rear bumper lower spoiler	1	fractured	800.00	400 800.00
Rear sport rim RH	1	abraded	650.00	250 650.00 650

Subtotal before discount 1,520.00 1,520.00

Percentage discount 0% and 0% 0.00 0.00

Sub total 2 1,520.00 1,520.00

Parts-total 3,704.70 3,486.23

### LABOUR

1. To straighten and panel beating rear RH tail lamp inner panel and rear frame members. To cut/weld rear RH fender. To remove and refit above parts.	1,400.00	1,100.00 700
2. To putty, re-spray painting and polish affected areas.	1,000.00	800.00 700
3. To check and rectify wiring system.	80.00	50.00 30
4. To rust proof affected areas.	120.00	60.00 30
5. To remove and refit rear windscreen glass.	150.00	120.00 nn X
6. To remove and refit lining, upholstery, cushion seats, garnish, fittings, etc. to assist repair.	200.00	150.00 60
7. To remove, refit rear RH sport rim/tyre and balancing.	50.00	40.00 30
8. To remove and refit rear suspension system.	400.00	350.00 X
9. To conduct electronic wheel alignment test.	180.00	150.00 60

Labour total 3,580.00 2,820.00 1800


Parts & Labour total 7,284.70 6,306.23 3220.13

Sdys

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on LUMP SUM repairs is : **\$5,000.00**  
and the recommended number of working days for the repairs is : **8**

  
B J Loi (I Eng. MIM, AIRTE)  
Automotive Appraiser





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGA 4493X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR TAIL LAMP RH	REPLACED	179.60	179.60
3	REAR TAIL LAMP CLIP RH	REPLACED	19.50	19.50
1	REAR BUMPER	REPLACED	528.60	528.60
2	REAR BUMPER SIDE RETAINER RH / LH	REPLACED	64.00	64.00
1	REAR WINDSCREEN GLASS MOULDING	NOT NECESSARY	64.00	-
1	REAR FENDER RH	REPAIRED SEE LABOUR	822.00	-
1	REAR SHOCK ABSORBER RH	NOT NECESSARY	216.00	-
1	REAR WHEEL HUB C/W BEARING RH	NOT NECESSARY	291.00	-
	LESS 10% DISCOUNT		-	-79.17
			2,184.70	712.53
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR WINDSCREEN GLASS SEALANT (SN)	NOT NECESSARY	70.00	-
1	REAR BUMPER LOWER SPOILER (SN)	REPLACED	800.00	400.00
1	REAR SPORT RIM RH (SN)	REPLACED	650.00	250.00
			1,520.00	650.00
<b><u>LABOUR</u></b>				
	TO STRAIGHTEN AND PANEL BEATING REAR RH TAIL LAMP INNER PANEL AND REAR FRAME MEMBERS. TO CUT / WELD REAR RH FENDER. TO REMOVE AND REFIT ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER RH.		1,400.00	700.00
	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS.		1,000.00	700.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	30.00
	TO RUST PROOF AFFECTED AREAS.		120.00	30.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT LINING, UPHOLSTERY, CUSHION SEATS, GARNISH, FITTINGS, ETC. TO ASSIST REPAIR.		200.00	60.00
	TO REMOVE, REFIT REAR RH SPORT RIM/ TYRE AND BALANCING.		50.00	30.00
	TO REMOVE AND REFIT REAR SUSPENSION SYSTEM.	NOT NECESSARY	400.00	-

Report Ref No. CS/AIG18015078/T1sbe2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT ELECTRONIC WHEEL ALIGNMENT TEST.		180.00	60.00
			3,580.00	1,610.00
GRAND TOTAL			7,284.70	2,972.53
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,350.00

Report Ref No. CS/AIG18015078/T1sbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.